

## U.S. Department of Housing and Urban Development

451 Seventh Street, SW Washington, DC 20410 www.hud.gov

espanol.hud.gov

# **Environmental Review for Activity/Project that is Categorically Excluded Subject to Section 58.5**

**Pursuant to 24 CFR 58.35(a)** 

#### **Project Information**

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano

Responsible Entity: Puerto Rico Department of Housing

State/Local Identifier: PR-CRP-000876

**Preparer:** William Sarriera, ACE Environmental, Inc.

#### **Certifying Officer Name and Title:**

Aldo Rivera, Permits and Environmental Compliance Director

Ángel G. López Guzmán - Permits and Environmental Compliance Deputy Director

María T. Torres- Bregón - Permits and Environmental Compliance Manager Sally Z. Acevedo-Cosme - Permits and Environmental Compliance Specialist Pedro de León Rodríguez - Permits and Environmental Compliance Specialist

Ivelisse Lorenzo Torres - Permits and Environmental Compliance Specialist

Santa Ramírez Lebrón - Permits and Environmental Compliance Specialist

Janette I. Cambrelen – Permits and Environmental Compliance Specialist

Limary Vélez Marrero - Permits and Environmental Compliance Specialist

Mónica Machuca Ríos - Permits and Environmental Compliance Specialist

Abdul Feliciano-Plaza: Permits and Environmental Compliance Specialist

Javier Mercado-Barrera: Permits and Environmental Compliance Specialist

Priscilla Toro-Rivera - Permits and Environmental Compliance Specialist

Grant Recipient (if different than Responsible Entity): Municipality of San Germán

Consultant (if applicable): ACE Environmental, Inc., PO Box 1005, Boquerón, PR 00622-1205 (787) 567-1302 - wsarriera.ace@gmail.com

**Direct Comments to:** Puerto Rico Department of Housing at *environmentcdbg@vivienda.pr.gov* 

**Project Location:** Plaza Santo Domingo and Plaza Mariano Quiñones Municipality of San Germán, Puerto Rico 00683.

Refer to Exhibit 1 Site Location Map.

Plaza Santo Domingo @Belvis, Félix Arce Lugo, Yamil Galib and Carro streets

Coordinates 18.0819, -67.0420

Cadaster Nos.: 334-034-032-01-000 & 334-034-033-01-000

Plaza Mariano Quiñones @ Padre San Agustinos, Ruiz Belvis, De la Cruz streets

Coordinates 18.0822, -67.0431 Cadaster No.: 334-034-019-01-000

#### **Description of the Proposed Project** [24 CFR 50.12 & 58.32; 40 CFR 1508.25]:

The Municipality of San Germán proposes the rehabilitation of the two most prominent public spaces in the city: Plaza Santo Domingo and Plaza Francisco Mariano Quiñones. Both squares make up the urban "backbone" of the town, they run in an east-west direction, are linked by the Ruiz Belvis Street and around by several of the most emblematic structures of "La Ciudad de las Lomas": the Church of San Germán de Auxerre, Porta Coeli, the original City Hall and notable residences, among them, the old House of Waldemar Morales in the "Queen Ann" architectural style, the house of Ernestito Quiñones and the so-called Casa de las Bahr. Both squares are longitudinal and are bordered by streets on all four sides. Mariano Quiñones Square is surrounded by Padres Agustinos, Ruiz Belvis, De la Cruz streets and a street space without its own name in front of the former mayor's office. Both squares are longitudinal and are bordered by streets on all four sides. the project footprint includes the two plazas and the original footprint surrounding the immediate streets and sidewalks as delimited in the project's plans. No other areas beyond this footprint will be impacted. Plaza Santo Domingo is surrounded by Belvis, Félix Arce Lugo, Yamil Galib and Carro streets. Plaza Mariano Quiñones covers 12,755.2 square feet; the Plaza de Santo Domingo comprises 13,013.6 square feet.

The proposed intervention for Mariano Quiñones Plaza and Santo Domingo Plaza —the pair of emblematic public spaces in San Germán—comprises improvements within their perimeter as well as in the surrounding streets and sidewalks, as delimited in the project's plans. The project respects the general appearance of both spaces, maintaining and repairing their paving, planters, vegetation, and sculptural elements; also restoring most existing materials and finishes. In parallel, selective technical and aesthetic improvements are incorporated for better functionality and appearance, including new lighting posts and benches. In Mariano Quiñones Plaza, a gazebo will be reincorporated to evoke one that previously existed there to encourage varied programming of various public activities. In Santo Domingo Plaza, we propose placing a pedestal clock that, visible from both plazas, will strengthen the spatial connection between them. At its east and west ends, new benches will be added for the enjoyment of the surrounding architecture. The footprint of each plaza will remain as is, not increased or reduced. The project includes construction work, repairs, improvements, material removals, and minor excavations in both plazas, partially intervening in surrounding streets, intersections, sidewalks, curbs, and gutters. The specific nature of the work to be carried out is detailed in the project's construction documents. As part of the project, safety measures will be implemented in compliance with federal and local regulations for pedestrians, cyclists, and vehicular traffic in this area.

#### **Level of Environmental Review Determination:**

The proposed projects is Categorically Excluded per 24 CFR 58.35(a) (3) (iii), and subject to §58.5: (1) Acquisition, repair, improvement, reconstruction, or rehabilitation of public facilities and improvements (other than buildings) when the facilities and improvements are in place and will be retained in the same use without change in size or capacity of more than 20 percent (e.g., replacement of water or sewer lines, reconstruction of curbs and sidewalks, repaying of streets).

## **Funding Information**

<b>Grant Number</b>	HUD Program	Funding Amount
B-17-DM-72-0001		
B-18-DM-72-0001	CDBG-DR	¢11 020 612 220
B-19-DP-78-0002	CDBG-DR	\$11,938,612,230
B-18-DE-72-0001		

**Estimated Total HUD Funded Amount: \$3,646,462.12** 

Estimated Total Project Cost (HUD and non-HUD funds) [24 CFR 58.32(d)]: \$3,646,462.12

## Compliance with 24 CFR 50.4, 58.5, and 58.6 Laws and Authorities

Record below the compliance or conformance determinations for each statute, executive order, or regulation. Provide credible, traceable, and supportive source documentation for each authority. Where applicable, complete the necessary reviews or consultations and obtain or note applicable permits of approvals. Clearly note citations, dates/names/titles of contacts, and page references. Attach additional documentation as appropriate.

Compliance Factors: Statutes, Executive Orders, and Regulations listed at 24 CFR §58.5 and §58.6	Are formal compliance steps or mitigation required?	Compliance determinations
STATUTES, EXECUTIVE OI & 58.6	RDERS, AND R	EGULATIONS LISTED AT 24 CFR 50.4
Airport Hazards  24 CFR Part 51 Subpart D	Yes No	The project site is located 73,806 feet northwest from the nearest civilian airport Mayagüez Eugenio Maria de Hostos Airport (MAZ) in Mayagüez, PR. The closest military airport is Luis Muñoz Marín International Airport (SJU) 378,259 feet northeast from the project site.  Project is not located within 15,000 feet of a military airport or 2,500 feet of a civilian airport. It is not located within an Airport Clear Zones and Accident Potential Zones. It will not be impacted by civilian or military airports; and will have no impact on any airports. The project is in compliance with the HUD's Airport Hazard regulations. No further evaluation is required.  Source Document: Exhibit 2 - Map depicting airports and heliports within the project Site.

		Reference: Federal Aviation Administration (FAA) <a href="https://adds-faa.opendata.arcgis.com/">https://adds-faa.opendata.arcgis.com/</a>
Coastal Barrier Resources Act, as amended by the Coastal Barrier Improvement Act of 1990 [16 USC 3501]	Yes No	The project is not located in a coastal barrier resource area. The nearest coastal barriers system PR-65P is located approximately 39,230 feet south from site. This project has no potential to impact a CBRS Unit and is in compliance with the Coastal Barrier Resources Act. No further evaluation is required.  Source Document: Exhibit 3 – Coastal Barriers Resources Map depicting coastal barriers resources within the project site. Reference: U.S. Fish and Wildlife Service Coastal Barriers Resources Mapper https://fwsprimary.wim.usgs.gov/CBRSMapper-v2/. https://fwsprimary.wim.usgs.gov/rest/directories/arcgisoutput/ExportWebMap_GPServer_ags_ec99b9996d9743df974abf8db31b0d25.pdf
*	Yes No	The Project site is not within the floodplain. It is located within FEMA designated Zone X Unshaded (an area of minimal flood hazard) as per Flood Insurance Rate Map 72000CO1560J. Effective Date: November 18, 2009.  Floodplain insurance will not be required for the project facilities. The project is in compliance with the requirements of the Executive Order 11988, particularly section 2(a); 24 CFR Part 55.  Source Document: Exhibit 4 FIRMette Reference: Flood Insurance Rate Map 72000CO1560J. Effective Date: November 18, 2009.
& 58.5 Clean Air	, I	The Project site is not located in county or air
Clean Air Act, as amended, particularly section 176(c) & (d); 40 CFR Parts 6, 51, 93	Yes No	quality management district in a non-attainment or maintenance status for all criteria pollutants. Project site is located about 33 miles from the Arecibo Lead non-attainment area, 60 miles from

Contamination and Toxic Substances 24 CFR Part 50.3(i) & 58.5(i)(2)	Yes No	Reference: Exhibit 6 – Municipalities and Coastal Sectors Map Source: Puerto Rico Planning Board, Puerto Rico Coastal Zone Management Program – Final EIS 1978 Estudios Técnicos, Inc. Puerto Rico Coastal Zone Management Program Revision and Update  A search of the NEPAssist database identified regulated sites within a 3,000-foot radius of the project site. As part of the environmental assessment, multiple evaluations were conducted to determine the presence of Recognized Environmental Conditions (RECs), underground storage tanks (USTs), Lead-based paint (LBP), and asbestos-containing materials (ACM) within the site. The findings of these evaluations are detailed below.
Coastal Zone Management  Coastal Zone Management Act, sections 307(c) & (d)	Yes No	The Project is located approximately 31,680 ft from the southwest shoreline of Puerto Rico. It will not a Coastal Zone as defined in the Puerto Rico Coastal Zone Management Plan. The Project is in compliance with the Coastal Zone Management Act.
		the nearest SO² non-attainment area and 52 miles from the PM <sub>10</sub> maintenance Area. The Project is in compliance with the requirements of the air quality regulations and the Clean Air Act. No further evaluation is required.  Reference: Exhibit 5 – Air Quality Map Exhibit 5A - Source: U.S. EPA Air Quality Non-attainment Areas (Shapefile) – NEPAssist Tool https://nepassisttool.epa.gov/nepaassist/nepamap.aspx USEPA Nonattainment and Maintenance Area Dashboard https://edap.epa.gov/public/extensions/S4S_Public_Dashboard_1.html

Based on a review of the EPA's ECHO database, several regulated facilities are located around the project site in a 3,000 ft buffer zone. After reviewing the detailed facility reports, none of these facilities would pose a contamination hazard or non-compliance issues to the proposed project.

- No Significant Violations: None of the facilities have reported significant violations or enforcement actions within the last three years.
- No Recent Penalties or Noncompliance: All reviewed facilities show zero quarters in noncompliance during the last three-year monitoring period and no penalties or enforcement fines have been assessed.
- No Hazardous Releases Reported: There are no records of hazardous waste discharges, toxic releases, or air/water emissions that could impact the project site.
- Upgradient/Distanced Facilities: Based on geospatial review and location data, the facilities are either downgradient or at a safe distance from the project site, minimizing any risk of contaminant migration.
- Permit Compliance: Facilities have with no active violations.

A review of available records, including EPA-provided mapping data, indicates that no open underground storage tanks (USTs) are present within a 3,000-foot radius of the project site. Based on this information, there are no known USTs that could present a potential environmental concern for the proposed project. Refer to Exhibit 7L for USTs Map.

An on March 18, 2023, an Asbestos Containing Material (ACM) inspection was performed by Zimmetry Environmental Management CORP, DRNA/AHERA certified-asbestos inspector. No ACM was identified in the inspection. On the same day, an inspection conducted by Zimmetry Environmental Management CORP, DRNA/AHERA certified inspector for Leadbased paint (LBP) identified in several elements of the project site for which a mitigation plan will be implemented. Refer to Exhibit 7M & Exhibit 7N

Regarding Radon, HUD issued Notice CPD-23-103 on January 11, 2024, requiring the consideration of radon in the Environmental Review process for all HUD-funded projects.

However, the recommended. best practices and alternative options for radon testing are deemed infeasible and impracticable for this project. As documented in the Radon Memorandum and agency correspondence, the Puerto Department of Housing (PRDOH) reached out to six (6) local, state, and federal agencies to assess the feasibility of radon testing. Responses were received from the United States Geological Survey, Centers for Disease Control and Prevention, Puerto Rico Department of Health, and the United States Environmental Protection Agency, confirming the lack of scientific data on radon testing for Puerto Rico and the technical challenges associated with complying with HUD's radon testing requirements. Due to these limitations, radon testing is determined to be infeasible and impracticable for this property, and no further consideration of radon is required in this environmental review. Refer to Exhibit 7O. A field reconnaissance took place at the proposed project site by William Sarriera, ACE environmental, on February 1, 2023, May 5, 2023, and May 31, 2024, with the intent of evaluate environmental aspects. No recognized environmental conditions (RECs) were identified within the project site. The inspection did not reveal any evidence of contamination related to hazardous substances or petroleum products, such as leaking storage tanks, improperly disposed chemicals, or malfunctioning equipment that could release contaminants into the environment.

#### Reference:

Exhibit 7 – Contamination and Toxic Substances Map

Exhibits 7B – 7K Contamination and Toxic Substances Envirofacts and ECHO Reports

Exhibit 7L UST Map

Exhibit 7M Asbestos-Containing Material Inspection Report

Exhibit 7N Lead-Based Paint Inspection Report Exhibit 7O – Radon Memorandum and agency correspondence

Exhibit 16 – Field Inspection Report

Source Document NEPAssist Tool Analysis https://nepassisttool.epa.gov/nepassist/nepamap. aspx

Endangered Species  Endangered Species Act of 1973, particularly section 7; 50 CFR Part 402	Yes No	A review of US Fish and Wildlife Service IPAc Website Database for the Project site provided a resource list of endangered species that might potentially be affected by the proposed. The list only identified the Puerto Rican Boa (Epicrates inornatus) and the Yellow-shouldered Blackbird (Agelaius xanthomus). There are no critical habitats at this location for the Puerto Rican Boa.
		However, the USFWS indicates the proposed project site overlaps an area identified as critical habitat for the Yellow-shouldered Blackbird. None of the endangered species listed above were observed within the Project area.
		The proposed project area was visited on February 1, 2023, and May 31, 2024. The site is completely developed. During site visit to the project site (February 1, 2023, and May 31, 2024) the Puerto Rican Boa (Epicrates inornatus) and the Yellow-shouldered Blackbird ( <i>Agelaius xanthomus</i> ) were not observed. It is important to note that no bird nests were observed at any of the existing trees on both the plazas.
		USFWS biological assessment concluded that the project would have no effect on the Puerto Rican Boa (Epicrates inornatus) and issued a No Effect Determination, dated February 14, 2024.
		The project activity will be conducted in a fully developed urban area and thus would have no effect on any natural habitats or federally protected species. The project site and its surroundings are entirely developed, lacks suitable tree coverage, therefore does not support the Yellow-shouldered Blackbird ( <i>Agelaius xanthomus</i> ) habitat requirements. USFWS biological assessment concluded that the project would have no effect on the Yellow-shouldered Blackbird ( <i>Agelaius xanthomus</i> ) and issued a No Effect Determination, dated February 14, 2024.
		The Project does not require further any further consultation/coordination under Section 7. The proposed activities are covered by the USFWS Blanket Clearance Letter for Federally sponsored projects, Housing and Urban Development of January 14 of 2013.

		If a Puerto Rican boa or the Yellow-shouldered Blackbird is found in the project activity site, work shall cease until the Boa or Yellow-shouldered Blackbird moves off on its own. If the Boa does not move off, the Construction Manager shall contact the Puerto Rico Department of Natural Resourses and Environment and request relocation of the Boa. 787-724-5700, 787-230-5550, 787-771-1124.  The project is in compliance with the Endangered Species Act of 1973, particularly section 7; 50 CFR Part 402.  Reference: Exhibit 8 and 8A – Critical Habitats Map and Endangered Species Supporting Documents  Source: US Fish & Life Service Information for Planning and Consultation IPAc Resource List USFWS Consistency letter for the project named 'Rehabilitation of Plaza Santo Domingo and Plaza Francisco Mariano, San Germán, Puerto Rico' for specified threatened and endangered species, that may occur in your proposed project location, pursuant to the IPaC determination key titled Caribbean Determination Key (DKey), dated December 12, 2024.  USFWS No Effect Determination for the Puerto Rican Boa (Epicrates inornatus) dated 14 February 2024.  ACE environmental, Flora and Fauna Description Plaza Santo Domingo and Plaza Francisco Mariano, San German, PR. 2024 Endangered Species and Critical Habitat Certification, Rehabilitation of Plaza Santo Domingo and Plaza Francisco Mariano, San Germán, Puerto Rico CDBG-DR Program – Municipality of San Germán Project No. 000876, dated 26 February 2024.
Explosive and Flammable Hazards  24 CER Port 51 Subport C	Yes No	The proposed project does not include a hazardous facility that mainly stores, handles, or processes flammable or combustible chemicals such as bulk fuel storage facilities. The project
24 CFR Part 51 Subpart C		would not include development, construction, rehabilitation that will increase residential densities, or conversion. The project would not increase the number of people that would be

Historic Preservation	Yes No	Consultation with the Puerto Rico State Historic Preservation Office (PRSHPO) regarding the Department of Housing of Puerto Rico (PRDOH) Program was initiated on April 30 24, 2024, with
		Reference: Exhibit 11 Floodplain Management Map Source Document: Advisory Base Flood Elevation (ABFE) Map for FIRM Panel No. 72000CO1560J.
Floodplain Management  Executive Order 11988, particularly section 2(a); 24 CFR Part 55	Yes No	The Project site is not in the floodplain, as indicated on the Advisory Base Flood Elevation map. The project site is within the Zone X Unshaded area of minimal flood hazard.  The Project is in compliance with Executive Order 11988, particularly section 2(a); 24 CFR Part 55. No formal compliance steps or mitigation are required. See Base Flood Elevations (ABFE) map included in Exhibit 11.
		Reference: Exhibit 10 Farmland Protection Map Source: United States Department of Agriculture, Natural Resources Conservation Services. Web Soil Survey. Internet Web Site: <a href="https://websoilsurvey.nrcs.usda.gov/app/WebSoilsurvey.aspx">https://websoilsurvey.nrcs.usda.gov/app/WebSoilsurvey.aspx</a>
Farmlands Protection  Farmland Protection Policy Act of 1981, particularly sections 1504(b) and 1541; 7 CFR Part 658	Yes No	The Project site consists of completely developed urban land. Project does not include any activities, including new construction, acquisition of undeveloped land or conversion, that could convert agricultural land to a non-agricultural use. The project is in compliance with the requirements of the Farmland Protection regulations.
		exposed to flammable or explosive hazards. The project is in compliance with the requirements of the regulations. Examination of the aerial views and street views shows no above ground storage tanks within the acceptable separation distance.  Reference: Exhibit 9 Explosive and Flammable Hazards Map Source: USEPA Enviro Mapper: https://geopub.epa.gov/myem/efmap//index.html?ve=13,47.236778259277344,- 122.35669708251953&pText=Fife,%20WA

National Historic Preservation Act of 1966, particularly sections 106 and 110; 36 CFR Part 800		a letter indicating that PRDOH contracted Horne Federal LLC to provide environmental registry review services, among others, that will support the objectives of the agenda for both CDBG-DR and CDBG -MIT Programs. On June 12, 2025, the PRSHPO concurred with a finding of No Adverse Effect upon historic properties conditioned to archaeological monitoring during all ground disturbing activities for the project.  An archaeological monitoring work plan was submitted to the PRSHPO on July 28, 2025. The PRSHPO concurred with the work plan on August 19, 2025, provided notification to the PRSHPO before 48 hours prior the initiation of the ground disturbing activities.  This project is in compliance with Historic Preservation requirements.  Reference: Refer to Exhibit 12 for Historic Preservation supporting documents.
Noise Control Act of 1972, as amended by the Quiet Communities Act of 1978; 24 CFR Part 51 Subpart B	Yes No	The proposed project does not involve establishment of new residences, an increase in residents, or introduction of other noise sensitive uses. The project does not require further evaluation under HUD's noise regulation. The noise that will be produced during construction is generated by the operation of construction equipment. All equipment and machinery will have noise dampers maintained in accordance with manufacturer's recommendations to control noise generation. Construction activities will be conducted during the day and have minimal impacts on the neighboring community. The noise levels attributable to construction activities will be temporary in nature and is not expected to exceed 65 dBA.  Therefore, the project complies with Noise Abatement and Control requirements.  Reference: Source:  U.S. Department of Housing and Urban Development: The Noise Guidebook Environmental Planning Division, Office of Environment and Energy. September 1900.  U.S. Department of Housing and Urban Development Environmental Criteria and Standards. 24 CFR Part 51.

Safe Drinking Water Act of 1974, as amended, particularly section 1424(e); 40 CFR Part 149	Yes No	There are no EPA sole source aquifers in Puerto Rico. Furthermore, the project consists of activities that are unlikely to have an adverse impact on groundwater resources. The project is in compliance with Sole Source Aquifer requirements.  Reference: Exhibit 13 – Sole Source Aquifer Map  Source: <a href="https://map23.epa.gov/arcgis/rest/directories/arcgisoutput/Utilities/PrintingTools_GPServer/agsgc10e62e-d70e-11ed-91d8-00505684bb18.pdf">https://map23.epa.gov/arcgis/rest/directories/arcgisoutput/Utilities/PrintingTools_GPServer/agsgc10e62e-d70e-11ed-91d8-00505684bb18.pdf</a> .
Wetlands Protection  Executive Order 11990, particularly sections 2 and 5	Yes No	According to the USFWS National Wetland Inventory Map the proposed project is not located within wetland areas. The closest wetland is about 1,302 ft north of the project site. Therefore, the proposed project is in compliance with the Wetlands Protection regulations.  Reference: Exhibit 14 – Wetlands Map Source: <a href="https://fwsprimary.wim.usgs.gov/server/rest/directories/arcgisoutput/Utilities/PrintingTools_GPServer/ags_3eb2adbe520c4b0eaf8f6c44f9450d0a.pdf">https://fwsprimary.wim.usgs.gov/server/rest/directories/arcgisoutput/Utilities/PrintingTools_GPServer/ags_3eb2adbe520c4b0eaf8f6c44f9450d0a.pdf</a> NEPAssist Tool Analysis <a href="https://nepassisttool.epa.gov/nepassist/nepamap.aspx">https://nepassisttool.epa.gov/nepassist/nepamap.aspx</a>
Wild and Scenic Rivers Act of 1968, particularly section 7(b) and (c)	Yes No	Puerto Rico has only three (3) rivers are designated as wild & scenic. These rivers are Rio de la Mina, Rio Icacos and Rio Mameyes. The proposed project is located approximately at 80 miles or 422,400 ft to the southwest of the Icaco River. No wild and scenic rivers are located within the Municipality San German, PR. The Project is in compliance with the requirements of the regulations.  Reference: Exhibit 15 - Wild and Scenic Rivers Map. Source: National Wild and Scenic Rivers System <a href="https://www.rivers.gov/puerto-rico.php">https://www.rivers.gov/puerto-rico.php</a> .

#### Field Inspection (Date and completed by):

A field reconnaissance took place at the proposed project site by William Sarriera, ACE environmental, on February 1, 2023, May 5, 2023, and May 31, 2024, with the intent of evaluate environmental aspects. No recognized environmental conditions (RECs) were identified within the project site. The inspection did not reveal any evidence of contamination related to hazardous substances or petroleum products, such as leaking storage tanks, improperly disposed chemicals, or malfunctioning equipment that could release contaminants into the environment. All other environmental aspects related to the proposed action have been summarized in the Environmental Assessment statutory form. Refer to Exhibit 16.

#### **Summary of Findings and Conclusions:**

The proposed activity has been found to not have any adverse effects on the environment nor is there the requirement for further consultation with federal agencies associated with the topics evaluated above. There is no environmental review topics addressed above that result in the need for additional formal compliance steps with federal agencies or the requirement for mitigations other than those listed below. There may be additional approvals or permits from local agencies. For example, the Office of Permit Management (OGPe) is responsible for granting permits, licenses, certifications, consultations, construction, and any other procedure necessary for business development and land use in Puerto Rico. In addition, the Project is anticipated to provide overall beneficial effect to the Municipality of San Germán by addressing the recreational needs of the community residents and visitors.

### Mitigation Measures and Conditions [40 CFR 1505.2(c)]

Summarize below all mitigation measures adopted by the Responsible Entity to reduce, avoid, or eliminate adverse environmental impacts and to avoid non-compliance or non-conformance with the above-listed authorities and factors. These measures/conditions must be incorporated into project contracts, development agreements, and other relevant documents. The staff responsible for implementing and monitoring mitigation measures should be clearly identified in the mitigation plan.

Law, Authority, or Factor	Mitigation Measure
Endangered Species	Conservation measures for the Puerto Rican Boa need to be implemented if the Boa is encountered during construction. If a Puerto Rican boa or the Yellow-shouldered Blackbird is found in the project activity site, work shall cease until the Boa or Yellow-shouldered Blackbird moves off on its own.
Solid Waste Disposal / Recycling	Salvaging/recycling of materials should be as determined feasible with other program requirements. A solid waste management plan should be developed and implemented.
Ground disturbance / Soil Suitability / Slope/ Erosion / Drainage / Storm Water Runoff	The project design will comply with current federal and state codes related to ground disturbance, erosion control and stormwater runoff. During construction activities, and in compliance with the USEPA NPDES Construction General Permit or the local stormwater runoff control regulations, the applicant will implement a Stormwater

	Pollution Prevention Plan that will include structural and		
	non-structural BMPs to keep sediment in place (erosion		
	control) and to capture any sediment that is moved by		
	stormwater before it leaves the site (sediment control).		
	There would be no significant permanent changes to the		
	site that would affect drainage, or stormwater runoff.		
Historic Preservation	An Archaeological Monitoring Plan prepared and		
	concurred by PRSHPO. The project would include		
	archaeological monitoring of any ground disturbing		
	activities and excavations, following the direction of the		
	PRSHPO-approved monitoring plan. PRSHPO would be		
	notified of the archaeological monitoring start date 48		
	hours prior to the initiation of work.		
	•		

#### **Determination:**

	This categorically excluded activity/project converts to Exempt, per 58 no circumstances which require compliance with any of the federal 1 §58.5. Funds may be committed and drawn down after certification	aws and a	uthorities cited at
$\boxtimes$	EXEMPT project, OR This categorically excluded activity/project cannot convert to I circumstances which require compliance with one or more federal la §58.5. Complete consultation/mitigation protocol requirements, <b>publi</b>	aws and au sh NOI/R	athorities cited at ROF and obtain
	"Authority to Use Grant Funds" (HUD 7015.16) per Section 58.70 a or drawing down any funds, OR This project is now subject to a full Environmental Assessment accord to extraordinary circumstances (Section 58.35(c)).		_
Signati	ure: Jol V Rosa	Date:	18NOV2025
Name/	Title/Organization: William Sarriera / Consultant / ACE Envi	ronmenta	I
	Sol Vanessa Rosa / Env Reviewer / Tetra	Tech	
Certify	ring Officer Signature:	Date: _	11/18/2025
Name/	Title: Priscilla M. Toro Rivera/ Environmental Specialist		

This original, signed document and related supporting material must be retained on file by the Responsible Entity in an Environmental Review Record (ERR) for the activity/project (ref: 24 CFR Part 58.38) and in accordance with recordkeeping requirements for the HUD program(s).

## **List of Exhibits and Agency Documents**


Exhibit 1	Location Map
Exhibit 2	Airport Hazards Map
Exhibit 3	Coastal Barrier Resources Act Map
Exhibit 4	Flood Insurance Map
Exhibit 5	Air Quality / Puerto Rico Nonattainment/Maintenance Status Map
Exhibit 5A	Air Quality / Puerto Rico Nonattainment/Maintenance Status
Exhibit 6	Coastal Zone Management Map
Exhibit 7	Toxic and Contamination Substances Map
Exhibi	t 7A Detailed Facility Report
Exhibi	t 7B Detailed Facility Report
Exhibi	t 7C Detailed Facility Report
Exhibi	t 7D Detailed Facility Report
Exhibi	t 7E Detailed Facility Report
Exhibi	t 7F Detailed Facility Report
Exhibi	t 7G Detailed Facility Report
Exhibi	t 7H Detailed Facility Report
Exhibi	t 7I Detailed Facility Report
Exhibi	t 7J Detailed Facility Report
Exhibi	t 7K Detailed Facility Report
Exhibi	t 7L Detailed Facility Report
Exhibi	t 7M Detailed Facility Report
Exhibi	t 7N Detailed Facility Report
Exhibi	t 70 Detailed Facility Report
Exhibi	t 7P Detailed Facility Report
Exhibi	t 7Q Detailed Facility Report
Exhibi	t 7R Detailed Facility Report
Exhibi	t 7S USTs Map
Exhibi	t 7T Asbestos-Containing Material Inspection Report
Exhibi	t 7U Lead-Based Paint Inspection Report
Exhibi	t 7V Radon Memorandum and agency correspondence

Critical Habitat Map Exhibit 8 **Endangered Species Supporting Document** Exhibit 8A Explosive and Flammable Hazards Map Exhibit 9 Farmland Protection Map Exhibit 10 Base Flood Elevations (ABFE) Map Exhibit 11 Historic Preservation Exhibit 12 Sole Source Aquifers Map Exhibit 13 Wetland Map Exhibit 14 Wild and Scenic Rivers Map Exhibit 15


Field Inspection Reports

Exhibit 16

#### **Exhibit 1: SITE LOCATION MAP**



#### **Exhibit 2: AIRPORTS AND HELIPORTS MAP**



# FISH & WILDLIFE SERVICE

#### U.S. Fish and Wildlife Service

#### **Coastal Barrier Resources System**

## PR-CRP-000876



October 30, 2024

#### **CBRS Units**

Otherwise Protected Area

System Unit

This map is for general reference only. The Coasial Barrier Resources System (CBRS) boundaries depicted on this map are representations of the controlling CBRS boundaries, which are shown on the official maps, accessible at <a href="https://www.fws.gov/library/collections/official-coastal-barrier-resources-system-maps">https://www.fws.gov/library/collections/official-coastal-barrier-resources-system-maps</a>. All CBRS related data should be used in accordance with the layer metadata found on the CBRS Mapper website.

The CBRS Buffer Zone represents the area immediately adjacent to the CBRS boundary where users are advised to contact the Service for an official determination (<a href="https://www.fvs.gov/service/coastal-barrier-resources-system-property-documen:ation">https://www.fvs.gov/service/coastal-barrier-resources-system-property-documen:ation</a>) as to whether the property or project site is located "in" or "out" of the CBRS.

CBRS Units normally extend seaward out to the 20- or 30-fool bathymetric contour (depending on the location of the unit). The true seaward

This page was produced by the CBRS Mapper



Exhibit 3 Coastal Barrier Resources Map Plaza Santo Domingo and Plaza Mariano Quiñones PR-CRP-000876 Municipality of San Germán

Legend:



Proposed Project Site




Scale: As shown



Reference: Coastal Barrier Resources Map. US Fish & Wildlife Service Source:

US Fish & Wildlife Service Coastal Barrier Resources Mapper https://fwsprimary.wim.usgs.gov/server/rest/directories/ arcgisoutput/ExportWebMap\_GPServer/ \_ags\_ec99b9996d9743df974abf8db31b0d25.pdf

Revised SVR - Tt






Flood Zones Map Plaza Santo Domingo and Plaza Mariano Quiñones PR-CRP-000876 Municipality of San Germán





#### PR-CRP-000876 PLAZA SANTO DOMINGO and PLAZA MARIANO QUIÑONES

#### **Exhibit 5: AIR QUALITY MAP**



#### Exhibit 5A

PR-CRP-000876 Plaza Santo Domingo and Plaza Francisco Mariano San Germán PR 00683 Coordinates 18.0819, -67.0420 / 18.0822, -67.0431

#### Green Book


You are here: EPA Home > Green Book > > National Area and County-Level Multi-Pollutant Information > Puerto Rico Nonattainment/Maintenance Status for Each County by Year for All Criteria Pollutants

## Puerto Rico Nonattainment/Maintenance Status for Each County by Year for All Criteria Pollutants

Data is current as of May 31, 2025

Listed by County, NAAQS, Area. The 8-hour Ozone (1997) standard was revoked on April 6, 2015 and the 1-hour Ozone (1979) standard was revoked on June 15, 2005.

\* The 1997 Primary Annual PM-2.5 NAAQS (level of 15 µg/m³) is revoked in attainment and maintenance areas for that NAAQS. For additional information see the PM-2.5 NAAQS SIP Requirements Final Rule, effective October 24, 2016. (81 FR 58009)



nportant Notes						Download I	National Data	set dbf
County	NAAQS	Area Name	Nonattainment in Year	Redesignation to Maintenance	Classification	Whole or/ Part County	Population (2010)	State/ County FIPS Code
PUERTO RICO	-							
Arecibo Municipio	Lead (2008)	Arecibo, PR	11 12 13 14 15 16 17 18 19 20 21 22 23 24 25	//		Part	32,185	72/013
Bayamon Municipio	Sulfur Dioxide (2010)	San Juan, PR	18 19 20 21 22 23 24 25	11		Part	22,921	72/021
Catano Municipio	Sulfur Dioxide (2010)	San Juan, PR	18 19 20 21 22 23 24 25	11		Whole	28,140	72/033
Guaynabo Municipio	PM-10 (1987)	Mun. of Guaynabo, PR	92 93 94 95 96 97 98 99 00 01 02 03 04 05 06 07 08 09	02/11/2010	Moderate	Part	90,470	72/061
Guaynabo Municipio	Sulfur Dioxide (2010)	San Juan, PR	18 19 20 21 22 23 24 25	11		Part	23,802	72/061
Salinas Municipio	Sulfur Dioxide (2010)	Guayama-Salinas, PR	18 19 20 21 22 23 24 25	11		Part	23,401	72/123
San Juan Municipio	Sulfur Dioxide (2010)	San Juan, PR	18 19 20 21 22 23 24 25	11		Part	147,963	72/127
Toa Baja Municipio	Sulfur Dioxide (2010)	San Juan, PR	18 19 20 21 22 23 24 25	11		Part	52,441	72/137

https://www3.epa.gov/airquality/greenbook/anayo pr.html







Exhibit 6 Coastal Zone Map
Coastal Zone Management
Plaza Santo Domingo and Plaza Mariano Quiñones
PR-CRP-000876
Municipality of San Germán

Legend:





Scale: As shown


Coordinates 18.0819, -67.0420 / 18.0822, -67.0431




Reference: Puerto Rico Coastal Zone Management Program

Junta de Planificacion de Puerto Rico Puerto Rico Coastal Zone Management Program - Final EIS 1978 Coordinates 18.0819, -67.0420 / 18.0822, -67.0431







Sources: Esri, TomTom, Garmin, FAO, NOAA, USGS, (c) OpenStreetMap contributors, and the GIS User Community, Maxar



## **Detailed Facility Report**

**Facility Summary** 

VIASYSTEMS PUERTO RICO INC.

PR-362 KM. 1.0, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110041992626

EPA Region: 02

Latitude: 18.088766

Longitude: -67.038739

Locational Data Source: TRIS

Industries: Computer and Electronic Product Manufacturing

Indian Country: N

#### **Enforcement and Compliance Summary**

Statute	RCRA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	01/24/2008
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	
Penalties from EPA Cases (5 years)	-

#### **Regulatory Information**

Clean Air Act (CAA): No Information
Clean Water Act (CWA): No Information

**Resource Conservation and Recovery Act (RCRA):** Active VSQG, (PRD991291857)

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

## Other Regulatory Reports

Air Emissions Inventory (EIS): No Information

**Greenhouse Gas Emissions (eGGRT):** No Information

Toxic Releases (TRI): 00753DGTLQPRROA

**Compliance and Emissions Data Reporting Interface (CEDRI):** No Information

#### Facility/System Characteristics

### **Facility/System Characteristics**

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110041992626					N	18.088766	-67.038739
ICIS		36120					N	18.088766	-67.038739
TRI	EP313	00753DGTLQPRROA	Toxics Release Inventory	Last Reported for 2000			N	18.088766	-67.038739
RCRAInfo	RCRA	PRD991291857	VSQG	Active (H A )			N	18.088766	-67.038739

#### **Facility Address**

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110041992626	VIASYSTEMS PUERTO RICO INC.	PR-362 KM. 1.0, SAN GERMAN, PR 00683	San Germán Municipio
ICIS		36120	VIASYSTEMS PR INC	HWY 362 KM 1.0 BO GUAMA, SAN GERMAN, PR 00683	San Germán Municipio
TRI	EP313	00753DGTLQPRROA	VIASYSTEMS PUERTO RICO INC	RD 362 KM 01 BARRIO GUAMA, SAN GERMAN, PR 00683	San Germán Municipio

System	Statute	Identifier	Facility Name	Facility Address	Facility County
RCRAInfo	RCRA	PRD991291857	PCB HORIZON TECHNOLOGY INC	RD 362 KM 1.0, SAN GERMAN, PR 00683	San Germán Municipio

#### **Facility SIC (Standard Industrial Classification)** Codes

### **Facility NAICS (North American Industry Classification System) Codes**

System	Identifier	SIC Code	SIC Description	System	Identifier	NAICS Code	NAICS Description
TRI	00753DGTLQPRROA	3672	Printed Circuit Boards	TRI	00753DGTLQPRROA	334412	Bare Printed Circuit Board Manufacturing
TRI	00753DGTLQPRROA	3679	Electronic Components	RCRAInfo	PRD991291857	334412	Bare Printed Circuit Board Manufacturing

#### **Facility Tribe Information**

Distance to Tribe (miles)

No data records returned

**Enforcement and Compliance** 

#### **Compliance Monitoring History** Last 5 Years

Statute	Source ID	System	Activity Type	Compliance Monitoring Type	Lead Agency	Date	Finding (if applicable)

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy < https://www.epa.gov/compliance/compliance-monitoringprograms> activities or because they are not counted as inspections within EPA's Annual Results <a href="https://www.epa.gov/enforcement/enforcement-data-and-results">https://www.epa.gov/enforcement/enforcement-data-and-results</a>.

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
RCRA	PRD991291857	No	10/11/2025	0	10/10/2025

## Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12+
RCRA	(Source ID: PRD991291857)	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
	Facility-Level Status	No Violation Identified											
	Violation Agency												

#### **Informal Enforcement Actions**

Statute System Source ID Type of Action Lead Agency Date
--

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

#### Formal Enforcement Actions | Last 5 Years

Section ID Action No. Agency Name Date Actions Date Assessed Assessed Collected Value Cost				Type of Action	Case No.	Lead Agency	Case Name	Issued/ Filed Date	Settlements/ Actions	Settlement/ Action Date	Federal Penalty Assessed	State/ Local Penalty Assessed	Penalty Amount Collected	SEP Value	Comp Action Cost
--	--	--	--	-------------------	-------------	----------------	--------------	-----------------------	-------------------------	----------------------------	-----------------------------	----------------------------------	-----------------------------	--------------	---------------------

No data records returned

**Environmental Conditions** 

#### Watersheds

12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database))  WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database))	State Water Body Name (ICIS (Integrated Compliance Information System))	Beach Closures Within Last Year	Beach Closures Within Last Two Years	Pollutants Potentially Related to Impairment	Watershed with ESA (Endangered Species Act)-listed Aquatic Species?
---	---	------------------------------------	---	---	--

No data records returned

#### Assessed Waters From Latest State Submission (ATTAINS)

Drinking Water Use Ecological Use Assessment Unit ID

No data records returned

#### **Air Quality Nonattainment Areas**

No data records returned

## Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works) Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

#### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

Community

### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic></a>.

General Statistics (ACS (American Community Survey))	
Total Persons	6,129
Population Density	1,965/sq.mi.
Housing Units in Area	3,171
Percent People of Color	99%
Households in Area	2,411
Households on Public Assistance	84
Persons With Low Income	4,847
Percent With Low Income	81%
Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.088766
Center Longitude	-67.038739
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%
Income Breakdown (ACS (American Community Survey	)) - Households (%)
Less than \$15,000	1,082 (44.95%)
\$15,000 - \$25,000	421 (17.49%)
\$25,000 - \$50,000	547 (22.73%)
\$50,000 - \$75,000	205 (8.52%)
Greater than \$75,000	152 (6.31%)

Children 5 years and younger	224 (4%)
Minors 17 years and younger	1,082 (18%)
Adults 18 years and older	5,046 (82%)
Seniors 65 years and older	1,729 (28%)
Race Breakdown (ACS (American Community Survey)) - Persons (%)	
White	4,157 (68%)
African-American	101 (2%)
Hispanic-Origin	6,058 (99%)
Asian	4 (0%)
Hawaiian/Pacific Islander	6 (0%)
American Indian	0 (0%)
Other/Multiracial	1,274 (21%)
Education Level (Persons 25 & older) (ACS (American Community Surv	ey)) - Persons (%)
Less than 9th Grade	395 (8.83%)
9th through 12th Grade	389 (8.7%)
High School Diploma	1,487 (33.24%)
Some College/2-year	365 (8.16%)
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,381 (30.87%)



## **Detailed Facility Report**

**Facility Summary** 

**CORDIS LLC** 

PR-362 KM 0.5, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110001142898

**EPA Region:** 02 **Latitude:** 18.087318 **Longitude:** -67.035285

**Locational Data Source:** RCRAINFO **Industries:** Chemical Manufacturing

Indian Country: N

## **Enforcement and Compliance Summary**

Statute	CAA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	-
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	_
Statute	RCRA
Statute  Compliance Monitoring Activities (5 years)	RCRA
Compliance Monitoring Activities (5 years)	-
Compliance Monitoring Activities (5 years)  Date of Last Compliance Monitoring Activity	 09/22/2011
Compliance Monitoring Activities (5 years)  Date of Last Compliance Monitoring Activity  Compliance Status	09/22/2011  No Violation Identified
Compliance Monitoring Activities (5 years)  Date of Last Compliance Monitoring Activity  Compliance Status  Qtrs in Noncompliance (of 12)	09/22/2011  No Violation Identified 0
Compliance Monitoring Activities (5 years)  Date of Last Compliance Monitoring Activity  Compliance Status  Qtrs in Noncompliance (of 12)  Qtrs with Significant Violation	09/22/2011  No Violation Identified 0
Compliance Monitoring Activities (5 years)  Date of Last Compliance Monitoring Activity  Compliance Status  Qtrs in Noncompliance (of 12)  Qtrs with Significant Violation  Informal Enforcement Actions (5 years)	09/22/2011  No Violation Identified  0
Compliance Monitoring Activities (5 years)  Date of Last Compliance Monitoring Activity  Compliance Status  Qtrs in Noncompliance (of 12)  Qtrs with Significant Violation  Informal Enforcement Actions (5 years)  Formal Enforcement Actions (5 years)	09/22/2011  No Violation Identified  0

## **Regulatory Information**

Clean Air Act (CAA): Operating Minor (PR0000007212500005)

Clean Water Act (CWA): No Information

 $\textbf{Resource Conservation and Recovery Act (RCRA):} \ \ \textbf{Inactive Other, (PRD156924573),}$ 

Inactive Other, (PRR000015016)

## **Other Regulatory Reports**

Air Emissions Inventory (EIS): 8943011

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): 00683LBNCXRD362

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

Facility/System Characteristics

#### **Facility/System Characteristics**

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110001142898					N	18.087318	-67.035285
ICIS-Air	CAA	PR0000007212500005	Minor Emissions	Operating	CAANSPS, CAASIP		N	18.087318	-67.035285
EIS	CAA	8943011					N	18.09	-67.038
TRI	EP313	00683LBNCXRD362	Toxics Release Inventory	Last Reported for 2011			N	18.087318	-67.035285
RCRAInfo	RCRA	PRD156924573	Other	Inactive ( )			N	18.087318	-67.035285
RCRAInfo	RCRA	PRR000015016	Other	Inactive ( )			N	18.087318	-67.035285

## **Facility Address**

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110001142898	CORDIS LLC	PR-362 KM 0.5, SAN GERMAN, PR 00683	San Germán Municipio
ICIS-Air	CAA	PR0000007212500005	OMJ PHARMACEUTICALS	PR 362 KM 0.5, SAN GERMAN, PR 00753	San Germán Municipio
EIS	CAA	8943011	CORDIS LLC	PR-362, KM 0.5, EL GUAMA INDUSTRIAL PARK, SAN GERMAN, PR 00683	San Germán Municipio
TRI	EP313	00683LBNCXRD362	CORDIS LLC	RD 362 KM 0.5, SAN GERMAN, PR 00683	San Germán Municipio
RCRAInfo	RCRA	PRD156924573	OMJ PHARMACEUTICALS INC	ROAD 362 KM. 05, SAN GERMAN, PR 00683	San Germán Municipio
RCRAInfo	RCRA	PRR000015016	CORDIS LLC	ROAD 362 KM 0.5, SAN GERMAN, PR 00683	San Germán Municipio

## Facility SIC (Standard Industrial Classification) Codes

System	Identifier	SIC Code	SIC Description
TRI	00683LBNCXRD362	2834	Pharmaceutical Preparations
TRI	00683LBNCXRD362	3841	Surgical And Medical Instruments
ICIS-Air	PR0000007212500005	2834	Pharmaceutical Preparations

## Facility NAICS (North American Industry Classification System) Codes

	-		
System	Identifier	NAICS Code	NAICS Description
TRI	00683LBNCXRD362	325412	Pharmaceutical Preparation Manufacturing
TRI	00683LBNCXRD362	339112	Surgical and Medical Instrument Manufacturing
EIS	8943011	339112	Surgical and Medical Instrument Manufacturing
ICIS-Air	PR0000007212500005	325412	Pharmaceutical Preparation Manufacturing
RCRAInfo	PRD156924573	325412	Pharmaceutical Preparation Manufacturing
RCRAInfo	PRR000015016	339112	Surgical and Medical Instrument Manufacturing

## **Facility Tribe Information**

Reservation Name	Tribe Name	EPA Tribal ID	Distance to Tribe (miles)
------------------	------------	---------------	---------------------------

No data records returned

**Enforcement and Compliance** 

## **Compliance Monitoring History**

Last 5 Years

Statute	Source ID	System	Activity Type	Compliance Monitoring Type	Lead Agency	Date	Finding (if applicable)

No data records returned


Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/

## **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
CAA	PR0000007212500005	No	10/11/2025	0	10/10/2025
RCRA	PRD156924573	No	10/11/2025	0	10/10/2025
RCRA	PRR000015016	No	10/11/2025	0	10/10/2025

## Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12+
CAA (Source ID: PR0000007212500005)		10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
	Facility-Level Status	No Violation Identified											
	HPV History												



## Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic</a>.

General Statistics (ACS (American Community Survey))	
Total Persons	6,503
Population Density	2,085/sq.mi.
Housing Units in Area	3,265
Percent People of Color	99%
Households in Area	2,542
Households on Public Assistance	88
Persons With Low Income	5,241
Percent With Low Income	82%

Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.087318
Center Longitude	-67.035285
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%

Income Breakdown (ACS (American Community Survey)) - Households (%)						
Less than \$15,000	1,127 (44.39%)					
\$15,000 - \$25,000	451 (17.76%)					
\$25,000 - \$50,000	600 (23.63%)					
\$50,000 - \$75,000	223 (8.78%)					
Greater than \$75,000	138 (5.44%)					

Age Breakdown (ACS (American Community Survey)) - Persons (%)							
Children 5 years and younger	224 (3%)						
Minors 17 years and younger	1,140 (18%)						
Adults 18 years and older	5,365 (83%)						
Seniors 65 years and older 1,809 (28%)							

Race Breakdown (ACS (American Community Survey)) - Persons (%)						
White	4,373 (67%)					
African-American	140 (2%)					
Hispanic-Origin	6,416 (99%)					
Asian	2 (0%)					
Hawaiian/Pacific Islander	14 (0%)					
American Indian	0 (0%)					
Other/Multiracial	1,333 (20%)					

Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%)						
Less than 9th Grade	448 (9.36%)					
9th through 12th Grade	417 (8.71%)					
High School Diploma	1,707 (35.67%)					
Some College/2-year	409 (8.55%)					
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,356 (28.33%)					



## **Detailed Facility Report**

**Facility Summary** 

PRASA WTP SAN GERMAN FILTER PLANT

INSIDE INTERAMERICAN UNIVERSITY, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110013695901

EPA Region: 02 Latitude: 18.085516 Longitude: -67.037123

**Locational Data Source: NPDES** 

Industries: --Indian Country: N

### **Enforcement and Compliance Summary**

Statute	CWA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	01/14/2013
Compliance Status	Terminated Permit
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

## **Regulatory Information**

Clean Air Act (CAA): No Information

Clean Water Act (CWA): Non-Major, Permit Terminated; Compliance Tracking Off (PR0022977) Greenhouse Gas Emissions (eGGRT): No Information

Resource Conservation and Recovery Act (RCRA): No Information

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a> **Other Regulatory Reports** 

Air Emissions Inventory (EIS): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Facility/System Characteristics

## **Facility/System Characteristics**

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110013695901					N	18.085516	-67.037123
ICIS		35823					N	18.085516	-67.037123
ICIS		2657021					N	18.085516	-67.037123
ICIS-NPDES	CWA	PR0022977	Non-Major: NPDES Individual Permit	Terminated; Compliance Tracking Off		11/30/2013	N	18.0875	-67.0375

## **Facility Address**

System	Statute	Identifier	Facility Name Facility Address			
FRS		110013695901	PRASA WTP SAN GERMAN FILTER PLANT	INSIDE INTERAMERICAN UNIVERSITY, SAN GERMAN, PR 00683	San Germán Municipio	
ICIS		35823	PRASA WTP SAN GERMAN FILTER PLANT	INTERAMERICAN UNIVERSITY, SAN GERMAN, PR 00683	San Germán Municipio	

System	Statute	Identifier	Facility Name	Facility Address	Facility County
ICIS		2657021	PRASA SAN GERMAN WTP	INSIDE INTERAMERICAN UNIVERSITY, SAN GERMAN, PR 00683	San Germán Municipio
ICIS-NPDES	CWA	PR0022977	PRASA WTP SAN GERMAN	RD 114 KM 0.89, INSIDE OF INTERAMERICAN UNIVERSITY, SAN GERMAN, PR 00683	San Germán Municipio

#### **Facility SIC (Standard Industrial Classification) Codes**

### **Facility NAICS (North American Industry Classification System) Codes**

System	Identifier	SIC Code	SIC Description	System	Identifier	NAICS Code	NAICS Description	
ICIS-NPDES	PR0022977	4941	Water Supply	No data records returned				
						NO data records returned	J	

## **Facility Industrial Effluent Guidelines**

## **Facility Tribe Information**

			•			
Identifier	Effluent Guideline (40 CFR Part)	Effluent Guideline Description	Reservation Name	Tribe Name	EPA Tribal ID	Distance to Tribe (miles)
No data records returned				No data	records returned	

**Enforcement and Compliance** 

## **Compliance Monitoring History**

Source ID Finding (if applicable) **Compliance Monitoring Type** 

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/compliance-monitoring-theyare-not-compliance-monitoring-not-complian programs> activities or because they are not counted as inspections within EPA's Annual Results <a href="https://www.epa.gov/enforcement/enforcement-data-and-results">https://www.epa.gov/enforcement/enforcement-data-and-results</a>.

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
CWA	PR0022977	No	06/30/2025	0	10/10/2025

## Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12	QTR 13+
CW	A (Source ID: PR0022977)	07/01-09/30/22	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-10/10/25
	Facility-Level Status	Terminated Permit												
	Quarterly Noncompliance Report History													
	Permit Schedule Violations													
CWA	Complete Required Work or On-Site Construction	05/30/1998	<b>→</b>											
CWA	Discharge Monitoring Report (DMR)	11/28/2003	<b>→</b>											
CWA	Quality Assurance Report	10/01/2006	<b>→</b>	<b>→</b>	<b>→</b>	<b>→</b>	<b>→</b>	<b>-</b>	<b>→</b>	<b>→</b>	<b>→</b>	<b>→</b>	<b>→</b>	<b>†</b>
CWA	Quality Assurance Report	10/01/2007	<b>→</b>	<b></b>										

## **Informal Enforcement Actions**

Last 5 Years

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

## Formal Enforcement Actions | Last 5 Years

Statute System	Law/ Section	Source ID	Type of Action	Case No.	Lead Agency	Case Name	Issued/ Filed Date	Settlements/ Actions	Settlement/ Action Date	Federal Penalty Assessed	State/ Local Penalty Assessed	Penalty Amount Collected	SEP Value	Comp Action Cost

No data records returned

#### **Environmental Conditions**

#### Watersheds

12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database))	WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database))	State Water Body Name (ICIS (Integrated Compliance Information System))	Beach Closures Within Last Year	Beach Closures Within Last Two Years	Pollutants Potentially Related to Impairment	Watershed with ESA (Endangered Species Act)-listed Aquatic Species?
210100030409	Rio Guanajibo at mouth	ESTERO RIVER	No	No	BOD, 5-day, 20 deg. C   Copper, total (as Cu)   Fluoride, total (as F)   Lead, total (as Pb)   Nitrogen, ammonia, total (as NH3)   Oxygen, dissolved (DO)   Turbidity	No

### **Assessed Waters From Latest State Submission (ATTAINS)**

St	ate	Report Cycle	Assessment Unit ID	Assessment Unit Name	Water Condition	Cause Groups Impaired	Drinking Water Use	Ecological Use	Fish Consumption Use	Recreation Use	Other Use	
F	PR	2024	PRWR77A	RIO GUANAJIBO	Impaired - 303(d) Listed - With Restoration Plan	METALS (OTHER THAN MERCURY)   NUTRIENTS   ORGANIC ENRICHMENT/OXYGEN DEPLETION   PATHOGENS   TOXIC INORGANICS   TURBIDITY	Not Supporting	Not Supporting		Not Supporting		

### **Air Quality Nonattainment Areas**

Pollutant	Within Nonattainment Status Area?	Nonattainment Status Applicable Standard(s)	Within Maintenance Status Area?	Maintenance Status Applicable Standard(s)	

No data records returned

**Pollutants** 

## Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works) Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

**Chemical Name** 

No data records returned

## CWA (Clean Water Act) Discharge Monitoring Report (DMR) Pollutant Loadings

DMR and TRI Multi-Year Loading Report

NPDES ID

No data records returned

Community

### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic></a>.

General Statistics (ACS (American Community Survey))	
Total Persons	6,949
Population Density	2,228/sq.mi.
Housing Units in Area	3,576
Percent People of Color	99%
Households in Area	2,735
Households on Public Assistance	105
Persons With Low Income	5,566
Percent With Low Income	81%
Caraminatus	
Geography	
Radius of Selected Area	1 mi.

Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.085516
Center Longitude	-67.037123
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%

Income Breakdown (ACS (American Community Su	urvey)) - Households (%)
Less than \$15,000	1,228 (44.92%)
\$15,000 - \$25,000	488 (17.85%)
\$25,000 - \$50,000	633 (23.15%)
\$50,000 - \$75,000	230 (8.41%)
Greater than \$75,000	155 (5.67%)

Age Breakdown (ACS (American Community Survey)) - Persons (%)	
Children 5 years and younger	243 (3%)
Minors 17 years and younger	1,178 (17%)
Adults 18 years and older	5,773 (83%)
Seniors 65 years and older	1,971 (28%)
Race Breakdown (ACS (American Community Survey)) - Persons (%)	
White	4,694 (68%)
African-American	134 (2%)
Hispanic-Origin	6,858 (99%)
Asian	3 (0%)
Hawaiian/Pacific Islander	14 (0%)
American Indian	0 (0%)
Other/Multiracial	1,415 (20%)
Education Level (Persons 25 & older) (ACS (American Community Surve	ey)) - Persons (%)
Less than 9th Grade	490 (9.55%)
9th through 12th Grade	456 (8.89%)
High School Diploma	1,805 (35.17%)
Some College/2-year	424 (8.26%)
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,467 (28.59%)



## **Detailed Facility Report**

**Facility Summary** 

REHABILITATION AND SCOUR PROTECTION OF BRIDGE #1096 OVER GUANAJIBO RIVER

STATE ROAD PR-102 FROM KM 35.4 TO KM 36.2, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110071348226

EPA Region: 02 Latitude: 18.0857 Longitude: -67.0408

Locational Data Source: NPDES

Industries: -Indian Country: N

#### **Enforcement and Compliance Summary**

Statute	CWA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	-
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

### **Regulatory Information**

Clean Air Act (CAA): No Information

Clean Water Act (CWA): Non-Major, Permit Effective (PRR1000G2)

Resource Conservation and Recovery Act (RCRA): No Information

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

### **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Facility/System Characteristics

## **Facility/System Characteristics**

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110071348226					N	18.0857	<del>-</del> 67.0408
ICIS-NPDES	CWA	PRR1000G2	Non-Major: General Permit Covered Facility	Effective	Construction Stormwater	02/16/2027	N	18.0857	-67.0408

## **Facility Address**

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110071348226	REHABILITATION AND SCOUR PROTECTION OF BRIDGE #1096 OVER GUANAJIBO RIVER	STATE ROAD PR-102 FROM KM 35.4 TO KM 36.2, SAN GERMAN, PR 00683	San Germán Municipio
ICIS-NPDES	CWA	PRR1000G2	REHABILITATION AND SCOUR PROTECTION OF BRIDGE #1096 OVER GUANAJIBO RIVER	STATE ROAD PR-102 FROM KM 35.4 TO KM 36.2, SAN GERMAN, PR 00683	

## **Facility SIC (Standard Industrial Classification)**

#### **Facility NAICS (North American Industry Classification System) Codes**

SIC Description NAICS Description

No data records returned

No data records returned

#### **Facility Industrial Effluent Guidelines**

#### **Facility Tribe Information**

Effluent Guideline (40 CFR Part) Effluent Guideline Description Reservation Name EPA Tribal ID Distance to Tribe (miles)

No data records returned

No data records returned

**Enforcement and Compliance** 

## **Compliance Monitoring History**

Finding (if applicable) **Activity Typ Compliance Monitoring Type** 

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/compliance-monitoring-to-monitoringprograms> activities or because they are not counted as inspections within EPA's Annual Results <a href="https://www.epa.gov/enforcement/enforcement-data-and-results">https://www.epa.gov/enforcement/enforcement-data-and-results</a>.

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
CWA	PRR1000G2	No	06/30/2025	0	10/10/2025

### Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12	QTR 13+
CWA	(Source ID: PRR1000G2)	07/01-09/30/22	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-10/10/25
	Facility-Level Status	No Violation Identified	Undetermined											
	Quarterly Noncompliance Report History													

#### **Informal Enforcement Actions**

Last 5 Years

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

#### **Formal Enforcement Actions**

Last 5 Years

Issued/ Filed Federal Penalty State/ Local Penalty Lead Case Settlements/ Settlement/ Action **Penalty Amount** SEP Comp Action Statute System

No data records returned

#### **Environmental Conditions**

#### Watersheds

12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database))	WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database))	State Water Body Name (ICIS (Integrated Compliance Information System))	Beach Closures Within Last Year	Beach Closures Within Last Two Years	Pollutants Potentially Related to Impairment	Watershed with ESA (Endangered Species Act)-listed Aquatic Species?
210100030409	Rio Guanajibo at mouth	GUANAJIBO RIVER	No	No		No

### **Assessed Waters From Latest State Submission (ATTAINS)**

State	Report Cycle	Assessment Unit ID	Assessment Unit Name	Water Condition	Cause Groups Impaired	Drinking Water Use	Ecological Use	Fish Consumption Use	Recreation Use	Other Use
PR	2024	PRWR77A	RIO GUANAJIBO	Impaired - 303(d) Listed - With Restoration Plan	METALS (OTHER THAN MERCURY)   NUTRIENTS   ORGANIC ENRICHMENT/OXYGEN DEPLETION   PATHOGENS   TOXIC INORGANICS   TURBIDITY	Not Supporting	Not Supporting		Not Supporting	

### **Air Quality Nonattainment Areas**

Pollutant	Within Nonattainment Status Area?	Nonattainment Status Applicable Standard(s)	Within Maintenance Status Area?	Maintenance Status Applicable Standard(s)						
No. data managaria da matemata d										

## Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at

Underground Injections Disposal to Land Total On-Site Releases

No data records returned

#### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Off-Site Transfers to POTWs (Publicly Owned Treatment Works)

Chemical Name

No data records returned

#### CWA (Clean Water Act) Discharge Monitoring Report (DMR) Pollutant Loadings

DMR and TRI Multi-Year Loading Report

NPDES ID Description

No data records returned

#### Community

#### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic>.

General Statistics (ACS (American Community Survey)	)
Total Persons	6,894
Population Density	2,210/sq.mi.
Housing Units in Area	3,706
Percent People of Color	99%
Households in Area	2,745
Households on Public Assistance	113
Persons With Low Income	5,413
Percent With Low Income	81%
Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.0857
Center Longitude	-67.0408
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%
Income Breakdown (ACS (American Community Surve	y)) - Households (%)
Less than \$15,000	1,254 (45.7%)
\$15,000 - \$25,000	489 (17.82%)
\$25,000 - \$50,000	605 (22.05%)
\$50,000 - \$75,000	214 (7.8%)
Greater than \$75,000	182 (6.63%)

Age Breakdown (ACS (American Community Survey)) - Persons (%)	
Children 5 years and younger	249 (4%)
Minors 17 years and younger	1,142 (17%)
Adults 18 years and older	5,753 (83%)
Seniors 65 years and older	2,002 (29%)
Race Breakdown (ACS (American Community Survey)) - Persons (%)	
White	4,698 (68%)
African-American	97 (1%)
Hispanic-Origin	6,814 (99%)
Asian	4 (0%)
Hawaiian/Pacific Islander	9 (0%)
American Indian	0 (0%)
Other/Multiracial	1,408 (20%)
Education Level (Persons 25 & older) (ACS (American Community Surve	ey)) - Persons (%)
Less than 9th Grade	473 (9.32%)
9th through 12th Grade	462 (9.1%)
High School Diploma	1,683 (33.16%)
Some College/2-year	392 (7.72%)
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,554 (30.61%)



**Facility Summary** 

SAN GERMÁN

CALLE RUIZ BELVIS, SAN GERMÁN, PR 00683

FRS (Facility Registry Service) ID: 110054103135

EPA Region: 02
Latitude: 18.0822
Longitude: -67.04351
Locational Data Source: FRS

Industries: --

Indian Country: N

#### **Enforcement and Compliance Summary**

Statute	CWA
Compliance Monitoring Activities (5 years)	1
Date of Last Compliance Monitoring Activity	09/25/2025
Compliance Status	Violation Identified
Qtrs in Noncompliance (of 12)	1
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

### **Regulatory Information**

Clean Air Act (CAA): No Information

Clean Water Act (CWA): Non-Major, Permit Expired; Compliance Tracking Partially Off

(PRR040035)

Resource Conservation and Recovery Act (RCRA): No Information

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

### **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

#### Facility/System Characteristics

### **Facility/System Characteristics**

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110054103135					N	18.0822	-67.04351
ICIS-NPDES	CWA	PRR040035	Non-Major: General Permit Covered Facility	Expired; Compliance Tracking Partially Off	Urban Stormwater (Small MS4)	06/30/2021	N	18.0822	-67.04351

### **Facility Address**

:	System	Statute	Identifier	Facility Name	Facility Address	Facility County
	FRS 110054103135 SAN GERMÁN C		CALLE RUIZ BELVIS, SAN GERMÁN, PR 00683			
ICI	IS-NPDES	CWA	PRR040035	SAN GERMÁN	CALLE RUIZ BELVIS, SAN GERMÁN, PR 00683	San Germán Municipio

## **Facility SIC (Standard Industrial Classification) Codes**

# Facility NAICS (North American Industry Classification System) Codes

System Identifier SIC Code SIC Description System Identifier NAICS Code NAICS Description

No data records returned

No data records returned

#### **Facility Industrial Effluent Guidelines**

#### **Facility Tribe Information**

Identifier Effluent Guideline (40 CFR Part) Effluent Guideline Description Reservation Name Tribe Name EPA Tribal ID Distance to Tribe (miles)

No data records returned

No data records returned

**Enforcement and Compliance** 

#### **Compliance Monitoring History**

ast 5 Years

Statute	Source ID	System	Activity Type	Compliance Monitoring Type	Lead Agency	Date	Finding (if applicable)
CWA	PRR040035	ICIS-NPDES	Inspection/Evaluation	Urban Stormwater (MS4) - Evaluation	EPA	09/25/2025	

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/compliance-monitoring-programs">https://www.epa.gov/compliance/compliance-monitoring-programs</a> activities or because they are not counted as inspections within EPA's Annual Results <a href="https://www.epa.gov/enforcement/enforcement-data-and-results">https://www.epa.gov/enforcement/enforcement-data-and-results</a>.

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
CWA	PRR040035	No	06/30/2025	1	10/10/2025

#### Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Vi Type	iolation	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12	QTR 13+
CW.	A (Source ID: PRR04003	35)	07/01-09/30/22	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-10/10/25
	Facility-Level Sta	tus	Unknown	Violation Identified											
	Quarterly Noncomp Report History		Undetermined												
	Single Event Violations	Agency													
CWA	Failure to develop a complete map of the MS4 system	EPA													09/25/2025
CWA	Failure to develop, maintain, or get approval of an adequate Stormwater Management Plan (SWMP)	EPA													09/25/2025
CWA	Failure to report MS4 information on the MS4 Program Report [40 CFR 122.34(d)(3) and 122.42(c)]	EPA													09/25/2025

#### **Informal Enforcement Actions**

Last 5 Years

Statute System Source ID Type of Action Lead Agency Date

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

### **Formal Enforcement Actions**

Last 5 Years

Statute System Law/ Source Type of Case Lead Case Issued/Filed Settlements/ Settlem

No data records returned

#### Watersheds

12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database))	WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database))	State Water Body Name (ICIS (Integrated Compliance Information System))	Beach Closures Within Last Year	Beach Closures Within Last Two Years	Pollutants Potentially Related to Impairment	Watershed with ESA (Endangered Species Act)-listed Aquatic Species?
210100030406	Rio Viejo	_	No	No		No

#### **Assessed Waters From Latest State Submission (ATTAINS)**

State	Report Cycle	Assessment Unit ID	Assessment Unit Name	Water Condition	Cause Groups Impaired	Drinking Water Use	Ecological Use	Fish Consumption Use	Recreation Use	Other Use
PR	2024	PRWR77D	RIO VIEJO	Impaired - 303(d) Listed - With Restoration Plan	METALS (OTHER THAN MERCURY)   NUTRIENTS   ORGANIC ENRICHMENT/OXYGEN DEPLETION   OTHER CAUSE   PATHOGENS   TEMPERATURE   TOXIC INORGANICS	Not Supporting	Not Supporting		Not Supporting	

#### **Air Quality Nonattainment Areas**

1111 &									
Pollutant	Within Nonattainment Status Area?	Nonattainment Status Applicable Standard(s)	Within Maintenance Status Area?	Maintenance Status Applicable Standard(s)					

No data records returned

**Pollutants** 

## Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works) Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

#### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

## CWA (Clean Water Act) Discharge Monitoring Report (DMR) Pollutant Loadings

DMR and TRI Multi-Year Loading Report

NPDES ID

No data records returned

Community

## Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic></a>.

General Statistics (ACS (American Community Survey))	
Total Persons	7,034
Population Density	2,255/sq.mi.
Housing Units in Area	4,019
Percent People of Color	99%
Households in Area	2,869
Households on Public Assistance	131
Persons With Low Income	5,473
Percent With Low Income	80%
Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.0822
Center Longitude	-67.04351
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%
Income Breakdown (ACS (American Community Survey)	- Households (%)
Less than \$15,000	1,353 (47.14%)
\$15,000 - \$25,000	514 (17.91%)
\$25,000 - \$50,000	601 (20.94%)

Age Breakdown (ACS (American Community Survey)) - Persons (%)				
Children 5 years and younger	252 (4%)			
Minors 17 years and younger	1,059 (15%)			
Adults 18 years and older	5,975 (85%)			
Seniors 65 years and older	2,145 (30%)			
Race Breakdown (ACS (American Community Survey)) - Persons (%)				
White	4,796 (68%)			
African-American	72 (1%)			
Hispanic-Origin 6,954 (99%)				
Asian	5 (0%)			
Hawaiian/Pacific Islander	8 (0%)			
American Indian	0 (0%)			
Other/Multiracial	1,462 (21%)			
Education Level (Persons 25 & older) (ACS (American Community Surve	ey)) - Persons (%)			
Less than 9th Grade	523 (9.92%)			
9th through 12th Grade	500 (9.49%)			
High School Diploma	1,712 (32.48%)			
Some College/2-year	385 (7.3%)			
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,625 (30.83%)			

Income Breakdown (ACS (American Community Survey)) - Households (%)			
\$50,000 - \$75,000	203 (7.07%)		
Greater than \$75,000	199 (6.93%)		



**Facility Summary** 

ESSO STANDARD OIL CO - PR CO-371

CALLE LUNA 22, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110004893802

EPA Region: 02 Latitude: 18.081938 Longitude: -67.048355

Locational Data Source: RCRAINFO

Industries: -Indian Country: N

#### **Enforcement and Compliance Summary**

	nena
Statute	RCRA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	-
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

### **Regulatory Information**

Clean Air Act (CAA): No Information
Clean Water Act (CWA): No Information

Resource Conservation and Recovery Act (RCRA): Inactive Other, (PRR000008276)

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

### **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

#### Facility/System Characteristics

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110004893802					N	18.081938	<b>-</b> 67.048355
RCRAInfo	RCRA	PRR000008276	Other	Inactive ( )			N	18.081938	-67.048355

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110004893802	ESSO STANDARD OIL CO - PR CO-371	CALLE LUNA 22, SAN GERMAN, PR 00683	San Germán Municipio
RCRAInfo	RCRA	PRR000008276	ESSO STANDARD OIL CO - PR CO-371	CALLE LUNA 22, SAN GERMAN, PR 00683-3955	San Germán Municipio

# Facility SIC (Standard Industrial Classification) Codes

# Facility NAICS (North American Industry Classification System) Codes

ystem Identifier SIC Code SIC Description System Identifier NAICS Code NAICS Description

No data records returned

No data records returned

#### **Facility Tribe Information**

Reservation Name Tribe Name EPA Tribal ID Distance to Tribe (miles)

No data records returned

**Enforcement and Compliance** 

### **Compliance Monitoring History**

Last 5 Years

Statute	Source ID	System	Activity Type	Compliance Monitoring Type	Lead Agency	Date	Finding (if applicable)

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
RCRA	PRR000008276	No	10/11/2025	0	10/10/2025

#### Three-Year Compliance History by Quarter

Statute	Program/Polluta Type		QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12+
RCRA	(Source ID: PRR00	00008276)	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
	Facility-Leve	el Status	No Violation Identified											
	Violation	Agency												

## **Informal Enforcement Actions**

Last 5 Years

Statute	System	Source ID	Type of Action	Lead Agency	Date

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

#### **Formal Enforcement Actions**

Last 5 Years

Statute	System	Law/ Section	Source ID	Type of Action	Case No.	Lead Agency	Case Name	Issued/ Filed Date	Settlements/ Actions	Settlement/ Action Date	Federal Penalty Assessed	State/ Local Penalty Assessed	Penalty Amount Collected	SEP Value	Comp Action Cost

No data records returned

**Environmental Conditions** 

#### Watersheds

Beach Closures WBD (Watershed Boundary Dataset) State Water Body Name (ICIS **Beach Closures** Pollutants Potentially Watershed with ESA (Endangered Dataset) HUC (RAD (Reach Address Subwatershed Name (RAD (Reach Address (Integrated Compliance Information Within Last Two Species Act)-listed Aquatic Species? Within Last Year Related to Impairment Database)) Database)) System))

#### Assessed Waters From Latest State Submission (ATTAINS)

tate Report Cycle Assessment Unit ID Assessment Unit Name Water Condition Cause Groups Impaired Drinking Water Use Ecological Use Fish Consumption Use Recreation Use Other Use

No data records returned

#### **Air Quality Nonattainment Areas**

Pollutant Within Nonattainment Status Area? Nonattainment Status Applicable Standard(s) Within Maintenance Status Area? Maintenance Status Applicable Standard(s)

No data records returned

**Pollutants** 

#### Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works) Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

#### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

#### Community

#### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic</a>.

General Statistics (ACS (American Community Survey))	
Total Persons	6,178
Population Density	1,980/sq.mi.
Housing Units in Area	3,644
Percent People of Color	100%
Households in Area	2,503
Households on Public Assistance	114
Persons With Low Income	4,638
Percent With Low Income	79%
Geography	
Radius of Selected Area	1 mi.

Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.081938
Center Longitude	-67.048355
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%

louseholds (%)
1,179 (47.08%)
446 (17.81%)
490 (19.57%)
170 (6.79%)
219 (8.75%)

Age Breakdown (ACS (American Community Survey)) - Persons (%)					
Children 5 years and younger	219 (4%)				
Minors 17 years and younger	891 (14%)				
Adults 18 years and older	5,288 (86%)				
Seniors 65 years and older	1,881 (30%)				

Race Breakdown (ACS (American Community Survey)) - Persons (%)						
White	4,283 (69%)					
African-American	26 (0%)					
Hispanic-Origin	6,123 (99%)					
Asian	6 (0%)					
Hawaiian/Pacific Islander	0 (0%)					
American Indian	0 (0%)					
Other/Multiracial	1,316 (21%)					

Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%)					
Less than 9th Grade	439 (9.56%)				
9th through 12th Grade	434 (9.45%)				
High School Diploma	1,384 (30.13%)				
Some College/2-year	317 (6.9%)				
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,541 (33.54%)				



**Facility Summary** 

**GRAVERO MAYAGUEZANO** 

PR-2 KM 176.0, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110001990588

EPA Region: 02

Latitude: 18.08133

Longitude: -67.04996

Locational Data Source: AIR

Industries: Mining (except Oil and Gas)

**Indian Country:** N

#### **Enforcement and Compliance Summary**

Statute	CAA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

#### **Regulatory Information**

Clean Air Act (CAA): Operating Minor (PR0000007212500001)

Clean Water Act (CWA): No Information

Resource Conservation and Recovery Act (RCRA): No Information

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

#### **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

**Compliance and Emissions Data Reporting Interface (CEDRI):** No Information

Facility/System Characteristics

### **Facility/System Characteristics**

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110001990588					N	18.08133	-67.04996
ICIS-Air	CAA	PR0000007212500001	Minor Emissions	Operating	CAASIP		N	18.08133	-67.04996

#### **Facility Address**

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110001990588 GRAVERO MAYAGUEZANO		PR-2 KM 176.0, SAN GERMAN, PR 00683	San Germán Municipio
ICIS-Air	CAA	PR0000007212500001	GRAVERO MAYAGUEZANO	CARR 2 KM 176.0, SAN GERMAN, PR 00753	San Germán Municipio

## Facility SIC (Standard Industrial Classification) Codes

## Facility NAICS (North American Industry Classification System) Codes

System	Identifier	SIC Code	SIC Description	System	Identifier	NAICS Code	NAICS Description
ICIS-Air	PR0000007212500001	1442	Construction Sand And Gravel	ICIS-Air	PR0000007212500001	212321	Construction Sand and Gravel Mining

#### **Facility Tribe Information**

Reservation Name Tribe Name EPA Tribal ID Distance to Tribe (miles)

No data records returned

**Enforcement and Compliance** 

#### **Compliance Monitoring History**

ast 5 Years

Statute Source ID System Activity Type Compliance Monitoring Type Lead Agency Date Finding (if applicable)

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
CAA	PR0000007212500001	No	10/11/2025	0	10/10/2025

#### Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12+
CA	AA (Source ID: PR0000007212500001)	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
	Facility-Level Status	No Violation Identified											
	HPV History												
	Violation Agency Programs Pollutants												

#### **Informal Enforcement Actions**

Last 5 Years

Statute System Source ID Type of Action Lead Agency Date

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

#### **Formal Enforcement Actions**

Last 5 Years

No data records returned

#### **Environmental Conditions**

#### Watersheds

12-Digit WBD (Watershed Boundary WBD (Watershed Boundary Dataset) State Water Body Name (ICIS Beach Closures **Beach Closures Pollutants Potentially** Watershed with ESA (Endangered Dataset) HUC (RAD (Reach Address Subwatershed Name (RAD (Reach Address (Integrated Compliance Information Within Last Two Related to Impairment Species Act)-listed Aquatic Species? Database)) System)) Database))

#### No data records returned

#### Assessed Waters From Latest State Submission (ATTAINS)

State Report Cycle Assessment Unit ID Assessment Unit ID Assessment Unit ID Assessment Unit Name Water Condition Cause Groups Impaired Drinking Water Use Ecological Use Fish Consumption Use Recreation Use Other Use

#### No data records returned

## **Air Quality Nonattainment Areas**

Pollutant Within Nonattainment Status Area? Nonattainment Status Applicable Standard(s) Within Maintenance Status Area? Maintenance Status Applicable Standard(s)

No data records returned

## Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works) Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

#### Community

### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic></a>.

General Statistics (ACS (American Community Survey))	
Total Persons	5,842
Population Density	1,872/sq.mi.
Housing Units in Area	3,395
Percent People of Color	100%
Households in Area	2,304
Households on Public Assistance	110
Persons With Low Income	4,341
Percent With Low Income	78%

Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.08133
Center Longitude	-67.04996
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%

Water Area	0%
Income Breakdown (ACS (American Community Sur	vey)) - Households (%)
Less than \$15,000	1,063 (46.14%)
\$15,000 - \$25,000	410 (17.8%)
\$25,000 - \$50,000	461 (20.01%)
\$50,000 - \$75,000	158 (6.86%)
Greater than \$75,000	212 (9.2%)

Age Breakdown (ACS (American Community Survey)) - Pe	rsons (%)
Children 5 years and younger	207 (4%)
Minors 17 years and younger	839 (14%)
Adults 18 years and older	5,003 (86%)
Seniors 65 years and older	1,734 (30%)
Race Breakdown (ACS (American Community Survey)) - P	ersons (%)
White	4,074 (70%)
African-American	21 (0%)

Race Breakdown (ACS (American Community Survey)) - Persons (70)	
White	4,074 (70%)
African-American	21 (0%)
Hispanic-Origin	5,793 (99%)
Asian	7 (0%)
Hawaiian/Pacific Islander	0 (0%)
American Indian	0 (0%)
Other/Multiracial	1,240 (21%)

Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%)					
Less than 9th Grade	415 (9.64%)				
9th through 12th Grade	409 (9.5%)				
High School Diploma	1,279 (29.71%)				
Some College/2-year	300 (6.97%)				
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,448 (33.64%)				



**Facility Summary** 

HORMIG MAYAGUEZANA

PR-2 KM 176, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110002063506

EPA Region: 02

Latitude: 18.08133

Longitude: -67.04996

Locational Data Source: AIR

Industries: Nonmetallic Mineral Product Manufacturing

Indian Country: N

#### **Enforcement and Compliance Summary**

Statute	CAA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	-
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

#### **Regulatory Information**

Clean Air Act (CAA): Operating Minor (PR0000007212500004)

Clean Water Act (CWA): No Information

Resource Conservation and Recovery Act (RCRA): No Information

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

#### **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

#### Facility/System Characteristics

### **Facility/System Characteristics**

9	System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
	FRS		110002063506					N	18.08133	-67.04996
1	ICIS-Air	CAA	PR0000007212500004	Minor Emissions	Operating	CAASIP		N	18.08133	-67.04996

#### **Facility Address**

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110002063506	HORMIG MAYAGUEZANA	PR-2 KM 176, SAN GERMAN, PR 00683	San Germán Municipio
ICIS-Air	CAA	PR0000007212500004	HORMIG MAYAGUEZANA	CARR 2 KM 176, SAN GERMAN, PR 00753	San Germán Municipio

## **Facility SIC (Standard Industrial Classification)**

#### **Facility NAICS (North American Industry Classification System) Codes**

System	Identifier	SIC Code	SIC Description	System	Identifier	NAICS Code	NAICS Description
ICIS-Air	PR0000007212500004	3273	Ready-Mixed Concrete	ICIS-Air	PR0000007212500004	327320	Ready-Mix Concrete Manufacturing

#### **Facility Tribe Information**

**Reservation Name** Tribe Name EPA Tribal ID Distance to Tribe (miles)

No data records returned

**Enforcement and Compliance** 

#### **Compliance Monitoring History**

Finding (if applicable) Source ID **Compliance Monitoring Type** 

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/ monitoring-programs> activities or because they are not counted as inspections within EPA's Annual Results < https://www.epa.gov/enforcement/enforcement-data-and-results>.

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
CAA	PR0000007212500004	No	10/11/2025	0	10/10/2025

#### Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12+
CA	CAA (Source ID: PR0000007212500004)		01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
	Facility-Level Status		No Violation Identified										
	HPV History												
	Violation Agency Programs Pollutants												

#### **Informal Enforcement Actions**

Last 5 Years

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

#### **Formal Enforcement Actions**

Last 5 Years

Settlement/ Action State/ Local Penalty Statute System Action Collected

No data records returned

#### **Environmental Conditions**

#### Watersheds

12-Digit WBD (Watershed Boundary WBD (Watershed Boundary Dataset) State Water Body Name (ICIS Beach Closures **Beach Closures Pollutants Potentially** Watershed with ESA (Endangered Dataset) HUC (RAD (Reach Address Subwatershed Name (RAD (Reach Address (Integrated Compliance Information Within Last Two Related to Impairment Species Act)-listed Aquatic Species? Database)) System)) Database))

No data records returned

#### Assessed Waters From Latest State Submission (ATTAINS)

**Cause Groups Impaired Drinking Water Use Ecological Use** 

No data records returned

### Air Quality Nonattainment Areas

Pollutant Within Nonattainment Status Area? Maintenance Status Applicable Standard(s)

No data records returned

## Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works) Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

#### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

#### Community

### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic></a>.

High School Diploma

Some College/2-year

B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More

General Statistics (ACS (American Community Survey))	
Total Persons	5,842
Population Density	1,872/sq.mi.
Housing Units in Area	3,395
Percent People of Color	100%
Households in Area	2,304
Households on Public Assistance	110
Persons With Low Income	4,341
Percent With Low Income	78%

Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.08133
Center Longitude	-67.04996
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%

Water Area	0%
Income Breakdown (ACS (American Community St	urvey)) - Households (%)
Less than \$15,000	1,063 (46.14%)
\$15,000 - \$25,000	410 (17.8%)
\$25,000 - \$50,000	461 (20.01%)
\$50,000 - \$75,000	158 (6.86%)
Greater than \$75,000	212 (9.2%)

Age Breakdown (ACS (American Community Survey)) - Pe	rsons (%)				
Children 5 years and younger	207 (4%)				
Minors 17 years and younger	839 (14%)				
Adults 18 years and older	5,003 (86%)				
Seniors 65 years and older	1,734 (30%)				
Race Breakdown (ACS (American Community Survey)) - P	ersons (%)				
White	4,074 (70%)				
African-American	21 (0%)				
Hispanic-Origin	5,793 (99%)				
Asian	7 (0%)				
Hawaiian/Pacific Islander	0 (0%)				
American Indian	0 (0%)				
Other/Multiracial	1,240 (21%)				
Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%)					
Less than 9th Grade	415 (9.64%)				
9th through 12th Grade	409 (9.5%)				

1,279 (29.71%)

300 (6.97%) 1,448 (33.64%)



**Facility Summary** 

ASFALTERA EMPRESAS INABON

CARR 2 KM 187.0, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110002063356

EPA Region: 02
Latitude: 18.07961
Longitude: -67.05076
Locational Data Source: FRS

Industries: Petroleum and Coal Products Manufacturing

**Indian Country:** N

#### **Enforcement and Compliance Summary**

Statute	CAA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	-
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

#### **Regulatory Information**

Clean Air Act (CAA): Temporarily Closed Minor (PR0000007212100036)

Clean Water Act (CWA): No Information

Resource Conservation and Recovery Act (RCRA): No Information

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

#### **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

**Greenhouse Gas Emissions (eGGRT):** No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

#### Facility/System Characteristics

### **Facility/System Characteristics**

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110002063356					N	18.07961	-67.05076
ICIS-Air	CAA	PR0000007212100036	Minor Emissions	Temporarily Closed	CAANSPS, CAASIP		N	18.077778	-67.04125

### **Facility Address**

System	Statute	Identifier	Identifier Facility Name Facility Address		Facility County
FRS		110002063356	ASFALTERA EMPRESAS INABON	CARR 2 KM 187.0, SAN GERMAN, PR 00683	San Germán Municipio
ICIS-Air	CAA	PR0000007212100036	ASFALTERA EMPRESAS INABON	CARR 2 KM 187.0, PONCE, PR 00683	Ponce Municipio

## **Facility SIC (Standard Industrial Classification)**

#### **Facility NAICS (North American Industry Classification System) Codes**

					-		
System	Identifier	SIC Code	SIC Description	System	Identifier	NAICS Code	NAICS Description
ICIS-Air	PR0000007212100036	2951	Asphalt Paving Mixtures And Blocks	ICIS-Air	PR0000007212100036	324121	Asphalt Paving Mixture and Block Manufacturing

#### **Facility Tribe Information**

**Reservation Name** EPA Tribal ID Distance to Tribe (miles)

No data records returned

**Enforcement and Compliance** 

#### **Compliance Monitoring History**

**Compliance Monitoring Type** Finding (if applicable)

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/ monitoring-programs> activities or because they are not counted as inspections within EPA's Annual Results <a href="https://www.epa.gov/enforcement/enforcement-data-and-results">https://www.epa.gov/enforcement/enforcement-data-and-results</a>.

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
CAA	PR0000007212100036	No	10/11/2025	0	10/10/2025

#### Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12+
CA	A (Source ID: PR0000007212100036)	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
	Facility-Level Status	No Violation Identified											
	HPV History												
	Violation Agency Programs Pollutants												

#### **Informal Enforcement Actions**

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

#### Formal Enforcement Actions | Last 5 Years

St	atute Syst	stem	Law/ Section	Source ID	Type of Action	Case No.	Lead Agency	Case Name	Issued/ Filed Date	Settlements/ Actions	Settlement/ Action Date	Federal Penalty Assessed	State/ Local Penalty Assessed	Penalty Amount Collected	SEP Value	Comp Action Cost

No data records returned

**Environmental Conditions** 

#### Watersheds

12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database))	WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database))	State Water Body Name (ICIS (Integrated Compliance Information System))	Beach Closures Within Last Year	Beach Closures Within Last Two Years	Pollutants Potentially Related to Impairment	Watershed with ESA (Endangered Species Act)-listed Aquatic Species?

No data records returned

#### Assessed Waters From Latest State Submission (ATTAINS)

Assessment Unit Name Drinking Water Use Cause Groups Impaired **Ecological Use** 

No data records returned

## **Air Quality Nonattainment Areas**

	<del>-</del>						
Pollutant	Within Nonattainment Status Area?	Nonattainment Status Applicable Standard(s)	Within Maintenance Status Area?	Maintenance Status Applicable Standard(s)			
	No data records returned						

## Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works) Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

#### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

#### Community

#### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic></a>.

High School Diploma

Some College/2-year

B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More

General Statistics (ACS (American Community Survey))	
Total Persons	5,513
Population Density	1,767/sq.mi.
Housing Units in Area	3,212
Percent People of Color	100%
Households in Area	2,158
Households on Public Assistance	105
Persons With Low Income	4,087
Percent With Low Income	78%

Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.07961
Center Longitude	-67.05076
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%

Income Breakdown (ACS (American Community Survey)) - Households (%)					
Less than \$15,000	987 (45.76%)				
\$15,000 - \$25,000	383 (17.76%)				
\$25,000 - \$50,000	437 (20.26%)				
\$50,000 - \$75,000	149 (6.91%)				
Greater than \$75,000	201 (9.32%)				

Age Breakdown (ACS (American Community Survey)) - Persons (%)					
Children 5 years and younger	190 (3%)				
Minors 17 years and younger	764 (14%)				
Adults 18 years and older	4,749 (86%)				
Seniors 65 years and older	1,636 (30%)				
Race Breakdown (ACS (American Community Survey)) - Persons	%)				
White	3,844 (70%)				
African-American	20 (0%)				
Hispanic-Origin	5,467 (99%)				
Asian	6 (0%)				
Hawaiian/Pacific Islander	0 (0%)				
American Indian	0 (0%)				
Other/Multiracial	1,183 (21%)				
Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%)					
Less than 9th Grade	404 (9.89%)				
9th through 12th Grade	389 (9.52%)				

1,215 (29.75%)

288 (7.05%)

1,362 (33.35%)



**Facility Summary** 

TOTAL PETROLEUM PUERTO RICO CORP - SERVICE STATION 104116

CARR 2 KM 174.3, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110043555514

EPA Region: 02 Latitude: 18.07961 Longitude: -67.05076

**Locational Data Source:** FRS **Industries:** Gasoline Stations

Indian Country:  $\,\,{\sf N}\,\,$ 

### **Enforcement and Compliance Summary**

Statute	RCRA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	-
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

## **Regulatory Information**

Clean Air Act (CAA): No Information
Clean Water Act (CWA): No Information

Resource Conservation and Recovery Act (RCRA): Active VSQG, (PRR000023705)

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

## **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

**Compliance and Emissions Data Reporting Interface (CEDRI):** No Information

#### Facility/System Characteristics

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110043555514					N	18.07961	<b>-</b> 67.05076
RCRAInfo	RCRA	PRR000023705	VSQG	Active (H )			N	18.092959	-67.032315

System	Statute	Identifier	Facility Address	Facility County	
FRS		110043555514	TOTAL PETROLEUM PUERTO RICO CORP - SERVICE STATION 104116	CARR 2 KM 174.3, SAN GERMAN, PR 00683	San Germán Municipio
RCRAInfo	RCRA	PRR000023705	TOTAL PETROLEUM PUERTO RICO CORP - SERVICE STATION 104116	CARR 2 KM 174.3, SAN GERMAN, PR 00683	San Germán Municipio

RCRAInfo

RCRAInfo

# Facility SIC (Standard Industrial Classification) Codes

No data records returned

assific	ation) Code	S		Classification System) Codes					
System	Identifier	SIC Code	SIC Description	System	Identifier	NAICS Code	NAICS Description		

**Facility Tribe Information** 

PRR000023705

PRR000023705

Reservation Name Tribe Name EPA Tribal ID Distance to Tribe (miles)

Gasoline Stations with Convenience Stores

Other Gasoline Stations

**Facility NAICS (North American Industry** 

44711

No data records returned

**Enforcement and Compliance** 

**Compliance Monitoring History** 

Last 5 Years

Statute Source ID System Activity Type Compliance Monitoring Type Lead Agency Date Finding (if applicable)

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/

#### **Compliance Summary Data**

Statu	e Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
RCR	PRR000023705	No	10/11/2025	0	10/10/2025

### Three-Year Compliance History by Quarter

Statute	Program/Pollut Typ		QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12+
RCRA	(Source ID: PRR0	00023705)	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
	Facility-Lev	el Status	No Violation Identified											
	Violation	Agency												

## **Informal Enforcement Actions**

Last 5 Years

Statute System Source ID Type of Action Lead Agency Date

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

**Formal Enforcement Actions** 

Last 5 Years

Statute System Law/ Source Type of Case Lead Case Issued/Filed Settlements/ Settlement/Action Federal Penalty State/ Local Penalty Penalty Amount SEP Comp Action Settlement/ Settlement/

No data records returned

**Environmental Conditions** 

#### Watersheds

12-Digit WBD (Watershed Boundary Dataset)

Database)

WBD (Watershed Boundary Dataset)

State Water Body Name (ICIS (Integrated Compliance Information Database))

State Water Body Name (ICIS (Integrated Compliance Information System))

Beach Closures Within Last Two Years

Pollutants Potentially Watershed with ESA (Endangered Species Act)-listed Aquatic Species?

#### Assessed Waters From Latest State Submission (ATTAINS)

Report Cycle Assessment Unit ID Assessment Unit Name **Water Condition Cause Groups Impaired Drinking Water Use Ecological Use** Fish Consumption Use

No data records returned

#### **Air Quality Nonattainment Areas**

Pollutant Within Nonattainment Status Area? Nonattainment Status Applicable Standard(s) Within Maintenance Status Area? Maintenance Status Applicable Standard(s)

No data records returned

**Pollutants** 

#### Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per **Year at Site**

TRI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works) Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

#### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

#### Community

Center Longitude

#### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-to-the-branch-new-to-t dictionary#demographic>.

High School Diploma

Some College/2-year

B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More

-67.05076

General Statistics (ACS (American Community Survey))	
Total Persons	5,513
Population Density	1,767/sq.mi.
Housing Units in Area	3,212
Percent People of Color	100%
Households in Area	2,158
Households on Public Assistance	105
Persons With Low Income	4,087
Percent With Low Income	78%
Geography	
Radius of Selected Area	1 mi.
Center Latitude	18 07961

Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%
Income Breakdown (ACS (American Community Sur	vey)) - Households (%)
Less than \$15,000	987 (45.76%)
\$15,000 - \$25,000	383 (17.76%)
\$25,000 - \$50,000	437 (20.26%)
\$50,000 - \$75,000	149 (6.91%)
Greater than \$75,000	201 (9.32%)

Children 5 years and younger	younger 190 (3%)					
Minors 17 years and younger	younger 764 (14%)					
Adults 18 years and older	4,749 (86%)					
Seniors 65 years and older 1,636 (30%)						
Race Breakdown (ACS (American Community Survey)) -	Persons (%)					
White	3,844 (70%)					
African-American	20 (0%)					
Hispanic-Origin	5,467 (99%)					
Asian	6 (0%)					
Hawaiian/Pacific Islander	0 (0%)					
American Indian	0 (0%)					
Other/Multiracial	1,183 (21%)					
Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%)						
Less than 9th Grade	404 (9.89%)					
9th through 12th Grade	389 (9.52%)					

1,215 (29.75%)

288 (7.05%)

1,362 (33.35%)

Age Breakdown (ACS (American Community Survey)) - Persons (%)



**Facility Summary** 

CENTRO DE SALUD FAMILIAR DOH

63 JAVILLA ST, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110004895622

EPA Region: --

**Latitude:** 18.082898 **Longitude:** -67.041896

Locational Data Source: FRS

Industries: -Indian Country: N

#### **Enforcement and Compliance Summary**

Statute	RCRA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	-
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

### **Regulatory Information**

Clean Air Act (CAA): No Information
Clean Water Act (CWA): No Information

Resource Conservation and Recovery Act (RCRA): Inactive Other, (PRR000012559)

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

### **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Facility/System Characteristics

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110004895622					N	18.082898	-67.041896
RCRAInfo	RCRA	PRR000012559	Other	Inactive ( )			N	18.082413	-67.040516

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110004895622	CENTRO DE SALUD FAMILIAR DOH	63 JAVILLA ST, SAN GERMAN, PR 00683	San Germán Municipio
RCRAInfo	RCRA	PRR000012559	CENTRO DE SALUD FAMILIAR DOH	63 JAVILLA ST, SAN GERMAN, PR 00683	San Germán Municipio

#### **Facility SIC (Standard Industrial Classification**) Codes

#### **Facility NAICS (North American Industry Classification System) Codes**

No data records returned

No data records returned

#### **Facility Tribe Information**

Distance to Tribe (miles)

No data records returned

**Enforcement and Compliance** 

### **Compliance Monitoring History** Last 5 Years

Statute	Source ID	System	Activity Type	Compliance Monitoring Type	Lead Agency	Date	Finding (if applicable)

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/ monitoring-programs> activities or because they are not counted as inspections within EPA's Annual Results <a href="https://www.epa.gov/enforcement/enforcement-data-and-results">https://www.epa.gov/enforcement/enforcement-data-and-results></a>.

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
RCRA	PRR000012559	No	10/11/2025	0	10/10/2025

#### Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violatio Type	QTR1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12+
RCRA	(Source ID: PRR000012559)	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
	Facility-Level Status	No Violation Identified											
	Violation Agency												

## **Informal Enforcement Actions**

Statute	System	Source ID	Type of Action	Lead Agency	Date

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

#### **Formal Enforcement Actions**

Last 5 Years

Statute System Continue ID Antinue No. Annual No. Annual No. Annual Collected Males	Statute System	Law/	Source	Type of	Case	Lead	Case	Issued/ Filed	Settlements/	Settlement/ Action	Federal Penalty	State/ Local Penalty	Penalty Amount	SEP	Comp Action
Section ID Action No. Agency Name Date Actions Date Assessed Assessed Collected Value C	Statute System	Section	ID	Action	No.	Agency	Name	Date	Actions	Date	Assessed	Assessed	Collected	Value	Cost

No data records returned

**Environmental Conditions** 

#### Watersheds

Beach Closures WBD (Watershed Boundary Dataset) State Water Body Name (ICIS **Beach Closures** Pollutants Potentially Watershed with ESA (Endangered Dataset) HUC (RAD (Reach Address Subwatershed Name (RAD (Reach Address (Integrated Compliance Information Within Last Two Species Act)-listed Aquatic Species? Within Last Year Related to Impairment Database)) Database)) System))

#### Assessed Waters From Latest State Submission (ATTAINS)

Report Cycle Assessment Unit ID Assessment Unit Name Water Condition Cause Groups Impaired Drinking Water Use Ecological Use Fish Consumption Use Recreation Use Other Use

No data records returned

#### **Air Quality Nonattainment Areas**

Pollutant Within Nonattainment Status Area? Nonattainment Status Applicable Standard(s) Within Maintenance Status Area? Maintenance Status Applicable Standard(s)

No data records returned

**Pollutants** 

#### Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works) Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

#### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

#### Community

Less than \$15,000

\$15,000 - \$25,000

\$25,000 - \$50,000

\$50,000 - \$75,000 Greater than \$75,000

#### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic</a>.

General Statistics (ACS (American Community Survey))	
Total Persons	7,216
Population Density	2,313/sq.mi.
Housing Units in Area	4,013
Percent People of Color	99%
Households in Area	2,921
Households on Public Assistance	129
Persons With Low Income	5,666
Percent With Low Income	81%
Geography	

Radius of Selected Area	1 mi.
Center Latitude	18.082898
Center Longitude	-67.041896
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%

1,363 (46.68%)

523 (17.91%)

628 (21.51%) 214 (7.33%)

192 (6.58%)

White	4,913 (68%)
African-American	90 (1%)
Hispanic-Origin	7,130 (99%)
Asian	4 (0%)
Hawaiian/Pacific Islander	10 (0%)
American Indian	0 (0%)
Other/Multiracial	1,476 (20%)
Education Level (Persons 25 & older) (ACS (American Community Surv	oul) Porcons (9/s)
Less than 9th Grade	529 (9.83%)
9th through 12th Grade	506 (9.4%)
High School Diploma	1,789 (33.23%)
Some College/2-year	404 (7.51%)
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,622 (30.13%)

258 (4%)

1,126 (16%)

6,090 (84%)

2,160 (30%)

Age Breakdown (ACS (American Community Survey)) - Persons (%)

Children 5 years and younger

Minors 17 years and younger

Adults 18 years and older

Seniors 65 years and older



**Facility Summary** 

**JAVILLA SS 1058** 

CALLE JAVILL 12, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110004892661

**EPA Region:** 02 **Latitude:** 18.082593 **Longitude:** -67.041143

Locational Data Source: RCRAINFO

Industries: -Indian Country: N

## **Enforcement and Compliance Summary**

RCRA
-
-
No Violation Identified
0
0
-
-
-
-

### **Regulatory Information**

Clean Air Act (CAA): No Information
Clean Water Act (CWA): No Information

Resource Conservation and Recovery Act (RCRA): Inactive Other, (PRR000003871)

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

### **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Facility/System Characteristics

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110004892661					N	18.082593	-67.041143
RCRAInfo	RCRA	PRR000003871	Other	Inactive ( )			N	18.082593	-67.041143

System	Statute	Identifier Facility Name		Facility Address	Facility County	
FRS		110004892661	JAVILLA SS 1058	CALLE JAVILL 12, SAN GERMAN, PR 00683	San Germán Municipio	
RCRAInfo	RCRA	PRR000003871	JAVILLA SS 1058	CALLE JAVILL 12, SAN GERMAN, PR 00683-4102	San Germán Municipio	

# Facility SIC (Standard Industrial Classification) Codes

# Facility NAICS (North American Industry Classification System) Codes

System Identifier SIC Code SIC Description System Identifier NAICS Code NAICS Description

No data records returned

No data records returned

#### **Facility Tribe Information**

Reservation Name Tribe Name EPA Tribal ID Distance to Tribe (miles)

No data records returned

**Enforcement and Compliance** 

## **Compliance Monitoring History**

Last 5 Years

Statute Source ID System Activity Type Compliance Monitoring Type Lead Agency Date Finding (if applicable)

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
RCRA	PRR000003871	No	10/11/2025	0	10/10/2025

#### Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violation Type	QTR1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	<b>QTR</b> 9	QTR 10	QTR 11	QTR 12+
RCRA	(Source ID: PRR000003871)	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
	Facility-Level Status	No Violation Identified											
	Violation Agency												

## **Informal Enforcement Actions**

Last 5 Years

Statute System Source ID Type of Action Lead Agency Date

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

#### **Formal Enforcement Actions**

Last 5 Years

No data records returned

**Environmental Conditions** 

#### Watersheds

Beach Closures WBD (Watershed Boundary Dataset) State Water Body Name (ICIS **Beach Closures** Pollutants Potentially Watershed with ESA (Endangered Dataset) HUC (RAD (Reach Address Subwatershed Name (RAD (Reach Address (Integrated Compliance Information **Within Last Two** Within Last Year Related to Impairment Species Act)-listed Aquatic Species? Database)) Database)) System)) Vears

#### Assessed Waters From Latest State Submission (ATTAINS)

State Report Cycle Assessment Unit ID Assessment Unit Name Water Condition Cause Groups Impaired Drinking Water Use Ecological Use Fish Consumption Use Recreation Use Other Use

No data records returned

#### **Air Quality Nonattainment Areas**

Pollutant Within Nonattainment Status Area? Nonattainment Status Applicable Standard(s) Within Maintenance Status Area? Maintenance Status Applicable Standard(s)

No data records returned

**Pollutants** 

#### Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works) Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

#### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

#### Community

#### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic</a>.

Hispanic-Origin

American Indian

Hawaiian/Pacific Islander

Asian

General Statistics (ACS (American Community Survey))	
Total Persons	7,277
Population Density	2,319/sq.mi.
Housing Units in Area	4,012
Percent People of Color	99%
Households in Area	2,933
Households on Public Assistance	129
Persons With Low Income	5,735
Percent With Low Income	81%
Geography	

Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.082593
Center Longitude	-67.041143
Total Area	3.14 sq.mi.
Land Area	100%
Water Area	0%

Income Breakdown (ACS (American Community Su	vey)) - Households (%)
Less than \$15,000	1,361 (46.43%)
\$15,000 - \$25,000	525 (17.91%)
\$25,000 - \$50,000	639 (21.8%)
\$50,000 - \$75,000	218 (7.44%)
Greater than \$75,000	188 (6.41%)

Age Breakdown (ACS (American Community Survey)) - Per	sons (%)
Children 5 years and younger	260 (4%)
Minors 17 years and younger	1,140 (16%)
Adults 18 years and older	6,137 (84%)
Seniors 65 years and older	2,166 (30%)
Race Breakdown (ACS (American Community Survey)) - Pe	ersons (%)
White	4,949 (68%)
African-American	100 (1%)

7,190 (99%)

4 (0%)

11 (0%)

0 (0%)

Other/Multiracial	1,484 (20%)
Education Level (Persons 25 & older) (ACS (America	n Community Survey)) - Persons (%)
Less than 9th Grade	534 (9.83%)
9th through 12th Grade	507 (9.33%)
High School Diploma	1,825 (33.6%)
Some College/2-year	415 (7.64%)
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or Moi	re 1,618 (29.79%)



**Facility Summary** 

**OLD MARKET PLAZA** 

96 INTERAMERICANA AVE, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110017614205

EPA Region: 02 Latitude: 18.08131 Longitude: -67.04141

Locational Data Source: RCRAINFO

**Industries:** Waste Management and Remediation Services

**Indian Country:** N

#### **Enforcement and Compliance Summary**

	nena
Statute	RCRA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	-
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

#### **Regulatory Information**

Clean Air Act (CAA): No Information
Clean Water Act (CWA): No Information

Resource Conservation and Recovery Act (RCRA): Inactive Other, (PRR000017012)

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

### **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Facility/System Characteristics

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110017614205					N	18.08131	<b>-</b> 67.04141
RCRAInfo	RCRA	PRR000017012	Other	Inactive ( )			N	18.08131	-67.04141

System	Statute	atute Identifier Facility Name		Facility Address	Facility County	
FRS		110017614205	OLD MARKET PLAZA	96 INTERAMERICANA AVE, SAN GERMAN, PR 00683	San Germán Municipio	
RCRAInfo	RCRA	PRR000017012	OLD MARKET PLAZA	96 INTERAMERICANA AVE, SAN GERMAN, PR 00683	San Germán Municipio	

#### **Facility SIC (Standard Industrial Classification**) Codes

## **Facility NAICS (North American Industry Classification System) Codes**

RCRAInfo PRR000017012 56291 Remediation Services

No data records returned

#### **Facility Tribe Information**

Reservation Name EPA Tribal ID Distance to Tribe (miles)

No data records returned

**Enforcement and Compliance** 

## **Compliance Monitoring History**

Source ID **Activity Type** Finding (if applicable) System **Compliance Monitoring Type Lead Agency** Date

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/ monitoring-programs> activities or because they are not counted as inspections within EPA's Annual Results <a href="https://www.epa.gov/enforcement/enforcement-data-and-results">https://www.epa.gov/enforcement/enforcement-data-and-results>.

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
RCRA	PRR000017012	No	10/11/2025	0	10/10/2025

#### Three-Year Compliance History by Quarter

Statute	Program/Pollut Typ		QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12+
RCRA	(Source ID: PRRO	000017012)	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
	Facility-Lev	el Status	No Violation Identified											
	Violation	Agency												

### **Informal Enforcement Actions**

Last 5 Years

Type of Action

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

### **Formal Enforcement Actions**

Last 5 Years

Issued/ Filed Settlements/ Settlement/ Action Federal Penalty State/ Local Penalty Penalty Amount SEP Statute System Action Date Actions Date Assessed Assessed Collected Value

No data records returned

**Environmental Conditions** 

#### Watersheds

12-Digit WBD (Watershed Boundary WBD (Watershed Boundary Dataset) State Water Body Name (ICIS **Beach Closures** Beach Closures Watershed with ESA (Endangered Pollutants Potentially Dataset) HUC (RAD (Reach Address Subwatershed Name (RAD (Reach Address (Integrated Compliance Information Within Last Two Within Last Year Related to Impairment Species Act)-listed Aquatic Species? Database)) System))

No data records returned

## Assessed Waters From Latest State Submission (ATTAINS)

**Assessment Unit Name Ecological Use** 

#### **Air Quality Nonattainment Areas**

Nonattainment Status Applicable Standard(s) Within Maintenance Status Area? Maintenance Status Applicable Standard(s)

No data records returned

**Pollutants** 

#### Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works)

Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

#### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

Community

#### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in dictionary#demographic>.

General Statistics (ACS (American Community Survey))	
Total Persons	7,239
Population Density	2,306/sq.mi.
Housing Units in Area	4,029
Percent People of Color	99%
Households in Area	2,933
Households on Public Assistance	131
Persons With Low Income	5,710
Percent With Low Income	81%
Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.08131
Center Longitude	-67.04141
Total Area	3.14 sq.mi.
Land Area	100%
Water Area	0%
Income Breakdown (ACS (American Community Survey))	- Households (%)
Less than \$15,000	1,370 (46.74%)
\$15,000 - \$25,000	525 (17.91%)
\$25,000 - \$50,000	634 (21.63%)
\$50,000 - \$75,000	215 (7.34%)
Greater than \$75,000	187 (6.38%)

Children 5 years and younger	260 (4%)				
Minors 17 years and younger	1,109 (15%)				
Adults 18 years and older	6,128 (85%)				
Seniors 65 years and older	2,177 (30%)				
Race Breakdown (ACS (American Community Survey)) - Persons (%)					
White	4,913 (68%)				
African-American	95 (1%)				
Hispanic-Origin	7,150 (99%)				
Asian	4 (0%)				
Hawaiian/Pacific Islander	12 (0%)				
American Indian	0 (0%)				
Other/Multiracial	1,487 (21%)				
Education Level (Persons 25 & older) (ACS (American Community Surv	vey)) - Persons (%)				
Less than 9th Grade	544 (10.02%)				
9th through 12th Grade	508 (9.36%)				
High School Diploma	1,832 (33.75%)				
Some College/2-year	411 (7.57%)				
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,604 (29.55%)				

Age Breakdown (ACS (American Community Survey)) - Persons (%)



**Facility Summary** 

**WALGREENS 167** 

CALLE LUNA & ESQUINA CARRO, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110007817595

**EPA Region:** 02 **Latitude:** 18.081369 **Longitude:** -67.042569

Locational Data Source: RCRAINFO

Industries: -Indian Country: N

#### **Enforcement and Compliance Summary**

	nena
Statute	RCRA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	-
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

### **Regulatory Information**

Clean Air Act (CAA): No Information
Clean Water Act (CWA): No Information

Resource Conservation and Recovery Act (RCRA): Inactive Other, (PRR000003467)

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

### **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Facility/System Characteristics

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110007817595					N	18.081369	-67.042569
RCRAInfo	RCRA	PRR000003467	Other	Inactive ( )			N	18.081369	-67.042569

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110007817595	WALGREENS 167	CALLE LUNA & ESQUINA CARRO, SAN GERMAN, PR 00683	San Germán Municipio
RCRAInfo	RCRA	PRR000003467	WALGREENS 167	CALLE LUNA & ESQUINA CARRO, SAN GERMAN, PR 00683	San Germán Municipio

# Facility SIC (Standard Industrial Classification) Codes

# Facility NAICS (North American Industry Classification System) Codes

System Identifier SIC Code SIC Description System Identifier NAICS Code NAICS Description

No data records returned

No data records returned

#### **Facility Tribe Information**

Reservation Name Tribe Name EPA Tribal ID Distance to Tribe (miles)

No data records returned

**Enforcement and Compliance** 

### **Compliance Monitoring History**

Last 5 Years

Statute Source ID System Activity Type Compliance Monitoring Type Lead Agency Date Finding (if applicable)

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
RCRA	PRR000003467	No	10/11/2025	0	10/10/2025

#### Three-Year Compliance History by Quarter

Statute	Program/Polluta Type		QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12+
RCRA	(Source ID: PRR0	00003467)	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
	Facility-Lev	el Status	No Violation Identified											
	Violation	Agency												

## **Informal Enforcement Actions**

Last 5 Years

Statute System Source ID Type of Action Lead Agency Date

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

#### **Formal Enforcement Actions**

Last 5 Years

Statute System Section ID Action No. Agency Name Date Actions Date Assessed Collected Value Cost	C+-	uto Svet	Law,	Source	Type of	Case	Lead	Case	Issued/ Filed	Settlements/	Settlement/ Action	Federal Penalty	State/ Local Penalty	Penalty Amount	SEP	Comp Action
	Sta	ute 3yst	Section	n ID	Action	No.	Agency	Name	Date	Actions	Date	Assessed	Assessed	Collected	Value	Cost

No data records returned

**Environmental Conditions** 

#### Watersheds

Beach Closures WBD (Watershed Boundary Dataset) State Water Body Name (ICIS **Beach Closures** Pollutants Potentially Watershed with ESA (Endangered Dataset) HUC (RAD (Reach Address Subwatershed Name (RAD (Reach Address (Integrated Compliance Information Within Last Two Species Act)-listed Aquatic Species? Within Last Year Related to Impairment Database)) Database)) System)) Vears

#### Assessed Waters From Latest State Submission (ATTAINS)

ate Report Cycle Assessment Unit ID Assessment Unit Name Water Condition Cause Groups Impaired Drinking Water Use Ecological Use Fish Consumption Use Recreation Use Other Use

No data records returned

#### **Air Quality Nonattainment Areas**

Pollutant Within Nonattainment Status Area? Nonattainment Status Applicable Standard(s) Within Maintenance Status Area? Maintenance Status Applicable Standard(s)

No data records returned

**Pollutants** 

#### Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works) Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

#### Community

#### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic</a>.

General Statistics (ACS (American Community Survey))	
Total Persons	7,122
Population Density	2,283/sq.mi.
Housing Units in Area	4,026
Percent People of Color	99%
Households in Area	2,899
Households on Public Assistance	132
Persons With Low Income	5,582
Percent With Low Income	81%
Geography	

Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.081369
Center Longitude	-67.042569
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%

Income Breakdown (ACS (American Community Surve	ey)) - Households (%)
Less than \$15,000	1,363 (47.03%)
\$15,000 - \$25,000	520 (17.94%)
\$25,000 - \$50,000	615 (21.22%)
\$50,000 - \$75,000	208 (7.18%)
Greater than \$75,000	192 (6.63%)

Age Breakdown (ACS (American Community Survey)) - Persons (%)	
Children 5 years and younger	254 (4%)
Minors 17 years and younger	1,071 (15%)
Adults 18 years and older	6,050 (85%)
Seniors 65 years and older	2,166 (30%)
Race Breakdown (ACS (American Community Survey)) - Persons (%)	
White	4,837 (68%)

Race Breakdown (ACS (American Community Survey)) - Person	ns (%)
White	4,837 (68%)
African-American	83 (1%)
Hispanic-Origin	7,036 (99%)
Asian	4 (0%)
Hawaiian/Pacific Islander	10 (0%)
American Indian	0 (0%)
Other/Multiracial	1,481 (21%)

Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%)	
Less than 9th Grade	540 (10.09%)
9th through 12th Grade	505 (9.44%)
High School Diploma	1,777 (33.21%)
Some College/2-year	397 (7.42%)
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,609 (30.07%)



**Facility Summary** 

INTERAMERICAN UNIV SAN GERMAN

CALLE LUNA, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110007810431

**EPA Region:** 02 **Latitude:** 18.080442 **Longitude:** -67.036833

**Locational Data Source:** RCRAINFO **Industries:** Educational Services

Indian Country: N

#### **Enforcement and Compliance Summary**

Statute	RCRA			
Compliance Monitoring Activities (5 years)	-			
Date of Last Compliance Monitoring Activity	01/31/2012			
Compliance Status	No Violation Identified			
Qtrs in Noncompliance (of 12)	0			
Qtrs with Significant Violation	0			
Informal Enforcement Actions (5 years)	-			
Formal Enforcement Actions (5 years)				
Penalties from Formal Enforcement Actions (5 years)				
EPA Cases (5 years)	-			
Penalties from EPA Cases (5 years)				

### **Regulatory Information**

Clean Air Act (CAA): No Information
Clean Water Act (CWA): No Information

**Resource Conservation and Recovery Act (RCRA):** Active VSQG, (PRD987367604)

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

### **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Facility/System Characteristics

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110007810431					N	18.080442	-67.036833
ICIS		31964					N	18.080442	-67.036833
RCRAInfo	RCRA	PRD987367604	VSQG	Active (H )			N	18.080442	-67.036833

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110007810431	INTERAMERICAN UNIV SAN GERMAN	CALLE LUNA, SAN GERMAN, PR 00683	San Germán Municipio
ICIS		31964	INTERAMERICAN UNIV SAN GERMAN	CALLE LUNA, SAN GERMAN, PR 00683	San Germán Municipio
RCRAInfo	RCRA	PRD987367604	INTER AMERICAN UNIVERISTY OF PR - SAN GERMAN CAMPUS	RD 102 KM 30.6, SAN GERMAN, PR 00683	San Germán Municipio

# Facility SIC (Standard Industrial Classification) Codes

# Facility NAICS (North American Industry Classification System) Codes

System Identifier SIC Code SIC Description System Identifier NAICS Code NAICS Description

No data records returned

RCRAInfo PRD987367604 611310 Colleges, Universities, and Professional Schools

## **Facility Tribe Information**

Reservation Name Tribe Name EPA Tribal ID Distance to Tribe (miles)

No data records returned

**Enforcement and Compliance** 

## **Compliance Monitoring History**

Last 5 Years

Statute Source ID System Activity Type Compliance Monitoring Type Lead Agency Date Finding (if applicable)

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
RCRA	PRD987367604	No	10/11/2025	0	10/10/2025

### Three-Year Compliance History by Quarter

:	Statute	Program/Pollut Typ	•	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12+
	RCRA	(Source ID: PRD9	87367604)	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
		Facility-Lev	el Status	No Violation Identified											
		Violation	Agency												

## **Informal Enforcement Actions**

Last 5 Years

Statute System Source ID Type of Action Lead Agency Date

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

#### **Formal Enforcement Actions**

Last 5 Years

Statute System Law/ Section ID Action No. Agency Name Date Settlements/ Settlements/ Settlement/Action Date Settlement/ Settle

No data records returned

**Environmental Conditions** 

#### Watersheds

12-Digit WBD (Watershed Boundary Dataset)

Database))

WBD (Watershed Boundary Dataset)

State Water Body Name (ICIS (Integrated Compliance Information System))

State Water Body Name (ICIS (Integrated Compliance Information System))

Beach Closures Within Last Two Years

Pollutants Potentially Related to Impairment Species?

#### **Assessed Waters From Latest State Submission (ATTAINS)**

ate Report Cycle Assessment Unit ID Assessment Unit Name Water Condition Cause Groups Impaired Drinking Water Use Ecological Use Fish Consumption Use Recreation Use Other Use

No data records returned

#### **Air Quality Nonattainment Areas**

Pollutant Within Nonattainment Status Area? Nonattainment Status Applicable Standard(s) Within Maintenance Status Area? Maintenance Status Applicable Standard(s)

No data records returned

**Pollutants** 

#### Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works) Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

#### e-Manifest Hazardous Waste History (Public)

Hazardous Waste Shipped in Kilograms by Year (Through 7/12/2025)

Source ID	Waste Description	2022	2023	2024	2025
PRD987367604	Hazardous Waste	282	408	168	
PRD987367604	Acute Hazardous Waste	0 - 0	0	1	
PRD987367604	Pharmaceutical Hazardous Waste	0	0	0	

<sup>&</sup>quot;Pharmaceutical Hazardous Waste" refers to quantities managed under 40 CFR part 266 subpart P and thus excluded from the Hazardous and Acute Hazardous Waste quantities shown above.

#### Community

## Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic></a>.

High School Diploma

General Statistics (ACS (American Community Survey))	
Total Persons	7,757
Population Density	2,487/sq.mi.
Housing Units in Area	4,030
Percent People of Color	99%
Households in Area	3,068
Households on Public Assistance	130
Persons With Low Income	6,255
Percent With Low Income	82%
Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.080442
Center Longitude	<b>-</b> 67.036833
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%

Age Breakdown (ACS (American Community Survey)) - Pe	ersons (%)
Children 5 years and younger	267 (3%)
Minors 17 years and younger	1,241 (16%)
Adults 18 years and older	6,515 (84%)
Seniors 65 years and older	2,235 (29%)
Race Breakdown (ACS (American Community Survey)) - F	Persons (%)
White	5,218 (67%)
African-American	155 (2%)
Hispanic-Origin	7,643 (99%)
Asian	2 (0%)
Hawaiian/Pacific Islander	23 (0%)
American Indian	0 (0%)
Other/Multiracial	1,571 (20%)
Education Level (Persons 25 & older) (ACS (American Con	nmunity Survey)) - Persons (%)
Less than 9th Grade	599 (10.34%)
9th through 12th Grade	527 (9.1%)

2.125 (36.68%)

Income Breakdown (ACS (American Community Survey)) - Households (%)	
Less than \$15,000	1,402 (45.71%)
\$15,000 - \$25,000	551 (17.97%)
\$25,000 - \$50,000	708 (23.08%)
\$50,000 - \$75,000	241 (7.86%)
Greater than \$75,000	165 (5.38%)

Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%)		
Some College/2-year	470 (8.11%)	
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,548 (26.72%)	



## **Detailed Facility Report**

**Facility Summary** 

**KMART #3896** 

AVE CASTO PEREZ INT CARR 2, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110004893848

**EPA Region:** 02 **Latitude:** 18.079932 **Longitude:** -67.03508

**Locational Data Source:** RCRAINFO **Industries:** General Merchandise Stores

Indian Country: N

### **Enforcement and Compliance Summary**

Statute	RCRA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	-
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

## **Regulatory Information**

Clean Air Act (CAA): No Information
Clean Water Act (CWA): No Information

Resource Conservation and Recovery Act (RCRA): Active VSQG, (PRR000008383)

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

## **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Facility/System Characteristics

## **Facility/System Characteristics**

System	Statute	Identifier	Universe	Status	Areas Permit Expiration Date		Indian Country	Latitude	Longitude
FRS		110004893848					N	18.079932	<b>-</b> 67.03508
RCRAInfo	RCRA	PRR000008383	vsQG	Active (H )			N	18.079932	-67.03508

### **Facility Address**

System	Statute Identifier Facility Name		Facility Name	Facility Address	Facility County		
FRS		110004893848	KMART #3896	AVE CASTO PEREZ INT CARR 2, SAN GERMAN, PR 00683	San Germán Municipio		
RCRAInfo	RCRA	PRR000008383	KMART #3896	AVE CASTO PEREZ INT CARR 2, SAN GERMAN, PR 00683	San Germán Municipio		

## Facility SIC (Standard Industrial Classification) Codes

# Facility NAICS (North American Industry Classification System) Codes

-,-----

 System
 Identifier
 NAICS Code
 NAICS Description

 RCRAInfo
 PRR000008383
 45299
 All Other General Merchandise Stores

No data records returned

### **Facility Tribe Information**

Reservation Name Tribe Name EPA Tribal ID Distance to Tribe (miles)

No data records returned

**Enforcement and Compliance** 

## **Compliance Monitoring History**

Last 5 Years

Statute Source ID System Activity Type Compliance Monitoring Type Lead Agency Date Finding (if applicable)

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/

### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
RCRA	PRR000008383	No	10/11/2025	0	10/10/2025

### Three-Year Compliance History by Quarter

Statute	Program/Pollut Typ		QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12+
RCRA (Source ID		00008383)	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
Facility-Level Status		el Status	No Violation Identified											
	Violation	Agency												

## **Informal Enforcement Actions**

Statute System Source ID Type of Action Lead Agency Date

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

## **Formal Enforcement Actions**

Last 5 Years

Last 5 Years

Statute System

Law/ Source Section ID Source Issued/Filed Settlements/ Source Issued/Filed Settlements/ Settlements/ Date Source Issued/Filed Settlements/ Date Settlement/Action ID Settlement/ Actions Date Settlement/ Assessed Collected Value Cost

No data records returned

**Environmental Conditions** 

#### Watersheds

12-Digit WBD (Watershed Boundary WBD (Watershed Boundary Dataset) State Water Body Name (ICIS **Beach Closures** Beach Closures Watershed with ESA (Endangered Pollutants Potentially Dataset) HUC (RAD (Reach Address Subwatershed Name (RAD (Reach Address (Integrated Compliance Information Within Last Two Within Last Year Related to Impairment Species Act)-listed Aquatic Species? Database)) System))

No data records returned

## **Assessed Waters From Latest State Submission (ATTAINS)**

State Report Cycle Assessment Unit ID Assessment Unit Name Water Condition Cause Groups Impaired Drinking Water Use Ecological Use Fish Consumption Use Recreation Use Other Use

#### **Air Quality Nonattainment Areas**

TRI Facility ID Year Air Emissions Surface Water Discharges

Within Nonattainment Status Area? Nonattainment Status Applicable Standard(s) Within Maintenance Status Area? Maintenance Status Applicable Standard(s)

No data records returned

#### **Pollutants**

### Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

Underground Injections Disposal to Land Total On-Site Releases

Age Breakdown (ACS (American Community Survey)) - Persons (%)

Children 5 years and younger

270 (3%)

No data records returned

#### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Off-Site Transfers to POTWs (Publicly Owned Treatment Works)

Chemical Name

No data records returned

#### Community

### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in dictionary#demographic>.

General Statistics (ACS (American Community Survey))	
Total Persons	7,877
Population Density	2,525/sq.mi.
Housing Units in Area	4,005
Percent People of Color	99%
Households in Area	3,092
Households on Public Assistance	129
Persons With Low Income	6,398
Percent With Low Income	82%
Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.079932
Center Longitude	-67.03508
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%
Income Breakdown (ACS (American Community Survey))	- Households (%)
Less than \$15,000	1,404 (45.42%)
\$15,000 - \$25,000	557 (18.02%)
\$25,000 - \$50,000	728 (23.55%)
\$50,000 - \$75,000	246 (7.96%)
Greater than \$75,000	156 (5.05%)

Minors 17 years and younger	1,274 (16%)				
Adults 18 years and older	6,604 (84%)				
Seniors 65 years and older	2,241 (28%)				
Race Breakdown (ACS (American Community Survey)) - Persons (%)					
White	5,284 (67%)				
African-American	173 (2%)				
Hispanic-Origin	7,756 (98%)				
Asian	2 (0%)				
Hawaiian/Pacific Islander	26 (0%)				
American Indian	0 (0%)				
Other/Multiracial	1,596 (20%)				
Education Level (Persons 25 & older) (ACS (American Community Surv	rey)) - Persons (%)				
Less than 9th Grade	617 (10.5%)				
9th through 12th Grade	529 (9%)				
High School Diploma	2,213 (37.65%)				
Some College/2-year	486 (8.27%)				
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,518 (25.83%)				



## **Detailed Facility Report**

**Facility Summary** 

AC-010118 PAV REH SAFETY IMPROV PR 101 KM 0.0 @ 10.0 SAN GERMAN

CARRETERA PR-101 KM 0.0 TO KM 10.0, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110071709513

EPA Region: 02 Latitude: 18.0756 Longitude: -67.0415

Locational Data Source: NPDES

Industries: --Indian Country: N

### **Enforcement and Compliance Summary**

Statute	CWA			
Compliance Monitoring Activities (5 years)	-			
Date of Last Compliance Monitoring Activity	-			
Compliance Status	No Violation Identified			
Qtrs in Noncompliance (of 12)	0			
Qtrs with Significant Violation	0			
Informal Enforcement Actions (5 years)	-			
Formal Enforcement Actions (5 years)	-			
Penalties from Formal Enforcement Actions (5 years)	-			
EPA Cases (5 years)	-			
Penalties from EPA Cases (5 years)	-			

### **Regulatory Information**

Clean Air Act (CAA): No Information

Clean Water Act (CWA): Non-Major, Permit Effective (PRR1000JA)

Resource Conservation and Recovery Act (RCRA): No Information

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

### **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

**Greenhouse Gas Emissions (eGGRT):** No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

#### Facility/System Characteristics

## **Facility/System Characteristics**

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110071709513					N	18.0756	-67.0415
ICIS-NPDES	CWA	PRR1000JA	Non-Major: General Permit Covered Facility	Effective	Construction Stormwater	02/16/2027	N	18.0756	-67.0415

### **Facility Address**

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110071709513	AC-010118 PAV REH SAFETY IMPROV PR 101 KM 0.0 @ 10.0 SAN GERMAN	CARRETERA PR-101 KM 0.0 TO KM 10.0, SAN GERMAN, PR 00683	
ICIS-NPDES	CWA	PRR1000JA	AC-010118 PAV REH SAFETY IMPROV PR 101 KM 0.0 @ 10.0 SAN GERMAN	CARRETERA PR-101 KM 0.0 TO KM 10.0, SAN GERMAN, PR 00683	

## **Facility SIC (Standard Industrial Classification)**

#### **Facility NAICS (North American Industry Classification System) Codes**

SIC Description NAICS Description

No data records returned

No data records returned

### **Facility Industrial Effluent Guidelines**

#### **Facility Tribe Information**

Effluent Guideline (40 CFR Part) Effluent Guideline Description Reservation Name EPA Tribal ID Distance to Tribe (miles) No data records returned No data records returned

**Enforcement and Compliance** 

## **Compliance Monitoring History**

Finding (if applicable) **Compliance Monitoring Type** 

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/compliance-monitoring-to-monitoringprograms> activities or because they are not counted as inspections within EPA's Annual Results <a href="https://www.epa.gov/enforcement/enforcement-data-and-results">https://www.epa.gov/enforcement/enforcement-data-and-results</a>.

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
CWA	PRR1000JA	No	06/30/2025	0	10/10/2025

### Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12	QTR 13+
cw/	A (Source ID: PRR1000JA)	07/01-09/30/22	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-10/10/25
	Facility-Level Status	No Violation Identified	Undetermined											
	Quarterly Noncompliance Report History													

#### **Informal Enforcement Actions**

Last 5 Years

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

#### **Formal Enforcement Actions**

Last 5 Years

Issued/ Filed **Federal Penalty** State/ Local Penalty Lead Case Settlements/ Settlement/ Action **Penalty Amount** SEP Comp Action Statute System

No data records returned

#### **Environmental Conditions**

#### Watersheds

12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database))	WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database))	State Water Body Name (ICIS (Integrated Compliance Information System))	Beach Closures Within Last Year	Beach Closures Within Last Two Years	Pollutants Potentially Related to Impairment	Watershed with ESA (Endangered Species Act)-listed Aquatic Species?
210100030409	Rio Guanajibo at mouth	RIVER	No	No		No

### **Assessed Waters From Latest State Submission (ATTAINS)**

:	State	Report Cycle	Assessment Unit ID	Assessment Unit Name	Water Condition	Cause Groups Impaired	Drinking Water Use	Ecological Use	Fish Consumption Use	Recreation Use	Other Use
	PR	2024	PRWR77A	RIO GUANAJIBO	Impaired - 303(d) Listed - With Restoration Plan	METALS (OTHER THAN MERCURY)   NUTRIENTS   ORGANIC ENRICHMENT/OXYGEN DEPLETION   PATHOGENS   TOXIC INORGANICS   TURBIDITY	Not Supporting	Not Supporting		Not Supporting	

### **Air Quality Nonattainment Areas**

Pollutant	Within Nonattainment Status Area?	Nonattainment Status Applicable Standard(s)	Within Maintenance Status Area?	Maintenance Status Applicable Standard(s)					
No date was and water was a									

## Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

Underground Injections Dispos

Disposal to Land Total On-Site Releases

----

No data records returned

### Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Off-Site Transfers to POTWs (Publicly Owned Treatment Works)

Chemical Name

No data records returned

## CWA (Clean Water Act) Discharge Monitoring Report (DMR) Pollutant Loadings

DMR and TRI Multi-Year Loading Report

NPDES ID Description

No data records returned

#### Community

### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic></a>.

General Statistics (ACS (American Community Survey))	
Total Persons	6,637
Population Density	2,127/sq.mi.
Housing Units in Area	3,773
Percent People of Color	99%
Households in Area	2,736
Households on Public Assistance	124
Persons With Low Income	5,283
Percent With Low Income	81%
Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.0756
Center Longitude	-67.0415
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%
Income Breakdown (ACS (American Community Survey	r)) - Households (%)
Less than \$15,000	1,310 (47.85%)
\$15,000 - \$25,000	488 (17.82%)
\$25,000 - \$50,000	587 (21.44%)
\$50,000 - \$75,000	190 (6.94%)
Greater than \$75,000	163 (5.95%)

Age Breakdown (ACS (American Community Survey)) - Persons (%)  Children 5 years and younger	241 (4%)
, , ,	, ,
Minors 17 years and younger	930 (14%)
Adults 18 years and older	5,706 (86%)
Seniors 65 years and older	2,069 (31%)
Race Breakdown (ACS (American Community Survey)) - Persons (%)	
White	4,433 (67%)
African-American	83 (1%)
Hispanic-Origin	6,540 (99%)
Asian	2 (0%)
Hawaiian/Pacific Islander	15 (0%)
American Indian	0 (0%)
Other/Multiracial	1,453 (22%)
Education Level (Persons 25 & older) (ACS (American Community Surv	ey)) - Persons (%)
Less than 9th Grade	562 (11.07%)
9th through 12th Grade	478 (9.42%)
High School Diploma	1,774 (34.94%)
Some College/2-year	380 (7.48%)
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,417 (27.91%)



## **Detailed Facility Report**

**Facility Summary** 

PAVEMENT REHABILITATION AND SAFETY IMPROVEMENTS, PR-101, FROM KM 0.0 TO KM 10.0

CARRETERA PR-101 KM 0.0 TO KM 10.0, SAN GERMAN, PR 00683

FRS (Facility Registry Service) ID: 110071662085

EPA Region: 02 Latitude: 18.0756 Longitude: -67.0415

Locational Data Source: NPDES

Industries: --Indian Country: N

### **Enforcement and Compliance Summary**

Statute	CWA
Compliance Monitoring Activities (5 years)	-
Date of Last Compliance Monitoring Activity	-
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

### **Regulatory Information**

Clean Air Act (CAA): No Information

Clean Water Act (CWA): Non-Major, Permit Effective (PRR1000IW)

Resource Conservation and Recovery Act (RCRA): No Information

Safe Drinking Water Act (SDWA): No Information

Go To Enforcement/Compliance Details

Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

### **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

#### Facility/System Characteristics

## **Facility/System Characteristics**

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110071662085					N	18.0756	-67.0415
ICIS-NPDES	CWA	PRR1000 <b>I</b> W	Non-Major: General Permit Covered Facility	Effective	Construction Stormwater	02/16/2027	N	18.0756	-67.0415

## **Facility Address**

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110071662085	PAVEMENT REHABILITATION AND SAFETY IMPROVEMENTS, PR-101, FROM KM 0.0 TO KM 10.0	CARRETERA PR-101 KM 0.0 TO KM 10.0, SAN GERMAN, PR 00683	
ICIS-NPDES	CWA	PRR1000IW	PAVEMENT REHABILITATION AND SAFETY IMPROVEMENTS, PR-101, FROM KM 0.0 TO KM 10.0	CARRETERA PR-101 KM 0.0 TO KM 10.0, SAN GERMAN, PR 00683	

## Facility SIC (Standard Industrial Classification) Codes

## Facility NAICS (North American Industry Classification System) Codes

Finding (if applicable)

System Identifier SIC Code SIC Description System Identifier NAICS Code NAICS Description

No data records returned

For illest Today Code SIC Description System Identifier NAICS Code NAICS Description

## **Facility Industrial Effluent Guidelines**

#### **Facility Tribe Information**

Identifier Effluent Guideline (40 CFR Part) Effluent Guideline Description Reservation Name Tribe Name EPA Tribal ID Distance to Tribe (miles)

No data records returned

Enforcement and Compliance

Compliance Monitoring History

Last 5 Years

Compliance Monitoring Type

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/

#### **Compliance Summary Data**

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
CWA	PRR1000 <b>I</b> W	No	06/30/2025	0	10/10/2025

### Three-Year Compliance History by Quarter

Stat	ute Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12	QTR 13+
	CWA (Source ID: PRR1000IW)	07/01-09/30/22	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-10/10/25
	Facility-Level Status	No Violation Identified	Undetermined											
	Quarterly Noncompliance Report History													

## Informal Enforcement Actions | Land

Last 5 Years

Statute System Source ID Type of Action Lead Agency Date

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

#### **Formal Enforcement Actions**

Last 5 Years

Statute System Law/ Section ID Action No. Agency Name Date Settlements/ Settlements/ Date Actions Date Settlements/ Settle

No data records returned

#### Watersheds

12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database))	WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database))	State Water Body Name (ICIS (Integrated Compliance Information System))	Beach Closures Within Last Year	Beach Closures Within Last Two Years	Pollutants Potentially Related to Impairment	Watershed with ESA (Endangered Species Act)- listed Aquatic Species?
210100030409	Rio Guanajibo at mouth	EL CHORRO RIVER (TRIBUTARY OF GUANAJIBO RIVER), MARESUA RIVER (TRIBUTARY OF GUANAJIBO RIVER), MARGARA RIVER (TRIBUTARY OF GUANAJIBO RIVER), PLANTINA RIVER (TRIBUTARY OF GUANAJIBO RIVER), PRINCIPAL WATER IRRIGATION	No	No	-	No

#### Assessed Waters From Latest State Submission (ATTAINS)

State	Report Cycle	Assessment Unit ID	Assessment Unit Name	Water Condition	Cause Groups Impaired	Drinking Water Use	Ecological Use	Fish Consumption Use	Recreation Use	Other Use
PR	2024	PRWR77A	RIO GUANAJIBO	Impaired - 303(d) Listed - With Restoration Plan	METALS (OTHER THAN MERCURY)   NUTRIENTS   ORGANIC ENRICHMENT/OXYGEN DEPLETION   PATHOGENS   TOXIC INORGANICS   TURBIDITY	Not Supporting	Not Supporting		Not Supporting	

### **Air Quality Nonattainment Areas**

Pollutant	Within Nonattainment Status Area?	Nonattainment Status Applicable Standard(s)	Within Maintenance Status Area?	Maintenance Status Applicable Standard(s)

No data records returned

**Pollutants** 

## Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

RI Facility ID Year Air Emissions Surface Water Discharges Off-Site Transfers to POTWs (Publicly Owned Treatment Works) Underground Injections Disposal to Land Total On-Site Releases Total Off-Site Transfers

No data records returned

## Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

## CWA (Clean Water Act) Discharge Monitoring Report (DMR) Pollutant Loadings

DMR and TRI Multi-Year Loading Report

1,774 (34.94%)

380 (7.48%)

NPDES ID

No data records returned

Community

### Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographic">https://epa.gov/help/reports/dfr-data-dictionary#demographic></a>.

High School Diploma

Some College/2-year

General Statistics (ACS (American Community Survey))	
Total Persons	6,637
Population Density	2,127/sq.mi.
Housing Units in Area	3,773
Percent People of Color	99%
Households in Area	2,736
Households on Public Assistance	124
Persons With Low Income	5,283
Percent With Low Income	81%
• · · · · · ·	
Geography	
Radius of Selected Area	1 mi.
Center Latitude	18.0756
Center Longitude	-67.0415
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%
Income Breakdown (ACS (American Community Survey)) - Hou	seholds (%)
Less than \$15,000	1,310 (47.85%)
\$15,000 - \$25,000	488 (17.82%)


Age Breakdown (ACS (American Community Survey)) - Per	sons (%)		
Children 5 years and younger	241 (4%)		
Minors 17 years and younger	930 (14%)		
Adults 18 years and older 5,706 (86%)			
Seniors 65 years and older 2,069 (31%)			
Race Breakdown (ACS (American Community Survey)) - Pe	ersons (%)		
White	4,433 (67%)		
African-American	83 (1%)		
Hispanic-Origin	6,540 (99%)		
Asian	2 (0%)		
Hawaiian/Pacific Islander	15 (0%)		
American Indian	0 (0%)		
Other/Multiracial	1,453 (22%)		
Education Level (Persons 25 & older) (ACS (American Com	munity Survey)) - Persons (%)		
Less than 9th Grade	562 (11.07%)		
9th through 12th Grade	478 (9.42%)		

Income Breakdown (ACS (American Community Survey)) - Households (%)				
\$25,000 - \$50,000	587 (21.44%)			
\$50,000 - \$75,000	190 (6.94%)			
Greater than \$75,000	163 (5.95%)			

Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%)	
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	1,417 (27.91%)


Exhibit 7S
PR-CRP-000876 Plaza Santo Domingo and Plaza Francisco Mariano
San Germán PR 00683

Coordinates 18.0819, -67.0420 / 18.0822, -67.0431



## PR-CRP-000876 PLAZA SANTO DOMINGO and PLAZA MARIANO QUIÑONES **Exhibit 8 CRITICAL HABITAT Map**

Coordinates 18.0819, -67.0420 / 18.0822, -67.0431



Maxar | Esri Community Maps Contributors, Esri, TomTom, Garmin, Foursquare, SafeGraph, GeoTechnologies, Inc, METI/NASA, USGS, NPS, US Census
Bureau, USFWS



## Asbestos Containing Building Materials Inspection Report

## Project:

Francisco Mariano Quiñones Square, Santo Domingo Park and streets surrounding both sites in San Germán, Puerto Rico

Client: JORGE RIGAU ARQUITECTOS PSC

**ZEM-23062** April 2023

Prepared By:

Zimmetry Environmental Management, Corp. www.zimmetry.com info@zimmetry.com ZIMMETRY ENVIRONMENTAL MANAGEMENT CORP. Asbestos Containing Materials Inspection 2 Public Sites (Mariano Quiñones Square & Santo Domingo Park) San Germán, Puerto Rico, Project No. ZEM-23062

### TABLE OF CONTENT

SECTION	1: Executive Summary	1
1.1	Introduction	1
1.2	Summary of Property Evaluation	1
SECTION	2: Asbestos Containing Building Materials Inspection Report	2
2.1	Overview of the Evaluation	2
2.2	Conditions and Limitations	2
2.3	Environmental Assessment Report Certification	3
SECTION	3: Appendices	4
App	endix A: Certifications, Licenses, and Accreditations	5
App	endix B: Certification of No Presence of Asbestos (Form PGC-009)	6

### **SECTION 1: EXECUTIVE SUMMARY**

#### 1.1 INTRODUCTION

An Asbestos Containing Building Materials (ACBM) inspection was conducted on March 18, 2023 at Francisco Mariano Quiñones Square, Santo Domingo Park and streets surrounding both sites in San Germán, Puerto Rico. The asbestos containing building materials sampling was performed to identify material that contains asbestos fibers above allowable levels and to assist with the compliance of local, state and federal regulations.

#### 1.2 SUMMARY OF PROPERTY EVALUATION

The project consisted in the evaluation of the areas of the aforementioned project. The evaluation found that **no** asbestos containing materials were identified during the inspection of the areas.

### SECTION 2: ASBESTOS CONTAINING MATERIALS SURVEY REPORT

#### 2.1 OVERVIEW OF THE EVALUATION

This asbestos containing materials (ACM) survey is an inspection to identify the location of any ACM that exist within. Throughout the inspection no asbestos containing materials were identified at the assessed areas.

The inspection was conducted by the Department of Natural and Environmental Resources (DRNA) of Puerto Rico and United States Environmental Protection Agency (USEPA) accredited Inspectors qualified by experience, education and training in the recognition of potential ACM and approved bulk sampling techniques. Some areas may not have been directly accessible due to the physical hazards encountered within. In these areas, assumptions based on findings in other areas were made whenever possible. These assumptions are duly noted as such in this report.

The inspection was performed in accordance with Environmental Protection Agency recommended procedures found in EPA-450/2-78-014 (Parts I and II), EPA 560/5-85-024, and 40 CFR 763. These procedures call for the visual inspection of the building for suspect friable material and collection and analysis of representative samples of suspect material.

#### 2.2 CONDITIONS AND LIMITATIONS—DISCLAIMER

Zimmetry Environmental Management Corp. has performed this asbestos containing building materials inspection in a thorough and professional manner consistent with commonly accepted industry standards. The Preparer cannot guarantee and does not warrant that this evaluation has identified all adverse environmental factors and/or conditions affecting this property on the date of the evaluation.

The results reported and conclusions reached by the Preparer are solely for the benefit of the Owner and occupants. The results and opinions in this report, based solely on the conditions found at the property on the date of the evaluation, are valid only on that date. The Preparer assumes no obligation to advise the client of any changes in any real or potential asbestos hazards at this structure beyond the date of the property evaluation.

The Asbestos Containing Building Materials inspection was performed to ready accessible components and surfaces. If suspected components that could contain asbestos are encountered, they shall be managed as containing asbestos until the appropriate laboratory analysis is performed.

ZIMMETRY ENVIRONMENTAL MANAGEMENT CORP.
Asbestos Containing Materials Inspection
2 Public Sites (Mariano Quiñones Square & Santo Domingo Park)
San Germán, Puerto Rico,
Project No. ZEM-23062

#### 2.3 ENVIRONMENTAL ASSESSMENT REPORT CERTIFICATION

Zimmetry Environmental Management Corp. has performed this asbestos containing building materials inspection in a thorough and professional manner consistent with commonly accepted industry standards. The inspection was conducted on March 18, 2023 by Harry Peña, state-certified inspector ASB-0223-0093-SI, qualified by experience, education and training in the recognition of asbestos containing materials and approved sampling techniques.

Harry Peña, MSEM

**Environmental Building Consultant** 

ZIMMETRY ENVIRONMENTAL MANAGEMENT CORP. Asbestos Containing Materials Inspection 2 Public Sites (Mariano Quiñones Square & Santo Domingo Park) San Germán, Puerto Rico, Project No. ZEM-23062

## **SECTION 3: APPENDICES**

Appendix A: Certifications, Licenses, and Accreditations

**Appendix B: Certification of No Presence of Asbestos (Form PGC-009)** 

## APPENDIX A: CERTIFICATIONS, LICENSES, AND ACCREDITATIONS



ZIMMETRY ENVIRONMENTAL MANAGEMENT CORP. Asbestos Containing Materials Inspection 2 Public Sites (Mariano Quiñones Square & Santo Domingo Park) San Germán, Puerto Rico, Project No. ZEM-23062

# APPENDIX B: CERTIFICATION OF NO PRESENCE OF ASBESTOS (FORM PGC-009)



#### GOBIERNO DE PUERTO RICO OFICINA DEL GOBERNADOR JUNTA DE CALIDAD AMBIENTAL



PGC-

Área de Calidad de Agua

Forma PGC-009

# CERTIFICACION DE NO PRESENCIA DE ASBESTO EN ESTRUCTURAS A DEMOLERSE

(Deberá completarse en letra de molde o impresa)

	PARA USO OFICIAL	
Yo, <u>Harry Peña</u> , mayor de edad, <u>casado</u> (Nombre) (Estado Civil)		
Dirección Postal PO Box 3545 Bayamón 00958 (Pueblo) (Zip Code)		_
Teléfonos: Residencial ( <u>787</u> ) <u>550</u> - <u>2061</u> Oficina ( <u>787</u> ) <u>550</u> - <u>0005</u>	<u>995</u> - <u>0005</u> Ext	
Certifico que:		
<ol> <li>La estructura localizada en Francisco Mariano Quiñones Square, Santo Domingo both sites in San Germán, Puerto Rico demolición se encuentra libre de asbesto.</li> <li>La información antes indicada es cierta y correcta.</li> <li>Afirmo y reconozco las consecuencias de incluir y someter informac</li> </ol>		na
4. Para que así conste, firmo la presente certificación enhoy día _14_ deabril de2023	Bayamón de Puerto Rico, (Municipio)	
Firma V Sello del Profesion Firma del Inspector de Asbesto registrado		

Nota: Ingenieros o Arquitectos deberán someter evidencia de que se encuentra al día en el pago de sus cuotas de colegiación e Inspectores de Asbesto deberán someter evidencia de la tarjeta de registro provista por la JCA.

Dirección Física: Ave. Ponce de León 1308, Carr. Estatal 8838, Sector el Cinco, Río Piedras, PR 00926

Dirección Postal: Apartado 11488, Santurce, PR 00910-1488

Tel. (787) 767-8181 • Fax (787) 767-1962



## **CERTIFICATION**





## Lead Based Paint Inspection Report

## Project:

Francisco Mariano Quiñones Square, Santo Domingo Park and streets surrounding both sites in San Germán, Puerto Rico

Client: JORGE RIGAU ARQUITECTOS PSC

**ZEM-23062** April 2023

Prepared By:

Zimmetry Environmental Management, Corp. www.zimmetry.com info@zimmetry.com

#### TABLE OF CONTENT

SECTION	N 1: EXECUTIVE SUMMARY	1
1.1	Introduction	1
1.2	Summary of Property Evaluation	1
1.3	Property Locations of Building Components with Lead Based Paint	1
Tab	ole 1-1 Summary of Building Components with Lead Based Paint	2
<b>G</b>	A V B B I B B	
	N 2: LEAD-BASED PAINT INSPECTION REPORT	
2.1	Overview of the Evaluation	
2.2	Sampling Procedure	3
2.3	Results Presentation	4
	2.3.1 Specific Findings	4
	2.3.2 Homogeneous Areas with Special Considerations	4
	2.3.3 Inaccessible Areas Presumed to be Lead-Based Painted	4
2.4	Lead Regulatory Levels	5
2.5	Conditions and Limitations	5
2.6	Abatement Conditions	5
2.7	Recommendations	6
2.8	Environmental Assessment Report Certification	6
SECTION	N 3: APPENDICES	7
App	pendix A: Certifications, Licenses, and Accreditations	8
App	pendix B: XRF Sampling Data	10
	pendix C: XRF's Performance Characteristics Sheet	
App	pendix D: Photographic Record	18
App	pendix E: Location of Positive Materials	29

### **SECTION 1: EXECUTIVE SUMMARY**

#### 1.1 INTRODUCTION

A Lead-Based Paint inspection was conducted on March 18, 2023 at Francisco Mariano Quiñones Square, Santo Domingo Park and streets surrounding both sites in San Germán, Puerto Rico. The lead-based paint inspection was performed to identify paint that contains lead above allowable levels and to assist with the compliance of local, state and federal regulations.

#### 1.2 SUMMARY OF PROPERTY EVALUATION

The project consisted of the evaluation of the areas of the aforementioned project. The evaluation found that lead based paint was present in selective components and surfaces through the project on the date of the inspection. Table 1-1 identifies the components positive for lead. Table 2-1 identifies lead-based paint as defined by the U.S. Environmental Protection Agency (EPA) and the Department of Natural and Environmental Resources (DRNA) of Puerto Rico. For specific locations and additional detail on the location of lead-reference Sections 2 and 3.

## 1.3 PROPERTY LOCATIONS OF BUILDING COMPONENTS WITH LEAD-BASED PAINT

Table 1-1 summarizes the site components and surfaces coated with lead-based paint. Details that identify positive lead-based paint findings within specific areas and on surfaces were provided in the lead-based paint inspection report. The "substrate" is the building component material directly beneath the painted surface. Photographic documentation is for reference purposes and doesn't necessarily include all the surfaces with lead-based paint and/or components containing lead. The quantification of positives materials presented in this table is only an estimate. If an abatement of the materials will be conducted, the Contractors shall estimate the amount of materials to be abated.

If homogeneous materials that were not accounted for are identified in areas that are not describe in this report or inaccessible areas described in Section 2.3.3, they shall be managed as containing lead. If suspected components that could contain lead are encountered underneath current installed tiles or other construction material, they shall be managed as containing lead until the appropriate test is performed. Refer to Appendix E: Location of Positive Materials for specific location.

Table 1-1: Summary of Components Containing Lead									
Location	Area	Component	Color	Substrate	Approximate Amount				
Santo Domingo Park	Streets Surroundings the Sites	Curb	Yellow, Blue	Concrete	230 LnFt				
Santo Donningo Fark	Santo Domingo Park	o Park Curb Yellow Concrete  Handrail Brown Metal	140 LnFt						
	Mariana Oviãonas Savara	Handrail	Brown	Metal	4 Units				
Mariano Quiñones Square	Mariano Quiñones Square	Curb	Yellow	Concrete	60 LnFt				
Mariano Quinones Square	Gazebo Exterior Areas	Column	Brown	Metal	6 Units				
	Streets Surroundings the Sites	Curb	Yellow, Brown	Concrete	300 LnFt				
In Between Both Sites		Sign Pole	Yellow	Metal	1 Unit				
		Hydrant	Yellow	Metal	1 Unit				
	Stop Sign	Yellow	Metal	1 Unit					

#### Note:

<sup>1.</sup> The quantification of positives materials presented in this table is only an estimate. If an abatement of the materials will be conducted, the Contractors shall estimate the amount of materials to be abated.

### **SECTION 2: LEAD-BASED PAINT INSPECTION REPORT**

#### 2.1 OVERVIEW OF THE EVALUATION

This lead-based paint inspection is an investigation to identify all lead-based paint on a surface-by-surface basis. A lead-based paint inspection conforming to HUD guidelines was performed at the aforementioned project.

Averages of 156 samples were taken at identified surfaces of the evaluated areas using X-ray fluorescence (XRF) analyzer. The evaluation found that lead-based paint was present in selective components and surfaces through the project on the date of the assessment (See Table 1-1).

Some of the remaining XRF test locations exhibited lead-in-paint levels below the level that EPA identifies as lead-based paint, namely 1.0 mg/cm<sup>2</sup>. Such surfaces could create dust-lead or soil-lead hazards if the paint is turned into dust by abrasion, scraping, or sanding. Should these or any lead containing components or surfaces be disturbed in any manner that generates dust, care should be taken to limit its spread.

Testing was performed by Dilia Rosado, state-certified risk assessor LBPRA-20322-195, using the Niton XLp-300A XRF, SN-101222. The credentials are provided in Section 3, Appendix A: Certifications, Licenses, and Accreditations. The XRF analyzer is designed to measure the lead content of surface coatings on a variety of building surfaces, substrates, and components. The measurement is rapid and nondestructive and, according to the manufacturer, is capable of detecting lead concentrations that occur within numerous layers of various surface coatings.

Please refer to the XRF Testing Results Section 3, Appendix B: XRF Sampling Data for the detailed analytical testing results for each distinct area inspected. The reports provide a complete testing data.

#### 2.2 SAMPLING PROCEDURE

The Lead Based Paint Sampling Procedure was design to evaluate and document all the data obtained form the inspection in a sequential method that provided confidence at the moment of the results presentation.

The survey was performed following the methodology established in the HUD Guidelines for the Evaluation and Control of Lead Based Paint in Housing (2012 revision) and the Department of Natural and Environmental Resources (DRNA) of Puerto Rico Regulation 9098: Regulation for Proper Management of Lead-Based Paint Activities. The surfaces evaluation was performed as follows:

• If the lead concentration measured by the XRF Spectrum Analyzer is less than 1.0 mg/cm<sup>2</sup> it is considered negative.

ZIMMETRY ENVIRONMENTAL MANAGEMENT CORP. Lead Based Paint Inspection 2 Public Sites (Mariano Quiñones Square & Santo Domingo Park) San Germán, Puerto Rico, Project No. ZEM-23062

• If the lead concentration measured by the XRF Spectrum Analyzer is equal or greater than 1.0 mg/cm<sup>2</sup> it is considered positive.

To each functional space of the project a name was assigned according to the use of that space. If no name could be assigned then a code letter or number was assigned.

Each wall surface was named with letters beginning with wall A the wall facing the main entrance direction. The wall at your left will be wall B, the wall at front wall C and the wall at you right will be wall D.

#### 2.3 RESULTS PRESENTATION

This section describes the project components and surfaces coated with lead-based paint (LBP), which were observed in the inspection. Please note that the recommendations given are always the minimum action, which in our professional judgment should be taken.

According to the DRNA lead regulations, prior to the demolishing of a structure containing lead-based paint, the contaminated surfaces or substrates must be abated or removed. The firm providing the abatement services must be certified as an abatement firm by the DRNA.

#### 2.3.1 SPECIFIC FINDINGS

The following LBP were found to contain more than 1.0 mg/cm<sup>2</sup> for what Department of Natural and Environmental Resources (DRNA) of Puerto Rico identifies as lead-based paint or materials containing lead:

Columns

Hydrants

Curb

• Sign Poles

Handrails

#### 2.3.2 HOMOGENEOUS AREAS WITH SPECIAL CONSIDERATIONS

**NONE** 

#### 2.3.3 INACCESSIBLE AREAS PRESUMED TO BE LEAD-BASED PAINTED

**NONE** 

#### 2.4 LEAD REGULATORY LEVELS

The lead regulatory levels provided below are those used when preparing this lead-based paint evaluation or when evaluating data collected. The EPA regulatory levels are the same as the state regulatory levels provided in the following table.

TABLE 2-1: LEAD REGULATORY LEVELS					
EPA/DRNA Levels					
Lead-Based Paint	1.0 mg/cm <sup>2</sup> or 0.5% by weight (or 5,000 ppm)				

#### 2.5 CONDITIONS AND LIMITATIONS—DISCLAIMER

Zimmetry Environmental Management Corp. has performed this lead-based paint inspection in a thorough and professional manner consistent with commonly accepted industry standards. The Preparer cannot guarantee and does not warrant that this evaluation has identified all adverse environmental factors and/or conditions affecting this project on the date of the evaluation.

The results reported and conclusions reached by the Preparer are solely for the benefit of the Owner. The results and opinions in this report, based solely on the conditions found at the project on the date of the evaluation, are valid only on that date. The Preparer assumes no obligation to advise the client of any changes in any real or potential lead-based paint hazards at this project beyond the date of the evaluation.

The lead inspection was performed to ready accessible components and surfaces. If suspected components that could contain lead are encountered underneath current installed tiles or other construction material, they shall be managed as containing lead until the appropriate test is performed. According to the DRNA on the "Regulation for the Proper Management of Lead-Based Paint Activities" Rule 139 (Section E, Part 17) all lead-based paint reports have a validity period of five (5) years.

#### 2.6 ABATEMENT CONDITIONS

Abatement, as defined by HUD and the Department of Natural and Environmental Resources (DRNA) of Puerto Rico, means any set of measures designed to eliminate lead-based paint and/or lead-based paint hazards permanently. The people providing these services must to be trained in accordance with the DRNA licensing/certification requirements. The product manufacturer and/or contractor must warrant abatement methods to last a minimum of 20 years, or these methods must have a design life of at least 20 years.

- onsite or offsite removal of lead-based paint from substrates and components
- replacement of components or fixtures painted with lead-based paint

ZIMMETRY ENVIRONMENTAL MANAGEMENT CORP. Lead Based Paint Inspection 2 Public Sites (Mariano Quiñones Square & Santo Domingo Park) San Germán, Puerto Rico, Project No. ZEM-23062

- permanent enclosure of lead-based paint with construction materials mechanicallyfastened to the substrate
- encapsulation of lead-based paint with specially designed encapsulant products
- removal or permanent covering (concrete or asphalt) of soil-lead-based paint hazards

If enclosure or encapsulation is conducted as an abatement method, the lead-based paint remains on the property, so ongoing lead-based paint maintenance is required.

#### 2.7 RECOMMENDATIONS

According to the DRNA lead regulations, prior to the demolishing of a structure containing lead-based paint, the contaminated surfaces or substrates must be abated or removed. The waste generated has to be characterized to determine if the waste generated is hazardous or non-hazardous waste. The firm providing the abatement services must be certified as an abatement firm by the DRNA. Workers conducting abatement must be trained and certified as abatement workers by a training provider accredited by the DRNA.

#### 2.8 ENVIRONMENTAL ASSESSMENT REPORT CERTIFICATION

Zimmetry Environmental Management Corp. has performed this lead-based paint inspection in a thorough and professional manner consistent with commonly accepted industry standards. The inspection was conducted on March 18, 2023 by Dilia Rosado, state-certified risk assessor LBPRA-20322-195, qualified by experience, education and training in the recognition of lead-based paint and approved sampling techniques using the Niton XLp-300A XRF, SN-101222.

Dilia Rosado MEM

**Environmental Risk Assessor** 

## **SECTION 3: APPENDICES**

Appendix A: Certifications, Licenses, and Accreditations

**Appendix B: XRF Sampling Data** 

**Appendix C: XRF's Performance Characteristics Sheet** 

**Appendix D: Photographic Record** 

**Appendix E: Location of Positive Materials** 

Project No. ZEM-23062

## APPENDIX A: CERTIFICATIONS, LICENSES, AND ACCREDITATIONS



Project No. ZEM-23062

## APPENDIX A: CERTIFICATIONS, LICENSES, AND ACCREDITATIONS





ZIMMETRY ENVIRONMENTAL MANAGEMENT CORP. Lead Based Paint Inspection 2 Public Sites (Mariano Quiñones Square & Santo Domingo Park) San Germán, Puerto Rico, Project No. ZEM-23062

## APPENDIX B: XRF SAMPLING DATA

ROJECT:	T: 2 Public Sites (Mariano Quiñones Square & Santo Domingo Park) San Germán, PR			CLIENT: JORGE RIGAU ARQUITECTOS PSC				
ATE:	3/18/2023			LBP Inspec	LBP Inspector: Dilia Rosado			
Sample ID.	Functional Space	Location	Color	Subst.	XRF Reading	Pos/Neg	Comments	
1	Calibration				1.00			
2	Calibration				1.00			
3	Calibration	Comb	W-11	Comments	1.00	NI	Ct- Di D	
4	Streets Surroundings the Site	Curb	Yellow	Concrete Concrete	0.60	Negative	Santo Domingo Par	
5	Streets Surroundings the Site Streets Surroundings the Site	Curb Curb	Blue Brown	Concrete	0.00	Negative Negative	Santo Domingo Par Santo Domingo Par	
7	Streets Surroundings the Site	Light Pole	Brown	Metal	0.00	Negative	Santo Donningo Par	
8	Streets Surroundings the Site	Meter	Pine	Metal	0.00	Negative	Santo Domingo Par	
9	Streets Surroundings the Site	Curb	Yellow	Concrete	4.30	Positive	Santo Domingo Par	
10	Streets Surroundings the Site	Curb	Blue	Concrete	0.00	Negative	Santo Domingo Par	
11	Streets Surroundings the Site	Curb	Yellow	Concrete	4.30	Positive	Santo Domingo Pa	
12	Streets Surroundings the Site	Curb	Blue	Concrete	0.00	Negative	Santo Domingo Pa	
13	Streets Surroundings the Site	Curb	Yellow	Concrete	4.50	Positive	Santo Domingo Par	
14	Streets Surroundings the Site	Curb	Yellow	Concrete	0.00	Negative	Santo Domingo Par	
15	Streets Surroundings the Site	Curb	Blue	Concrete	1.10	Positive	Santo Domingo Pa	
16	Streets Surroundings the Site	Curb	Brown	Concrete	0.00	Negative	Santo Domingo Pa	
17	Streets Surroundings the Site	Curb	Yellow	Concrete	1.10	Positive	Santo Domingo Pa	
18	Streets Surroundings the Site	Light Pole	Brown	Metal	0.00	Negative	Santo Domingo Pa	
19	Streets Surroundings the Site	Curb	Brown	Concrete	0.01	Negative	Santo Domingo Pa	
20	Streets Surroundings the Site	Curb	Blue	Concrete	0.00	Negative	Santo Domingo Pa Santo Domingo Pa	
21 22	Streets Surroundings the Site	Curb Curb	Yellow Brown	Concrete Concrete	1.20 0.00	Positive Negative	Santo Domingo Pa	
23	Streets Surroundings the Site	Curb	Yellow	Concrete	4.60	Positive	Santo Donningo Pa	
24	Streets Surroundings the Site Streets Surroundings the Site	Curb	Blue	Concrete	0.00	Negative	Santo Donningo Pa	
25	Streets Surroundings the Site	Curb	Yellow	Concrete	1.60	Positive	Santo Domingo Pa	
26	Streets Surroundings the Site	Curb	Yellow	Concrete	5.40	Positive	Santo Domingo Pa	
27	Streets Surroundings the Site	Light Pole	Brown	Metal	0.00	Negative	Santo Domingo Pa	
28	Streets Surroundings the Site	Curb	Blue	Concrete	0.01	Negative	Santo Domingo Pa	
29	Streets Surroundings the Site	Curb	Blue	Concrete	0.00	Negative	Santo Domingo Pa	
30	Streets Surroundings the Site	Curb	Yellow	Concrete	0.50	Negative	Santo Domingo Pa	
31	Streets Surroundings the Site	Curb	Yellow	Concrete	0.00	Negative	Santo Domingo Pa	
32	Streets Surroundings the Site	Curb	Brown	Concrete	0.01	Negative	Santo Domingo Pa	
33	Streets Surroundings the Site	Light Pole	Brown	Metal	0.00	Negative	Santo Domingo Pa	
34	Streets Surroundings the Site	Curb	Blue	Concrete	0.00	Negative	Santo Domingo Pa	
35	Streets Surroundings the Site	Curb	Brown	Concrete	0.00	Negative	Santo Domingo Pa	
36	Streets Surroundings the Site	Curb	Yellow	Concrete	0.01	Negative	Santo Domingo Pa	
37	Streets Surroundings the Site	Curb	Blue	Concrete	0.00	Negative	Santo Domingo Pa	
38	Streets Surroundings the Site	Curb	Yellow	Concrete	0.04	Negative	Santo Domingo Pa	
39 40	Streets Surroundings the Site	Curb Hydrant	Brown	Concrete Metal	0.00	Negative	Santo Domingo Pa Santo Domingo Pa	
41	Streets Surroundings the Site	Light Pole	Yellow Brown	Metal	0.00	Negative Negative	Santo Donningo Pa	
42	Streets Surroundings the Site Streets Surroundings the Site	Curb	Brown	Concrete	0.00	Negative	Santo Domingo Pa	
43	Streets Surroundings the Site	Curb	Blue	Concrete	0.00	Negative	Santo Domingo Pa	
44	Streets Surroundings the Site	Curb	Yellow	Concrete	0.00	Negative	Santo Domingo Pa	
45	Streets Surroundings the Site	Curb	Yellow	Concrete	2.00	Positive	Santo Domingo Pa	
46	Streets Surroundings the Site	Curb	Blue	Concrete	0.00	Negative	Santo Domingo Pa	
47	Streets Surroundings the Site	Curb	Brown	Concrete	0.00	Negative	Santo Domingo Pa	
48	Streets Surroundings the Site	Curb	Yellow	Concrete	0.02	Negative	Santo Domingo Pa	
49	Streets Surroundings the Site	Curb	Blue	Concrete	0.02	Negative	Santo Domingo Pa	
50	Streets Surroundings the Site	Curb	Yellow	Concrete	3.40	Positive	Santo Domingo Pa	
51	Santo Domingo Park	Bollards	Brown	Metal	0.00	Negative		
52	Santo Domingo Park	Bollards	Brown	Metal	0.00	Negative		
53	Santo Domingo Park	Bollards	Brown	Metal	0.00	Negative		
54	Santo Domingo Park	Bollards	Brown	Metal	0.00	Negative		
55	Santo Domingo Park	Curb	Yellow	Concrete	0.00	Negative		
56	Santo Domingo Park	Curb	Blue	Concrete	0.01	Negative		
57	Santo Domingo Park	Light Pole	Brown	Metal	0.00	Negative		
58 59	Santo Domingo Park Santo Domingo Park	Light Pole	Brown	Metal Metal	0.00	Negative		
ンソ	Samo Domingo Park	Light Pole	Brown	ivietal	0.00	Negative	1	

PROJECT:	T: 2 Public Sites (Mariano Quiñones Square & Santo Domingo Park) San Germán, PR		CLIENT: JORGE RIGAU ARQUITECTOS PSC				
DATE:	3/18/2023			LBP Inspector: Dilia Rosado			
Sample ID.	Functional Space	Location	Color	Subst.	XRF Reading	Pos/Neg	Comments
61	Santo Domingo Park	Curb	Yellow	Concrete	0.00	Negative	
62	Santo Domingo Park	Curb	Brown	Concrete	0.01	Negative	
63	Santo Domingo Park	Bench	Green	Metal	0.00	Negative	
64 65	Santo Domingo Park Santo Domingo Park	Bench Bench	Green Green	Metal Metal	0.00	Negative	
66	Santo Domingo Park Santo Domingo Park	Bench	Green	Metal	0.00	Negative Negative	
67	Santo Domingo Park	Bench	Green	Metal	0.00	Negative	
68	Santo Domingo Park	Curb	Yellow	Concrete	3.50	Positive	
69	Santo Domingo Park	Floor Markings	Blue	Concrete	0.00	Negative	
70	Santo Domingo Park	Curb	Yellow	Concrete	0.00	Negative	
71	Santo Domingo Park	Curb	Yellow	Concrete	1.20	Positive	
72	Mariano Quiñones Square	Raiser	Yellow	Concrete	0.00	Negative	
73	Mariano Quiñones Square	Pole	Yellow	Concrete	0.00	Negative	
74	Mariano Quiñones Square	Pole	Yellow	Concrete	0.01	Negative	
75	Mariano Quiñones Square	Curb	Brown	Concrete	0.01	Negative	
76	Mariano Quiñones Square	Curb	Yellow	Concrete	0.00	Negative	
77 <b>-</b> 2	Mariano Quiñones Square	Pole	Yellow	Concrete	0.00	Negative	
78	Mariano Quiñones Square	Pole	Yellow	Concrete	0.00	Negative	
79	Mariano Quiñones Square	Curb	Yellow	Concrete	0.00	Negative	
80 81	Mariano Quiñones Square	Raiser Curb	Yellow Yellow	Concrete Concrete	0.02	Negative	
82	Mariano Quiñones Square	Raiser	Yellow	Concrete	0.00	Negative Negative	
83	Mariano Quiñones Square Mariano Quiñones Square	Handrail	Brown	Metal	5.00	Positive	
84	Mariano Quiñones Square  Mariano Quiñones Square	Planter	Yellow	Concrete	0.00	Negative	
85	Mariano Quiñones Square	Planter	Yellow	Concrete	0.00	Negative	
86	Mariano Quiñones Square	Light Pole	Brown	Metal	0.00	Negative	
87	Mariano Quiñones Square	Light Pole	Brown	Metal	0.00	Negative	
88	Mariano Quiñones Square	Handrail	Brown	Metal	4.12	Positive	
89	Mariano Quiñones Square	Handrail	Brown	Metal	5.00	Positive	
90	Mariano Quiñones Square	Handrail	Brown	Metal	5.00	Positive	
91	Mariano Quiñones Square	Curb	Yellow	Concrete	0.00	Negative	
92	Mariano Quiñones Square	Raiser	Yellow	Concrete	0.00	Negative	
93	Mariano Quiñones Square	Curb	Yellow	Concrete	0.01	Negative	
94	Mariano Quiñones Square	Curb	Blue	Concrete	0.01	Negative	
95	Mariano Quiñones Square	Curb	Yellow	Concrete	4.10	Positive	
96	Mariano Quiñones Square	Curb	Yellow	Concrete	1.60	Positive	
97	Mariano Quiñones Square	Curb	Blue	Concrete	0.00	Negative	
98	Mariano Quiñones Square	Curb	Blue	Concrete	0.00	Negative	
99 100	Mariano Quiñones Square	Curb	Brown White	Concrete	0.00	Negative	
100	Mariano Quiñones Square	Curb Wall A	White	Concrete Concrete	0.00	Negative Negative	Gazebo Interior
102	Mariano Quiñones Square Mariano Quiñones Square	Wall B	White	Concrete	0.00	Negative	Gazebo Interior
103	Mariano Quiñones Square	Wall C	White	Concrete	0.00	Negative	Gazebo Interior
104	Mariano Quiñones Square	Wall D	White	Concrete	0.00	Negative	Gazebo Interior
105	Mariano Quiñones Square	Floor Tile	Cream	Ceramic	0.00	Negative	Gazebo Interior
106	Mariano Quiñones Square	Wall A	Yellow	Concrete	0.00	Negative	Gazebo Exterior
107	Mariano Quiñones Square	Wall B	Yellow	Concrete	0.00	Negative	Gazebo Exterior
108	Mariano Quiñones Square	Wall C	Yellow	Concrete	0.00	Negative	Gazebo Exterior
109	Mariano Quiñones Square	Wall D	Yellow	Concrete	0.03	Negative	Gazebo Exterior
110	Mariano Quiñones Square	Column	Brown	Metal	2.50	Positive	Gazebo Exterior
111	Mariano Quiñones Square	Column	Brown	Metal	2.50	Positive	Gazebo Exterior
112	Mariano Quiñones Square	Window Casing	Brown	Metal	0.00	Negative	Gazebo Exterior
113	Mariano Quiñones Square	Wall A	Brown	Concrete	0.00	Negative	Gazebo Exterior
114	Mariano Quiñones Square	Wall B	Brown	Concrete	0.01	Negative	Gazebo Exterior
115	Mariano Quiñones Square	Wall C	Brown	Concrete	0.00	Negative	Gazebo Exterior
116	Mariano Quiñones Square	Wall D	Brown	Concrete	0.00	Negative	Gazebo Exterior
117	Mariano Quiñones Square	Door Frama	Brown	Wood Wood	0.00	Negative	Gazebo Exterior
118 119	Mariano Quiñones Square Mariano Quiñones Square	Door Frame Soffit	Brown Brown	Wood	0.00	Negative Negative	Gazebo Exterior Gazebo Exterior
				. vv ( )( )( )	U.UU		CIAZEDO EXICIOR

PROJECT:	2 Public Sites (Mariano Quiñones Square & Santo Domingo Park) San Germán, PR		CLIENT: JORGE RIGAU ARQUITECTOS PSC				
DATE:	3/18/2023		LBP Inspector: Dilia Rosado				
Sample ID.	Functional Space	Location	Color	Subst.	XRF Reading	Pos/Neg	Comments
121	Streets Surroundings the Site	Curb	Yellow	Concrete	0.00	Negative	M. Quiñones Square
122	Streets Surroundings the Site	Curb	White	Concrete	0.00	Negative	M. Quiñones Square
123	Streets Surroundings the Site	Curb	Brown	Concrete	0.00	Negative	M. Quiñones Square
124	Streets Surroundings the Site	Curb	Blue	Concrete	0.00	Negative	M. Quiñones Square
125	Streets Surroundings the Site	Curb	Yellow	Concrete	1.20	Positive	M. Quiñones Square
126	Streets Surroundings the Site	Curb	Brown Blue	Concrete	1.10	Positive	M. Quiñones Square
127 128	Streets Surroundings the Site	Curb Curb	Yellow	Concrete Concrete	0.00 8.10	Negative Positive	M. Quiñones Square
128	Streets Surroundings the Site	Curb	Yellow	Concrete	1.80	Positive	M. Quiñones Square
130	Streets Surroundings the Site Streets Surroundings the Site	Curb	Blue	Concrete	0.00	Negative	M. Quiñones Square M. Quiñones Square
131	Streets Surroundings the Site	Curb	Yellow	Concrete	1.00	Positive	M. Quiñones Square
132	Streets Surroundings the Site	Curb	Yellow	Concrete	3.80	Positive	M. Quiñones Square
133	Streets Surroundings the Site	Drain	Yellow	Metal	0.00	Negative	M. Quiñones Square
134	Streets Surroundings the Site	Curb	Yellow	Concrete	2.10	Positive	M. Quiñones Square
135	Streets Surroundings the Site	Curb	Blue	Concrete	0.00	Negative	M. Quiñones Square
136	Streets Surroundings the Site	Curb	Yellow	Concrete	2.10	Positive	M. Quiñones Square
137	Streets Surroundings the Site	Drain	Blue	Metal	0.00	Negative	M. Quiñones Square
138	Streets Surroundings the Site	Curb	Yellow	Concrete	1.40	Positive	M. Quiñones Square
139	Streets Surroundings the Site	Curb	Brown	Concrete	0.01	Negative	M. Quiñones Square
140	Streets Surroundings the Site	Curb	Brown	Concrete	0.00	Negative	M. Quiñones Square
141	Streets Surroundings the Site	Light Pole	Blue	Concrete	0.00	Negative	Between Both Site
142	Streets Surroundings the Site	Sign Pole	Yellow	Metal	1.30	Positive	Between Both Site
143	Streets Surroundings the Site	Pole	Blue	Wood	0.00	Negative	Between Both Site
144	Streets Surroundings the Site	Hydrant	Yellow	Metal	5.60	Positive	Between Both Site
145	Streets Surroundings the Site	Curb	Yellow	Concrete	0.00	Negative	Between Both Site
146	Streets Surroundings the Site	Curb	Brown	Concrete	0.00	Negative	Between Both Site
147	Streets Surroundings the Site	Light Pole	Black	Metal	0.00	Negative	Between Both Site
148	Streets Surroundings the Site	Curb	Blue	Concrete	0.00	Negative	Between Both Site
149	Streets Surroundings the Site	Stop Sign	Yellow	Metal	2.10	Positive	Between Both Site
150	Streets Surroundings the Site	Curb	Yellow	Concrete	0.01	Negative	Between Both Site
151	Streets Surroundings the Site	Curb	Blue	Metal	0.00	Negative	Between Both Site
152	Streets Surroundings the Site	Curb	Brown	Metal	0.00	Negative	Between Both Site
153	Streets Surroundings the Site	Light Pole	Brown	Metal	0.00	Negative	Between Both Site
154	Calibration				1.00		
155	Calibration				1.00		
156	Calibration				1.00		

ZIMMETRY ENVIRONMENTAL MANAGEMENT CORP. Lead Based Paint Inspection 2 Public Sites (Mariano Quiñones Square & Santo Domingo Park) San Germán, Puerto Rico, Project No. ZEM-23062

# APPENDIX C: XRF's PERFORMANCE CHARACTERISTICS SHEET

# **Performance Characteristic Sheet**

EFFECTIVE DATE: September 24, 2004 EDITION NO.: 1

#### MANUFACTURER AND MODEL:

Make: Niton LLC
Tested Model: XLp 300
Source: 109Cd

Note: This PCS is also applicable to the equivalent model variations indicated

below, for the Lead-in-Paint K+L variable reading time mode, in the XLi and

XLp series:

XLi 300A, XLi 301A, XLi 302A and XLi 303A. XLp 300A, XLp 301A, XLp 302A and XLp 303A. XLi 700A, XLi 701A, XLi 702A and XLi 703A. XLp 700A, XLp 701A, XLp 702A, and XLp 703A.

Note: The XLi and XLp versions refer to the shape of the handle part of the instrument. The differences in the model numbers reflect other modes available, in addition to Lead-in-Paint modes. The manufacturer states that specifications for these instruments are identical for the source, detector, and detector electronics relative to the Lead-in-Paint mode.

## FIELD OPERATION GUIDANCE

#### **OPERATING PARAMETERS:**

Lead-in-Paint K+L variable reading time mode.

## **XRF CALIBRATION CHECK LIMITS:**

0.8 to 1.2 mg/cm<sup>2</sup> (inclusive)

The calibration of the XRF instrument should be checked using the paint film nearest 1.0 mg/cm<sup>2</sup> in the NIST Standard Reference Material (SRM) used (e.g., for NIST SRM 2579, use the 1.02 mg/cm<sup>2</sup> film).

If readings are outside the acceptable calibration check range, follow the manufacturer's instructions to bring the instruments into control before XRF testing proceeds.

#### SUBSTRATE CORRECTION:

For XRF results using Lead-in-Paint K+L variable reading time mode, substrate correction is <u>not</u> needed for: Brick, Concrete, Drywall, Metal, Plaster, and Wood

#### INCONCLUSIVE RANGE OR THRESHOLD:

K+L MODE READING DESCRIPTION	SUBSTRATE	THRESHOLD (mg/cm²)
Results not corrected for substrate bias on any	Brick	1.0
substrate	Concrete	1.0
	Drywall	1.0
	Metal	1.0
	Plaster	1.0
	Wood	1.0

#### **BACKGROUND INFORMATION**

#### **EVALUATION DATA SOURCE AND DATE:**

This sheet is supplemental information to be used in conjunction with Chapter 7 of the HUD *Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing* ("HUD Guidelines"). Performance parameters shown on this sheet are calculated from the EPA/HUD evaluation using archived building components. Testing was conducted in August 2004 on 133 testing combinations. The instruments that were used to perform the testing had new sources; one instrument's was installed in November 2003 with 40 mCi initial strength, and the other's was installed June 2004 with 40 mCi initial strength.

#### **OPERATING PARAMETERS:**

Performance parameters shown in this sheet are applicable only when properly operating the instrument using the manufacturer's instructions and procedures described in Chapter 7 of the HUD Guidelines.

#### SUBSTRATE CORRECTION VALUE COMPUTATION:

Substrate correction is not needed for brick, concrete, drywall, metal, plaster or wood when using Lead-in-Paint K+L variable reading time mode, the normal operating mode for these instruments. If substrate correction is desired, refer to Chapter 7 of the HUD Guidelines for guidance on correcting XRF results for substrate bias.

#### **EVALUATING THE QUALITY OF XRF TESTING:**

Randomly select ten testing combinations for retesting from each house or from two randomly selected units in multifamily housing. Use the K+L variable time mode readings.

Conduct XRF retesting at the ten testing combinations selected for retesting.

Determine if the XRF testing in the units or house passed or failed the test by applying the steps below.

Compute the Retest Tolerance Limit by the following steps:

Determine XRF results for the original and retest XRF readings. Do not correct the original or retest results for substrate bias. In single-family housing a result is defined as the average of three readings. In multifamily housing, a result is a single reading. Therefore, there will be ten original and ten retest XRF results for each house or for the two selected units.

Calculate the average of the original XRF result and retest XRF result for each testing combination.

Square the average for each testing combination.

Add the ten squared averages together. Call this quantity C.

Multiply the number C by 0.0072. Call this quantity D.

Add the number 0.032 to D. Call this quantity E.

Take the square root of E. Call this quantity F.

Multiply F by 1.645. The result is the Retest Tolerance Limit.

Compute the average of all ten original XRF results.

Compute the average of all ten re-test XRF results.

Find the absolute difference of the two averages.

If the difference is less than the Retest Tolerance Limit, the inspection has passed the retest. If the difference of the overall averages equals or exceeds the Retest Tolerance Limit, this procedure should be repeated with ten new testing combinations. If the difference of the overall averages is equal to or greater than the Retest Tolerance Limit a second time, then the inspection should be considered deficient.

Use of this procedure is estimated to produce a spurious result approximately 1% of the time. That is, results of this procedure will call for further examination when no examination is warranted in approximately 1 out of 100 dwelling units tested.

#### **TESTING TIMES:**

For the Lead-in-Paint K+L variable reading time mode, the instrument continues to read until it is moved away from the testing surface, terminated by the user, or the instrument software indicates the reading is complete. The following table provides testing time information for this testing mode. The times have been adjusted for source decay, normalized to the initial source strengths as noted above. Source strength and type of substrate will affect actual testing times. At the time of testing, the instruments had source strengths of 26.6 and 36.6 mCi.

	Testing Times Using K+L Reading Mode (Seconds)					
	All Data			Median for laboratory-measured lead levels (mg/cm²)		
Substrate	25 <sup>th</sup> Percentile	Median	75 <sup>th</sup> Percentile	Pb < 0.25	0.25 <u>&lt;</u> Pb<1.0	1.0 <u>&lt;</u> Pb
Wood Drywall	4	11	19	11	15	11
Metal	4	12	18	9	12	14
Brick Concrete Plaster	8	16	22	15	18	16

#### **CLASSIFICATION RESULTS:**

XRF results are classified as positive if they are greater than or equal to the threshold, and negative if they are less than the threshold.

#### **DOCUMENTATION:**

A document titled *Methodology for XRF Performance Characteristic Sheets* provides an explanation of the statistical methodology used to construct the data in the sheets, and provides empirical results from using the recommended inconclusive ranges or thresholds for specific XRF instruments. For a copy of this document call the National Lead Information Center Clearinghouse at 1-800-424-LEAD.

This XRF Performance Characteristic Sheet was developed by the Midwest Research Institute (MRI) and QuanTech, Inc., under a contract between MRI and the XRF manufacturer. HUD has determined that the information provided here is acceptable when used as guidance in conjunction with Chapter 7, Lead-Based Paint Inspection, of HUD's *Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing*.

<b>Photo No.</b> 8449	<b>Date:</b> 3/18/2023	
Description:  Mariano Quiñones Square Lead containing metal handrail.		
<b>Photo No.</b> 8451	<b>Date:</b> 3/18/2023	
Description:  Mariano Quiñones Square Lead containing metal handrail.		

<b>Photo No.</b> 8452	<b>Date:</b> 3/18/2023		
Description:  Mariano Quif Gazebo Exter Lead containin	i <b>ones Square</b>   <b>ior</b> g metal handrail.		

Photo No.	Date:
8455	3/18/2023

# **Description:**

Mariano Quiñones Square | Streets Surroundings the Sites Lead-based painted concrete curb.



Mariano Quiñones Square | Streets Surroundings the Sites Lead-based painted concrete

curb.

Photo No.	Date:	
8457	3/18/2023	
Description:  In Between Both Sites Lead-based painted metal stop sign.		PARE
<b>Photo No.</b> 8458	<b>Date:</b> 3/18/2023	
Description:		

Photo No. 8459	Date: 3/18/2023	
Description:  Mariano Quiñones Square   Streets Surroundings the Sites Lead-based painted concrete curb.		
<b>Photo No.</b> 8460	<b>Date:</b> 3/18/2023	
Description:  Mariano Quiñones Square   Streets Surroundings the Sites Lead-based painted concrete curb.		

<b>Photo No.</b> 8461	<b>Date:</b> 3/18/2023	
Description:  Mariano Quiño	ones Square   ndings the Sites	
<b>Photo No.</b> 8462	<b>Date:</b> 3/18/2023	
Description:  Mariano Quiñones Square   Streets Surroundings the Sites Lead-based painted concrete curb.		

Photo No.	Date:	
8463	3/18/2023	
Description:  Mariano Quiñones Square   Streets Surroundings the Sites Lead-based painted concrete curb.		
Photo No.	Date:	1
8464	3/18/2023	
Description:  Mariano Quiñones Square   Streets Surroundings the Sites Lead-based painted concrete curb.		

Photo No.	<b>Date:</b> 3/18/2023	
Photo No. 8465  Date: 3/18/2023  Description:  Mariano Quiñones Square   Streets Surroundings the Sites Lead-based painted concrete curb.		
<b>Photo No.</b> 8466	<b>Date:</b> 3/18/2023	
Description:  Mariano Quiñones Square   Streets Surroundings the Sites Lead-based painted concrete curb.		

Photo No.	Date:	
Photo No. 8467  Date: 3/18/2023  Description:  In Between Both Sites Lead-based painted metal hydrant.		
<b>Photo No.</b> 8468	<b>Date:</b> 3/18/2023	
Description:  In Between Both Sites Lead-based painted metal sign.		ZONA CARCA DESCARCA RIBERTURA

<b>Photo No.</b> 8469	<b>Date:</b> 3/18/2023	
Description:  Mariano Quiño Streets Surrou Lead-based pair curb.	ones Square   ndings the Sites nted concrete	
<b>Photo No.</b> 8471	<b>Date:</b> 3/18/2023	
Description:  Mariano Quiñones Square   Streets Surroundings the Sites Lead-based painted concrete curb.		

Photo No.	Date:	
Photo No. 8474  Date: 3/18/2023  Description:  Mariano Quiñones Square   Streets Surroundings the Sites Lead-based painted concrete curb.		
<b>Photo No.</b> 8475	<b>Date:</b> 3/18/2023	
Description:  Mariano Quiñones Square   Streets Surroundings the Sites Lead-based painted concrete curb.		

<b>Photo No.</b> 8477	<b>Date:</b> 3/18/2023	
Description:  Mariano Quif	ĭones Square   undings the Sites	CHARSEGURITY CONTROL OF THE PROPERTY OF THE PR
Photo No.	Date:	
Description:  Mariano Quiñones Square Lead-based painted concrete curb.		

ZIMMETRY ENVIRONMENTAL MANAGEMENT CORP. Lead Based Paint Inspection 2 Public Sites (Mariano Quiñones Square & Santo Domingo Park) San Germán, Puerto Rico, Project No. ZEM-23062

# APPENDIX E: LOCATION OF POSITIVE MATERIALS



# PLAZA FRANCISCO MARIANO QUIÑONES

# <u>Note:</u>

The layout of materials shown in this figure is for illustrative purposes only. For actual location and quantity of materials refer to the Lead Based Paint survey report dated March 2023.

# LBP Legend:

- 1 Hand Rails
- 2 Columns
- 3 Concrete Curb
- 4 Fire Hydrant
- 5 Sign Pole

# Zimmetry Environmental Environmental Building Inspectors Indoor Environmental Quality / Mold Assessments, Asbestos, Lead Base Paint Consulting - Phone - Fax (787) 995-0005

Project: Francisco Mariano Quiñones Square—Santo Domingo Par

Date: March 2023

Project No. ZEM-23062

Drawing:



# PLAZA SANTO DOMINGO

# Note:

The layout of materials shown in this figure is for illustrative purposes only. For actual location and quantity of materials refer to the Lead Based Paint survey report dated March 2023.

# LBP Legend:

1 Hand Rails

2 Columns

3 Concrete Curb

4 Fire Hydrant

5 Sign Pole

# Zimmetry Environmental Environmental Building Inspectors Indoor Environmental Quality / Mold Assessments, Asbestos, Lead Base Paint Consulting - Phone - Fax (787) 995-0005

Project: Francisco Mariano Quiñones Square—Santo Domingo Parl San German, PR

Date: March 2023

Project No. ZEM-23062

Drawing:





## Memorandum to File

Date: October 13, 2025

From: Sol V Rosa Ramos

Env Reviewer - Tetra-Tech

CDBG-DR Program

Dol V Rosa

City Revitalization Program

Puerto Rico Department of Housing

Application Number: PR-CRP-000876

Project: Plaza Santo Domingo and Plaza Mariano Quiñones

Re: Justification for the Infeasibility and Impracticability of Radon Testing

After reviewing Application Number PR-CRP-000876 Plaza Santo Domingo and Plaza Mariano Quiñones under the City Revitalization Program, administered by the Puerto Rico Department of Housing (**PRDOH**), to complete the property's contamination analysis in accordance with 24 C.F.R. § 50.3(i) and 24 C.F.R. § 58.5(i), we have determined that testing the property's radon levels is infeasible and impracticable.

Per the U.S. Department of Housing and Urban Development's (**HUD**) CPD Notice 23-103, the recommended best practices and alternative options for radon testing are infeasible and impracticable in this case due to the following reasons:

- As required by the CPD Notice 23-103, the scientific data reviewed in lieu of testing must consist of a minimum of ten documented test results over the previous ten years. If there are less than ten documented results over this period, it is understood that there is a lack of scientific data. The latest report for radon testing in Puerto Rico was prepared in 1995 by the U.S. Department of the Interior in Cooperation with the U.S. Environmental Protection Agency. No other completed studies and reports on radon testing are available in Puerto Rico.
- There is no available science-based or state-generated information for Puerto Rico for the last ten years that can be used to determine whether the project site

CDBG-DR Program
City Revitalization Program
Memorandum to File
Infeasibility and Impracticability of Radon Testing
Page 2 of 2

is in a high-risk area. The Department of Health and Human Services, Centers for Disease Control and Prevention (CDC), National Environmental Public Health Tracking, and Radon Testing map do not include Puerto Rico data.

- There are only two (2) licensed professionals in Puerto Rico who can conduct radon testing using the American National Standards Institute/American Association of Radon Scientists and Technologists (ANSI/AARST) testing standards, which makes it difficult, time-consuming, and highly expensive to coordinate and secure a site visit for the contamination evaluation.
- Do-it-yourself (DIY) radon test kits are known to be unreliable in assuring and controlling the quality of the test results; they are not readily available in Puerto Rico, and the cost and time required for purchasing and sending them for analysis are unreasonable when weighed against the results' reliability and the need for prompt results.
- Local authorities in Puerto Rico do not have the specialized radon monitoring equipment or trained staff needed to conduct the radon testing analysis and ensure proper quality control and quality assurance practices are adhered to. We also do not have a radiation laboratory certified for radon testing.

As part of the evaluation for this determination, PRDOH sent information requests to six (6) local agencies at the state and federal levels. We received responses from the following agencies:

- United States Geological Survey
- Centers for Disease Control and Prevention
- Puerto Rico Department of Health; and
- United States Environmental Protection Agency.

The agencies mentioned above confirmed the lack of scientific data on Radon testing for Puerto Rico and the technical difficulties that we face to comply with HUD's Radon testing requirement. For the above-mentioned reasons, Radon testing is infeasible and impracticable for this property, and no further consideration of Radon is needed for the environmental review.

# Radon Attachments



August 20, 2024

Mrs. Carmen R. Guertero Pérez Director Caribbean Environmental Protection Division City View Plaza II – Sulte 7000 #48 Rd, 165 km 1,2 Guavnabo, PR 00948-8069

Vía email: guerrero.carmen@epa.gov

# RE: Request for Information regarding available data on radon testing and levels within Puerto Rico

The Puerlo Rico Department of Housing (PRDOH) kindly requests your assistance in gathering data, information, or reports related to radon testing in Puerlo Rico, as this Information is crucial for our compliance with the U.S. Department of Housing and Urban Development (HUD) Community Planning and Development (CPD) Nolice CDP-23-103.

Community Planning and Development (CPD) Notice CDP-23-103. This Notice emphasizes the importance of radon testing and milligation in ensuring safe living environments, particularly in HUD-assisted properties. PRDOH, as the grantee of the Community Development Black Grant for Blasster Recovery and Miligation (CDBS-DR/MII); is responsible to ensuring compliance with environmental requirements under CDBG-DR/MIT programs, To hulfill our obligations under this Notice, we must compile comprehensive and up-to-date information on radon levels, testing practices, and any mitigation efforts within the Islands of Puerto Rico.

Specifically, we are seeking for possible availability of the following information:

Radon lesting data – Results from radon testing conducted within your agency's purview, including details on location, testing methods, and recorded radon levels.

Barbosa Ave #606 , Building Juan C. Cordero Davilla, Rio Penillas, PR 009th (PO Box 21565 San Juan, PR 00955-1965 Tel (787) 214-2527 ( pp. 17 months of dis



August 20, 2024

Dr. Slivina Cancelos Frofessor College of Engineering University of Puerto Rico—Mayagüez Campus 259 Norte Biva, Alfonso Valdés Cobián Mayagüez, Puerto Rica

Via email: silvina.cancelos@upr.edu

# RE: Request for information regarding available data on radon testing and levels within Puerto Rico

The Puerto Rico Department of Housing (PRDOH) kindly requests your assistance in gathering data, information, or reports related to radon testing in Puerto Rico, as this information is crucial for our compliance with the U.S. Department of Housing and Urban Development (HUD) Community Planning and Development (CPD) Notice CDP-23-103.

Community Planning and Development (CPD) Notice CDP-23-103. This Notice emphasizes the importance of radon testing and milligation in ensuring safe living environments, particularly in HUD-assited properties. PRDOH, as the grantee of the Community Development Block Grant for Disaster Recovery and Milligation (CDBC-DR/MIT), is responsible for ensuring compliance with environmental requirements under CDBG-DR/MIT programs. To fulfill our obligations under this Notice, we must compile comprehensive and up-to-date information on radon levels, testing practices, and any milligation efforts within the islands of Puerto Rico.

Specifically, we are seeking for possible availability of the following information:

Radon testing data – Results from radon testing conducted within your agency's purview, including details on location, testing methods, and recorded radon levels,

Barbora Ave. #606 ; Building Juan C. Cordero Dávila. Rio Piedrec. PR 00918 ) PO Box 21365 San Juan, PR 00928-1365 Tel (787) 274-2527 | 10000009803182 (68) CDBG-DR/MIT Program

Keeperst for Information in relation with HUD CPD-35-100 for Puerto Sico

Poero 2 / 2

Reports and assessments – Any reports, studies, or assessments your agency has produced or commissioned that address radon testing or miligation.

<u>Policies and auidelines</u> – information or any policy, guideline, or protocol your agency follows concerning radon testing, exposure limits, or milligation.

<u>Historical data</u> – If available, historical data or frends in radon levels within the regions you manifor that may impact HUD-assisted housing.

This information is vital to ensure that our radon management strategies are practical and compiliant with federal requirements. It some of this information may be sensitive or confidential, we are prepared to discuss any necessary agreements or protocols for sharing this data securely.

Please let us know if you require additional details or have any questions regarding this request. We would greatly appreciate your response by September 15, 2024, so we can incorporate this data into our origoing compliance efforts.

Thank you in advance for your cooperation and support. We look forward to working together on this critical initiative.

Willam O. Rodriguez Rodriguez, Esq.

e:

Sincerel

Mr. Oleg Povetko, <u>Povetko, Olegišepa, gov</u>

CDBG-DR/MIT Program Request for Information in relation with HUD CPD-23-103 for Pusers 2 / 2

Reports and assessments — Any reports, studies, or assessments your agency has produced or commissioned that address radon testing or mitigation.

<u>Policies and guidelines</u> – information or any policy, guideline, or protocol your agency follows concerning radon testing, exposure limits, or mitigation.

Historical data —if available, historical data or trends in radon levels within the regions you monitor that may impact HUD-assisted housing.

This information is vital to ensure that our radon management strategies are practical and compliant with federal requirements. It some of this information may be sensitive or confidential, we are prepared to discuss any necessary agreements or protocols for sharing this data socurely.

Please let us know if you require additional details or have any questions regarding this request. We would greatly appreciate your response by September 15, 2024, so we can incorporate this data into our ongoing compliance efforts.

Thank you in advance for your cooperation and support, We look forward to working together on this critical initiative.

Sincerely,

Willight O. Rodríguez Rodríguez, Esq.

Jocion

Dr. Carlos Marín, carlos marin 3@upr.edu



August 20, 2024

Dr. Jessica Irizary Director Office of Island Affairs U.S. Centles for Disease Confrol and Prevention 1324 CII Canada, San Juan, 00920 Guaynabo, PR 00968-8069

Via email: OIA@cdc.aov

# RE: Request for Information regarding available data on radon testing and levels within Puerto Rico

The Puerto Rico Department of Housing (PRDOH) kindly requests your assistance in gathering data, information, or reports related to radon testing in Puerto Rico, as this information is crucial for our compliance with the U.S. Department of Housing and Urban Development (HUD) Community Planning and Development (CPD) Notice CDP-23-103,

This Notice emphasizes the importance of radon testing and milligation in ensuring safe living environments, particularly in HIDD-assisted properties. PRODH, as the grantee of the Community Development Black Grant for Disaster Recovery and Milligation (CDBG-DR/MIT), is responsible for ensuring compliance with environmental requirements under CDBG-DR/MIT programs. To HIBIT our obligations under this Notice, we must compile comprehensive and up-to-date information on radon levels, testing practices, and any miligation efforts within the islands of Puerto Rico.

Specifically, we are seeking for possible availability of the following information:

 $\underline{Radon\ lesting\ data} - \text{Results\ from\ radon\ testing\ conducted\ within\ your\ agency's\ purview,\ including\ details\ on\ location,\ testing\ methods,\ and\ recorded\ radon\ levels.}$ 

Barbosa Ave. #606 , Building Juan C. Cordero Dávila, Rio Piedras, PR 00318 | PO Box 21365 San Juan PR 00928-1365 Fel (1991-274-2527 | Juan P. 00318 | PO Box 21365 San Juan PR 00928-1365



August 20, 2024

Mrs. Anais Rodríguez Secretary Puerto Rico Department of Natural Resources Carretera 8838, km. 6.3. Sector El Cinco. Río Piedras San Juan, PR 00926

Via email: anais.rodriguez@dma.pr.gov

# RE: Request for Information regarding available data on radon testing and levels within Puerto Rico

The Puerto Rico Department of Housing (PRDOH) kindly requests your assistance in gathering data, information, or reports related to radon testing in Puerto Rico, as this information is crucial for our compliance with the U.S. Department of Housing and Urban Development (HUD) Community Planning and Development (CPD) Notice CDP-23-103.

This Notice emphasizes the importance of radon testing and miligation in ensuring safe living environments, particularly in HUD-assisted properties, PRDOH, as the granitee of the Community Development Black Grant for PROGH, as the granitee of the Community Development Black Grant for ensuring compliance with environmental requirements under CDBG-DR/MIT programs. To fulfill our obligations under this Notice, we must compile comprehensive and up-to-date information on radon levels, testing practices, and any miligation efforts within the islands of Puerlo Rico.

Specifically, we are seeking for possible availability of the following

Radon testing data - Results from radon testing conducted within your agency's purview, including details on location, testing methods, and recorded radon levels.

Reports and assessments – Any reports, studies, or assessments your agency has produced or commissioned that address radon testing or mitigation.

Barbosa Aye. #606 , Building Juan C. Cordero Davilla. Rio Piedres. PR 00918 J PO Box 21365 San Juan, PR 00926-1365 Tel (787) 274-7527 | m.W.box = 51 0795 CDBG-DR/MIT Program
(sequest for information in teletion with HUD CFD-23-103 for Puerto Rico

Reports and assessments – Any reports, studies, or assessments your agency has produced or commissioned that address radon testing or mitigation.

<u>Policies and quidelines</u> – Information or any policy, guideline, or protocol your agency follows concerning radon testing, exposure limits, or miligation.

<u>Historical data</u> – If available, historical data or trends in radon levels within the regions you monitor that may impact HUD-assisted housing.

This information is vital to ensure that our radon management strategies are practical and compliant with federal requirements, it some of this information may be sensitive or confidential, we are prepared to discuss any necessary agreements or protocols for sharing this data securely.

Please let us know it you require additional details or have any questions regarding this request. We would greatly appreciate your response by September 15, 2024, so we can incorporate this data into our ongoing compliance efforts.

Thank you in advance for your cooperation and support. We look forward to working together on this critical initiative.

Sincaral

Willigh & Rodriguez Rodriguez, Esq.

CDBC-DR/MIT Program Request for Information in relation with HUD CPD-23-103 for Puerto Ricc Page 2.73

<u>Policies and guidelines</u> – intormation or any policy, guideline, or protocol your agency follows concerning radon testing, exposure limits, or miligation.

<u>Historical data</u> – If available, historical data or Irends in radon levels within the regions you manifor that may impact HUD-assisted housing.

This information is vital to ensure that our radon management strategies are practical and complicant-with federal requirements. It some of this information may be sensitive or confidential, we are prepared to discuss any necessary agreements or protocols for shating this data securely.

Please let us know it you require additional details or have any questions regarding this request. We would greatly appreciate your response by September 15, 2024, so we can incorporate this data into our ongoing compliance efforts.

Thank you in advance for your cooperation and support. We look forward to working together on this critical initiative.

Sincerely

William O. Rodríguez Rodríguez, Esq.

Secretary

:
Mr. Luis Márquez, <u>secretariaaire@drna.pr.gov</u>
Erig. Amarilys Rosario, <u>aire@drna.pr.gov</u>
Mrs. Elid Ortega, <u>sortega@drna.pr.gov</u>



August 20, 2024

Dr. Carlos R. Mellado López Secretary Puerto Rica Department of Health PO Box 70184 San Juan, PR 00936-8184

Vía email: drcarlos.mellado@salud.pr.gov

# RE: Request for Information regarding available data on radon testing and levels within Puerlo Rico

The Puerlo Rico Department of Housing (PRDOH) kindly requests your assistance in gathering data, information, or reports related to radon festing in Puerlo Rico, as this information is crucial for our compliance with the U.S. Department of Housing and Utban Development (HJID) Community Planning and Development (CPD) Notice CDP-23-103.

This Notice emphasizes the importance of radon testing and mitigation in ensuring safe living environments, particularly in HUD-assisted properties. PRDOH, as the grantee of the Community Development Block Grant for Disaster Recovery and Mitigation (CDBG-DR/MIT), is responsible for ensuring compliance with environmental requirements under CDBG-DR/MIT programs. To Utilli our obligations under this Notice, we must compile comprehensive and up-to-date information on radon levels; testing practices, and any mitigation efforts within the islands of Puerto Biscon

Specifically, we are seeking for possible availability of the following information:

Radon testing data – Results from radon testing conducted within your agency's purview, including details on location, testing methods, and recorded radon levels.

Reports and assessments – Any reports, studies, or assessments your agency has produced or commissioned that address radon testing or milligation.

Barbosa Ave. \$106 / Building Juan C. Cordero Davila, Ro Flednas, PR 009/8 | PO Box 21565 San Juan, PR 00926-1305 Tel. (787) 274-2527 | 1000-1006/55 C. 032



August 20, 2024

Mrs. Holly Weyers Regional Director, Southeast – Puerto Rico US Geological Survey 3916 Sunset Ridge Road Raleigh, NC 27607

Via email: hsweyers@usgs.gov

# RE: Request for Information regarding available data on radon testing and levels within Puerto Rico

The Puerto Rico Department of Housing (PRDOH) kindly requests your assistance in gathering data, information, or reports related to radon testing in Puerto Rico, as this information is crucial for our compliance with the U.S. Department of Housing and Urban Development (HUD) Community Planning and Development (CPD) Notice CDP-23-103.

This Notice emphasizes the importance of radon testing and mitigation in ensuring safe living environments, particularly in HUD-assisted properties. PRDOH, as the grantee of the Community Development Black Grant for Disaster Recovery and Mitigation (CDBG-DR/MIT), is responsible for ensuring compliance with environmental requirements under CDBG-DR/MIT programs. To fulfill our obligations under this Notice, we must compile comprehensive and up-to-date information on radon levels, testing practices, and any mitigation efforts within the islands of Puerto Rico.

Specifically, we are seeking for possible availability of the following information:

Radon Jesting data – Results from radon testing conducted within your agency's purview, including details on location, testing methods, and recorded radon levels.

<u>Reports and assessments</u> - Any reports, studies, or assessments your agency has produced or commissioned that address radon lesting or mitigation.

Barboca Ave. #606, Building Juan C. Cordero Davila, Rio Piedras. PR 00918 | PO Box 21%6 San Juan, PR 00928-1365 Tel (787) 274-2577 | 1000-101 Sept. 1019 CDBD-DR/MIT Program
Request for Information in relation with HUD CPD-23-103 for Puetro Blood
Request for Information in relation with HUD CPD-23-103 for Puetro Blood
Request for Information in relation with HUD CPD-23-103 for Puetro Blood
Request for Information in relation with HUD CPD-23-103 for Puetro Blood
Request for Information in relation with HUD CPD-23-103 for Puetro Blood
Request for Information in relation with HUD CPD-23-103 for Puetro Blood
Request for Information in relation with HUD CPD-23-103 for Puetro Blood
Request for Information in relation with HUD CPD-23-103 for Puetro Blood
Request for Information in relation with HUD CPD-23-103 for Puetro Blood
Request for Information in Relation with HUD CPD-23-103 for Puetro Blood
Request for Information in Relation with HUD CPD-23-103 for Puetro Blood
Request for Information in Relation in Relation

<u>Policies and auldelines</u> – information or any policy, guideline, or protocol your agency follows concerning radon testing, exposure limits, or mitigation.

<u>Historical data</u> – if available, historical data or trends in radon levels within the regions you monitor that may impact HUD-assisted housing.

This information is vital to ensure that our radon management strategies are practical and compliant with federal requirements. It some of this information may be sensitive or confidential, we are prepared to discuss any necessary agreements or protocois for sharing this data securely.

Please let us know if you require additional details or have any questions regarding this request. We would greatly appreciate your response by September 15, 2024, so we can incorporate this data into our ongoing compliance efforts.

Thank you in advance for your cooperation and support. We look forward to working together on this critical initiative.

sincerely.

William O. Rodríguez Rodríguez, Esq

secretar

Mr. Raúl Hernández Doble, <u>rhernandez28salud pr. gov</u>

CDBG-DR/MIT Program
Request for information in relation with HUD CPD-23-103 for Pulsito Rece
Page 2 /:

<u>Policies and guidelines</u> – Information or any policy, guideline, or protocol your agency follows concerning radon testing, exposure limits, or mitigation.

<u>Historical data</u> – if available, historical data or trends in radon levels within the regions you monitor that may impact HUD-assisted housing.

This information is vital to ensure that our radon management strategies are practical and compliant with federal requirements, if some of this information may be sensitive or confidential, we are prepared to discuss any necessary agreements or protocols for sharing this data securely.

Please let us know if you require additional details or have any questions regarding this request. We would greatly appreciate your response by September 15, 2024, so we can incorporate this data into our ongoing compliance efforts.

Thank you in advance for your cooperation and support. We look forward to working together on this critical initialive.

Sincerely,

William & Rodríguez Rodríguez, Esc

Cc:

Mr. R. Randall Schumann, ischumann@usgs.cov

From: Charp, Paul (CDC/NCEH/DEHSP) <pac4@cdc.gov>

Sent: Tuesday, September 3, 2024 6:36 AM

To: Miranda, Sandra (CDC/PHIC/DPS); Irizarry, Jessica (CDC/PHIC/DPS); Rzeszotarski, Peter

(CDC/NCEH/DEHSP); Vinson, D. Aaron (CDC/NCEH/DEHSP)

Cc: Kostak, Liana (CDC/PHIC/DPS); Vazquez, Germaine (CDC/NCEH/DEHSP)

Subject: RE: REHi: Puerto Rico Request for Information- Randon testing and levels

## Good morning, Sandra and others,

In response to the request from Mr. William Rodriguez of the Department of Housing, Government of Puerto Rico, I have reviewed all the available data within the CDC National Environmental Public Health Tracking Network system for data related to radon in Puerto Rico. In addition to the tracking data available on the internet, I also reached out to Mr. Aaron Vinson of the NCEH Tracking Branch.

I was not able to find any data in the CDC systems and this was confirmed by Mr. Vinson. We also reached out the US Environmental Protection Agency who indicated they had no radon data in their systems. Please relay this information to Mr. Rodríguez in your response to his requests

If you have any additional questions, please contact me.

Thank you and best regards,

Paul A. Charp, Ph.D., Fellow, HPS
Senior Health Physicist
Emerging Environmental Hazards and Health Effects Branch (EEHHEB)
Division of Environmental Health Science and Practice (DEHSP)
National Center for Environmental Health (NCEH)
Centers for Disease Control and Prevention (CDC)
pcharp@cdc.gov
770-488-0723 office
404.388.0614 Cell



From: Schumann, R. Randall <rschumann@usgs.gov>

Sent: Wednesday, August 21, 2024 4:39 PM

To: Melanie Medina Smaine <mmedina@vivienda.pr.gov>; Weyers, Holly S <hsweyers@usgs.gov> Cc: Elaine Dume Mejia <Edume@vivienda.pr.gov>; Luz S Colon Ortiz <Lcolon@vivienda.pr.gov>; Aldo A.

Rivera-Vazquez <aarivera@vivienda.pr.gov>

Subject: RE: Request for Information- Radon testing and levels

Dear Ms. Medina Smaine,

In the early 1990s the U.S. Geological Survey (USGS) conducted geologic assessments of radon potential for all 50 states and the territories of Guam and Puerto Rico, in collaboration with the U.S. EPA. I conducted the geologic radon potential assessment for Puerto Rico. The PDF file of the report is too large to attach to this message but it can be obtained at <a href="https://pubs.usgs.gov/of/1993/0292k/report.pdf">https://pubs.usgs.gov/of/1993/0292k/report.pdf</a>. The USGS did not conduct indoor radon testing and we did not conduct field studies associated with this assessment; it was based on existing data. Mr. David Saldana of the Puerto Rico Department of Health kindly provided us with data for 610 homes that were tested for indoor radon by his agency between 1993 and 1995, which are summarized in the report. I am not aware of any other radon-related geologic studies conducted in the Commonwealth of Puerto Rico by the U.S. Geological Survey.

Best regards,

R. Randall Schumann
Scientist Emeritus
U.S. Geological Survey
Geociences and Environmental Change Science Center
Denver, Colorado, USA
rschumann@usgs.gov
https://www.usgs.gov/staff-profiles/r-randall-schumann

----

From: Raul Hernandez Doble <rhernandez2@salud.pr.gov>

Sent: Wednesday, August 21, 2024 2:13:31 PM

To: Melanie Medina Smaine <mmedina@vivienda.pr.gov>; Dr. Carlos Mellado <drcarlos.mellado@salud.pr.gov>
Cc: Elaine Dume Mejia <Edume@vivienda.pr.gov>; Luz S Colon Ortiz <Lcolon@vivienda.pr.gov>; Aldo A. Rivera-Vazquez <aarivera@vivienda.pr.gov>; Mayra Toro Tirado <mtoro@salud.pr.gov>

Subject: RE: [EXTERNAL]Request for Information-Randon testing and levels

Good afternoon, Ms. Medina

I regret to inform that we do not have any recent information on radon testing, since we do not have a certified radiation laboratory certified for radon testing. There are companies that sell test kits available online that can be done and mailed to a testing laboratory. There are also lists of radon contractors and these companies that process radon testing cartridges with instructions, on the Environmental Protection Agency Indoor air Quality web page. The last radon study in Puerto Rico done by the PR Department of Health was done on the year 1993.

Raul Hernandez Doble
Director, Seccion Salud Radiologica
Division de Salud Ambiental
Secretaria Auxiliar para la Vigilancia y la Proteccion de la Salud Publica
rhernandez2@salud.gov.pr

Phone: (787)765-2929 ext. 3210

From: Reyes, Brenda < Reyes. Brenda@epa.gov> Sent: Wednesday, September 18, 2024 11:48 AM

To: Cesar O Rodriguez Santos <cesarrodriguez@drna.pr.gov>; Maritza Rosa Olivares <maritzarosaolivares@drna.pr.gov>; Silvina Cancelos Mancini <silvina.cancelos@upr.edu>; Melanie Medina Smaine <mmedina@vivienda.pr.gov>

Cc: Elaine Dume Mejia <Edume@vivienda.pr.gov>; Luz S Colon Ortiz <Lcolon@vivienda.pr.gov>; Aldo A. Rivera-Vazquez

<aarivera@vivienda.pr.gov>; Povetko, Oleg (he/him/his) <Povetko.Oleg@epa.gov>

Subject: RE: Request for Information- Randon testing and levels

#### Saludos.

La EPA esta trabajando una respuesta a su petición. Se sometió borrador a la directora y el subdirector para su aprobación y firma.

Brenda Reyes Tomassini
Public Affairs
U.S. EPA
Region 2
Caribbean Environmental Protection Division
(787) 977-5869/(787) 977-5865
Mobile: 202-834-1290

\_\_\_

From: Silvina Cancelos Mancini <silvina.cancelos@upr.edu>

Sent: Friday, September 6, 2024 15:04

To: Melanie Medina Smaine < mmedina@vivienda.pr.gov >

Cc: Elaine Dume Mejia < Edume@vivienda.pr.gov >; Luz S Colon Ortiz < Lcolon@vivienda.pr.gov >; Aldo A. Rivera-Vazquez

<aarivera@vivienda.pr.gov>; Maritza Rosa Olivares <<u>maritzarosaolivares@drna.pr.gov</u>>; Reyes, Brenda

<<u>Reyes.Brenda@epa.gov</u>>; Povetko, Oleg <<u>Povetko.Oleg@epa.gov</u>>

Subject: Re: Request for Information- Randon testing and levels

#### Estimada Melanie Medina

Quería dejarle saber que recibimos su correo el 21 de agosto al igual que el de Maritza Rosa el pasado 4 de septiembre. Ya las personas involucradas de EPA, junto conmigo y el Dr. Marín estamos al tanto del asunto y estamos trabajando para poder enviarles la información.

## Atentamente

Silvina Cancelos
Professor
Associate Director
Mechanical Engineering Department
University of Puerto Rico - Mayaguez
Call BOX 9000 Mayaguez PR 00680
Tel: 787-832-4040 ext 5956
email: silvina.cancelos@upr.edu





September 23, 2024

#### VIA EMAIL

William O. Rodriguez Rodriguez, Esq. Secretary Puerto Rico Department of Housing Barbosa Ave. 606 Building Juan C. Cordero San Juan, PR 00917 Email: W.Rodriguez@vivienda.pr.gov

#### RE: EPA Response to August 20, 2024 request for information of data on radon testing and levels in Puerto Rico

Dear Honorable Secretary Rodríguez Rodríguez:

This communication is in response to your letter of August 20, 2024 addressed to the Puerto Rico Department of Natural and Environmental Resources (DNER) and referred to the U.S. Environmental Protection Agency (EPA) regarding available data on radon testing and levels within Puerto Rico.

EPA's National Radon Action Plan 2021–2025 sets a goal for the nation to find, fix and prevent high indoor radon levels in 8 million buildings by 2025 and prevent 3,500 lung cancer deaths per year. Under this Plan, leaders from across multiple sectors are working together to plan, guide, and sustain nationwide action to prevent exposure to radon.

Due to the lack of data in Puerto Rico, EPA undertook an investigation in collaboration with the University of Puerto Rico-Mayaguez (UPRM) Campus, Departments of Civil Engineering and Surveying and Mechanical Engineering, to find out if radon presented a problem in Puerto Rico, by until 2021, the only data we had for Puerto Rico was a 1993-1995 mail-in radon screening study referred to by the U.S. Geological Survey report (USSC), 1995) in which the USSC concluded that several areas of Puerto Rico have the geologic potential to generate indoor radon levels exceeding the EPA Action Level of 4 pC/L, (circouries per liter), perhaps locally reaching very high levels above 50 pC/L, if a house construction and

CITY VIEW PLAZA II BUILDING, 7<sup>TH</sup> FLOOR ROUTE 165 GUAYNABO, PR 00968 ventilation allow for soil-gas radon to enter and concentrate within the structure. <sup>1</sup> According to the USGS report, most of these areas are located in the northwest part of the island. Please note that the actual 1993-1995 study documentation is not available to the EPA.

Typical radon testing technology used in mainland United States (charcoal canisters or electric-powered devices) are impractical in Puerto Rico because of high humidity and power outages. The recovery and rebuilding of communities following the aftermath of 2017 Hurricanes Irma and Maria presented an opportunity to develop radon prevention and mitigation strategies in 2019. Initially, EPA sampled indoor radon air in over 170 single-family residences in the municipalities of San Sebastian, Lares, Ciales, Arecibo, Morovis, Camuy, and Hatillo and later expanded the project to other municipalities such as Rincon, Aguada, Aguadalli, stabela, Questradillas, Barecloneta and Vega Baja. The quality assurance protocols were anchored in American National Standards institute/American Association of Radon Scientists and Technologists (ANSI/AARS) standards of practice (ANSI/AARS) 1939. The sampling was designed in two stages: scoping and confirmatory sampling. The scoping sampling was conducted using Corentium Home (CH) electronic monitors and E-Perm ystems. Locations measuring above the EPA Action Level 64 of 201/L with CH were measured at the second stage of the sampling using RAD7 and Corentium Pro Continuous Radon Monitors (CRMs). Nationally certified andon sampling professionals led by one such professional from the UPRM conducted confirmatory sampling in the second stage. Also, during the study, the nationally certified radon mitigation professionals inspected several homes with elevated indoor radon levels.

Mapping radon in Puerto Rico proved to be a complicated endeavor given the COVID-19 pandemic in 2020. EPA and UPRM continue to work on the project, however, results have not been finalized, and no scientific report has been published yet. Unfortunately, EPA cannot share preliminary data at this time because it contains privileged information. Nevertheless, preliminary data at from the study does show homes with levels over 4 pG/L (EPA Action Level) that might need mitigation to protect the health of their inhabitants.

Although many states have developed laws and regulations governing radon disclosure, certification, and mitigation, Puerto Rico lacks legislation or mandatory radon testing provisions for new construction, remodeling, selling or buying homes. Given this loophole and aimling to answer your request, the EPA can provide information on Best Management Practices for sampling indoor radon in Puerto Rico.

2

If you have any questions or need any additional information, please contact me at 787-977-5865 or <u>guerrero.carmen@epa.gov</u> or have your staff contact Reyes, Brenda at <u>reyes.brenda@epa.gov</u> or (787) 977-5869.

Sincerely,

Director

CARMEN GUERRERO PEREZ

Digitally signed by CARMEN GUERRERO PEREZ Date: 2024.09.23 09;41:39 -04'00'

PEREZ -04'0
Carmen R. Guerrero Pérez

cc: Roberto Mendez, Esq (Acting Secretary, PR Department of Natural and Env. Resources)

Melany Medina: mmedina@vivienda.pr.gov
Elaine Dume Mejia: Edume@wivienda.pr.gov
Lus S Colon Ortiz: Lcolon@wivienda.pr.gov
Aldo A. Rivera-Vazquez: gartivera@wivienda.pr.gov
Cesar O. Rodriguez: cesarrodriguez@drna.pr.gov
Marita Rosa Olivares; maritzarosaolivares@drna.pr.gov

Reference: USGS. Geologic Radon Potential of Guam and Puerto Rico, Report 93-292-K. Washington, DC: USGS. Retrieved 9/11/2024, from https://pubs.usgs.gov/of/1993/0292k/report.pdf.







# Transmittal Letter



Based on the information provided, we determined the project proposed qualifies for the blanket clearance letter. Nevertheless, if the project is modified this office should be contacted concerning the need for the initiation of consultation under section 7 of Endangered Species Act of 1973.

eviewer DAMARIS ROMAN RUIZ Digitally signed by DAMARIS ROMAN RUIZ Date: 2024.12.03 10:35:30 -04'00'

**LOURDES MENA** 

Digitally signed by LOURDES MENA Date: 2024.12.04 07:12:27 -04'00'

Caribbean ES Field Supervisor

Caribbean Ecological Services Field Office U.S. Fish and Wildlife Service

P.O. Box 491

December 2, 2024

Boquerón, Puerto Rico 00622

Email: <a href="mailto:caribbean@es@fws.gov">caribbean@es@fws.gov</a>

RE: USFWS Endangered Species Act Certifications – City Revitalization Program November 2024

We are submitting the following Self-Certifications for projects under the CDBG-DR City Revitalization Program. Attached are included the Self-Certifications that certify that the projects are in compliance and are not likely to adversely affect federally-listed species.

The following table includes the projects that are in compliance with the Blanket Clearance Letter for the Endangered Species act of 1973, as amended, and the Fish and Wildlife Coordination Act.

Project Number	Project Name
PR-CRP-000205	Hotel del Valenciano
PR-CRP-000771	Revitalization of Plaza Luis Muñoz Rivera in the Urban Center of Arecibo
PR-CRP-000876	Domingo and Plaza Mariano Quiñones
PR-CRP-001179	Rehabilitación y Mejoras al Edificio de Biblioteca Municipal

For more information, please contact the Permits and Environmental Compliance Division at environmental g@vivienda.pr.gov or at (787)274.2527 ext. 4320.

Sincerely,

Permits and Environmental Compliance Division Disaster Recovery Office





# **Self-Certification**

# http://www.fws.gov/caribbean/ES/Index.html

# **Endangered Species Act Certification**

The U.S. Fish and Wildlife Service, Caribbean Ecological Services Field Office developed a Blanket Clearance Letter in compliance with Endangered Species Act of 1973, as amended, and the Fish and Wildlife Coordination Act for federally funded projects.

The Service determined that projects in compliance with the following criteria are not likely to adversely affect federally-listed species.

The Puerto Rico Department of Housing (PRDOH) certifies that the following project Plaza Santo **Domingo and Plaza Mariano Quiñones (PR-CRP-000876),** consisting of improvements within the Plaza's perimeter and also outside, partially intervening in some streets and surrounding intersections, the proposed project limits will be partially repaved. In the plazas as such, various repairs are proposed: curbs, low walls, brick paving, river chinos and mortar. The works also include the replacement of the "Canarian" slab. The scope of works also include, electrical improvements, lighting poles, plumbing improvements and drains, changes in the landscaping design and various improvements in concrete and tarnished. The project located at Calle Ruiz Belvis, Plaza Francisco Mariano Quiñones, San German PR, 00683, complies with:

Check	Project Criteria
	1. Street resurfacing.
	2. Construction of gutters and sidewalks along existing roads.
	3. Reconstruction or emergency repairs of existing buildings, facilities and homes.
	4. Rehabilitation of existing occupied single-family homes, and buildings; provided that equipment storage or staging areas are not located on vacant property harboring a wetland and/or forested vegetation and that the lighting associated to the new facilities is not visible directly or indirectly from a beach.
	5. Demolition of dilapidated single-family homes or buildings; provided that the demolition debris is disposed in certified receiving facilities; equipment storage or staging areas are not located on vacant property harboring a wetland and/or forested vegetation.

6. Rebuilding of demolished single-family homes or buildings, provided that the new construction is within the existing footprint of the previous structure and/or within pre- existing grassed or paved areas, and that the lighting associated to the new facilities are not visible directly or indirectly from a beach.	
7. Activities within existing Right of Ways (ROWs) of roads, bridges and highways, when limited to actions that do not involve cutting native vegetation or mayor earth moving; and are not located within, or adjacent to, drainages, wetlands, or aquatic systems. These activities include the installation of potable water and sanitary pipelines.	
8. Improvements to existing recreational facilities, including the installation of roofs to existing basketball courts, provided that the lighting associated to the facilities are not visible directly or indirectly from the beach.	
9. Construction of electric underground systems in existing towns and communities, provided that the property is not a wetland area and the lighting associated to the facilities are not visible directly or indirectly from the beach.	
10. Construction of facilities on vacant properties covered with grasses in urban areas, provided that the lighting associated to the facilities are not visible directly or indirectly from the beach.	
11. Construction of houses, buildings or acquiring lands in urban areas covered by grass for relocation of low-income families and/or facilities that have been affected by weather conditions.	

Ángel G. López-Guzmán Deputy Director

Permits and Environmental Compliance Division

Office of Disaster Recovery

Address: P.O. Box 21365 San Juan, PR 00928 Telephone and Ext: 787-274-2527 ext. 4320 Email: environmentcdbg@vivienda.pr.gov lov. 20,2024

Date

June 12, 2024

# Applicant ID: PR-CRP-000876

Street Address: Pueblo Ward, Ruiz Belvis Street, San German, Puerto Rico 00683

Municipality: San German, Puerto Rico 00683

#### RE: No Effect Determination for PR-CRP-000876

## **EXECUTIVE SUMMARY**

Section 7 of the Endangered Species Act (ESA) mandates that federal agencies ensure the actions that they authorize, fund, or carry out shall not jeopardize the continued existence of federally listed plants and animals or result in the adverse modification or destruction of designated critical habitat. Where their actions may affect resources protected by the ESA, agencies must consult with the Fish and Wildlife Service and/or the National Marine Fisheries Service ("FWS" and "NMFS" or "the Services").

This memo serves to document that the proposed project, PR-CRP-000876, located at Ruiz Belvis Street, San Germán, Puerto Rico (Plaza Santo Domingo Parcel ID #334-034-032-01-000 and Plaza Mariano Quiñones Parcel ID #334-034-019-01-000) was reviewed in accordance with Section 7 of the Endangered Species Act of 1973 (16 USC 1536) as well as the Fish and Wildlife Coordination Act (47 Stat. 401, as amended; 16 U.S.C. 661 *et seq.*) by a qualified Biologist, resulting in a 'No Effect' determination.

The goal of the City Revitalization Program is to help shape and implement the future vision of communities that were affected by Hurricanes Irma and María and will support the municipal governments and other eligible organizations to undertake a variety of recovery activities aimed at reinvigorating downtown areas, urban centers, and key community corridors. As such, The Municipality of San Germán proposes the rehabilitation of the two most prominent public spaces in the city: Plaza Santo Domingo and Plaza Francisco Mariano Quiñones. Both squares make up the urban "backbone" of the town of San Germán.

# **Project Description**

The property, Plaza Santo Domingo and Plaza Francisco Mariano Quiñones, are longitudinal and are bordered by streets on all four sides. Francisco Mariano Quiñones is surrounded by Padre San Agustinos, Ruiz Belvis, De la Cruz streets and an unnamed street space in front of the mayor's office. Plaza Santo Domingo is surrounded by Belvis, Félix Arce Lugo, Yamil Galib and Carro streets. Plaza Mariano Quiñones and Plaza Santo Domingo are surrounded by Ruiz Belvis, Félix Arce Lugo, Yamil Galib and Carro streets. Plaza Francisco Mariano Quiñones covers 1,185 square meters; and Plaza de Santo Domingo comprises 1,209 square meters.

The project scope includes improvements within the Plaza's perimeter and also outside, partially intervening in some streets and surrounding intersections. The street areas within the proposed project limits will be partially repaved. In the plazas as such, various repairs are proposed: curbs, low walls, brick paving, river chinos and mortar. The works also include the

replacement of the "Canarian" slab. The scope of works also include, electrical improvements, lighting poles, plumbing improvements and drains, changes in the landscaping design and various improvements in concrete and tarnished. The Plaza Santo Domingo and Plaza Francisco Mariano Quiñones rehabilitation will take place at the following approximate coordinates:

- Plaza Santo Domingo
   Lambert Coordinates (Datum NAD 83) for the proposed project are: X= 18.082 Y= -67.042
- Plaza Mariano Quiñones
   Lambert Coordinates (Datum NAD 83) for the proposed project are: X= 18.0822 Y= -67.0431

See Site map at Appendix A, Figure 1.

The field observations depicting and clarifying the extend and location of the project activities and a description of observed flora and fauna, are included in Appendix B.

As indicated by the USFWS Official Species List obtained from the Information and Planning Consultation (IPaC) system (Appendix C) and USFWS Critical Habitat Data (Appendix C and Appendix A, Figure 6), the proposed project lies within the range of the following federally listed species and critical habitats:

Federally Listed Species			
Species	Status		
Yellow-shouldered Blackbird (Agelaius xanthomus)	Endangered		
Puerto Rican Boa ( <i>Chilabothrus inornatus</i> )	Endangered		
Critical Habitats			
Yellow-shouldered Blackbird ( <i>Agelaius xanthomus</i> )			

# **Existing Conditions**

The project area consists of approximately 0.59-acres (Plaza Santo Domingo 0.30-acres or 1,209 m² and Plaza Francisco Mariano Quiñones 0.29-acres or 1,185 m²). A topographic map is included (see Appendix A, Figure 1). The project is located in Zone X on the FEMA Flood map and ABFE map, panel number 72000CO1560J dated November 18, 2009 (see Flood Map Appendix A, Figure 3 and ABFE map Appendix A, Figure 4). A Preliminary FIRM has not been developed for this area. There are no wetlands at the project site or within a 500 meters radius of the project site. There are no surface water bodies (natural or manmade) located at the project site or within a 500-meters radius of the project location. The project activities will not occur within a natural or manmade wetland and no direct or indirect impacts are anticipated as a result of the project activities (see wetlands map Appendix A, Figure 5).

# **Species Analysis**

Puerto Rican Boa (Chilabothrus inornatus): The Puerto Rican boa (Chilabothrus inornatus) is endemic to Puerto Rico. It is a large, semi-arboreal nocturnal and nonvenomous snake with color variations from tan to very dark brown and some black body markings. Although the actual life span of Puerto Rican boas in the wild is unknown, some information suggests they may live up to 20–30 years. The Puerto Rican boa is considered a habitat generalist and tolerates a wide variety of habitat types (terrestrial and arboreal) from coastal forest to wet karst and montane forest, along streams, forest and road edges and within rural, suburban and some urban areas. Cave systems and their surrounding forests are identified as particularly important because of the ecological resources available (e.g., prey and shelter) for the Puerto Rican boa. The species is considered widely distributed, but not uniformly abundant across the island. It has been reported in all of the municipalities of mainland Puerto Rico. The Puerto Rican boa\_can persist in fragmented urban landscapes when suitable habitat is available, but\_preferred forest land cover over urban or grassland¹.

Yellow-shouldered Blackbird (Agelaius xanthomus): Known in Puerto Rican Spanish as mariguita de Puerto Rico or capitán, is a species of blackbird endemic to Puerto Rico. It has black plumage with a prominent yellow patch on the wing. Adult males and females are of similar appearance. The species is predominantly insectivorous. The species was once commonly found in the coastal forests of the archipelago of Puerto Rico, but during the early 20th century, these forests were cut down to allow for the development of sugarcane plantations. After the decline of the sugar industry after the 1930s the coastal areas were developed for housing. As a result, the species is now limited to three areas: the islands of Mona and Monito, where a subspecies developed (A. g. xmonensis); the former Roosevelt Roads Naval Station area in eastern Puerto Rico; and the southern Puerto Rican dry forests and mangroves. Although all three locations are considered coastal subtropical dry forests, the species has been observed as far inland as the mountain town of Lares and in subtropical wet forests during the non-breeding season. The species has also been observed at the Cabo Rojo National Wildlife Refuge. The destruction of habitat and brood parasitism by the shiny cowbird (Molothrus bonariensis) led to a drastic population decline. Conservation efforts have population. yellow-shouldered increased the The blackbird breeding season commonly spans from April to August but breeding activity has been observed from February to November. Nests contain from one to four eggs with an average of three. As with other Agelaius species, it usually builds open, cup-shaped nests in trees, but nest locations and shapes may vary depending on location and availability of building materials. The Roosevelt Roads' population builds nests on hollows in dead mangroves, while the Mona subspecies builds nests in ledges or crevices near the coastal cliffs. In all, the species uses eight distinct nesting habitats: mudflats and salinas; offshore red mangrove cays; black mangrove forest; lowland pastures (dry coastal forest); suburban areas; coconut plantations; and coastal cliffs. Building of the nest is performed solely by females while feeding of the young is performed by both sexes. Yellow-shouldered blackbirds

-

<sup>&</sup>lt;sup>1</sup> U.S. Fish and Wildlife Service, Puerto Rican Boa (*Chilabothrus inornatus*) Species Status Assessment, Version 1.2. April 2021

are non-migratory birds, but a portion of the population of the nominate form moves from coastal areas to inland areas during the non-breeding season to feed<sup>2</sup>.

## **Effects Determination**

Based on a review of site photos and other information gathered during a site visit on February 1, 2023 and May 31, 2024, none of the species listed above were observed at the project location and in its vicinity. The species observed at Plaza Mariano Quiñones and Plaza Santo Domingo and adjacent streets are widely distributed in Puerto Rico. No threatened or endangered species was observed at the project site<sup>3</sup>. There are no critical habitats at the project location for the Puerto Rican Boa; however, USFWS indicates the proposed project site overlaps an area identified as critical habitat for the Yellow-shouldered Blackbird. During site visit to the project site (February 1, 2023 and May 31, 2024) the Yellow-shouldered Blackbird (*Agelaius xanthomus*) was not observed. It is important to note that no bird nests were observed at the existing trees on both the plazas. Having carefully analyzed the project site and the information available, including the IPaC species list and available Dkey(s), critical habitat data, nature of the project, previous site disturbance, and scope of project activities, the following effect determinations have been made:

Species	Effect Determination	Conservation Measures to be Implemented (if needed)
Yellow-shouldered Blackbird (Agelaius xanthomus)	No Effect	None Required
Puerto Rican Boa (Chilabothrus inornatus)	No Effect	None Required

William Sarriera

12 June 2024


U.S. Fish and Wildlife Service, Species profile for Yellow-shouldered Blackbird".. Retrieved February 14, 2023. Oberle, Mark (2003). Las aves de Puerto Rico en fotografías (in Spanish). Editorial Humanitas. Raffaele, Herbert A., Una Guía a las Aves de Puerto Rico y las Islas Vírgenes. Publishing Resources, Inc. Princeton University Press. Segunda Edición. 1970.

<sup>3</sup> ACEnvironmental, Flora and Fauna Description, Plaza Santo Domingo y Plaza Mariano Quiñones, San Germán, Puerto Rico. 2024

### Appendix A Figures

#### PR-CRP-000876 PLAZA SANTO DOMINGO and PLAZA MARIANO QUIÑONES

#### FIGURE 1 CRITICAL HABITAT FOR THREATENED & ENDANGERED SPECIES



and that may require special management and protection.

Maxar | Esri Community Maps Contributors, Esri, TomTom, Garmin, Foursquare, SafeGraph, GeoTechnologies, Inc, METI/NASA, USGS, NPS, US Census
Bureau, USFWS

#### PR-CRP-000876


Figure 2 - Aerial photographp

Rehabilitation of Plaza Santo Domingo and Plaza Francisco Mariano Quiñones, San Germán, Puerto Rico

Reference: Google Satellite Hybrid (Imagery date: 05/01/2018)

Source: http://mt0.google.com/vt/lyrs=y&hl=en&x= $\{x\}$ &y= $\{y\}$ &z= $\{z\}$ &s=Ga





#### Legend:

Proposed Project Site

Reference: Google Satellite Hybrid

Project Location: Calle Ruiz Belvis y Calle Arce Lugo, San German, PR

50 0 50 m

100 0 100 200 ft

Appendix B Flora and Fauna Description, Plaza Santo Domingo y Plaza Mariano Quiñones, San Germán, Puerto Rico

Municipality: San German, Puerto Rico

## Flora and Fauna Description Plaza Santo Domingo y Plaza Mariano Quiñones San Germán, Puerto Rico

#### **Project Description**

The Municipality of San Germán has proposed the rehabilitation of the two most outstanding public spaces in the city: the Santo Domingo Plaza and the Francisco Mariano Quiñones Plaza. Both squares make up the urban "backbone" of the town, linked by Ruiz Belvis Street, which they share. Both plazas are longitudinal and are bordered on all four sides by streets. Plaza Mariano Quiñones is surrounded by Padre San Agustinos, Ruiz Belvis, De la Cruz and an unnamed street space in front of the mayor's office. Plaza Santo Domingo is surrounded by Belvis, Félix Arce Lugo, Yamil Galib and Carro streets. Plaza Mariano Quiñones covers 1,185 square meters; Plaza Santo Domingo covers 1,209 square meters. See Appendix A, Figures 1 and 2.

The project proposed here for both spaces includes improvements inside the perimeter and outside, partially intervening some streets and the surrounding intersections. The taxiway areas will be partially repaved. In the plazas as such, various repairs are proposed: embankments, low walls, brick paving, river stones and mortar. The works also include the replacement of canary stone slabs. Electrical upgrades, lighting poles, plumbing and drainage improvements, as well as landscaping changes are part of the scope of work. In addition, various concrete and plastering improvements.

The proposed project area was visited on February 1, 2023 and May 31, 2024. The site is completely developed.

#### **Plaza Santo Domingo**

The flora at Plaza Santo Domingo consists of ten (10) yellow elder or roble amarillo (*Tecoma stans*) trees located on the south side of the Plaza. On the northern side of the plaza, there was one roughbark lignum-vitae (*Guaiacum officinale*) and one red bottlebrush (*Melaleuca citrina*). Table 1 below summarizes the flora species observed at Plaza Santo Domingo.

Table 1 – List of Flora Observed Within Plaza Santo Domingo

Common Name	Scientific Name	References	
Yellow elder or Roble amarillo	Tecoma stans (L.)	Little, Elbert; Wadsworth, Frank; José Marrero, Árboles Comunes de Puerto Rico y las Islas Vírgenes, Editorial de	
Roughbark lignum- vitae or Guayacán	Guaiacum officinale	Ia Universidad de Puerto Rico, 2001  Edwin & García M.O. (1990) Guía ilustrada de yerbas comunes en	
Red bottlebrush or Cepillo de botella	Melaleuca citrina	Puerto Rico. UPR-RCM Colegio de Ciencias Agrícolas / Servicio de Extensión Agrícola.	

The observed fauna at Plaza Santo Domingo was represented exclusively by bird species of wideranging distribution in Puerto Rico. No presence of reptile or amphibian species was observed Municipality: San German, Puerto Rico

during the site visit. Table 2 below summarizes the fauna species observed at Plaza Santo Domingo.

Table 2 – List of Fauna Observed Within Plaza Santo Domingo

Common Name	Scientific Name	References	
Paloma común	Columba livia	Raffaele, Herbert A., Una Guía a las Aves de Puerto Rico y las Islas Vírgenes. Publishing Resources, Inc. Princeton University Press. Segunda Edición. 1970.	

#### Plaza Mariano Quiñones

The flora at Plaza Mariano Quiñones is comprised of eight (8) weeping fig tree (*Ficus benjamina*) trees located on the south side of the Plaza. On the northern side of the plaza, there was one roughbark lignum-vitae (*Guaiacum officinale*) and one red bottlebrush (*Melaleuca citrina*). Table 3 below summarizes the flora species observed at Plaza Santo Domingo.

Table 3 – List of Flora Observed Within Plaza Mariano Quiñones

Common Name	Scientific Name	References	
Weeping fig tree or Ficus tree	Ficus benjamina	Little, Elbert; Wadsworth, Frank; José Marrero, Árboles Comunes de Puerto	
Silver buttonwood tree or Mangle plateado	Conocarpus erectus var. sericeus	Rico y las Islas Vírgenes, Editorial de la Universidad de Puerto Rico, 2001	
Croto or Dracaena	Cordyline fruticose (L.) A. Chev.	Edwin & García M.O. (1990) Guía ilustrada de yerbas comunes en Puerto Rico. UPR-RCM Colegio de Ciencias	
Cape plumbago Isabel Segunda	Plumbago auriculata	Agrícolas / Servicio de Extensión Agrícola.	

The observed fauna at Plaza Mariano Quiñones was represented exclusively by bird species of wide-ranging distribution in Puerto Rico. No presence of reptile or amphibian species was observed during the site visit. Table 4 below summarizes the fauna species observed at Plaza Santo Domingo.

Table 4 – List of Fauna Observed Within Plaza Mariano Quiñones

Common Name	Scientific Name	References	
Rock dove or Paloma común	Columba livia	Raffaele, Herbert A., Una Guía a las Aves de Puerto Rico y las Islas	
Caribbean martin or Golondrina de iglesias	Progne dominicesis	Vírgenes. Publishing Resources, Inc. Princeton University Press. Segunda Edición. 1970.	

#### Applicant ID: PR-CRP-000876

Street Address: Pueblo Ward, Ruiz Belvis Street, San German, Puerto Rico

Municipality: San German, Puerto Rico

#### **USFWS Critical Habitat and Federal Listed Species**

As indicated by the Official Species List obtained from the Information and Planning Consultation (IPaC) system (Appendix C) and USFWS Critical Habitat data (Appendix C, and Appendix A Figure 2), the proposed project lies within the ranges of the following federally listed species and critical habitats:

**Table 5 - Federally Listed Species** 

Species	Status	
Yellow-shouldered Blackbird	Endangered	
(Agelaius xanthomus)		
Puerto Rican Boa	Endangered	
(Chilabothrus inornatus)	Endangered	
Critical	Habitats	
Yellow-should	ered Blackbird	
(Agelaius x	kanthomus)	

The species observed at Plaza Mariano Quiñones and Plaza Santo Domingo and adjacent streets are widely distributed in Puerto Rico. No threatened or endangered species was observed at the project site.

While the USFWS has identify the Puerto Rican Boa (*Epicrates inormatus*) and the Yellow-shouldered Blackbird (*Agelaius xanthomus*) endangered species that might potentially be affected by the proposed project these species were not observed at the project site.

There are no critical habitats at the project location for the Puerto Rican Boa however, USFWS indicates the proposed project site overlaps an area identified as critical habitat for the Yellow-shouldered Blackbird. During site visit to the project site (February 1, 2023 and May 31, 2024) the Yellow-shouldered Blackbird (*Agelaius xanthomus*) was not observed. It is important to note that no bird nests were observed at the existing trees on both the plazas.

#### **Photos**



Photo #1 – Tecoma stans trees at Plaza Santo Domingo.



Photo #2 - Guaiacum officinale tree at Plaza Santo Domingo



Photo #3 - Melaleuca citrina tree at Plaza Santo Domingo.



Photo #4 – Columba livia individuals resting on a building.



Photo #5 - Progne dominicesis individual resting on a cable.



Photo #6 - View of Plaza Mariano Quiñones



Photo #7 - Ficus benjamina trees at Plaza Mariano Quiñones.



Photo #8 - Cordyline fruticose (L.) A. Chev. at Plaza Mariano Quiñones.




Photo #9 - *Plumbago auriculata* at Plaza Mariano Quiñones.




Photo #10 - Conocarpus erectus var. sericeus at Plaza Mariano Quiñones.

Coordinates 18.0819, -67.0420 / 18.0822, -67.0431









Sources: Esri, TomTom, Garmin, FAO, NOAA, USGS, (c) OpenStreetMap contributors, and the GIS User Community, Maxar

#### **Exhibit 10: FARMLAND PROTECTION MAP**

Coordinates 18.0819, -67.0420 / 18.0822, -67.0431





Soil Map-San German Area, Southwestern Puerto Rico (Proposed Project Site) MAP LEGEND MAP INFORMATION The soil surveys that comprise your AOI were mapped at 1:20,000. Area of Interest (AOI) Spoil Area Storry Spot Warning: Soil Map may not be valid at this scale Very Stony Spot Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of confresting soils that could have been shown at a more detailed scale. Wet Spot Soil Map Unit Lines △ Other Soil Map Unit Points se Special Line Features Special Point Features Water Features (D) Blowout Please rely on the bar scale on each map sheet for map measurements Streams and Canals Borow Pit Clay Spot Source of Map: Natural Resources Conservation Service Web Soil Survey URL: Coordinate System: Web Mercator (EPSG:3857) +++ Rails Closed Depression US Routes Maps from the Web Soil Survey are based on the Web Mercator maps from the version and solvey are based on the version whe date projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equil-area conic projection, should be used if more accurate calculations of distance or area are required. Gravelly Spot Major Roads ☐ Landil Local Roads A Lava Flow Background This product is generated from the USDA-NRCS certified data as of the version date(s) listed below Marsh or swamp Mineor Quarry Soil Survey Area: San German Area, Southwestern Puerto Ric. Survey Area Data: Version 15, Sep 10, 2024 Miscellaneous Water Perennial Water Soil map units are labeled (as space allows) for map scales 1:50,000 or larger Rock Outcrop Date(s) serial images were photographed: Jan 23, 2022-Mar I \_\_ Saline Spot Sandy Spot The orthophotoor other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident. Severely Eroded Spot Sinkhole Sideor Sip Sode Spot

Soil Map—San German Area, Southwestern Puerto Rico Proposed Project Site

#### Map Unit Legend

Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI
Ua	Urban land	1.5	100.0%
Totals for Area of Interest		1.6	100,0%

Natural Resources
Conservation Service

Web Soil Survey National Cooperative Soil Survey 10/31/202



Reference: Soil Map—San German Area, Southwestern Puerto Rico National Resource Conservation Service Web Soil Survey Source:


U.S. Department of Agriculture
National Resource Conservation Service Web Soil Survey
https://websolsurvey.nrcs.usda.gov/app/WebSolSurvey.aspx


Author: Edgar Vázquez Date: October 31, 2024 Farmland Protection (Soil Map)
Plaza Santo Domingo and Plaza Mariano Quiñones
PR-CRP-000876
Municipality of San Germán




Scale: As shown









Junta de Planificación, FEMA Maxar | PRPB; FEMA | Junta de Planificación. Programa de Sistema de Información Geográfica |



Executive Director | Carlos A. Rubio Cancela | carubio@prshpo.pr.gov

August 19, 2025

#### Lauren B Poche

269 Avenida Ponce de León San Juan, PR 00917

Referencia: SHPO-CF-07-28-25-02 - PR-CRP-000876 (San Germán), Plaza Santo Domingo and Plaza Francisco Mariano

Dear Ms. Poche,

We have reviewed the archaeological monitoring plan, dated July 17, 2025, prepared for the above referenced project. The plan is deemed acceptable.

If you have any questions regarding our comments, please do not hesitate to contact our Office.

Sincerely,

Carlos A. Rubio Cancela

Couly afaction

State Historic Preservation Officer

CARC/GMO/MB

YOARRES ES





March 24, 2025

Samir El Hage Arocho General Partner, HORNE LLP 269 Juan Ponce de León Ave. Hato Rey, Puerto Rico 00917-00918

Via email: <a href="mailto:samir.elhage@horne.com">samir.elhage@horne.com</a>

RE: Authorization for Grant Management (GM) to Conduct the Required Environmental Consultations with Federal and Local Agencies on PRDOH's Behalf

Dear Mr. El Hage,

Provisions at 24 C.F.R. Part 58 establish the environmental review procedures for entities assuming the U.S. Department of Housing and Urban Development (HUD) environmental responsibilities under the National Environmental Policy Act (NEPA) and other applicable laws. The Puerto Rico Department of Housing (PRDOH), as the designated CDBG-DR/MIT grantee, has assumed HUD's environmental responsibilities under NEPA and related laws (Responsible Entity) by directly implementing multiple CDBG-DR/MIT projects.

One of the Responsible Entity's many responsibilities under 24 C.F.R. Part 58 is consulting with State, Federal, and non-federal entities in preparing an Environmental Review Record (ERR). Regarding a Responsible Entity's interactions with State, Federal, and non-Federal entities, 24 C.F.R. § 58.14 states that:

A responsible entity shall consult with appropriate environmental agencies, State, Federal and non-Federal entities and the public in the preparation of an EIS, EA or other environmental reviews undertaken under the related laws and authorities cited in § 58.5 and § 58.6. [...].

In conducting its role as a Responsible Entity that directly undertakes a project, as per 24 C.F.R. § 58.4(b)(1), PRDOH "must assume the environmental review responsibilities for the State's activities and those of any non-governmental entity that may participate in the project." Accordingly, a Responsible Entity may delegate certain tasks in the preparation of ERRs but retains full legal responsibility for compliance with environmental requirements.

To effectively manage available environmental resources and expedite the preparation of ERRs, PRDOH—as Responsible Entity—wishes to delegate the task of consulting with State, Federal, and non-Federal entities contained in 24 C.F.R. § 58.14. Therefore, PRDOH hereby authorizes Alberto Mercado Vargas, GM Environmental SME, or his authorized representative) to conduct on its behalf the environmental consultations with Federal and local agencies required to prepare ERRs for the implementation of CDBG-DR and CDBG-MIT projects, while still maintaining the ultimate and full legal responsibility for compliance with environmental requirements. This authorization extends to both early and formal consultations before Federal agencies such as the U.S. Fish and Wildlife Service (USFWS) and the State Historic Preservation Office (SHPO), among others required for compliance with applicable laws and regulations as established in 24 C.F.R. § 58.14 and § 58.5. GM should include and copy the PRDOH Environmental Division in all communications with Federal and local agencies for these purposes.

PRDOH appreciates GM's commitment to Puerto Rico's recovery and is confident in its ability to execute this task effectively. Please feel free to contact me with any questions.

Sincerely,

Ciary Pérez Peña

Secretary

Puerto Rico Department of Housing

Cc. Alberto Mercado Vargas GM Environmental SME

alberto.mercadovargas@horne.com



July 28, 2025

Carlos A. Rubio Cancela
State Historic Preservation Officer
Puerto Rico State Historic Preservation Office
Cuartel de Ballajá (Tercer Piso)
San Juan, PR 00902-3935

PUERTO RICO DISASTER RECOVERY, CDBG-DR CITY REVITALIZATION (CITY-REV)
PROGRAM

RE: SHPO-CF-05-23-25-01- PR-CRP-000876, PLAZA SANTO DOMINGO AND PLAZA FRANCISCO MARIANO, SAN GERMÁN, PUERTO RICO - ARCHAEOLOGY MONITORING WORK PLAN SUBMISSION

Dear Architect Rubio Cancela,

On behalf of the Puerto Rico Department of Housing (PRDOH), we thank you for your letter dated June 12, 2025, in response to the submission of documentation for PR-CRP-000876, Plaza Santo Domingo and Plaza Francisco Mariano project. The letter stated your office had determined your records supported the finding of no adverse effect for the proposed undertaking conditioned to archaeological monitoring during all ground disturbing activities for the project.

As such, we are submitting the requested Archaeological Monitoring Plan prepared by Archaeologist Roberto G. Muñoz-Pando and Archaeologist Victor Oppenheimer.

We are requesting your review of the prepared plan and concurrence that the implementation of the plan is appropriate for the undertaking.

Please contact me with any questions or concerns by email at <a href="mailto:kristin.sanders@horne.com">kristin.sanders@horne.com</a> or phone at 225-276-2109.



Kindest regards,

Kristin P. Sanders

Historic Preservation Manager

Lusten P. Sonders

Attachments

# PRDOH CDBG-DR CRP PROGRAM Remodelación de la Plaza Santo Domingo y Plaza Francisco Mariano Quiñones

## en el Municipio de San Germán, Puerto Rico

PR-CRP-000876/ SHPO: SHPO-CF-05-23-25-01 / CP-PAE: PENDING / OGPe: PENDING

# **Archaeological Monitoring and Protection Plan**





Prepared by:

Roberto G. Muñoz-Pando, PhD Archaeologist - **Tetra Tech, Inc.** Victor Oppenheimer Archaeologist - **Tetra Tech, Inc.** July 17<sup>th</sup>, 2025.

#### I. PREAMBLE

The Municipality of San Germán was approved Community Development Block Grant disaster recovery funds financed by the Federal Department of Housing and Urban Development in the aftermath of damages received by the 2017 Hurricanes Irma and Maria. An Agreement was established with the Puerto Rico Department of Housing (PRDOH) for the City Revitalization Program funds as part of the Community Development Block Grant for Disaster Recovery (CDBG-DR) Program. The Municipality of San Germán was approved to rehabilitate and renovate (*Remodelación de la Plaza Santo Domingo y Plaza Francisco Mariano Quiñones en el Municipio de San Germán, Puerto Rico*) and strategically restore it as a resilience area for the community, while preserving the historic development of the space and of the Municipality of San Germán (Figure 1). The Puerto Rico State Historic Preservation Office (PRSHPO), in a letter dated (*June 12, 2025*), concurred with a decision of No Adverse Effect for this undertaking, conditioned to the implementation of an archaeological monitoring during all ground disturbing activities.



**Figure 1: General Project Location in the Satellite Image** 

**Figure -1-**Aerial shot of the General Project Area. (GoogleEarth 2016) (from Jorge Rigau 2022 Schematic Drawings 30%: p. 1)

Figure 2 - Aerial photographp
Rehabilitation of Plaza Santo Domingo and Plaza Francisco Mariano Quiñones, San Germán, Puerto Rico
Reference: Google Satellite Hybrid (Imagery date: 05/01/2018)
Source: http://mt0.google.com/vt/lyrs=y&hl=en&x={x}&y={y}&z={z}&s=Ga






Figure 2: Project Location in the Aerial Map with the direct APE delimitated in red (from Rigau, Jorge and Tamara Gonzalez Vega 2024: p. 45 of the EDF)




Figure 3: Project Parcel Location at the 7.5-Minute Topographic Map with the direct APE delimitated in red (from Regis Martinez, Schmid, Rivera Calderón and Muñoz-Pando 2024: p. 47 of the EDF)

The objectives of this archaeological monitoring plan are: (1) to establish the protocol to be followed in archaeological monitoring; (2) to establish the protocol to be followed if previously unknown resources are identified; (3) to establish the protocol to be followed if there are any unexpected or previously unanticipated adverse effects; (4) to establish the protocol for cleaning the culverts, (5) to establish the parameters for documentation and evaluation of the structures, and (6) to establish the consultation protocol to be followed in case the structures require major repairs. The objectives of archaeological monitoring, according to ICPR Regulation #8932 are: (1) To locate, evaluate and document archaeological resources during project development; (2) To recover as much archaeological information and materials as possible during excavation and construction work; (3) To conserve and enhance the value of the archaeological resources located and documented; and (4) In the event that the archaeological resource cannot be conserved in situ, to conserve it through documentation.

This document complies with applicable federal and state laws, regulations, and guidelines, and is consistent with the Secretary of the Interior's (SOI) Guidelines for Archeological Documentation, the Advisory Council on Historic Preservation's (ACHP) recommendations on the recovery of significant information from archaeological sites as updated in 2009, and Regulation #8932 of the Institute of Puerto Rican Culture (IPRC). The plan was prepared by archaeologists Roberto G. Muñoz-Pando, and Víctor Oppenheimer Rodriguez, who meet the Professional Qualifications Standards set forth in 36 CFR Part 61 to conduct Phase I, Phase II, Phase III studies and Archaeological Monitoring of Projects.

This scope of work is divided into six (6) sections and one (1) appendix. The section following this preamble includes a brief description of the project area and discusses the proposed construction works. In the third section the archaeological potential of the project area is discussed. The fourth section provides a detailed description of the archaeological monitoring procedure to be carried out before, during and after the construction works. Section V includes the professional qualifications of the team that will implement this monitoring plan and the last section includes the references cited. The plan closes with an appendix with a model of a monitoring daily activity sheet.

#### II. PROJECT DESCRIPTION

The Municipality of San Germán proposes the rehabilitation of the two most prominent public spaces in the city: Plaza Santo Domingo and Plaza Francisco Mariano Quiñones. Both squares make up the urban backbone" of the town, they run in an east-west direction, are linked by the Ruiz Belvis Street and around we find several of the emblematic structures of "La Ciudad de las Lomas": the Church of San Germán de Auxerre, Porta Coeli, the original City Hall and several notable residences, among them, the old House of Waldemar Morales in the "Queen Ann" architectural style, the house of Ernestito Quiñones and the so-called Casa de las Bahr. Both squares are longitudinal and are bordered by streets on all four sides. Mariano Quiñones Square is surrounded by Padre San Agustinos, Ruiz Belvis, De la Cruz streets and a street space without its own name in front of the former mayor's office. Both squares are longitudinal and are bordered by streets on all four sides. Mariano Quiñones Square is Plaza Santo Domingo is surrounded by Belvis, Félix Arce Lugo, Yamil Galib and Carro streets. Plaza Mariano Quiñones covers 1,185 square meters; the Plaza de Santo Domingo comprises 1,209 square meters.

The proposed intervention for Mariano Quiñones Plaza and Santo Domingo Plaza, the pair of emblematic public spaces in San Germán, comprises improvements within their plans. The project respects the general appearance of both spaces, maintaining and repairing their paving, planters, vegetation, and sculptural elements; also restoring most existing materials and finishes. In parallel, selective technical and aesthetic improvements are incorporated for better functionality and appearance, including new lighting posts and benches. This project aims to attract more people to both plazas. In Mariano Quiñones Plaza, a gazebo will be re-incorporated to evoke one that previously existed there to encourage varied programming of various public activities. In Santo Domingo Plaza, we propose placing a pedestal clock that, visible from both

plazas, will strengthen the spatial connection between them. At its east and west ends, new benches will be added for the enjoyment of the surrounding architecture. The footprint of each plaza will remain as is, not increased or reduced. The project includes construction work, repairs, improvements, material removals, and minor excavations in both plazas, partially intervening in surrounding streets, intersections, sidewalks, curbs, and gutters. The specific nature of the work to be carried out is detailed ahead. As part of the project, safety measures will be implemented in compliance with federal and local regulations for pedestrians, cyclists, and vehicular traffic in this area.

**Existing conditions in streets:** The proposed project includes the repaying of the streets surrounding both plazas and improvements to the adjacent sidewalks. The limits of this intervention are established in the project's Situation Plan SHEET A-01.

Existing conditions in the plazas; Currently, both plazas are in use and host various events: craft fairs, gastronomic celebrations, commemorations, and musical performances. Activities tend to be held more in the *Plaza de Santo Domingo* than in the *Plaza Mariano Quiñones*, as the former is longer and leveled, with several active establishments around. Both plazas are elevated from the street level that surrounds them and are accessed by steps whose number and height vary according to the elevation. Each plaza features vegetation, shrubs, planters, benches, and light posts. Not all light posts are working, and several are missing pieces. The brick paving and planters have suffered excessive wear to the point that, at ground level, the loss of material represents a danger. In *Plaza Mariano Quiñones* (still paved with mortar and imitating Canary Islands tile) there is a kiosk to the northeast that remains part of the project. At center, a grass rectangle is the footprint of the fountain that was once located there.

On both sides of *Plaza Santo Domingo* (north and south), pedestals lined up hold busts of illustrious city personalities. The pedestals are clad in marble, with little detail. Through the center of the plaza, at ground level, runs a marble pavement with carved phrases alluding to the history of San Germán. These pieces were installed to cover a "water thread" that was part of the previous remodeling of the space under the former "*Directoría de Urbanismo*". The workmanship was not the best; the water channel was "filled in" without achieving a homogeneous character. It now appears to be "patched".

**Existing conditions in sidewalks, curbs, and gutters:** Currently, the sidewalks are paved with brick, originally bound by mortar. There are numerous instances of hollows, impacts, breaks, and wear. The loss of material is notable in various instances and represents a risk for pedestrians walking on them. In various locations, the lack of mortar adds to the insecurity of passersby. The concrete curbs show some breaks and cracks, but they do not need to be replaced, only repaired. The depth of the existing brick gutters contributes to the insecurity of those wanting to cross the street.

**Proposed improvements for the streets:** The project includes replacing the existing paving material (river pebbles and bricks) on the roadways around both plazas. While the finish adopted in the 1980's was based on replicating the character of the streets at a given point in the town's history, this project echoes another stage in the town's history: those times when the streets of the population were of covered with compacted earth. We will keep the existing concrete slab in place, without the need to dig under it. The river pebbles and bricks will be removed, disposing of the gravel in an authorized landfill or officially using it as fill for some municipal project soon.

After cleaning and scarifying the concrete slab that is to remain, a 2-inch layer of Surface Deactivator brand cementitious mortar with resistant aggregates, Color 306 Toffee, will be applied. The texture, color, and appearance of the material evoke the character of the compacted earth in driving areas that, for a long time, remained unpaved in our towns, including in San Germán. This new layer will be solid and leveled to eliminate the problem of pebble detachment and brick breakage; it will include segments to be repaved in brick and the restoration of several of the existing sections. The material meets the specifications for use

on roadways. Thus, we will improve the durability and resilience of the work, within a framework of historical veracity. We avoid using, as others have done, fragile pieces that yield or break under the weight and passage of cars and trucks, whose impact was not contemplated years ago.

It is worth mentioning that, although the 1980's renovation was encouraged by a given historical intention, the products used, their quality, and their installation proved to be ineffective, unconvincing, and less durable than expected. We are unaware of the circumstances at that time, but we mention it because the finish now proposed will allow us to address similar conditions with greater flexibility. As the application of this material will be done without removing the concrete slab that served as the base for the works in the 1980's, no excavation will be required for these works.

Proposed improvements for sidewalks, curbs, and gutters: The project does not contemplate any change in the geometry of the streets or sidewalks. The existing brick paving on the sidewalks will be maintained, filling in the cracks and hollows with mortars of a composition like the physical constitution of the clay. To this end, preliminary tests will be conducted on-site to corroborate differences in consistency and hue. There is no plan to demolish the existing concrete curbs, only if one, unexpectedly, should present a problem during construction. In that case, authorities would be consulted before any action is taken. The existing gutters, furbished with clay tiles, were built deep, posing a fall risk for pedestrians. Where the streets are repaved, the gutters will be reconstructed in the same cementitious material to be applied to the street, removing the current brick facings, and improving their slope to prevent falls. Many of the improvements proposed by this project aim to minimize the difficulties currently confronted by pedestrians, but in-keeping with the historical bearing of San Germán.

Proposed works for Plaza Mariano Quiñones: At Plaza Mariano Quiñones, pavements and the walls of the low planters will be repaired. All bricks with cracks and hollows in the low walls of the planters have been meticulously documented and identified to be filled with a compatible mortar. Repairs will be carried out on-site, inside and outside the perimeter of the space. Low walls will not be demolished, only two small segments to accommodate the circular benches at each end of *Plaza Santo Domingo*. In both plazas, low walls will be maintained and repaired. The eight (8) concrete benches lining the perimeter of the plaza will be rehabilitated. The current appearance of these benches corresponds to a previous intervention of a crude nature. Built using integral terrazzo, these pieces are of poor quality, with an out-of-scale thickness and clumsy handling of the terrazzo joints when the material changes color. Included in these planters are healthy and attractive trees that currently contribute to the aesthetics and shade of the plaza. These trees will be maintained.

Taking everything into account, the project proposes rehabilitating each concrete bench by removing the seating component, restructuring the base of the planter to include a new backrest and "arms" (as a niche) to now include a traditional bench that will introduce a more human scale in line with the scale and character of the city and its history. The terrazzo bench seats will be partially removed but retaining the planters and the existing trees on them. We now propose - in contrast to the crude treatment of these pieces in situ - to promote a more diverse, sculptural use of the benches with an area to place food, computers, shopping bags, or also for sitting. New lighting posts (of traditional design) will replace the existing ones in the same place where previously posts were located. A concrete gazebo will be incorporated, evoking a previously existing one that was in the same plaza at the beginning of the 20th century and served as a stage/platform for musical groups and performances.

Photos from the era illustrate the hierarchical presence of the former gazebo in the space. The new gazebo has been designed in concrete with steel details, railings, and a functional "ring" to hold lighting equipment.

It includes an access ramp and electrical facilities for lighting and sound. In the area where the gazebo is to be erected, already exists an electrical connection from an old fountain, therefore digging will not be required to incorporate new electricity conduits. The foundations of the gazebo will reach one foot (1'-0") below the surface, without the need for further excavation.

Around the gazebo, "losa canaria" paving will be incorporated where there is now "argamasa". Work in the plaza includes providing Canary Island tile where it is broken, battered, or simply missing. This happens particularly in pieces around the perimeter. Mortar in the joints will be removed to facilitate the extraction of these pieces; the mortar that appears underneath will be removed, this material will be disposed of, surfaces cleaned, and new tiles will be installed after identifying the correct color so that the new mortar matches the original. Once the tiles are installed, the work done will be protected from the weather until it consolidates. The "losa canaria" tile also appears as edging or frieze and steps along the plaza.

**Proposed works for Plaza Santo Domingo:** In Plaza Santo Domingo, the low walls of the planters will also be repaired on site, without demolishing them, except for brief segments to be substituted by curved ones. The broken and perforated bricks will be filled-in with a mortar mix, designed for this purpose. Where the brick is in critical condition, it will be replaced with a similar, new one or recuperated.

The plaza will incorporate benches and posts like those proposed for Plaza Mariano Quiñones. The central section of the space will be repaved with honed granite slabs, 1'-8"x 0'-10" each, and a polished peripheral strip of 1.5" and a frame in mortar panels measuring 1'-6" x 0'-6". The aim is to create a homogeneous environment, something that was not achieved when covering the "water thread". Then, cuts to the existing bricks were made with little delicacy, as well as in the application of mortar. Both ends of what was the old Parque de Santo Domingo will be reorganized to improve the spatial connection with what happens to the east and west of the plaza. At each end of the space, a semicircular bench (in concrete) will be placed, which, along with a pair of lighting posts (like the rest), will frame the entrance to the plaza. To the west, the bench incorporates a pedestal clock, around which visitors can sit, children can play, and visitors can take photos. To the east, the bench is oriented towards Porta Coeli, thus highlighting the presence of the monument in the urban space. The turn of the bench suggests that the end of the plaza figuratively becomes the atrium of Porta Coeli. The existing vegetation in the plaza will be maintained, reusing the already existing infrastructure facilities, improving the electrical wiring (without digging) and a water outlet. The marble veneers of the sculpture pedestals and busts will be repaired, applying conservation techniques for the correct treatment of marble and bronze.

**Infrastructure:** Minor electrical improvements are part of the scope of work, as the existing installations will be utilized, such as the one running from the old town hall westward to reach the very center of *Plaza Mariano Quiñones* where the gazebo will be erected. Excavations for electrical piping are not contemplated. The new wiring will run through conduits already in place. The lighting posts will be placed where the previous ones were, except for four (4) new ones to be located at both ends of *Plaza Santo Domingo* (2 + 2). These are not solar posts. We have already considered that to wire these, the electrical installations can run through the planters next to each of them. The project does not include improvements related to plumbing, drains, or sewers.

#### **Excavations and removals:**

Site Assessment & Planning: Prior to any removal work, a thorough site assessment will be conducted to evaluate existing conditions and identify potential hazards. Engineers and environmental experts will assess the site for contaminants like asbestos, lead, or other hazardous materials, requiring proper handling and removal. Contractor and Municipality will outline a proper sequence of components removal, ensuring implementation of safety measures, and approved waste disposal procedures. The Municipality will require

the Contractor to provide evidence of proper and legal disposition of any removed materials. Removal and substitution work to be carried out inside the plaza will be performed with lightweight equipment considering not to damage any possible important elements below ground. Contractor shall take special precautions on areas identified as sensitive: environmental, architectural, and archeological.

During the construction process, erosion and sedimentation control measures will be implemented to avoid the discharge of sediments into road surfaces, sidewalks, and the storm sewer system during rainfall events. These will include installation of hay bales (or silt socks) on drainage structures, provision of a silt fence around the project limits, and implementation of a washout entrance for trucks to avoid sediments migrating into the streets. Staging and storage areas for construction materials will be protected with a silt fence. We propose that the street in front of the old town hall, east of *Plaza Mariano Quiñones*, be used as staging area, as it would be at a reasonable distance between both plazas and in a space that would not significantly alter traffic. Construction equipment and materials will be stored outside both plazas, avoiding possible adverse impacts to the already paved surfaces. A Maintenance of Traffic Plan (MOT) and temporary control devices will be implemented to control vehicular traffic and provide a safe route for pedestrians during construction of the project. The MOT will be prepared in compliance with the PRHTA and FHWA standards and regulations. Streets, sidewalks, and plazas have been subjected to multiple interventions over the years. In contrast, this project proposes the removal of some surface elements and minimal excavations.

#### Streets, Gutters, and Sidewalks

1. Asphalt and "chinos de río" (pebble stones; stone pavement) will be removed using an excavator or jackhammer; when needed, by hand. The existing concrete slab will not be demolished. Debris will be transported off-site by dump truck to a preapproved location. Depth of stones to be removed: 0'-02". Area: 3,560 sq. mts.

#### Mariano Quiñones Plaza

- 1. Excavations for footings for the construction of the gazebo. Depth 1'-0" x 0'-6" x 53'-0"; Area: 232 sq. ft.
- 2. Removal of the curved seats of the integral terrazzo benches. 18 sq. ft. per bench (8 benches = 144 sq. ft.)
- 3. Removal of existing mortar in the central area (not including the concrete slab that serves as a base). Depth: 2'-0"; Area: 100 sq. mts.

#### Santo Domingo Plaza

- 1. Excavation to remove the central pavement strip running east/west. Depth: 0'-11/2" and Area: 86 sq. mts.
- 2. Excavation for new foundations for the four (4) lighting posts: 1'-0" x 4'-0" = 4'-0"
- 3. Excavation for footings of the semi-circular benches/planter; 30 sq. ft.
- 4. Excavation for the footing of the pedestal clock: 10'-0" sq. ft.
- 5. Damaged bricks and marble slabs will be removed, without demolishing the concrete slab beneath. Removal of tree stump remnants in planters by grubbing.

Landscaping: The existing vegetation, including trees, shrubs, and grass, will be preserved. The Municipality is committed to strengthening the plant material already on-site once the planters are rehabilitated. No excavation is contemplated for these purposes, except for planting. The Municipality of San Germán will require the project contractors to present evidence of the legal disposal of debris and gravel. measures will be implemented to avoid the sediments to discharge into the road surface and storm sewer system during rainfall events, including installation of hay bales (or silt socks) on drainage structures, installation of silt fence around the project limit, and implementation of a washout entrance for trucks to

avoid sediments migration into the streets. The staging area for the construction equipment and materials will be located at Betances Street. Construction equipment and materials will be storage outside the plaza area, avoiding possible adverse impacts to the Plaza surface. Staging and storage areas for construction materials will be protected with silt fence. A Maintenance of traffic plan and temporary control devices will be implemented to control the vehicular traffic and provide a safe route to pedestrians during the construction works.

#### **AREA OF POTENTIAL EFFECTS:**

As defined in 36 CFR §800.16(d), the area of potential effects (APE) is the geographic area or areas within which an undertaking may directly or indirectly cause changes in the character or use of historic properties if any such properties exist. Based on this definition and the nature and scope of the Undertaking, the Program has determined that the direct APE for this project is Plaza Santo Domingo and Plaza Francisco Mariano Quiñones footprint, or 2,394 square meters and the visual APE is the viewshed of the proposed project.

Mariano Quiñones Plaza is surrounded by Padres Agustinos street (to the north), Ruiz Belvis street (to the south), De la Cruz street (to the west), and a stretch of a street with no name in front of the former town hall (to the east). Santos (to the south), Yamil Galib street (to the east), and Carro street (to the west). The project includes the rehabilitation of both plazas, their surrounding streets, and sidewalks up to the area where they intersect, defined by brick pavement strips as illustrated and explained later. According to *CRIM*, Mariano Quiñones Plaza covers 889.75 square meters. Santo Domingo Plaza consists of two parcels: Parcel 334-034-032-01 occupies 355.61 square meters, and Parcel 334-034-033-01 occupies 308.93 square meters. However, the current area of this plaza exceeds the sum of the two parcels. In the past, a street ran between the two parcels. The street was eliminated, and its space was joined to both parcels to grant continuity to Santo Domingo Plaza, thus reaching its current size. We have not referred here to any to deed documents since the Municipality of San Germán does not have them.

The APE considers repairs/Improvements of the Plaza Santo Domingo and Plaza Francisco Mariano Quiñones in the same location, the APE for visual effects is within the geographic area of the project and does not have the potential to introduce visual elements that diminish or alter the setting, including the landscape, where the setting is a character defining feature of a historic property that makes it eligible for listing on the National Register. The visual effects of the APE for the repairs/Improvements of the Plaza Santo Domingo and Plaza Francisco Mariano Quiñones will be visible from all the NRHP-eligible and listed properties. The Visual or Indirect Areas of Potential Effect of the proposed project are not within the immediate physical footprint of the project. The consequences of the indirect APE will be during the construction phase only due to changes in aesthetics or disruptions to local transit that may extend beyond the project's physical boundaries. Access roads and staging areas will be coordinated to minimize the disturbance in the traditional urban center. The proposed design considers the urban scale in relation of the surrounding setting.

As the plazas (APE) are a public space serve as hubs for civic activities and provide resources to the community. The proposed project will enhance historical significance using 21st century design strategies and is not expected to compromise the traditional urban center and listed or eligible properties.

## III. ARCHAEOLOGICAL POTENTIAL AND HISTORIC PROPERTIES

The information below is taken from the Section 106 NHPA Effect Determination Form completed by architect José Rigau and archaeologist Tamara Gonzalez Vega in 2024.

#### **Identification of Historic Properties - Archaeology**

Existing information on previously identified historic properties has been reviewed to determine if any such properties are located within the APE of this undertaking. The review of this existing information, by a Program contracted Historic Preservation Specialist meeting the Secretary of the Interior's Professional Qualification Standards (36 CFR Part 61), shows that the project area is within the San Germán Historic District listed (1024-0018).

Partido de San Germán, Villa de San Germán de Auxerre, Nueva Salamanca, Ciudad de las Lomas and is roughly bounded by Luna, Estrella, Concepción, Javilla, and Ferrocarril streets in the western section of San Germán, Puerto Rico. The proposed project is within the Traditional Urban Center of San Germán. San Germán has a great number of archaeological sites and historic structures. The National Register of Historic Places nomination lists 152 resources contributing to the historic significance of the area, including Plaza Santo Domingo and Plaza Francisco Mariano Quiñones, where the proposed project will be located.

#### Possibility of pre-Hispanic archaeological findings

From the analysis of the inventory of archaeological resources and the reports consulted, it emerges for the territory of the municipality in San Germán Historic District no specific evidence of indigenous occupation has been found. However, the absence or presence of pre-Hispanic archaeological material within the APE cannot be empirically determined. To carry out an archaeological sensitivity analysis of the APE, it is important to keep in mind that San Germán in its different locations was one of the places that was part of the early Spanish colonization in Puerto Rico, so we would be looking for material elements that represents interactions between Spaniards and natives in the early period of the conquest and European colonization.

#### **Spanish Colonial Period:**

#### San German Historic District

The San Germán Historic District encompasses an area of approximately 35.8107 acres. The city's layout presents an uneven grid pattern with streets oriented along the cardinal points. Its modern axis, Calle Luna (PR #102) bisects the east-west grid. This was the old road that linked the Villa with the town of Sabana Grande and the city of Mayagüez. To the north, other important streets of the urban nucleus run: Santiago Veve (formerly Comercio) and Estrella Streets. Until the mid-19th century, the latter were the main boundaries of the city's organization chart, expanding southward once the Manzanares Creek was controlled by the construction of vaulted storm sewers, completed in the 1850's. There is no clear distinction between residential and other areas, although in the past most of the main commercial establishments were lined along Luna, Santiago Veve and Ruiz Belvis streets.

San Germán today has two main open spaces, Plaza Francisco Mariano Quiñones or main square (bounded by Carro, José Julián Acosta, Ruiz Belvis and Cruz streets), and the Plazuela de Santo Domingo (bounded by Carro, Santiago Veve, Ramas and Ruiz Belvis streets). The importance of these sites to the overall appearance of the district and the layout of the city's design cannot be underestimated.

In Latin American cities, plazas fulfilled at least two functions. Squares were focal points for the distribution of urban space, in a coherent and hierarchical whole, where social and political activities were organized. The spaces around the main square were reserved for state buildings and ecclesiastical authorities. Thus, the parish church is located on the western edge of the Plaza Francisco Mariano Quiñones, while the Mayor's Office is located at the opposite end. Thus, the first ordinances of the city reserved the spaces around the plazas for the "well-bred" inhabitants and commerce. As there was no strict delimitation of areas within the heart of the old city, the plurality of functions, and its long period of continuous constitution makes the historic center a mixture of widely differentiated architectural styles ranging from early Spanish Colonial architecture, such as the Porta Coeli Chapel (1606), to Neoclassical, Neo-Gothic, and Queen Anne, among others. Interspersed with these structures, there are structures reflecting Spanish Revival and Art Deco, and structures of more recent construction characterized by a non-descript style. Sixty percent of the buildings within the San German Historic District contributing as resources for inclusion in the NRHP. Approximately 50% of the contributing resources were built between the 1860s and 1920s, a period characterized in Puerto Rico's urban and architectural history as one of intense development and experimentation. Most of them are built with traditional materials, such as masonry, brick, and wood, while in the early 20th century there was an increased use of new materials, such as concrete, particularly since the earthquake of 1918 and the severe hurricanes that occurred between 1899 and 1930.

The architectural vocabulary is very broad. The general character of the core has not undergone serious alterations in terms of street layout and the ratio of open public spaces to build area. Although new structures have altered the physiognomy, enough buildings remain to maintain its historic appearance. Finally, as noted above, the visual and spatial sense derived from the urban core remains one that presents coherence and architectural value unique to San Germán. In the late 18th and early 19th centuries, the city had two main open spaces. One was the Plaza del Rey, the other was the Plaza Principal which has been known as Plaza Mayor, Plaza Principal, Plaza Vendimia, Plaza Automática, Plaza General Contreras, and today, Plaza Francisco Mariano Quiñones. It seems that before the construction of the Mayor's Office in 1844, the Plaza was much larger and extended as far as the Porta Coeli Chapel, while today, the old Government Building and Carro Street divide this area into two unequal open spaces.

Public open spaces are crucial to the urban character of the San Germán Historic District, as they lend coherence to the urban grid and present the viewer with an unobstructed view of some of the city's most significant buildings. The Plaza served a crucial commercial function for the small retailers of goods gathered there for the Sunday market. Efforts to improve the streetscape that characterized the second half of the 19th century included the leveling of the plaza, repair work on the surrounding streets and sidewalks. On the other hand, the placement of "chinos de río" [pebbles as paving in the plaza was approved in 1851, and gas lighting was installed in 1860. By 1890 the plaza had undergone other alterations, perhaps the most important of which was the transfer of the Sunday market to the Little Plazuela Santo Domingo, behind City Hall. As a result of the modifications to the city plan, the two main open spaces became three, as the Plazuela Santo Domingo took shape after the construction of Alcaldía y Carro street. This small rectangular plaza was once part of the main square. At the end of the 19th century, it replaced the main square as the city's Sunday market. The Plazuela became the park filled with trees and shrubs that contrasted with the plaza. Plazas used to be reserved for public gatherings and collective affairs, while places like the Plazuela were dedicated to activities of a more individual nature sitting on benches, strolling, reading or just relaxing. The close relationship between the Catholic Church and the State, which characterized the Spanish period, and symbols of political and ecclesiastical authority dominate one or more sides of the plazas. In the Plazuela Santo Domingo, the outstanding building is the Chapel of the former Dominican Convent, while the Cabildo and the Parish Church face across the main square, and the Hospital de la Concepción and the Casa del Rey were built facing one side of the former Plaza del Rey. In a sense, the same pattern prevailed during the first decades of the United States government. Thus, public schools replaced some of the symbols of the Spanish colonial past in key spaces facing one or more of the city's open areas. In San Germán, the Rafael García Cabrera Public School replaced the old Casa del Rey. In the investigations performed by

Adalberto Maurás (2011) for the project "Lajas - San Germán Potable Water Transmission System Expansion", two areas were identified positive for the presence of cultural remains including human remains. If so, it would corroborate the presence of the ancient cemetery in this area. Also, within the Historic District of the City (García Goyco, 1993), were identified different areas of archaeological potential.

In 1821, the San Germán square was a large esplanade of land bordered on the west side by the San Germán de Auxerre Parish Church and on the east by the Porta Coeli Convent. Between 1848-53 this large square was divided in two by Carro Street, which runs from north to south behind the Old City Hall. This is how the Plazuela de Santo Domingo came into being. On March 11, 1853, Martin Albertucci presented to the town council a plan to join the square with Carro Street, but it was not a street for cart traffic but a pedestrian street because it was in the form of stairs. By 1970, given the increase in the flow of vehicles, the stairs were eliminated and the street that leads from Carro Street, on the north side of the Old City Hall, which was baptized as José Julián Acosta, now Padres Agustinos Street.

For decades, two distinct spaces - a park and a plaza - were unified into homogenized plazas with paved surfaces. During the late 19th and early 20th centuries, both spaces, initially lit by gas and later by electricity, served as focal points for social gatherings and public events. Santo Domingo and Mariano Quiñones were also places for leisure, landscaped in the style of the English "square" popular in Europe at that time. Streets were paved, further enhancing their urban character. In the heart of Mariano Quiñones Plaza, once adorned by two towering trees, a transformation occurred in the 1960s: the trees were replaced with a brief- lived low fountain. Positioned on a slope like the plaza itself, the fountain had water pooling at its lower end, rendering the upper section dry and preventing the pump from functioning effectively. To safeguard pedestrians from vehicular traffic, low brick walls were subsequently erected near some of the planters.

#### **Possibility of Archaeological Findings**

Because the city was established in its present location since the 1570s, certain areas of the urban core were identified as archaeologically significant. Phase IA-IB and monitoring by García Goyco (1993) identified artifactual material that provided the basis for identifying such areas.

#### Areas of High Archaeological Potential

Of particular importance is the period prior to 1850, due to the absence of maps. In the Santo Domingo and Francisco Mariano Quiñones Plazas, the original stone pavement was identified in both cases; however, no artifactual material was found underneath it. In front of the old City Hall, when crossing to the main plaza, the foundations of the old Hospital were discovered, as well as the smooth stones from the river (chinos) that were used to pave the streets.

Prior to the 1850s, most of the construction seems to have been centered along Ramas, Alfonso XII and a section of Esperanza and Manzanares streets, thus, this zone represents the area of the longest settlement in the history of San Germán's urban life. On Ramas Street, a water well revealed artifactual material, dating from the 17th and 18th centuries, a significant amount of majolica was found. Several fill events were identified on what appears to be the former bank of the Quebrada Manzanares, to control the flow of the creek. The most important find in this area, however, was what appears to be "transculturation earthenware," probably dating to the late sixteenth or early seventeenth century.

#### Areas of Medium Archaeological Potential

Test samples in other streets mentioned above also produced artifactual material from the 18th century, particularly majolica, as is the case of Manzanares and Esperanza streets. There are other areas that could produce evidence of human habitation in the form of skeletal remains: the Atrium, interior and patio of the Parish Church, as well as the Porta Coeli Chapel. Parish death records show that until the early 19th century, parishioners were buried here. Finally, within the proposed district, places were identified where the artifactual material places their habitational temporality to the nineteenth century or later, where remnants of earlier structures can still be found and where the archaeological context has barely been disturbed. This could be the case of those houses that were built on the ground without cellars, latrines, or cisterns. With the placement of a sanitary water supply system, many of these features lost their usefulness and were then used as storage spaces or garbage dumps. Along José Julián Acosta Street and Dr. Veve Street (formerly Comercio), the artifactual material dates to the 19th century. Both locations have produced large quantities of animal bones that may be useful in establishing the location of the city's butcher shop, as well as other urban amenities, such as places to eat. In addition, sections of the vaulted storm sewer system that cross or flow into Veve and Manzanares Streets, where a hotel and three drug stores lay, have produced 19th century coarse creole pottery.

#### Areas of Low Archaeological Potential.

Carro Street, from Luna to Estrella Streets, and Veve Street, from Carro to Ramas Streets, have not yielded much archaeological material; they are, therefore, considered areas of low archaeological potential. Bedrock is close to the surface at this point.

#### **Summary**

The artifactual material found in the archaeological surveys in the San German historic District produced 16th to 17th century materials such as contact material, "transculturation artifacts" and colonial pottery; 18th century material, mainly pottery; and 19th century material such as earthenware, porcelain, bottles, glass, and animal remains (bovine, burgao shells, tortoise). The most recurrent element during the excavations were the colonial pavements of river stones. This finding corroborated the documentary sources that demonstrated that the streets in the center of town and the main square were, at one point, paved with river stones.

Also documented were a cobblestone pavement of large slate stones, a rustic road in limestone, two small brick inlets, a compacted brick floor, two branches of the so-called tunnels, which are brick vaulted sewers and two possible stone curbs "sardineles". Also documented were the branches or small brick vaulted sewers that connected with the tunnel of the Quebrada Manzanares. The oldest pipes were made of vitrified clay. Early street pavements in cobblestones were documented from a depth of 12 cm to 210 cm. In addition, during phase IA, IB, two sardineles of river stones were discovered in Carro and Dr. Veve Streets, although in general, these were built in brick, as were the sidewalks. The archaeological artifacts found corresponded mostly to colonial ceramics from the semi-refined earthenware assemblage. We can mention the "creamware", "pearlware" and "whiteware" ring styles, hand-painted floral, shell rim, transfer "ironstone" and "Mulberry Ironstone". Daily use artifacts such as bone brushes and spoons, majolica, whiteware and porcelain ointment knobs, animal skeletal remains, tiles, bricks, game artifacts such as bone dominoes and ceramic tokens, and metal cutlery were also documented. A peculiar fragment had as decoration a Puerto Rican coat of arms in white ware, elaborated with the transfer technique. The relative chronology of the ceramics in the sample obtained probably fluctuated between the 18th and 20th centuries. Many blown glass bottles made in molds were documented, some of medicine perfume and poisons from the 19th century, a Hiram Cod type soda bottle with an inner glass marble lid circa 1870's and blown glass liquor bottles made in molds from the 18th and 20th centuries.

Also, in the old movie theater (Teatro Sol) a large amount of material related to entertainment activities and advertising techniques, used during the second half of the 20<sup>th</sup> century, was found. It can be concluded that the proposed District has excellent possibilities to produce artifactual material related to the four hundred years and more of the city's history. In the excavations in the historic center of San Germán we expected to document early artifacts associated with the first years of colonization, but this evidence was minimal; pearlware and whiteware of English origin dominated in practically all levels within the sewers and under the streets. including:

- Historic sidewalks
- Aqueducts from the colonial era
- Archaeological material related to the different activities that took place in the square in the colonial era, for example, remains of a sugar mill.

The APE includes sidewalks and/or streets within a traditional urban center, with potential archaeological remains underneath these features, like historic pavements, historic drainage systems and historic lighting systems. Also, during the reconstruction process there's a possibility to find cultural layers associated with demolition and reconstruction due to disasters like fires, earthquakes, hurricanes etc. Is the possibility that the proposed project can expose foundations of old buildings along the street if realignment of facades was performed. The properties/streets that survive to the present are the most recent facade of the town, reminiscences of these properties. However, they give us an idea of the archaeological potential of the Plazas and its surroundings. They are vestiges of previous constructions, and under the floors of the plaza and its surrounding streets the potential for the presence of Spanish colonial archaeological sites is high. It is possible the existence of in situ nineteenth century Euro-Spanish material remains in the APE.

#### IV. ARCHAEOLOGICAL MONITORING PROCEDURE

The monitoring activities can be divided into three groups: activities before the project begins, activities during construction, and post-construction activities. Monitoring is limited to activities that entail demolition and excavations. Those construction activities that do not entail excavations or earth movements do not require an archaeological monitor.

#### A. Before Construction Begins

- 1. The Construction Manager (CM) will notify the Project Manager (PM), Grant Manager (GM), and Monitor of the proposed activities' start date. The PM is responsible for coordination between the CM and the SOI-qualified archaeologist who will oversee the monitoring (Monitor). The GM shall notify the SHPO and PAE of the construction start date and the archaeology company charged with implementing this Plan.
- 2. Before any demolition or construction begins, the PM, CM, GM, and Monitor will have a kickoff meeting to discuss the procedure for archaeological monitoring, including the coordination protocol between the Monitor and the Contractor. The Monitor will provide an orientation on the area's cultural resources and potential resources and their proper treatment. The Monitor will also explain which project activities require archaeological monitoring.
- 3. The CM, PM, and construction crew will complete and sign a statement outlining the activities that may not be performed without the Monitor's presence, demonstrating their understanding and commitment to following the archaeological monitoring procedures.

4. The Monitor will document the historic properties (NRHP-listed and eligible) located within the project's area of potential effects by means of verbal descriptions and photographs. This documentation shall be included as an appendix to the first weekly report. This report will be submitted to the PAE with the first monthly report.

#### **B.** During Demolition and Construction

- 1. The Monitor shall be in the field during all project activities involving demolition and ground disturbance; access and clear sightlines to all demolition and excavation activities and debris removal will be provided to the Monitor. In the event of simultaneous excavations in different areas of the project, an archaeologist should be assigned to each area.
- 2. The Monitor shall provide instructions directly to the construction field personnel concerning how to proceed when there is a potential to impact an archaeological resource. The construction field personnel will abide by these requests: excavate slowly, stop the excavation work to evaluate a finding, etc.
- 3. The Monitor shall keep a record of monitored activities. The Monitor shall fill out the Daily Record of Activities Form (see **Appendix 1**). These Forms will be attached to the f inal report as an appendix. These forms should be send weekly to the GM for review.
- 4. A monthly report will be prepared, including photos of the area of interest. The report shall be emailed to the GM during the week following the month in which the monitoring was conducted. The PRDOH or the GM on behalf of PRDOH will be responsible for submitting the report to the SHPO and the PAE.
- 5. The Monitor shall document all archaeological remains identified during construction activities, except for previously unidentified historically significant findings (refer to B-8 below). The documentation shall include a detailed description of the discovery, context, horizontal and vertical provenience, photos, and a plan drawing. This documentation shall be done within a reasonable amount of time, trying as much as possible, not to impact on the project schedule.
  - a. The documentation may require extending the contractor excavations to expose and define the finds. Associated stratigraphy will be documented and representative samples of associated artifactual material will be recovered. For structural remains, construction materials and techniques will be documented. The controlled units may vary in size according to the nature and dimensions of the archaeological find. These will be excavated by strata, cultural or natural, with vertical and horizontal control. When warranted, the removed soil will be sifted through ¼ inch mesh. The recovered artifactual material will be bagged and labeled by specific origin. It shall proceed in accordance with the protocol included in item B-7.
- 6. Any subsurface feature may be demolished and removed after being documented by the Monitor and approved by the GM. The information recorded will be included in the final report.
- 7. If the identified archaeological remains are considered historically significant— i.e., complex structures, precolonial remains or stratified deposits the Monitor shall instruct the construction crew to (1) immediately cease work in the vicinity of the discovery, (2) take all reasonable measures to avoid or minimize harm to the property, and (3) notify the PM, CM, and GM. The GM shall immediately notify the PAE, and the SHPO, as per stipulation III.B.1.b. of the PA. The following protocol shall be followed:

- a. The Monitor shall make a preliminary assessment of the finding. The assessment shall include a description of the discovery, location, horizontal and vertical extent (if known), context, photographs, and drawings, as deemed necessary. The assessment shall also include a work plan for implementing a National Register of Historic Places' eligibility evaluation of the exceptional remains (in other words, an evaluation of significance and integrity).
- b. The assessment and NRHP-eligibility evaluation work plan shall be submitted via email to the PM and GM within 24 hours of the discovery. The GM will comment on the work plan within 24 hours of receiving it.
- c. The Monitor shall implement the work plan after receiving the GM's authorization to proceed. After completing the fieldwork, the Monitor shall prepare an End of Field Report, summarizing the results. Said report should include an NRHP-eligibility determination. The End of Field Report shall be submitted via email to the PM and GM within 48 hours after completing the fieldwork.
- d. The GM shall notify the SHPO and PAE of the NRHP-eligibility determination.
  - i. If the finding is **not eligible** to the NRHP, the GM shall notify the SHPO and PAE and provide supporting documentation. Construction activities may resume under archaeological monitoring unless the SHPO or PAE disagrees with the NRHP determination and makes a timely objection within 48 hours of the notification.
  - ii. If the finding is **eligible** to the NRHP, the criteria of adverse effect shall be applied. If the project activities do not adversely affect the finding, the GM shall notify the SHPO and PAE, and provide supporting documentation. Construction activities may resume under archaeological monitoring unless the SHPO or PAE makes a timely objection within 48 hours of the notification.
  - iii. If the project activities have an **adverse effect** on the NRHP-eligible finding, a Data Recovery will be implemented as a Treatment Measure per Appendix F of the PA. The Monitor shall develop a data recovery plan with a research design consistent with the Secretary of the Interior's Guidelines for Archeological Documentation (<a href="http://www.nps.gov/history/locallaw/arch\_stnds\_7.htm">http://www.nps.gov/history/locallaw/arch\_stnds\_7.htm</a>), the Advisory Council on Historic Preservation's (ACHP) recommendations on the recovery of significant information from archaeological sites as updated in 2009, at

https://www.achp.gov/protectinghistoricproperties/Section\_106\_Archaeology\_Guidance, and Regulation #8932. The data recovery plan shall be submitted via email to the GM for comments. The GM shall be responsible for submitting the data recovery plan to the SHPO and PAE for comments and approval. This treatment measure does not apply to burials or human remains (refer to IV.D of this work plan).

- 8. If architectural features are found, as far as possible, the finding should be preserved and protected, and every effort should be made to adapt the design of the project and avoid negative impact to the finding.
- 9. Processing of archaeological artifacts, if any, will be conducted concurrently with the field work. A summary of these activities shall be included in the monthly report. Artifacts shall be curated

and processed in accordance with the standards set forth in 36 CFR Part 79 Curation of Federally-Owned and Administered Archaeological Collections.

- a. Artifacts shall be washed and sorted. Materials such as ceramics, lithics, shell, bone, glass, metal, and others, should be subject to general analysis considering aspects such as material, manufacture, style, function, type, variety, use, and others. Due to their nature, some of these materials require specialized analysis such as studies of malacology, zooarchaeology, bioarchaeology, among others, which should be carried out by specialists. The classification scheme used in the classification will be chosen by the archaeologist according to the context, type of material recovered and previous experience. The classification scheme shall be referenced with available bibliographic references.
- b. The materials laboratory shall include a quantitative, qualitative, and comparative analysis of all archaeological materials recovered during archaeological monitoring. An inventory of artifacts by category, and a catalog of artifacts by material type shall be prepared.
- c. Photographic documentation shall be made of representative artifacts in the collection.
- d. If necessary, documentary research will be conducted for analysis and interpretation of artifacts and other finds.
- e. Samples from strata or from particular cultural elements must be properly packaged, labeled and preserved. The data resulting from their analysis must be included in the final report.
- 10. If any additional construction activities are added or design changes are made after the project has begun, the CM and PM, prior to performing the work, shall inform the GM and the Monitor. The Monitor, in conjunction with GM, shall evaluate these activities and apply the adverse effect criteria. If it is determined that the effect is adverse, the archaeologist will provide recommendations on how to avoid, minimize, or mitigate the adverse effect. These recommendations will be consulted with the SHPO and PAE prior to implementation. The SHPO and PAE will have 15 days to comment on the recommendations. If no communication is received within that time frame it will be assumed that the SHPO and PAE has no objection and concurs with the recommendations outlined.
- 11. If during construction activities a historic property is affected in an unanticipated manner, the CM shall stop work immediately, and inform the PM, GM, and Monitor. The Monitor, in conjunction with GM, shall evaluate the unanticipated effects and apply the adverse effect criteria within no more than 24 hours. If the effect is determined to be adverse, the Monitor and GM will provide recommendations on how to avoid, minimize, or mitigate such adverse effects. The GM shall consult with the SHPO and PAE on the recommendations prior to implementation. The SHPO and PAE will have 48 hours to comment on the recommendations. If no communication is received within that timeframe, it will be understood that the SHPO and PAE has no objection and concurs with the recommendations outlined.

#### C. After Construction Ends

1. Upon the completion of archaeological monitoring, the PM and GM shall be notified. The estimated date of delivery of the final report shall be indicated in the said notification.

- 2. The Monitor shall again document the historic properties located within the project's area of potential effects. The condition of the properties should be compared with those documented at the beginning of the project. This documentation shall be included in the final technical report.
- 3. The Monitor shall prepare an Archaeological Supervision End of Field Report, which shall include the main findings and their location, the methodology used for their excavation and documentation, conclusions on the effectiveness of the archaeological supervision, the integrity and importance of the archaeological resources discovered, meritorious protection aspects and clear recommendations as to the course of action to be followed. It should also include the date of delivery of the Final Report. This report will be delivered to the GM. The GM shall be responsible for submitting it to the SHPO and the PAE. The report shall be submitted to the GM no later than two (2) weeks after completing the archaeological monitoring work. The GM shall submit the report to the SHPO and PAE no later than one (1) week after receiving it.
- 4. A Final Archaeological Monitoring Report shall be prepared and submitted by the date stipulated in the End of Field Report. This report shall include a description of the work performed, the construction activities that were archaeologically monitored, and documentation of unexpected finds, if any. It should also include final documentation of the condition of the properties along with a comparison of the final condition of the structures to the initial condition. The report shall comply with Article 10 Section 8 of Regulation #8932, which outlines the content and format it should have.
  - a. If the Final Archaeological Monitoring Report cannot be delivered on the established date, an extension of time will be requested from the Council, indicating the reasons why the report cannot be delivered. The request for extension shall be submitted, to the extent possible, fifteen (15) working days prior to the established date. The Council shall reply within fifteen (15) working days, in accordance with the provisions of Article 10 Section 7 of Regulation #8932, setting a final deadline for the delivery of the report. The request for extension of time must be copied to the SHPO.
- 5. The Principal Investigator will be responsible for retaining his or her original field notes, digital photographs, expert reports, drawings, maps and any other digital photographs, expert reports, drawings, maps, and any other documents associated with the study conducted (including digital files) and shall ensure future reference by other researchers for future reference. If unable to keep these documents, the archaeologist shall deliver them to the PAE.

**D. Human Remains:** If human remains are discovered, the protocol established in Stipulation III.B.1.c. of the PA and IPRC Regulation #8932, must be followed:

- 1. Stop work immediately.
- 2. Notify the local law enforcement office and coroner/medical examiner following applicable Commonwealth statute(s).
- 3. Protect the remains from any harm.
- 4. The GM shall be responsible for notifying the SHPO and PAE within twenty-four (24) hours of identifying human remains.
- 5. The services of a physical anthropologist or specialist in bioarchaeology will be required.

# V. PROFESSIONAL QUALIFICATIONS

The Monitor must meet the minimum Secretary of the Interior Professional Qualifications Standards for Archaeology established in 36CFR Part 61. These are: a graduate degree in archaeology, anthropology, or closely related field, plus at least one (1) year of full-time professional experience or equivalent specialized training in archaeological research, administration, or management; at least four (4) months of supervised field and analytic experience in general Puerto Rican archaeology; the demonstrated ability to carry research to completion; and at least one (1) year of full-time professional experience at a supervisory level in the study of archaeological resources of the pre-Columbian and colonial periods. Please see https://www.nps.gov/history/local-law/arch\_stnds\_9.htm for more information.

The SOI-qualified archaeologist shall not defer their monitoring responsibilities to any other person who does not meet the minimum professional qualifications. Any additional personnel to intervene in monitoring efforts shall have vast experience in historic archaeology, in working in evaluation (Phase II), documentation (Phase III), and monitoring projects dealing with colonial period properties.

The Principal Investigator may not transfer his or her duties, obligations, and responsibilities to subordinates or other technicians who are not professionally trained in archaeology. In the case of hiring archaeologists and trained technicians to assist in archaeological monitoring, the Principal Investigator must be present for at least 25 percent of the duration of the fieldwork to supervise them.

## VI. CITED REFERENCES

#### Advisory Council on Historic Preservation

ACHP recommendations on the recovery of significant information from archaeological sites <a href="https://www.achp.gov/protectinghistoricproperties/Section 106 Archaeology Guidance">https://www.achp.gov/protectinghistoricproperties/Section 106 Archaeology Guidance</a>.

Consejo para la Protección del Patrimonio Arqueológico Terrestre de Puerto Rico.

2017 Reglamento para la radicación y evaluación arqueológica de proyectos de construcción y desarrollo. San Juan: ICP. Reglamento #8932 del 8 de febrero de 2017.

#### National Park Service

- s/f "Archeology and Historic Preservation: Secretary of the Interior's Standards and Guidelines [As Amended and Annotated] Professional Qualification Standards".

  <a href="https://www.nps.gov/history/local-law/arch\_stnds\_9.htm">https://www.nps.gov/history/local-law/arch\_stnds\_9.htm</a>
- s/f "Archeology and Historic Preservation: Secretary of the Interior's Standards and Guidelines for Archeological Documentation". <a href="http://www.cr.nps.gov/local-law/arch">http://www.cr.nps.gov/local-law/arch</a> stnds 7.htm

# Rigau, Jorge and Tamara González Vega

2024 Puerto Rico 2017 Disaster Recovery, CDBG- DR CRP Program. PR-CRP-000876 section 106 Form

# APPENDIX A: MONITORING DAILY ACTIVITY SHEET

City Revitalization Program (City-Rev) Section 106 NHPA Effect Determination		HOUSING
Project Name:		
Case ID:		City
Project Coordinates:		
SOI Qualified-Archaeologist:		
Archaeologist Assistant:		
Date of Monitoring:		
Work Hours:		
	YES	NO
Was an archaeological remain documented during the day. If yes, include required information below.	YES	NO.
during the day. If yes, include required information below.  Was an exceptional archaeological remain	1 1797	71.
during the day. If yes, include required information below.	0	71.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DR PROGR. CITY REVITALIZATION PROGRAM (CITY-REV)	M HOUSING
Section 106 NHPA Effect Determination	3
Project Name:	
Case ID:	City:
Project Coordinates:	
Site Photos	
Direction of Photo: Description:	
Direction of Photo: Description:	

**APPENDIX B: PAE & PRSHPO LETTERS** 

Executive Director | Carlos A. Rubio Cancela | carubio@prshpo.pr.gov

Thursday, June 12, 2025

# Lauren B Poche

269 Avenida Ponce de León, San Juan, PR, 00917

SHPO-CF-05-23-25-01 PR-CRP-000876 (San German), Plaza Santo Domingo and Plaza Francisco Mariano

Dear Ms. Poche.

Our Office has received and reviewed additional information regarding the above referenced project in accordance with 54 USC 306108 (commonly known as Section 106 of the National Historic Preservation Act, as amended) and 36 CFR Part 800: Protection of Historic Properties from the Advisory Council on Historic Preservation. The State Historic Preservation Officer (SHPO) is to advise and assist federal agencies and other responsible entities when identifying historic properties, assessing effects upon them, and considering alternatives to avoid or reduce the project's effects.

After a review of all the documentation provided, the PRSHPO agrees with your finding that the proposed project will have no adverse effect upon historic properties pursuant that the following condition proposed by the agency is met:

1. Archaeological monitoring will be carried out during all ground disturbing activities.

Please note that should the Agency discover any historic properties including archaeological findings at any point during project implementation, you should notify the SHPO immediately. If you have any questions concerning our comments, do not hesitate to contact our Office.

Sincerely,

Carlos A. Rubio Cancela

State Historic Preservation Officer

CARC/GMO/SG





Arch. Carlos A. Rubio Cancela

Executive Director Puerto Rico State Historic Preservation Office Cuartel de Ballajá, Third Floor San Juan, Puerto Rico 00901

Re: Authorization to Submit Documents for Consultation

Dear Arch. Rubio Cancela,

The U.S. Department of Housing (HUD) approved the allocations of Community Development Block Grant (CDBG-DR) funds on February 9, 2018. It also approved the allocation of Community Development Block Grant Mitigation (CDBG-MIT) funds on January 27, 2020. The purpose of these allocations is to address unsatisfied needs as a result of Hurricanes Irma and Maria in September 2017; and to carry out strategic and high-impact activities to mitigate disaster risks and reduce future losses.

To comply with the environmental requirements established by HUD, the Department of Housing of Puerto Rico (PRDOH) contracted Horne Federal LLC to provide environmental review services, among others, that will support the objectives of the agenda for both CDBG-DR and CDBG -MIT Programs.

To expedite the processes, Horne Federal LLC, is authorized to submit to the State Historic Preservation Officer, documentation of projects related to both the CDBG-DR and CDBG-MIT on behalf of PRDOH.

Cordially,

Aldo A. Rivera Vázquez, PE

Director

Division of Environmental Permitting and Compliance

Office of Disaster Recovery



May 23, 2025

Carlos A. Rubio Cancela
State Historic Preservation Officer
Puerto Rico State Historic Preservation Office
Cuartel de Ballajá (Tercer Piso)
San Juan, PR 00902-3935

### PUERTO RICO DISASTER RECOVERY, CDBG-DR CITY REVITALIZATION PROGRAM

RE: ADDITIONAL INFORMATION REQUEST FOR SHPO-CF-02-19-25-09, PR-CRP-000876, PLAZA SANTO DOMINGO AND PLAZA FRANCISCO MARIANO, SAN GERMÁN, PUERTO RICO – *NO ADVERSE EFFECT, CONDITIONED* 

#### Dear Architect Rubio Cancela,

On behalf of the Puerto Rico Department of Housing (PRDOH), we thank you for your letter dated March 17, 2025, in response to the documentation submitted for consultation regarding the Plaza Santo Domingo and Plaza Francisco Mariano Project in the Municipality of San Germán. In that letter, the you stated that, "While intended to improve them from an aesthetic and technical standpoint, and the general approach is to consider how they convey San Germán's historic significance, the proposed undertaking contemplates numerous and diverse activities that we believe should be presented and discussed prior to our concurrence with the agency's proposed finding. To that end, we would like to suggest a meeting between our staffs and any consultant you deem necessary be coordinated at your earliest convenience to continue our review of this significant project."

Two meetings were held on April 7 and April 9, 2025, to discuss the project. As a result of these meetings, the Subrecipient's architect has proposed design changes to address the issues raised, including adjustments to the curved benches, lowering the planters, and the paving. The proposed pedestal clock will remain. The attached memo from Architect Jorge Rigau further outlines these design amendments.

We believe that the proposed changes support our original determination that the undertaking for this project will result in no adverse effect to historic properties. Therefore, based on the provided documentation, the Program requests a concurrence with a determination that "No Adverse Effect" is appropriate for this undertaking, conditioned to archaeological monitoring all ground-disturbing activities. If this condition is deemed appropriate, an archaeological monitoring plan will be prepared and submitted to the PRSHPO for review and concurrence of the appropriateness of its



implementation for this undertaking. for review and concurrence of the appropriateness of its implementation for this undertaking.

Please contact me with any questions or concerns by email at <a href="mailto:lauren.poche@horne.com">lauren.poche@horne.com</a> or phone at 225-405-7676.

Kindest regards,

Lauren Bair Poche. M.A.

Architectural Historian, EHP Senior Manager

LBP/KPS

**Attachments** 

# JORGE RIGAU FAIA ARQUITECTOS PSC

May 20, 2025

TO: Kristin Sanders

Historic Preservation Manager, Government Services I

**HORNE** 

FROM: Jorge Rigal, FAIA

Jorge Rigau Arquitectos, PSC

RE: Rehabilitation Project of Plaza Mariano Quiñones & Plaza Santo Domingo

Municipality of San Germán

PR-CRP-00876 / Project Description Amendment

This project description amendment pertains to the design of the abovementioned project which was discussed with SHPO personnel in two different meetings on April 7 and 9, 2025; one virtual, the second held at the state agency's office in Old San Juan.

The first meeting was scheduled to explain the project and answer questions to the SHPO review team regarding our proposal for Plaza Santo Domingo. After explaining the design for Plaza Mariano Quiñones, the conversation focused on Plaza Santo Domingo. Three issues were raised by the SHPO staff:

1. Shape, height & look of benches at east and west ends of the open space. Introducing curved shapes in an otherwise orthogonal plaza was questioned, and the height of the adjacent planters was considered excessive, given the prevailing horizontality of the plaza. Moreover, we were requested to specify the finish material of the benches, not defined in the plans submitted.

# 2. Paving pattern in the surrounding streets.

Concern was raised regarding the possible visual/contrasting impact of the street paving materials that are being recommended to substitute the existing, deteriorating pattern of pebbles and bricks.

3. Addition of a pedestal clock west of the plaza.

The need to incorporate a previously non-existing element in the plaza, its relevance to the space, and its remade historical character were questioned.

A second meeting was set up to address these matters in presence of San Germán's Mayor Virgilio Olivera Olivera. After said meeting, all issues were productively clarified, acknowledging both the project's design and SHPO's recommendations.

In summation, the following was established in agreement with all parties:

The **curved benches** will highlight the ends of Plaza Santo Domingo, underlining the space's axial condition. Facing Porta Coeli, the benches will rotate slightly to face the church, endowing it with a contemplation atrium. Benches will be finished in cement aggregate. All new planters will be lowered, as suggested by SHPO. After explaining the location, configuration, and materiality of the **paving pattern**, everyone agrees that it should not "compete" with the plazas as protagonical urban components. We will take this into account when evaluating mockups required from the contractor to be selected. Apropos the **pedestal clock**, Mayor Olivera expressed his desire to install the clock as a long-lasting legacy of his administration. He wants to follow the practice of previous majors in town who contributed added elements to the plaza and do so with a traditional-looking element.

To acknowledge all the above mentioned, this Project Description Amendment is presented for record.•

Monday, March 17, 2025

# Lauren B Poche

269 Avenida Ponce de León, San Juan, PR, 00917

SHPO-CF-02-19-25-09 PR-CRP-000876 (San Germán), Plaza Santo Domingo and Plaza Francisco Mariano

Dear Ms. Poche,

The SHPO has received and reviewed the above referenced project in accordance with 54 USC 306108 (commonly known as Section 106 of the National Historic Preservation Act, as amended) and 36 CFR Part 800: Protection of Historic Properties. The State Historic Preservation Officer (SHPO) is to advise and assist federal agencies and other responsible entities when identifying historic properties, assessing effects upon them, and considering alternatives to avoid or reduce the project's effects.

As established in the Section 106 Effect Determination Form, the indirect and direct Area of Potential Effects (APE) are located within the San Germán Historic District, which is listed in the National Register of Historic Places (Ref #94000084). As individually eligible sites, the Plaza de Santo Domingo - and especially the Plaza Francisco Mariano Quiñones - have recently been the object of further documentation efforts carried out by our Office for their uniqueness to most of Puerto Rico's urban settings.

While intended to improve them from an aesthetic and technical standpoint, and the general approach is to consider how they convey San Germán's historic significance, the proposed undertaking contemplates numerous and diverse activities that we believe should be presented and discussed prior to our concurrence with the agency's proposed finding. To that end, we would like to suggest a meeting between our staffs and any consultant you deem necessary be coordinated at your earliest convenience to continue our review of this significant project.

If you have any questions concerning our comments or require further assistance, do not hesitate to contact us.





Sincerely,

Carlos A. Rubio Cancela

State Historic Preservation Officer

CARC/GMO/SG







Arch. Carlos A. Rubio Cancela

Executive Director Puerto Rico State Historic Preservation Office Cuartel de Ballajá, Third Floor San Juan, Puerto Rico 00901

Re: Authorization to Submit Documents for Consultation

Dear Arch. Rubio Cancela,

The U.S. Department of Housing (HUD) approved the allocations of Community Development Block Grant (CDBG-DR) funds on February 9, 2018. It also approved the allocation of Community Development Block Grant Mitigation (CDBG-MIT) funds on January 27, 2020. The purpose of these allocations is to address unsatisfied needs as a result of Hurricanes Irma and Maria in September 2017; and to carry out strategic and high-impact activities to mitigate disaster risks and reduce future losses.

To comply with the environmental requirements established by HUD, the Department of Housing of Puerto Rico (PRDOH) contracted Horne Federal LLC to provide environmental review services, among others, that will support the objectives of the agenda for both CDBG-DR and CDBG -MIT Programs.

To expedite the processes, Horne Federal LLC, is authorized to submit to the State Historic Preservation Officer, documentation of projects related to both the CDBG-DR and CDBG-MIT on behalf of PRDOH.

Cordially,

Aldo A. Rivera Vázquez, PE

Director

Division of Environmental Permitting and Compliance

Office of Disaster Recovery



#### 2/19/2025

Carlos A. Rubio Cancela State Historic Preservation Officer Puerto Rico State Historic Preservation Office Cuartel de Ballajá (Tercer Piso) San Juan, PR 00902-3935

# Puerto Rico Disaster Recovery, CDBG-DR City Revitalization (City-Rev) Program

Section 106 NHPA Effect Determination Submittal for PR-CRP-000876, Plaza Santo Domingo and Plaza Francisco Mariano, San Germán, Puerto Rico – No Adverse Effect, Conditioned

Dear Architect Rubio Cancela,

On February 9, 2018, an allocation of Community Development Block Grant - Disaster Recovery (CDBG-DR) funds was approved by the United States Department of Housing and Urban Development (HUD) under the Federal Register Volume 83, No. 28, 83 FR 5844, to assist the Commonwealth of Puerto Rico in meeting unmet needs in the wake of Hurricanes Irma and Maria. On August 14, 2018, an additional \$8.22 billion recovery allocation was allocated to Puerto Rico under the Federal Register Volume 83, No. 157, 83 FR 40314. With these funding allocations, the Puerto Rico Department of Housing (PRDOH) aims to lead a comprehensive and transparent recovery for the benefit of Puerto Rico residents. To faithfully comply with HUD's environmental requirements, PRDOH contracted Horne Federal, LLC (HORNE) to provide environmental records review services that will support their objectives for the CDBG-DR funds.

On behalf of PRDOH, HORNE is submitting documentation for the proposed Plaza Santo Domingo and Plaza Francisco Mariano project, which is located within the National Register listed San Germán Historic District and San Germán's Traditional Urban Center. The Municipality of San Germán proposes improvements within the plazas, as well as in the surrounding streets and sidewalks. At Plaza Mariano Quiñones, pavements and the walls of the low planters will be repaired, the eight (8) concrete benches lining the perimeter of the



plaza will be rehabilitated, and a gazebo will be re-incorporated to evoke one that previously existed there. In Plaza Santo Domingo, the low walls of the planters will also be repaired on site, without demolishing them, except for brief segments to be substituted by curved ones. The plaza will incorporate benches and posts like those proposed for Plaza Mariano Quiñones and the central section of the space will be repaved. At each end of the space, a semicircular bench (in concrete) will be placed, which, along with a pair of lighting posts, will frame the entrance to the plaza. To the west, the bench incorporates a pedestal clock. The existing vegetation, including trees, shrubs, and grass, will be preserved. The full scope of the project is described in the submitted documentation, which includes mapping, photographs, and the 90% design development plans.

Based on the documentation provided, the Program requests a concurrence with a determination that "**No Adverse Effect**" is appropriate for this undertaking, conditioned to archaeological monitoring during all ground-disturbing activities. If this condition is deemed appropriate, an archaeological monitoring plan will be prepared and submitted to the PRSHPO for review and concurrence of the appropriateness of its implementation for this undertaking. for review and concurrence of the appropriateness of its implementation for this undertaking.

If you have any questions or concerns, please contact me by email at <a href="mailto:lauren.poche@horne.com">lauren.poche@horne.com</a> or phone at 225-405-7676.

Kindest regards,

Lauren Bair Poche. M.A.

Architectural Historian, EHP Senior Manager

LBP/KPS

Attachments

# PR-CRP-000876 Plaza Santo Domingo and Plaza Francisco Mariano Project San Germán, Puerto Rico

Section 106 Effect Determination Form

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Subrecipient: Municipality of San German	
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

**Project Location**: Plaza Santo Domingo and Plaza Francisco Mariano, Municipality of San Germán, PR

Project Coordinates: PMQ 18.082269 -67.043145, PSD 18.081937, -67.043145

**TPID** (Número de Catastro): Plaza Santo Domingo, Cadaster Nos.: 334-034-032-01-000 and 334-034-033-01-000. Plaza Mariano Quiñones Cadaster No.: 334-034-019-01-000

# Type of Undertaking:

■ Substantial Repair

■ New Construction

Construction Date (AH est.): 1960's/1980's Property Size (acres): 1.422 rehab for both plazas

SOI-Qualified Architect/Architectural Historian: Jorge Rigau

Date Reviewed: July 30, 2024 / December 17, 2024 / January 27, 2025

**SOI-Qualified Archaeologist**: Tamara González Vega

Date Reviewed: July 24, 2024 /

In compliance with Section 106 of the National Historic Preservation Act (NHPA), the Program is responsible for identifying historic properties listed in the NRHP and any properties not listed that would be considered eligible for listing that are located within the geographic area of potential effects (APE) of the proposed project and assessing the potential effects of its undertakings on these historic properties. It has been determined by the SOI-qualified professionals that the project undertaking does not conform to Stipulation II.A (Project Review-Programmatic Allowances) of the Section 106 Programmatic Agreement (PA) among FEMA, SHPO and COR3, as amended (May 3, 2023).

#### PROJECT DESCRIPTION (Undertaking)

The Municipality of San Germán proposes the rehabilitation of the two most prominent public spaces in the city: Plaza Santo Domingo and Plaza Francisco Mariano Quiñones. Both squares make up the urban "backbone" of the town, they run in an east-west direction, are linked by the Ruiz Belvis Street and around by several of the most emblematic structures of "La Ciudad de las Lomas": the Church of San Germán de Auxerre, Porta Coeli, the original City Hall and notable residences, among them, the old House of Waldemar Morales in the "Queen Anne" architectural style, the house of Ernestito Quiñones and the so-called Casa de las Bahr. Both squares are longitudinal and are bordered by streets on all four sides. Mariano Quiñones Square is surrounded by Padre San Agustinos, Ruiz Belvis, De la Cruz streets and a street space without its own name in front of the former mayor's office. Both squares are longitudinal and are bordered by streets on all four sides.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Plaza Santo Domingo is surrounded by Belvis, Félix Arce Lugo, Yamil Galib and Carro streets. Plaza Mariano Quiñones covers 12,755.2 square feet; the Plaza de Santo Domingo comprises 13,013.6 square feet.

The proposed intervention for Mariano Quiñones Plaza and Santo Domingo Plaza the pair of emblematic public spaces in San Germán—comprises improvements within their perimeter as well as in the surrounding streets and sidewalks, as delimited in the project's plans. The project respects the general appearance of both spaces, maintaining and repairing their paving, planters, vegetation, and sculptural elements; also restoring most existing materials and finishes. In parallel, selective technical and aesthetic improvements are incorporated for better functionality and appearance, including new lighting posts and benches. In Mariano Quiñones Plaza, a gazebo will be re-incorporated to evoke one that previously existed there to encourage varied programming of various public activities. In Santo Domingo Plaza, the proposed intervention includes placing a pedestal clock that, visible from both plazas, will strengthen the spatial connection between them. At its east and west ends, new benches will be added for the enjoyment of the surrounding architecture. The footprint of each plaza will remain as is, not increased or reduced. The project includes construction work, repairs, improvements, material removals, and minor excavations in both plazas, partially intervening in surrounding streets, intersections, sidewalks, curbs, and gutters. The specific nature of the work to be carried out is detailed ahead. As part of the project, safety measures will be implemented in compliance with federal and local regulations for pedestrians, cyclists, and vehicular traffic in this area.

# **EXISTING CONDITIONS IN STREETS**

The proposed project includes the repaving of the streets surrounding both plazas and improvements to the adjacent sidewalks.

#### **EXISTING CONDITIONS IN THE PLAZAS**

Both plazas are elevated from the street level that surrounds them and are accessed by steps whose number and height vary according to the elevation. Each plaza features vegetation, shrubs, planters, benches, and light posts. Not all light posts are working, and several are missing pieces. The brick paving and planters have suffered excessive wear to the point that, at ground level, loss of material represents a danger. To the northeast of *Plaza Mariano Quiñones* (still paved with mortar and imitating Canary Islands tile) there is a kiosk that remains part of the project. At the center, a grass rectangle is the footprint of the fountain that was once located there.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

At both sides of Plaza Santo Domingo (north and south), eight (8) pedestals made of marble with scarce ornamentation present busts of notable city figures. Through the center of the plaza, at ground level, runs a marble pavement with carved phrases alluding to the history of San Germán. These pieces were installed to cover a "water thread" that was part of the previous remodeling of the space under the former "Directoría de Urbanismo" in the 1980's. The workmanship was not the best; the water channel was "filled in" without achieving a homogeneous character. It now appears to be "patched".

#### EXISTING CONDITIONS IN SIDEWALKS, CURBS, AND GUTTERS

Currently, the sidewalks are paved with brick, originally bound by mortar. There are numerous instances of hollows, impacts, breaks, and wear. The loss of material is notable in various instances and represents a risk for pedestrians walking on them. In various locations, the lack of mortar adds to the insecurity of passersby. The concrete curbs show some breaks and cracks, but they do not need to be replaced, only repaired. The depth of the existing brick gutters contributes to the insecurity of those wanting to cross the street.

# PROPOSED IMPROVEMENTS FOR THE STREETS

The project includes replacing the existing paving material (river pebbles and bricks) on the roadways around both plazas. See Figure 1 below.




Figure 1. Sample of state of disrepair of river pebbles pavement at streets.

While the finish adopted in the 1980's was based on replicating the character of the streets at a given point in the town's history, this project echoes another stage

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

in the town's history: those times when the streets of the population were covered with compacted earth. The existing concrete slab will remain in place, without the need to dig under it. The river pebbles and bricks will be removed, disposing of the gravel in an authorized landfill and/or officially using it as fill for some municipal project soon. After cleaning and scarifying the concrete slab that is to remain, a 2-inch layer of Surface Deactivator brand cementitious mortar with resistant aggregates, Color 306 Toffee, will be applied. The texture, color, and appearance of the material evoke the character of the compacted earth in driving areas that, for a long time, remained unpaved in Puerto Rican towns, including in San Germán. See Figure 2 as follows:



**Figure 2. Sample of cementitious material to be applied on the existing concrete slab. Brand:** Solomon Colors/Surface deactivator/Exposed Aggregate Concrete; **Distributor:** Álvarez Trading.)

This new layer will be solid and leveled to eliminate the problem of pebble detachment and brick breakage; it will include segments to be repaved in brick and the restoration of several of the existing sections. The proposed material meets Federal and State specifications for use on roadways. Thus, the durability and resilience of the pavement will be enhanced within a framework of historical veracity. Use of fragile aggregates that yield or break under the weight and run of cars and trucks, whose impact was not contemplated years ago, has been avoided. Although the 1980's renovation was informed by a given historical intention, the products used, their quality and installation proved to be ineffective for the expected wear and tear. See Figure 3 ahead.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

The pavement finishes now proposed will allow us to address similar conditions with greater flexibility. As the application of this material will be done without removing the concrete slab that served as the base for the works in the 1980's, no excavation will be required for this work.



Figure 3. Crude design of pebble and brick finish and gutters.

#### PROPOSED IMPROVEMENTS FOR SIDEWALKS, CURBS, AND GUTTERS

The project does not contemplate any change in the geometry of the streets or sidewalks. The existing brick paving on the sidewalks will be maintained, filling in the cracks and hollows with mortars of a composition like the physical constitution of the clay. To this end, preliminary tests will be conducted on-site to corroborate differences in consistency and hue. There is no plan to demolish the existing concrete curbs, unless unexpectedly, one should present a problem during construction. If so, authorities would be consulted before any action is taken. The existing gutters, furbished with clay tiles, were built deep, posing a fall risk for pedestrians. Where the streets are repaved, the gutters will be reconstructed in the same cementitious material to be applied to the street, removing the current brick facings and improving their slope to prevent falls. Many of the improvements proposed by this project aim to minimize the difficulties currently confronted by pedestrians, but inkeeping with the historical bearing of San Germán.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

#### PROPOSED WORKS FOR PLAZA FRANCISCO MARIANO QUIÑONES

At Plaza Mariano Quiñones, pavements and the walls of the low planters will be repaired. All bricks with cracks and hollows in the low walls of the planters have been meticulously documented and identified to be filled with a compatible mortar. Repairs will be carried out on-site, inside and outside the perimeter of the space. Low walls will not be demolished, only two small segments to accommodate the circular benches at each end of *Plaza Santo Domingo*. In both plazas, low walls will be maintained and repaired.

The eight (8) concrete benches lining the perimeter of the plaza will be rehabilitated. The current appearance of these benches corresponds to a previous intervention of a crude nature. Built using integral terrazzo, these pieces are of poor quality, with an out-of-scale thickness and clumsy handling of the terrazzo joints when the material changes color. Included in these planters are healthy and attractive trees that currently contribute to the aesthetics and shade of the plaza. These trees will be maintained.

Taking everything into account, the project proposes rehabilitating each concrete bench by removing the seating component, restructuring the base of the planter to include a new backrest and "arms" (as a niche) to now include a traditional bench that will introduce a more human scale in line with the scale and character of the city and its history. The terrazzo bench seats will be partially removed but retaining the planters and the existing trees on them. In contrast to the crude treatment of these pieces in situ, the benches are now designed with a feature to place food, computers, shopping bags, also for just sitting. New lighting posts (of traditional design) will replace the existing ones in the same place where previously posts were located. A concrete gazebo will be incorporated, evoking a previously existing one that was in the same plaza at the turn of the 20th century and served as a stage/platform for musical groups and performances. See Figure 4 below.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	



Figure 4: Historical photograph of Plaza Mariano Quiñones illustrating the gazebo of yesteryear (1898).

The hierarchical presence of the former gazebo in the space is now reinstated by a new gazebo designed in concrete with steel details, railings, and a functional "ring" to hold lighting equipment. It includes an access ramp and electrical facilities for lighting and sound. In the area where the gazebo is to be erected, already exists an electrical connection from an old fountain, therefore digging will not be required to incorporate new electricity conduits. The foundations of the gazebo will reach one foot (1'-0") below the surface, without the need for further excavation.

Around the gazebo, "losa canaria" paving will be incorporated where there is now "argamasa". Work in the plaza includes providing Canary Island tile where it is broken, battered, or simply missing. This happens particularly in pieces around the perimeter. Mortar in the joints will be removed to facilitate the extraction of these pieces; the mortar that appears underneath will be removed, this material will be disposed of, surfaces cleaned, and new tiles will be installed after identifying the correct color so that the new mortar matches the original. Once the tiles are installed, the work done will be protected from the weather until it consolidates. The "losa canaria" tile also appears as edging or frieze and steps along the plaza.

#### PROPOSED WORKS FOR PLAZA SANTO DOMINGO

In Plaza Santo Domingo, the low walls of the planters will also be repaired on site, without demolishing them, except for brief segments to be substituted by curved ones. The broken and perforated bricks will be filled-in with a mortar mix, designed for this purpose. Where the brick is in critical condition, it will be replaced with a similar, new one or recuperated. The plaza will incorporate benches and posts like those proposed for Plaza Mariano Quiñones. The central section of the space will

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

be repaved with honed granite slabs, 1'-8" x 0'-10" each, and a polished peripheral strip of 1'-5" and a frame in mortar panels measuring 1'-6" x 0'-6". The aim is to create a homogeneous environment, something that was not achieved when covering the "water thread". Then, cuts to the existing bricks were made with little delicacy, as well as in the application of mortar.

Both ends of what was the old Parque de Santo Domingo will be reorganized to improve the spatial connection with what happens to the east and west of the plaza. At each end of the space, a semicircular bench (in concrete) will be placed, which, along with a pair of lighting posts (like the rest), will frame the entrance to the plaza. To the west, the bench incorporates a pedestal clock, around which visitors can sit, children can play, and visitors can take photos. To the east, the bench is oriented towards Porta Coeli, thus highlighting the presence of the monument in the urban space. The turn of the bench suggests that the end of the plaza figuratively becomes the atrium of Porta Coeli.

The existing vegetation in the plaza will be maintained, reusing the already existing infrastructure facilities, improving the electrical wiring (without digging) and a water outlet. The marble veneers of the sculpture pedestals and busts will be repaired, applying conservation techniques for the correct treatment of marble and bronze.

#### **INFRASTRUCTURE**

Minor electrical improvements are part of the scope of work, as the existing installations will be utilized, such as the one running from the old town hall westward to reach the very center of *Plaza Mariano Quiñones* where the gazebo will be erected. Excavations for electrical piping are not contemplated. The new wiring will run through conduits already in place. The lighting posts will be placed where the previous ones were, except for four (4) new ones to be located at both ends of *Plaza Santo Domingo* (2 + 2). These are not solar posts. To wire these, electrical installations can run through the planters next to each of one of them. The project does not include improvements related to plumbing, drains, or sewers.

#### **EXCAVATIONS AND REMOVALS**

Site Assessment & Planning: Prior to any removal work, a thorough site assessment will be conducted to evaluate existing conditions and identify potential hazards. Engineers and environmental experts will assess the site for contaminants like asbestos, lead, or other hazardous materials, requiring proper handling and removal. Contractor and Municipality will outline a proper sequence of components removal, ensuring implementation of safety measures, and approved waste disposal procedures. The Municipality will require the Contractor to provide

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

evidence of proper and legal disposition of any removed materials. Removal and substitution work to be carried out inside the plaza will be performed with lightweight equipment considering not to damage any possible important elements below ground. Contractor shall take special precautions on areas identified as sensitive: environmental, architectural, and archeological.

During the construction process, erosion and sedimentation control measures will be implemented to avoid the discharge of sediments into road surfaces, sidewalks, and the storm sewer system during rainfall events. These will include installation of hay bales (or silt socks) on drainage structures, provision of a silt fence around the project limits, and implementation of a washout entrance for trucks to avoid sediments migrating into the streets. Staging and storage areas for construction materials will be protected by the silt fence, installed over a 0'-4" trench with stakes driven 0'-6" below. The short street in front of the old town hall, east of *Plaza Mariano Quiñones*.

will be used as staging area, as it would be at a reasonable distance between both plazas and in a space that would not significantly alter traffic. Construction equipment and materials will be stored outside both plazas, avoiding possible adverse impacts to the already paved surfaces. A Maintenance of Traffic Plan (MOT) and temporary control devices will be implemented to control vehicular traffic and provide a safe route for pedestrians during construction of the project. The MOT will be prepared in compliance with the PRHTA and FHWA standards and regulations. Streets, sidewalks, and plazas have been subjected to multiple interventions over the years. In contrast, this project proposes the removal of some surface elements and minimal excavations.

#### Streets, Gutters, and Sidewalks

1. Asphalt and "chinos de río" (pebble stones; stone pavement) will be removed using an excavator or jackhammer; when needed, by hand. The existing concrete slab will not be demolished. Debris will be transported off-site by dump truck to a preapproved location. Depth of stones to be removed: 0'-02". Area: 3,560 sq.mts.

#### Mariano Quiñones Plaza

- 1. Excavations for footings for the construction of the gazebo. Depth 1'-0" x 0'-6" x 53'-0'"; Area: 232 sq. ft.
- 2. Removal of the curved seats of the integral terrazzo benches. 18 sq. ft. per bench (8 benches = 144 sq. ft.)
- 3. Removal of mortar in the central area (not including the concrete slab that serves as a base). Depth: 2'-0"; Area: 100 sq. mts.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

#### Santo Domingo Plaza

- 1. Excavation to remove the central pavement strip running east/west. Depth: 0'-1.5" and Area: 925.6 sq ft.
- 2. Excavation for new foundations for the four (4) lighting posts: 1'-0" x 4'-0" = 4'-0"
- 3. Excavation for footings of the semi-circular benches/planter; 30 sq. ft.
- 4. Excavation for the footing of the pedestal clock: 10'-0" sq. ft.
- 5. Damaged bricks and marble slabs will be removed, without demolishing the concrete slab beneath. Removal of tree stump remnants in planters by grubbing.

#### **LANDSCAPING**

The existing vegetation, including trees, shrubs, and grass, will be preserved. The Municipality is committed to strengthening the plant material already on-site once the planters are rehabilitated. No excavation is contemplated for these purposes, except for planting. The Municipality of San Germán will require the

project contractors to present evidence of the legal disposal of debris and gravel. measures will be implemented to avoid the sediments to discharge into the road surface and storm sewer system during rainfall events, including installation of hay bales (or silt socks) on drainage structures, installation of silt fence around the project limit, and implementation of a washout entrance for trucks to avoid sediments migration into the streets.

The staging area for the construction equipment and materials will be located at Betances Street. Construction equipment and materials will be storage outside the plaza area, avoiding possible adverse impacts to the Plaza surface. Staging and storage areas for construction materials will be protected with silt fence. A Maintenance of Traffic Plan and temporary control devices will be implemented to control the vehicular traffic and provide a safe route to pedestrians during the construction works.

#### AREA OF POTENTIAL EFFECTS

As defined in 36 CFR §800.16(d), the area of potential effects (APE) is the geographic area or areas within which an undertaking may directly or indirectly cause changes in the character or use of historic properties if any such properties exist. Based on this definition and the nature and scope of the Undertaking, the Program has determined that the direct APE for this project is the area encompassed by the footprints of Plaza Santo Domingo, Plaza Francisco Mariano Quiñones, the street connecting both, the old city hall, and all surrounding streets and sidewalks. The APE

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	•

comprises 75,300 square feet. Total length is 815'-0". Width at Francisco Mariano Quiñones Plaza, Ruiz Belvis stretch and old city hall averages 110'-0". Width at Plaza Santo Domingo averages 90'-0". This is the viewshed of the proposed project. Mariano Quiñones Plaza is surrounded by Padres Agustinos street (to the north), Ruiz Belvis street (to the south), De la Cruz street (to the west), and a stretch of a street with no name in front of the former town hall (to the east). Santos (to the south), Yamil Galib street (to the east), and Carro street (to the west). The project includes the rehabilitation of both plazas, their surrounding streets, and sidewalks up to the area where they intersect, defined by brick pavement strips as illustrated and explained later. According to CRIM, Mariano Quiñones Plaza covers 9,577.2 square feet. Santo Domingo Plaza consists of two parcels: Parcel 334-034-032-01 occupies 3,827.8 square feet, and Parcel 334-034-033-01 occupies 3,325.3 square feet. However, the current area of this plaza exceeds the sum of the two parcels. In the past, a street ran between the two parcels. The street was eliminated, and its space was joined to both parcels to grant continuity to Santo Domingo Plaza, thus reaching its current size. No deed documents can be referenced reference because the Municipality of San Germán does not have them.

The APE considers repairs/Improvements of the Plaza Santo Domingo and Plaza Francisco Mariano Quiñones in the same location, the APE for visual effects is within the geographic and does not have the potential to introduce visual elements that diminish or alter the setting area of the project, including the landscape, where the setting is a character-defining feature of a historic property that makes it eligible for listing on the National Register. The visual effects of the APE for the repairs/Improvements of the Plaza Santo Domingo and Plaza Francisco Mariano Quiñones will be visible from all the NRHP-eligible and listed properties, given that the APE is within the NRHP Listed San Germán Historic District (Ref # 94000084) and the NR Eligible San Germán Centros Urbanos. The Visual or Indirect Areas of Potential Effect of the proposed project are not within the immediate physical footprint of the project. The consequences of the indirect APE will be during the construction phase only due to changes in aesthetics or disruptions to local transit that may extend beyond the project's physical boundaries. Access roads and staging areas will be coordinated to minimize the disturbance in the traditional urban center. The proposed design considers the urban scale in relation of the surrounding setting.

As the plazas are public spaces that serve as hubs for civic activities and provide resources to the community, the project is intended to enhance historical significance using some 21st century design strategies without compromising the traditional urban center and listed or eligible properties.


PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

# Identification of Historic Properties - Archaeology

The proposed project is within the Traditional Urban Center of San Germán. San Germán has a great number of archaeological sites and historic structures. The National Register of Historic Places nomination lists 152 resources contributing to the historic significance of the area, including among these Plaza Santo Domingo and Plaza Francisco Mariano Quiñones, where the proposed project will be located.

As per FEMA's Flood Maps, the project area is not within a flooding zone (official or advisory). The closest significant body of water is Río Guanajibo, 0.43 kilometers north of town. The Caribbean Sea lies 12.25 kilometers south.

Based on the U.S.G.S. Geological Map of the San Germán Quadrangle, Santo Domingo Plaza is located on Serpentinite (Unit KJs), a metamorphic rock. Conversely, the Francisco Mariano Quiñones Plaza lies over Mariquita Chert (Unit KJm), which is a hard, dense sedimentary rock. The geologic unit KJs consist of black, blackish-green, pale green, bluegreen, pervasively fractured and sheared rock made primarily of serpentine minerals. Vague outlines of pyroxene and olivine grains are in some specimens. Pyroxene grains are serpentinized in a characteristic boxwork texture and persist as bastite, displaying megascopic reflective surfaces of relict cleavage planes.






Figure 5. Web Soil Survey, National Cooperative Soil Survey (National Resources Conservation Service), 2023.

The Mariquita Chert (KJm) is yellowish-red, brownish-red or grayish-green, medium grained bedded chert with rare basalt and silicified limestone lenses. Subsoil explorations in nearby areas have been able to find both geologic formations in a residual, completely weathered state, stiff to hard consistency, reddish-brown to olive, silty clay with variable amounts of sand and severely weathered rock fragments. Explorations have also been able to find the presence of approximately 3 to 5 feet of man-made fill made of dark brown silty clay mixed with gravel and brick fragments. Fill layer shows medium to stiff consistency or medium dense to dense state, with Standard Penetration Tests showing N-values between 10 to 20 blows per foot (bpf).

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Existing information on previously identified historic properties has been reviewed to determine if any such properties are located within the APE of this undertaking. The review of this existing information, by a Program contracted Historic Preservation Specialist meeting the Secretary of the Interior's Professional Qualification Standards (36 CFR Part 61), shows that there are thirty-three (33) known archaeological sites or NRHP listed/eligible historic properties within a quarter-mile research radius of the APE. The result of this background research shows that out of these 33 known archaeological sites or NRHP listed/eligible historic properties, 33 are positive for historic materials. Out of these 33 historic properties, only one (1) has been positive for precontact materials (Antiguo Hospital de la Concepción, #28 in Table 1 and #4 in Table 3.

Table 1. Archaeological sites or NRHP listed/eligible historic properties within a quarter-mile research radius of the APE.

#	Name	SHPO id #	IPRC id #	Distance/ Direction	Description	NRHP (listed, eligible, non- eligible, no data)
1	Alcantarilla pluvial sobre la Quebrada Manzanares	SG0200008	No data	1,151 lft east	Partially underground pluvial system of the colonial era to collect the waters of Quebrada Manzanares and allow the extension of town to the south. area. More than two kilometers long, some areas can be traveled on horseback.	Listed
2	Casa de los Ponce de León	No data	No data	505 lft west	No data	Eligible
3	La Casona	No data	No data	91 Ift north	Former residence of Tomás Agrait Font. Built from 1856-1871, it hosted the social activities of the Círculo de Recreo around 1876. A ball was offered in 1903 in honor of Alice Roosevelt (daughter of Pres. Theodore Roosevelt) during her visit to San Germán.	Eligible
4	Plaza Francisco Mariano Quiñones	No data	No data	Within	Sits between San Germán de Auxerre Church and the old city hall. It was also the market square ( <i>Plaza de Viandas</i> ) until the beginning of the 20th century.	Eligible
5	Puente de Bolas	No data	No data	2,198 lft west	Located at Interamerican University Avenue (old Luna Street) west of town. Official and important visitors – governors, bishops - were formally received here in the past. It used to define the urban limit.	Eligible
6	Iglesia de San Germán de Auxerre	No data	No data	91 lft west	Built in 1739 to replace the old, ruined church built in 1570. It has undergone several renovations and restorations. In its central nave is suspended an impressive glass chandelier dating from 1869. Its altars are made of marble, and the ceiling is handpainted.	Eligible

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

#	Name	SHPO id #	IPRC id #	Distance/ Direction	Description	NRHP (listed, eligible, non- eligible, no data)
7	Museo Alfredo Ramírez de Arellano	No data	No data	656 lft southeast	Elegant example of early 20th century manor house architecture. Built in 1903 in masonry. It includes steel straps for seismic protection.	Eligible
8	Ruinas de la Casa del Componte Residencia Sanabria	No data	No data	449 Ift southwest	Once a two-story house with commercial lodging below, it was the local seat of the repressive political campaign known as the <i>Componte</i> of 1887, initiated by Governor Romualdo Palacios to suppress revolutionary opposition against Spain.	Eligible
9	Casa Morales	No data	No data	85 lft east	Singular Queen-Anne style residence, built in 1915. Located at the end of Ruiz Belvis Street, in front of Porta Coeli. Built by local master builder Juan Barón Capriles, for the family of Tomás Vivoni, after the design of Pedro Vivoni.	Eligible
10	Antigua Casa Alcaldía	No data	H-3	19 lft east	Built between 1839-1844, following prototypical local mayor's' offices under the Spanish government. City Hall functions were housed on the upper level and the District Jail was located on the first floor. In 1989, official functions were relocated at a new building on Interamerican University Avenue.	Eligible
11	Museo de la Farmacia	No data		13 lft south		Eligible
12	Estación del Tren	SG0200001 2	H-13	853 lft southwest	Built at the beginning of the 20th century for the San Juan-Ponce railroad line through Arecibo and Mayagüez. It was in operation until 1953. Today, railroad tracks and a teresina (track Inspection vehicle) remain.	Eligible
13	Casa Jaime Acosta y Forés	No data	No data	377 lft	Built between 1917-18 and designed by the master craftsman Luis Pardo for the landowner Jaime Acosta y Forés, this residence keeps intact and restored the best local examples of stenciling ("estarcidos") in Art Nouveau style in Puerto Rico.	Eligible
14	Casa Ramírez Roggio	No data	No data	276 lft east	Singular example of modernist eclectic architecture of the late 19th century, where the use of polychrome stained glass and wall painted murals stand out.	Eligible

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

#	Name	SHPO id #	IPRC id #	Distance/ Direction	Description	NRHP (listed, eligible, non- eligible, no data)
15	Teatro Sol	No data	No data	22 lft east	Founded in 1915 - 1920 and managed by its owner Don Jorge Quiñones, it sports an Art Deco façade that integrates Spanish "azulejos".	Eligible
16	Casa Juan Ortiz Perichi (Residencia Hamid Galib)	No data	No data	426 lft west	Built around 1920 and designed by architect Isidro Román. Contains examples of Puerto Rican architectural ornamental craftsmanship in wood by artisan Luis Pardo, and colored glass.	Listed
17	Casa Fernando Rivera Ufret	No data	No data	173 lft southeast	Designed by Don Pedro Vivoni in 1915.	Eligible
18	Plaza Santo Domingo	No data	No data	Within	Formerly a longitudinal park with trees and lawn, it was later pavemented. Includes benches, lighting, and busts of distinguished sangermeños. In times of Spain, bullfights were performed. here It was used to install "picas" and amusement machines during the patron saint's festivities.	Eligible
19	Iglesia Porta Coeli	No data	N 010001 3 H-1	Adjacent	Built in 1606-607 as a chapel of the Convent of Santo Domingo (demolished), it is the oldest religious temple outside San Juan and one of the best existing examples of colonial architecture and art in Puerto Rico. Its interior structure of columns and wood and tile roof is representative of Puerto-Rican construction of the XVII- XVIII centuries. Today it houses a museum of religious colonial art operated by the Institute of Culture of Puerto Rico. It serves as headquarters for important cultural activities.	Eligible
20	Tajea	No data	No data	No data	No data	Eligible
21	Casa de Francisco Mariano Quiñones.	No data	No data	994 Ift southwest	House of a Politician, abolitionist and writer, after whom tone of the two most important plazas of San Germán was named.	Eligible
22	Ceiba de la Libertad	No data	No data	652 lft north	Tree planted in commemoration of the establishment of the autonomous government of Puerto Rico in 1898, on the Cerro de la Libertad, north end of Esperanza Street.	Eligible

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	·

#	Name	SHPO id #	IPRC id #	Distance/ Direction	Description	NRHP (listed, eligible, non- eligible, no data)
23	Museo y Casa Estudio Aurelio Tió.	No data	H-26	495 lft west	Example of an urban residence of colonial architecture of the XIX century. Local historical figure Lola Rodríguez de Tió lived here before marrying Don Bonocio Tió. Her correspondence and literary works are preserved here.	Eligible
24	Casa Placita Tolín	No data	No data	419 Ift southwest	Typical construction for grocery stores in the first half of the 20th century.	Eligible
25	Logia Luz de las Lomas.	No data	No data	272 lft south	Built in 1912. Headquarters of the Freemasonry in San Germán. Gift of Don Tomás Pabón.	Eligible
26	Escuela Longfellow	No data	No data	1,459 lft southeast	First school for boys and girls built under the American regime in San Germán, erected shortly after the US invasion in 1898.	Eligible
27	Casa Francisco (Paco) Ramírez.	No data	No data	941 lft west	House of politician, abolitionist and writer Ramírez. The property later belonged to Quintín Ramírez de Arellano.	Eligible
28	Antiguo Hospital de la Concepción	No data	H-23	1,302 lft southwest	Built in 1850, Operated as a hospital until 1962.	Eligible
29	Universidad Interamericana	No data	No data	1,423 lft northwest	Founded in 1912 as a Polytechnic Institute by Reverend John W. Harris, in 1956 it became Inter-American University, the first one in Puerto Rico to be approved by the Middle State Association of Universities.	Eligible
30	Cuartel de la Milicia Española o Casa del Rey	No data	No data	836 lft northwest	Built in 1854. In 1922 it became a school named after Lola Rodríguez de Tió.	Eligible
31	House of José Martín Betancourt	No data	No data	Adjacent	The residence formerly belonged to. Joaquín Nazario de Figueroa and Juan Llaneras. It was also the office of Miguel A. García Méndez, Speaker of Puerto Rico's Legislative Chamber.	Eligible
32	Casa Vivoni	No data	No data	Adjacent	House of the Forés family, an illustrious family of San Germán. Benito Forés was an assemblyman and civic leader.	Eligible
33	Lola Rodríguez de Tió	No data	No data	No data	No data	Eligible

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Three (3) cultural resource surveys have been conducted within the quarter mile radius. Out of these surveys, zero (0) were positive for pre-contact materials, three (3) were positive for historic materials; and zero (0) were positive for both pre-contact and historic materials. See Table 2 below.

Table 2. Cultural Resource Surveys within the quarter mile radius of project area

#	Author	Phase/Title	Year	SHPO/IPRC code	Results	Distance/ Direction
A	Osvaldo García Goyco	IA-IB / "San Germán Siempre Galante "Revitalización del Distrito Histórico de San Germán, PR	1993	SG-90-02-03	Positive in calle Esperanza, calle Ruiz Belvis, calle Dr. Santiago Veve, calle Alfonso XII, calle Raul Mercado. Archeological supervision recommended.	Within APE.
В	Osvaldo García Goyco	Monitoría Arqueológica Proyecto de Soterrado, "San Germán Siempre Galante"	1993	No data	Positive, outside of the proposed project area.	Within APE.
С	Luis Pumarada- O'Neill, Miguel Cruz- Arocho	IA-IB / Study and Recommendations of the San Germán Vaulted Brick Tunnel Storm Water System	1988	14-08- 000001-G- 1249	Positive, outside of the proposed project area. There is a historic stormwater drainage system.	Within APE.

Eight (8) archeological studies have been conducted within the quarter mile radius. Out of these surveys, one (1) was positive for pre-contact materials, eight (8) were positive for historic materials; and one (1) was positive for both pre-contact and historic materials. See Table 3 as follows:

Table 3. Archeological studies within the quarter mile radius of project

i	#	Author	Phase/Title	Year	SHPO / IPRC code	Results	Distance Direction
	1	Osvaldo García Goyco	IA-IB "San Germán Siempre Galante". Revitalización del Distrito Histórico de San Germán, PR.	1993	SG-90-02-03.	Positive in Esperanza, Ruiz Belvis. Veve. Alfonso XII, and Raúl Mercado streets. Suggests archaeological Supervision.	Within
	2	Osvaldo García Goyco	Monitoria Arqueológica Proyecto de Soterrado, "San Germán Siempre Galante"	1993	No data	Positive	Within

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

#	Author	Phase/Title	Year	SHPO / IPRC code	Results	Distance Direction
3	Juan R. González Mendoza PhD, Historian, Osvaldo García Goyco, Doris Maza, M. Arch	US Dept. of the Interior NPS RECEIVED Jan. 25, 1994. NATIONAL REGISTER OF HISTORIC PLACES REGISTRATION FORM	1994	NFS Form 10- 900 : 0MBNo. 1(  J24- 0018) (Rev. 10-90)	San Germán Historic District	Within
4	Jaime Vélez	IA-IB – Hospital La Concepción, San Germán	2001	No data	Positive. Presence of historical/cultural resources and a deposit as a multi component pre-Columbian and colonial site and need of further studies.	397 meters SW
5	Adalberto Maurás	IA-IB – Residencia Alfredo Mercado y Sra., San Germán, PR.	2013	SG-13-11-01.	Result: positive. Recommendation: preservation of existing structures.	158 meters SW
6	Adalberto Maurás	II – Residencia Alfredo Mercado y Sra., San Germán, PR.	2014	SG-14-11-02.	Positive, excavation and photo documentation of s.XVIII house with most walls and foundations present. Recommends monitoring to ensure that no impact is caused to the historic structures.	158 meters SW
7	Eduardo Questell	IA, Fase II del soterrado de la Avenida Universidad Interamericana.	2007	SG-07-08-01.	Positive. Recommends monitoring during the work to ensure that no impact is caused to the historic structures.	76 meters south
8	Federico Freites	IA Casa Real Boutique & Spa., San Germán, PR.	2015	SG-15-11-05	Positive. Recommends monitoring during the work to ensure that no impact is caused to the historic structures.	80 meters south

# Possibility of archeological findings

Based on the results of previous surveys, the number of reported archaeological sites, and use history of the APE, low, medium, and high archeological potentials have been identified for the presence of cultural materials within it.

Because the city was established in its present location since the 1570s, certain areas of the urban core were identified as archaeologically significant in the 1993 Report by Osvaldo García Goyco "Survey de Recursos Culturales, Fase 1A, Fase 1B Parcial", submitted to the Municipality of San Germán, as part of the Project "San Germán Siempre Galante", Revitalización del Distrito Histórico de San Germán". Phase 1A was completed between June/July 1990, consisting of documents'

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

review. Phase 1B was completed between July/August 1990, consisting of site visits, visual inspections, and selective strata sampling to identify soil composition, textural qualities, size of particles, integrity, historical period, color, Munsell ID, and strata depth in centimeters. The materials recovered span a range of periods: prehistoric, historic, and modern. Regarding integrity, materials were classified as very adulterated, adulterated, slightly adulterated, virgin, sterile. The García Goyco report and the Archaeological Monitoring carried out in 1993 identify the existence of an underground layer of stones at the third strata where Carro and Santiago Veve streets intersect (0'-8.66") used formerly as street pavement. This condition was also documented at the street in front of the old City Hall.

The San Germán District Nomination for the National Register of Historic Places, 1994, authored by Juan R. González Mendoza, Osvaldo García Goyco, and Doris Maza Maza, acknowledges the archeological potential of the district and mentions areas of high, good, and little or no archeological potential. The nomination refers to an archeological study by Gus Pantel regarding the pavement at Santo Domingo Plaza. This study is not included in the nomination bibliography and could not be located at the consulted agencies. The García Goyco study results are quoted in agreement with the aforementioned areas of archeological potential.

## Areas of high archeological potential

The period prior to 1850 is absent in cartographical documentation. For both the Santo Domingo and Francisco Mariano Quiñones Plazas, the strata sampling documented in the Garcia Goyco report, did not reveal archeological material. As mentioned above, the 1990 strata sampling documented earlier street pavement in two locations: under the street in front of the old City Hall, when crossing to the main plaza, and at the intersection of Carro and Santiago Veve streets. The Garcia Goyco report asserts that the old City Hall was built on the site of an old hospital (Hospital de la Concepción, not at its current location) as revealed through document review, however the strata sampling did not reveal archeological findings beyond the earlier pavement.

Prior to the 1850s, most of the construction seems to have been centered along Ramas and Alfonso XII streets and a section of Esperanza and Manzanares streets, thus, this zone represents the area of the longest settlement in the history of San Germán's urban life.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

# Areas of medium archeological potential

Strata samples in other streets mentioned above also produced artifactual material from the 18th century, particularly majolica, as is the case of Manzanares

and Esperanza streets. There are other areas that could produce evidence of human habitation in the form of skeletal remains: the Atrium, interior and patio of the Parish Church, as well as the Porta Coeli Chapel. Parish death records show that until the early 19th century, parishioners were buried here.

Finally, within the proposed district, places were identified where the artifactual material places their habitational temporality to the nineteenth century or later, where remnants of earlier structures can still be found and where the archaeological context has barely been disturbed. This could be the case of those houses that were built on the ground without cellars, latrines or cisterns. With the placement of a sanitary water supply system, many of these features lost their usefulness and were then used as storage spaces or garbage dumps. Along José Julián Acosta Street and Dr. Veve Street (formerly Comercio), the artifactual material dates to the 19th century. Both locations have produced large quantities of animal bones that may be useful in establishing the location of the city's butcher shop, as well as other urban amenities, such as places to eat. In addition, sections of the vaulted storm sewer system that cross or flow into Veve and Manzanares Streets, where a hotel and three drug stores lay, have produced 19th century coarse creole pottery.

### Areas of low archeological potential

Carro Street, from Luna to Estrella Streets, and Veve Street, from Carro to Ramas Streets, have not yielded much archaeological material; they are, therefore, considered areas of low archaeological potential. Bedrock is close to the surface at this point.

#### Possibility of pre-Hispanic archaeological findings

From the analysis of the inventory of archaeological resources and the reports consulted, it emerges for the territory of the municipality in San Germán Historic District that only on one (1) instance, specific evidence of indigenous occupation has been found, and this one (1) instance is outside the APE. However, the absence or presence of pre- Hispanic archaeological material within the APE cannot be empirically determined. To carry out an archaeological sensitivity analysis of the APE, it is important to acknowledge that

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

San Germán was one of the places relevant to the early Spanish colonization period in Puerto Rico, therefore, a location where material elements that represent interactions between Spaniards and natives in the early period of the conquest and European colonization could be found.

# Summary

The artifactual material found in the above-mentioned archaeological surveys in the San German Historic District produced 16th to 17th century materials such as contact material, "transculturation artifacts" and colonial pottery; 18th century material, mainly pottery; and 19th century material such as earthenware, porcelain, bottles, glass, and animal remains (bovine, burgao shells, tortoise). The most recurrent element during the excavations were the colonial pavements of river stones. This finding corroborated the documentary sources that demonstrated that the streets in the center of town and the main square were, at one point, paved with river stones. Also documented were a cobblestone pavement of large slate stones, a rustic road in limestone, two small brick inlets, a compacted brick floor, two branches of the so-called tunnels, which are brick vaulted sewers and two possible stone curbs "sardineles". Also documented were the branches or small brick vaulted sewers that connected with the tunnel of the Quebrada Manzanares. The oldest pipes were made of vitrified clay. Early street pavements in cobblestones were documented from a depth of 4.7" to 6'11". In addition, during phase IA, IB, two sardineles of river stones were discovered in Carro and Dr. Veve Streets, although in general, these were built in brick, as were the sidewalks. The archaeological artifacts found corresponded mostly to colonial ceramics from the semi-refined earthenware assemblage, including "creamware", "pearlware" and "whiteware" ring styles, hand-painted floral, shell rim, transfer "ironstone" and "Mulberry Ironstone". Daily use artifacts such as bone brushes and spoons, majolica, whiteware and porcelain ointment knobs, animal skeletal remains, tiles, bricks, game artifacts such as bone dominoes and ceramic tokens, and metal cutlery were also documented. A peculiar fragment had as decoration a Puerto Rican coat of arms in white ware, elaborated with the transfer technique. The relative chronology of the ceramics in the sample obtained probably fluctuated between the 18th and 20th centuries. Many blown glass bottles made in molds were documented, some of medicine perfume and poisons from the 19th century, a Hiram Cod type soda bottle with an inner glass marble lid circa 1870's and blown glass liquor bottles made in molds from the 18th and 20th centuries.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Also, in the old movie theater (Teatro Sol) a large amount of material related to entertainment activities and advertising techniques, used during the second half of the 20th century, was found. It can be concluded that the proposed District has excellent possibilities to produce artifactual material related to the four hundred years and more of the city's history.

In the excavations in the historic center of San Germán it was expected that early artifacts associated with the first years of colonization could be documented, but this evidence was minimal; pearlware and whiteware of English origin dominated in practically all levels within the sewers and under the streets, including:

Historic sidewalks

Aqueduct segments from the colonial era

Archaeological material related to the different activities that took place in the square in the colonial era, for example, remains of a sugar mill.

The APE includes sidewalks and/or streets within a traditional urban center, with potential archaeological remains underneath these features, like historic pavements, historic drainage systems and historic lighting systems. Also, during the reconstruction process there's a possibility to find cultural layers associated with demolition and reconstruction due to disasters like fires, earthquakes, hurricanes etc. Is the possibility that the proposed project can expose foundations of old buildings along the street if realignment of facades was performed. The properties/streets that survive to the present are the most recent facade of the town, reminiscences of these properties. However, they give us an idea of the archaeological potential of the Plazas and its surroundings. They are vestiges of previous constructions, and under the floors of the plaza and its surrounding streets the potential for the presence of Spanish colonial archaeological sites is high. It is possible the existence of in situ nineteenth- century Euro-Spanish material remains in the APE.

#### San German Historic District

The San Germán Historic District encompasses an area of approximately 35.8107 acres. The city's layout presents an uneven grid pattern with streets oriented along the cardinal points. Its modern axis, Calle Luna (PR #102) bisects the east-

west grid. This was the old road that linked the Villa with the town of Sabana Grande and the city of Mayagüez. To the north, other important streets of the urban nucleus run: Santiago Veve (formerly Comercio) and Estrella Streets. Until the mid-19th century, the latter were the main boundaries of the city's organization chart,

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

expanding southward once the Manzanares Creek was controlled by the construction of vaulted storm sewers, completed in the 1850's. There is no clear distinction between residential and other areas, although in the past most of the main commercial establishments were lined along Luna, Santiago Veve and Ruiz Belvis streets. San Germán today has two main open spaces, Plaza Francisco Mariano Quiñones or main square (bounded by Carro, José Julián Acosta, Ruiz Belvis and Cruz streets), and the Plazuela de Santo Domingo (bounded by Carro, Santiago Veve, Ramas and Ruiz

Belvis streets). The importance of these sites to the overall appearance of the district and the layout of the city's design cannot be underestimated.

In Latin American cities, plazas fulfilled at least two functions. Squares were focal points for the distribution of urban space, in a coherent and hierarchical whole, where social and political activities were organized. The spaces around the main square were reserved for state buildings and ecclesiastical authorities. Thus, the parish church is located on the western edge of the Plaza Francisco Mariano Quiñones, while the Mayor's Office is located at the opposite end. Thus, the first ordinances of the city reserved the spaces around the plazas for the "well-bred" inhabitants and commerce. As there was no strict delimitation of areas within the heart of the old city, the plurality of functions, and its long period of continuous constitution makes the historic center a mixture of widely differentiated architectural styles ranging from early Spanish Colonial architecture, such as the Porta Coeli Chapel (1606), to Neoclassical, Neo-Gothic, and Queen Anne, among others. Interspersed with these structures, there are structures reflecting Spanish Revival and Art Deco, and structures of more recent construction characterized by a non-descript style.

Sixty percent of the buildings within the San Germán Historic District contribute as resources for inclusion in the NRHP. Approximately 50% of the contributing resources were built between the 1860s and 1920s, a period characterized in Puerto Rico's urban and architectural history as one of intense development and experimentation. Most of them are built with traditional materials, such as masonry, brick and wood, while in the early 20th century there was an increased use of new materials, such as concrete, particularly since the earthquake of 1918 and the severe hurricanes that occurred between 1899 and 1930.

The architectural vocabulary is very broad. The general character of the core has not undergone serious alterations in terms of street layout and the ratio of open public spaces to build area. Although new structures have altered the physiognomy, enough buildings remain to maintain its historic appearance. Finally, as noted above, the visual and spatial sense derived from the urban core remains

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

one that presents coherence and architectural value unique to San Germán. In the late 18th and early 19th centuries, the city had two main open spaces. One was the Plaza del Rey, the other was the Plaza Principal which has been known as Plaza Mayor, Plaza Principal, Plaza Vendimia, Plaza Automática, Plaza General Contreras, and today, Plaza Francisco Mariano Quiñones. It seems that before the construction of the Mayor's Office in 1844, the Plaza was much larger and extended as far as the Porta Coeli Chapel, while today, the old Government Building and Carro Street divide this area into two unequal open spaces.

Public open spaces are crucial to the urban character of the San Germán Historic District, as they lend coherence to the urban grid and present the viewer with an unobstructed view of some of the city's most significant buildings. The Plaza served a crucial commercial function for the small retailers of goods gathered there for the Sunday market. Efforts to improve the streetscape that characterized the second half of the 19th century included the leveling of the plaza, repair work on the surrounding streets and sidewalks.

On the other hand, the placement of "chinos de río", pebbles as paving in the plaza was approved in 1851, and gas lighting was installed in 1860. By 1890 the plaza had undergone other alterations, perhaps the most important of which was the transfer of the Sunday

market to the Little Plazuela Santo Domingo, behind City Hall. As a result of the modifications to the city plan, the two main open spaces became three, as the Plazuela Santo Domingo took shape after the construction of Alcaldía y Carro street. This small rectangular plaza was once part of the main square. At the end of the 19th century, it replaced the main square as the city's Sunday market. The Plazuela became the park filled with trees and shrubs that contrasted with the plaza.

Plazas used to be reserved for public gatherings and collective affairs, while places like the Plazuela were dedicated to activities of a more individual nature sitting on benches, strolling, reading or just relaxing. The close relationship between the Catholic Church and the State, which characterized the Spanish period, and symbols of political and ecclesiastical authority dominate one or more sides of the plazas. In the Plazuela Santo Domingo, the outstanding building is the Chapel of the former Dominican Convent, while the Cabildo and the Parish Church face across the main square, and the Hospital de la Concepción and the Casa del Rey were built facing one side of the former Plaza del Rey.

In a sense, the same pattern prevailed during the first decades of the United States government. Thus, public schools replaced some of the symbols of the Spanish

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

colonial past in key spaces facing one or more of the city's open areas. In San Germán, the Rafael García Cabrera Public School replaced the old Casa del Rey. In the investigations performed by Adalberto Maurás (2011) for the project "Lajas - San Germán Potable Water Transmission System Expansion", two areas were identified positive for the presence of cultural remains including human remains. If so, it would corroborate the presence of the ancient cemetery in this area.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT
PORTFOLIO FOR GROWTH (IPG)
Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

Case ID: PR-CRP-000876

City: San German

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano

#### HISTORICAL CARTOGRAPHY AND PHOTOGRAPHIC RECORD OF THE APE





Figure 6. Sketch of the town of San Germán executed by Commander Captain José de Elola y Gutiérrez, 1888, Fondo del Mapa Militar de la Isla de Puerto Rico. Topographic Commission of 1888-1889-1891-1892. Original scale 1:5000.

https://archivonacional.com/ISAD\_G.aspx?ID=?enc=fSJkK2MW9Ybx3127WQ8mKPYpqxnwFOsRM3/b6gQrdNo=



Figure 7. The village of San Germán, as drawn by French naturalist Auguste Plée, ca. 1821. At left, the church of San Germán de Auxerre and the open space that would become Plaza Mariano Quiñones. At the right, Porta Coeli Convent; Plaza Santo Domingo seems "edited" by the artist. In 1821, the San Germán square was a large esplanade of land bordered on the west side by the San Germán de Auxerre Parish Church and on the east by the Porta Coeli Convent. Between 1848-53 this large square was divided in two by Carro Street, which runs from north to south behind the Old City Hall. This is how the Plazuela de Santo Domingo came into being. On March 11, 1853, Martin Albertucci presented to the town council a plan to join the square with Carro Street, but it was not a street for cart traffic but a pedestrian street because it was in the form of stairs. By 1970, given the increase in the flow of vehicles, the stairs were eliminated and the street that leads from Carro Street, on the north side of the Old City Hall, which was baptized as José Julián Acosta, now Padres Agustinos Street.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	



**Figure 8.** "Street View in San German, with Natives in the Foreground, and the Old Dominican Monastery, Nearly 400 Years Old, in the Background", **photo and caption from** "The Story of Beautiful Porto Rico by Pen and Camera", **Charles H. Rector, photographs by Wilbur F. Turner**, Laird & Lee, Publishers, **Chicago**, **1898**, **page 51**.



Figure 9. "The Plaza of San Germán on Market-Day"" photo of Plaza Francisco Mariano Quiñones and caption from "A Recent Campaign in Puerto Rico" by Karl Stephen Herrman, Boston, Massachusetts,1907, page 39, with copyright from 1899. City Hall lies in the background (East).

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	




Figure 10. Map of San Germán, 1910. Manuscritos de William H. Armstrong, vol. 10, p. 31. http://bibliotecadigital.uprrp.edu/cdm/singleitem/collection/william/id/2. For decades, two distinct spaces - a park and a plaza - were unified into homogenized plazas with paved surfaces. During the late 19th and early 20th centuries, both spaces, initially lit by gas and later by electricity, served as focal points for social gatherings and public events. Santo Domingo and Mariano Quiñones plazas were also places for leisure, landscaped in the style of the English "square" popular in Europe at that time. Streets were paved, further enhancing their urban character. In the heart of Mariano Quiñones Plaza, once adorned by two towering trees, a transformation occurred in the 1960s: the trees were replaced with a brief- lived low fountain. Positioned on a slope like the plaza itself, the fountain had water pooling at its lower end, rendering the upper section dry and preventing the pump from functioning effectively. To safeguard pedestrians from vehicular traffic, low brick walls were subsequently erected near some of the planters




Figure 11. Plaza de Recreo/Plaza de las Viandas, until 1900 known as Plaza General Contreras, when it was renamed to honor Francisco Mariano Quiñones. Market days were held on Sundays. View from west to east, San Germán de Auxerre church in the background. https://www.circuloderecreo.org/Historia/Foto.htm

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	




Figure 12. Aerial photo, 1936 Photogrammetry, Puerto Rico Department of Transportation and Public Works (DTOP). Original scale: 1:18,000.



Figure 13. San Germán, Puerto Rico, 1930; photo by Luis Toro. Francisco Mariano Quiñones Plaza, including trees, lampposts, and benches, surrounded by paved roads.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	



Figure 14. Plaza de Santo Domingo Postcard, 1930; photo of Luis Toro. <a href="https://www.gettyimages.com.mx/fotos/san-german-puerto-rico">https://www.gettyimages.com.mx/fotos/san-german-puerto-rico</a>.




Figure 15. Aerial Photo, 1951. Photogrammetry, Puerto Rico Department of Transportation and Public Works (DTOP).

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	




Figure 16. Aerial Photo, 1986. Photogrammetry, Puerto Rico Department of Transportation and Public Works (DTOP).



Figure 17. Visual APE over 2023 Aerial Photo.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	




Figure 18. Aerial Photo, 2023, showing APE's quarter-mile radii.




Figure 19. Topographic Map showing APE's quarter-mile radii.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

#### Identification of Historic Properties - Architecture

Existing information on previously identified historic properties has been reviewed to determine if any such properties are located within the APE of this undertaking. The review of this existing information, by a Program contracted Historic Preservation Specialist meeting the Secretary of the Interior's Professional Qualification Standards (36 CFR Part 61), shows that the project area project area is within the San Germán Historic District and San Germán's Traditional Urban Center, which is larger than the listed district itself. The district was added to the National Register of Historic Places in 1994 and contains more than 100 significant buildings, including the Church San Germán de Auxerre and the Convento de Porta Coeli.

#### IDENTIFICATION OF HISTORIC PROPERTIES - ARCHITECTURE

Existing information on previously identified historic properties has been reviewed to determine if they are located within f this undertaking. The review of this existing information, by a Program contracted Historic Preservation Specialist meeting the Secretary of the Interior's Professional Qualification Standards (36 CFR Part 61), shows that the project area is within the boundaries of the NRHP San Germán Historic District. (See Figures 18 and 19.) Archival research activities were undertaken at the PRSHPO and the IPRC to identify previously recorded architectural resources in the project site. An architectural survey of the project area is currently being undertaken by the Puerto Rico State Historic Preservation Office (PRSHPO) and in 1983, the Colegio de Arquitectos de Puerto Rico (CAPR) completed a Survey and Documentation Project for PRSHPO embracing key spaces, buildings and architectural features in San Germán. To currently ascertain the historic context of the Municipality of San Germán and the project's location, several architectural windshield surveys were carried out in 2023 and 2024. In addition, key written references were consulted, as well as some of the archaeological survey reports.

### DESCRIPTION OF THE HISTORICAL DEVELOPMENT OF BOTH PLAZAS

The town of San Germán is known as the "Ciudad Fundadora de Pueblos" in recognition that multiple municipalities detached from the old San Germán District in the 18th century, when only the San Juan District existed on the Island. Therefore, this settlement is traditionally associated with the initial development of Puerto Rican identity. Simultaneously, the town boasts another nickname: "The City of Hills." This is due to its location on the hills southwest Puerto Rico, a topographic condition that partially dictated the elongated, longitudinal shape of both plazas, situated atop the crests of its hills.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Santo Domingo Plaza can be considered an atrium for one of Puerto Rico's oldest buildings, the *Porta Coeli* church, founded and managed in early Spanish colonial times by the Order of Preachers. The Dominican friars built a convent adjacent to this temple, but only a fragment of said convents' walls remains. The chapel's elevated location and shape make of it a hierarchical presence in Santo Domingo Plaza's. Between one plaza and another, the building that was once the city's town hall stands.

To the west of Mariano Quiñones Plaza rises the church dedicated to the town's patron saint, San Germán de Auxerre. Also built on a set of steps like *Porta Coeli* - but in contrast to its austere facade - the Church of San Germán boasts a facade consonant with Renaissance canons, displaying classical vocabulary and details in a composition that evokes the triumphal arches and temples of Imperial Rome.

In its early days – and for many years – streets around both plazas were finished in compacted earth and surrounded by dwellings of the settlement's affluent "vecinos". This is attested by historian Aida R. Caro de Delgado in her book "La Villa de San Germán: Its Rights and Privileges During the 16th, 17th, and 18th Centuries" (ICP, 1962). It was common for residents - dedicated to the cultivation of sugarcane and primarily coffee – to dry the beans of this stimulant in the open air in these plazas.

As Puerto Rican colonial society became more sophisticated, interest in "ornato público" as a mirror of progress promoted the beautification of the town's most important spaces. By the end of the 19th century, Mariano Quiñones Plaza was paved and provided with characteristic urban furniture of the period, including a gazebo. In contrast, its counterpart was then a green, tree-filled space known as Santo Domingo Park.

Even today, many San Germán residents still refer to this plaza as "el parque," even though in the 1960s, Ricardo Alegría, then director of the Puerto Rican Culture Institute, chose to cut down its trees and pave it with brick to endow it with a more Spanish-colonial flavor, the character that (despite some changes) it has retained to this day. See Figure 15. The drawing suggests that for this phase, Alfonso XII street, which previously divided the park into two areas, was paved over. Alegría's project granted continuity to the space.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT
PORTFOLIO FOR GROWTH (IPG)
Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

Case ID: PR-CRP-000876

City: San German

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano




Figure 20. Schematic Drawing of Santo Domingo Plaza designed by architect Eladio López Tirado in cyanotype (blueprint) dated May 1, 1959).

What for decades were two complementary but different spaces - one a park and the other a plaza - was lost by homogenizing both as plazas with hard pavement. At the turn of the 20<sup>th</sup> century, the park/plaza binomial as an urban spine characterized important towns on the Island such as Arecibo, Mayagüez, Yauco, and Ponce. The theme is addressed by architect Héctor Arce in "Notes on the Plaza and the Public Surroundings: An Interpretation Two Interventions" (Plástica Magazine, September 1986) and by architect/historian Jorge Rigau in "Puerto Rico 1900: Turn-of-the-Century Architecture in the Hispanic Caribbean" (Rizzoli, 1992). During the turn of the 19th and 20th centuries, both spaces were illuminated, first with gas and then by electricity. Santo Domingo and Mariano Quiñones became places for social gatherings, hosting public events, and as places of leisure.

The spaces were landscaped, influenced by the English "square" popular in European landscaping at the time. By this time, the streets were paved. In the center of Mariano Quiñones Plaza, two immense trees once grew, but were cut down in the 1960's and replaced by a low fountain that was in operation only a short time. It was located on a slope (like the plaza itself), causing water to accumulate at the lower section, remaining dry at the upper section, without allowing the pump to operate. Citing the need to protect pedestrians from cars, low brick perimeter walls were built next to some planters. These remain. See Figure 16. Plans here quoted are filed in the Western Regional Headquarters of the Puerto Rican Institute of Culture. There are also, undated - from the second half of the 20th century - plans by Architect Miguel A. Carlo for various improvements to Francisco Mariano Quiñones Plaza, some of which were not built. See Figure 17.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT
PORTFOLIO FOR GROWTH (IPG)
Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

Case ID: PR-CRP-000876

City: San German

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano




Figure 21. Undated blueprints [cyanotypes] by consulting engineers E. García Molina & Associates illustrating layout for the fountain at center of Francisco Mariano Quiñones Plaza, from the archive at the Western Regional Headquarters of the Puerto Rican Institute of Culture.




Figure 22. Undated blueprints [cyanotypes] from the second half of the 20th century of plans by Architect Miguel A. Carlo for various improvements to be executed at Francisco Mariano Quiñones Plaza.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

In the 1980s, both plazas underwent changes that remain today, including brick floors and borders, iron and wood benches, and colonial-style streetlamps. This "Underground/Urban Furniture Project" was developed under Mayor Jorge Alberto Ramos Comas, and the design was reviewed by Architect Doris Maza and surveyor Nelson4, as evidenced in cyanotypes at the archive of the Puerto Rican Institute of Culture. See Figure 18. By that time, the surrounding streets were finished in concrete and/or asphalted. Parallel to the designation as a historic zone of the sector, the streets were paved to evoke the "ancient/historic", paving using river pebbles ("chinos de río") and incorporating brick bands between these as a pattern accent. Mariano Quiñones Plaza was repaved with mortar imitating "losa canaria" and volcanic stone. A central grass area and a small sales kiosk were included.

In 1994, the historic district of San Germán was incorporated into the National Register of Historic Places of the United States Department of the Interior, increasingly highlighting the historical/architectural/urban importance of the urban ensemble. At the beginning of the 21st century, as an initiative of the "Directoría de Urbanismo" then operating island-wide, marble plaques with historical/foundational data of San Germán were incorporated into Santo Domingo Plaza. In 2023, the city celebrated its 450th anniversary, and the rehabilitation of both plazas underscores the extended life of the population and its "will to continue being here." The proposed project aims to echo past experiences as well as look forward to the town's future life.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

Case ID: PR-CRP-000876

City: San German

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano





Figure 23. Two plans from "Proyecto de Soterrado - Amueblamiento Urbano" developed under Mayor Jorge Alberto Ramos Comas, reviewed by Architect Doris Maza and surveyor Nelson Pagán, from cyanotypes at the archive of the Western Regional Headquarters of the Puerto Rican Institute of Culture

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Table 4. Properties listed in the National Register of Historic Places for San Germán.

NOTE: Descriptions are included as they appear on the register's website:

	Name and number	Date listed	Location (all included within the ¼ mile and the visual APE)	Barrio	Description
1	Jaime Acosta y Forés Residence #90000767	May 24, 1990	70 Santiago Veve St.	Pueblo	Vernacular criollo house, 1917.
2	Alcantarilla Pluvial sobre la Quebrada Manzanares #9000552	April 12, 1990	From the junction of Ferrocarril & Esperanza streets to the junction of Javilla & Ensanche streets.*	Pueblo	Brick and rubble storm sewer system built in 1835 spanning subterranean length of Manzanares Creek under San Germán.
3	Casa de los Ponce de León #83002295	March 9, 1983	13 Santiago Veve St.	Pueblo	Possibly the oldest single-family residence in PR, historically owned by the Ponce de León family and Associated with poet and abolitionist Lola Rodríguez de Tió.
4	Church of San Germán de Auxerre #84000461	Dec. 10, 1984	De la Cruz St.	Pueblo	Historic church built in 1688, famous for its well-preserved altar and religious imagery.
5	Convento de Porta Coeli #76002252	Sept. 8, 1976	Plaza Santo Domingo	Pueblo	Historic chapel of the former Santo Domingo de Porta Coeli Dominican Convent from 1609; one of the oldest church buildings in the Western Hemisphere.

<sup>\*</sup> Also locally designated as "Túneles de San Germán, by the Institute of Puerto Rican, registered as of Dec 2022 list (2000-(RO)-19-JP-SH). In addition, San Germán's Historic Zone is listed by the ICP (93-56-0002-JP-ZH).

In addition, San Germán Historic District was listed on February 16, 1994, #94000084 and described as follows: "Colonial historic center of the town of San Germán, founded as Nueva Salamanca by Spanish settlers in 1573, making it the second oldest European-established settlement in the island after San Juan. In addition to its contributing properties, it contains more than 100 architecturally and historically significant buildings, many of which date to at least 1606."

In the municipality there are seven (7) properties listed in the NRHP. Properties #2, #6, and #7 are not visible from any of the two plazas to be rehabilitated. Properties #4, and #5, San Germán de Auxerre Church and Porta Coeli (what remains of the former convent), respectively, are the two most important, hierarchical buildings within the proposed project's area. Property #1 is partially visible 400'-0" linear feet away from Porta Coeli, alongside Santiago Veve street.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Historic properties were documented in 1983 by a Survey and Planning Study carried out in San Germán by the Colegio de Arquitectos de Puerto Rico, under the auspices of the Puerto Rico State Historic Conservation Office. When in 1994 PRSHPO carried out a "Photographic Survey of Historic Properties in Urban Centers in Puerto Rico", San Germán was not included. Throughout time, properties around both plazas have retained their historic character; time has added more value to them as an urban whole. In that sense, now, most properties surrounding the pair of open spaces are contributing components and eligible for inclusion in the National Register of Historic Places.

As such, they embody key considerations of integrity of location, design, setting, materials, workmanship, feeling, and association. These properties can also be associated to an important historic context by meeting at least one of four (4) established criteria for consideration by the National Register of Historic Places, reproduced here verbatim:

Criterion A: Association with events that have made a significant contribution to the broad patterns of our history.

Criterion B: Association with the lives of persons significant in our past.

Criterion C: Properties that embody the characteristics of a type, period, or method of construction; represent the work of a master; possess high artistic values; and represent a significant and distinguishable entity whose components may lack individual distinction

Criterion D: Properties that have yielded, or may be yield, information important about prehistory or history.

The historical, archaeological, and architectural information provided in this document supports the above stated.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

#### Determination

As mentioned before, the project is situated within an NRHP-Eligible Historic District and is within the NR Eligible Traditional Urban Center, and when considering architectural and archeological elements both individually and together, their importance from historical point of view is undeniable. These plazas are eligible under Criterion A and Criterion C. The Mariano Quiñones and Santo Domingo Public Squares have been the center of commercial and civil activity since the 18th century and is an integral part of the identity and history of the municipality and the region. In archaeological terms, given the past experiences with previous construction projects in traditional urban centers in Puerto Rico, it is known the sensitivity of these areas in terms of archaeological findings. For these reasons, the potential of finding previously unidentified archaeological resources with integrity within the project area is very high; it would be necessary to conduct archaeological monitoring of all ground disturbing activities and excavations occurring within the APE.

The project will have no adverse effect on the built environment and the traditional urban center visually since the proposed design will reflect an architectural language from the 21st century and does not mimic architectural features from eligible and historical properties adjacent to APE. The proposed design will not enhance a false sense of history and historical responsible design strategies have been considered to produce a contribution of the 21st century to the Utuado traditional urban center. The placement of the new construction and features considers historical evolution of the plaza as so not to modify or differ from what has been typical for the APE.

The following historic properties have been identified within the APE:

- Direct Effect: Plaza Santo Domingo and Plaza Francisco Mariano Quiñones.
   Archaeological resources might also be directly affected, but this will be determined after carrying out the recommended archaeological Supervision & Monitoring to address the inadvertent discovery of cultural materials and human remains, accompanied by desk-based research.
- Indirect Effect: Customary construction quotidian inconveniences for citizens may occur. However, mitigation measures will be implemented. In addition, preparation of a Protection and Preservation Plan for several properties is recommended below.

Based on the results this project's efforts to identify historic properties, the Program has determined that project actions will not adversely affect the historic properties that compose the Area of Potential Effect. For this reason, a No Adverse Effect determination is appropriate for this project if the recommendation to carry an archaeological Supervision/Monitoring with a plan of inadvertent discovery of cultural materials and human remains is followed.


PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination	GOVERNMENT OF PUERTO RICO	
Subrecipient: Municipality of San German		
Case ID: PR-CRP-000876	City: San German	
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano		
Recommendation (Please keep on same page as SHPO Staff Section The Puerto Rico Department of Housing requests that the Puerto the following determination is appropriate for the undertaking □ No Historic Properties Affected □ No Adverse Effect Condition (if applicable): An archaeological with a plan of inadvertent discovery of cultural materials and hu □ Adverse Effect	Rico SHPO concur that g (Choose One):	
Proposed Resolution (if appliable		
This Section is to be Completed by SHPO Staff Only		

The Puerto Rico State Historic Preservation Office has reviewed the above		
information and:		
☐ <b>Concurs</b> with the information provided.		
□ Does not concur with the information provided.		
bocs not concar with the information provided.		
Comments:		
Carlos Rubio-Cancela		
Carios kudio-Cariceia	Date:	
State Historic Preservation Officer		

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	


### MAPS

Figure 24. Visual APE over 2023 Aerial Photo.




PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Figure 25. Aerial Photo, 2023, with Previously Recorded Cultural Resources




PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Figure 26. USGS Topographic Map with Previously Recorded Cultural Resources




PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Figure 27. - Aerial Map with Previous Archaeological Investigations



PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	


Figure 28. Web Soil Survey, National Cooperative Soil Survey (National Resources Conservation Service), 2023.



PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	


#### **SCHEMATIC PLANS**

Figure 29. Existing Conditions Survey Plan for Plaza Francisco Mariano Quiñones.




PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Figure 30. Existing Conditions Survey Plan for Plaza Santo Domingo.




PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Figure 31. Grading Plans for Plaza Francisco Mariano Quiñones and Plaza Santo Domingo




PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Figure 32. Site Plan for Plaza Santo Domingo.




PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Figure 33. Plan, sections and elevations West flank of Plaza Santo Domingo




PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	<u>.</u>

Figure 34. Plan, sections and elevations East flank of Plaza Santo Domingo.




PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Figure 35. Existing Conditions and Interventions at Plaza Francisco Mariano Quiñones.



PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Figure 36. Site Plan of Plaza Francisco Mariano Quiñones.



PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	

Figure 37. New Gazebo at Plaza Francisco Mariano Quiñones.




Figure 38. Properties within the Indirect/Viewshed APE (Plaza Francisco Mariano Quiñones)



Image	Parcel or Lot No./Coordinates	Address	Name (if any)	Approx. Constr. Date	NRHP Status/ NRHP Eligibility	
Name and Address of the Control of t	Lat:18°4'56' N Lon:67°2'36''W	#19 Calle José J. Acosta (Padres Agustinos), San Germán, Puerto Rico, 00683.	Casa de las Bahr	1851	Eligible	
	Photo #1 USE: Former residence. Empty No historic properties affected.					
0 23°NE(1) ● 18°4′56°N, 67°2′35′W±32ft 4 218ft	Lat: 18°27'9''N Lon:67°2'35"W	3		XXth century	Non eligible	
	<b>Photo #2</b> USE: COMMERCIAL/Co No historic propertie	'				

NW NE NE 0.7°N(T) ● 18°4 56°N 67°2°35°W ± 16/t ▲ 214/t	Lat: 18°4'56''N Lon:67°2'35''W	#22 Calle José J Acosta (Padres Agustinos), San Germán, Puerto Rico, 00683.	Teatro Sol	1930's	Eligible
	Photo #3 USE: COMMERCIAL/ TI No historic propertie				
NW N NE E  O 15°N (T) ● 18°4′55°N 67°2°34°W±16ft ▲ 209ft	Lat: 18°4'55''N Lon:67°2'34''W	#23 Calle José J Acosta (Padres Agustinos), San Germán, Puerto Rico, 00683.		Late 19 <sup>th</sup> century	Eligible
10 1 - 700 M 100 M	Photo #4 USE: Former residence. No historic propertie				
NW N NE 60 11°N (T) № 18°4′55°N 67°2′33°W ±16ft ▲ 210tt	Lat: 18°4'55''N Lon:67°2'33''W	#25 Calle José J Acosta (Padres Agustinos), San Germán, Puerto Rico, 00683.	BLACK BELT FITNESS CENTER	19 <sup>th</sup> century	Eligible
S CO	Photo #5  USE: COMMERCIAL/Sports Gym  No historic properties affected.				
NW NE NE O 8°N (T) ■ 18°4′55′N 67°2′33′W ±16ft ± 185′t	Lat: 18°4'55''N Lon:67°2'33''W	,		Turn of the 20 <sup>th</sup> Century	Eligible
	Photo #6 USE: RESIDENCE No historic propertie	es affected.			
O 181'S (1) ● 18'4 56'N € 7'72'36'W ± 16ft ▲ 233th	Lat: 18°4'56''N Lon:67°2'36''W	Calle Ruiz Belvis, San Germán, Puerto Rico, 00683	Oficina de Arte y	1930's	Non eligible

Photo #7

USE: COMMERCIAL

No historic properties affected.

SE SW W  0 180°S (T) ● 18°4 56°N, 67°2°25°W ±16ft ▲ 231ft	Lat: 18°4'56''N Lon:67°2'35''W	Calle Ruiz Belvis, San Germán, Puerto Rico, 00683.	San Germán Christian Academy	Turn of the XXth century Remodeled mid- XXth century	Eligible	
	Photo #8 USE: COMMERCIAL/ Sc No historic properties					
© 181°S (T)	Lon:67°2'35''W	Calle Ruiz Belvis (44c calle Félix Arce Lugo) San Germán, Puerto Rico, 00683.	El Cubujón	Late XIXth c	Eligible	
	Photo #9 USE: COMMERCIAL No historic properties affected.					
SE 19 5W 20 183°S (T) ● 18°4'55°N, 67°2'34°W ±16ft ▲ 206ft		#14, Calle Ruiz Belvis, San Germán, Puerto Rico, 00683		XIXth century	Eligible	
	<b>Photo #10</b> USE: COMMERCIAL. No historic propert	ies affected.				
SE \$ \$W • 187*S (1) • 18*4*56*N, 67*2*34*W±16ft ▲ 206ft		Calle Ruiz Belvis, San Germán, Puerto Rico, 00683.		1950's	Non eligible	
GYCAL MENICA DE PROPERTO	<b>Photo 11</b> USE: MUNICIPAL GO No historic propert		ES .			

# PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) GOVERNMENT OF PUERTO RICO Section 106 NHPA Effect Determination Subrecipient: Municipality of San German

<b>Case ID:</b> PR-CRP-000876				City:	San German	
Project Name: Plaza Santo Do	mingo and Plaza Frai	ncisco Mariano				
9W NW N 0 2772"W (T) ● 18*4*96*N.67*2*36*W ±16ft ▲ 211ft	Lat: 18°4'56''N Lon:67°2'36''W	Calle De La Cruz, San Germán, Puerto Rico, 00683.	lglesia San Germá Auxerre	in de	1688	Eligible
	<b>Photo #12</b> USE: RELIGIOUS No historic propert	ies affected.				
NE SE	Lat: 18°4'56''N Lon:67°2'34''W	Calle Ruiz Belvis, San Germán, Puerto Rico, 00683.	Antigu Casa Alcaldi		1842	Eligible
So German	Photo #13 USE: MUNICIPAL GO No historic propert	OVERNMENT OFFICES ies affected.				
9 274*W (T) ● 18*4*55*N, 67*2*34*W ±18/th ▲ 215/th	Lat: 18°4'55''N Lon:67°2'34''W Photo #14 USE: PUBLIC SPACE No historic properties affected.	Calle Ruiz Belvis, San Germán, Puerto Rico, 00683.	Plaza Franciso Mariano Quiñon (Vista a Oeste).	es I	N/A	Eligible
NE E SE S S S S S S S S S S S S S S S S	Lat: 18°4'56''N Lon:67°2'37''W	Calle Ruiz Belvis, San Germán, Puerto Rico, 00683.	Plaza Franciso Mariano Quiñon (Vista a Este).	es	N/A	Eligible
San German 00 Dec 2020, 15 25 de AST	Photo #15 USE: PUBLIC SPACE No historic propert	ies affected.				

- 1	.at: 18°4'56''N	Calle Ruiz Belvis, San Germán, Puerto Rico, 00683.	Plaza Francisco Mariano Quiñones (Vista al Este).	N/A	Eligible
San Germán	rhoto #15 ISE: PUBLIC SPACE No historic properti	es affected.			·

Figure 33. Properties within the Indirect/Viewshed APE (Plaza Santo Domingo)



Image	Parcel or Lot No./Coordinates	Address	Name (if any)	Approx. Constr. Date	NRHP Status/ NRHP Eligibility
N NE	Lat: 18°4'55''N Lon:67°2'32''W	#22 Esquina Calle Carro (Al Este), Calle Ruiz Belvis, San Germán, Puerto Rico, 00683.	Farmacia Martín	XIXth century	Eligible
	<b>Photo #1</b> USE: COMMERCIAL / No historic propert	_			
0 8°N (1) ● 18°4′55″N, 67°2′32″W±114ft À 333ft	Lat: 18°4'55''N Lon:67°2'32''W	#26 Calle Ruiz Belvis, San Germán, Puerto Rico, 00683.	Farmacia Martín Annex	XIXth century	Eligible
Paus Sarito Domingo 64 Dec 2022 6 Gall 7 Act	<b>Photo #2</b> USE: COMMERCIAL / No historic propert				
NW N NE E 0 9°N (1) ■ 18°4′55°N, 67°2′31°W ±16ft ▲ 182ft	Lat: 18°4'55''N Lon:67°2'31''W	Calle Ruiz Belvis,	Empty lot	N/A	N/A
The same of the sa	<b>Photo #3</b> USE: EMPTY LOT No historic propert	ies affected.			

				aley: our der	
Project Name: Plaza Santo I	Domingo and Plaza F	rancisco Mariano			
NW 3 NE NE 0 5°N (T) ■ 18°4 55°N 67°2'31°W ±16ft ▲ 177ft	Lat: 18°4'55''N Lon:67°2'31''W	#12 Esquina Calle Raúl Mercado (al Oeste), Calle Ruiz Belvis, San Germán, Puerto Rico, 00683.		1950's	Non eligible
-8 8	Photo #4				
Santo Domingo. On Decisión 1998	No historic prop				
NW NE NE 0 5°N (T) © 18°4′55°N, 67°2′30°W ±32ft A 200ft	Lat: 18°4'55''N Lon:67°2'30''W	Esquina Calle Raúl Mercado (al Este), Calle Ruiz Belvis, San Germán, Puerto Rico, 00683.	Empty lot with extant cement fence.	N/A	N/A
Sandy Doublogy	Photo #5 USE: EMPTY LOT No historic prope	erties affected.			
NW N NE 05°N (T) ● 18°4°54°N (57°2°29°W ± 183ft ▲ 178ft	Lat: 18°4'54''N Lon:67°2'29''W	Calle Ruiz Belvis, San Germán, Puerto Rico, 00683.		XIXth century	Eligible
Section 2019	Photo #6 USE: COMMERCIA No historic prop				
0 354*N (1) 0 18*4*55*N, 67*2*29*W ±16h. ▲ 181h		#34 Calle Ruiz Belvis, San Germán, Puerto Rico, 00683.		Turn of the XXth century	Eligible
Sanya Domnyo 00 Dec 2028, 15-39	Photo #7 USE: COMMERCIA No historic prop				
0 354°N (T) ● 18°4′54°N, 67°2′29°W ±16ft ▲ 167ft	Lat: 18°4'54''N Lon: 67°2'29''W	#36 Calle Ruiz Belvis, San Germán, Puerto Rico, 00683.		1950's	Non eligible

Photo #8

use: residential

No historic properties affected.

63



Lat: 18°4'54''N [ Lon: 67°2'28''W	Belvis, Esquina	Residencia Waldemar Morales	1898	Eligible
Photo #9				

USE: RESIDENCE No historic properties affected.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

**Case ID:** PR-CRP-000876 City: San German

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



GOVERNMENT OF PUERTO RICO

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

Case ID: PR-CRP-000876 City: San German

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



Photo #:1

Date: Dec-08-2023

Facing southwest, streetlamp post.



Photo #2

Date: Dec-08-2023

Facing south, pedestrian access to Dr. Santiago Veve Street.

GOVERNMENT OF PUERTO RICO

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

**Case ID:** PR-CRP-000876

City: San German

GOVERNMENT OF PUERTO RICO

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



Photo #:3 Date: Dec-08-2023

Facing north, pedestrian access to Ruiz Belvis Street.



Photo #4

Date: Dec-08-2023,

Facing north, bust and planter.

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

Case ID: PR-CRP-000876

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



City: San German



Photo #: 5 Date: Dec-08-2023,

Facing south, bust, tally and planter.



Photo#6

Date: Dec-08-2023,

Facing south, bust and planter.

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

**Case ID:** PR-CRP-000876 City: San German

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



Photo #: 7 Date: Dec-08-2023,

Facing south, bust and planter.



Photo#8

Facing north, bust, tree and planter.

Date: Dec-08-2023,

GOVERNMENT OF PUERTO RICO

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

**Case ID:** PR-CRP-000876

City: San German

GOVERNMENT OF PUERTO RICO

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



Photo #: 9 Date: Dec-08-2023,

Facing north, bust and planter.



Photo #10

Date: Dec-08-2023,

Facing north, park bench, planter and brick pavement.

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

**Case ID:** PR-CRP-000876 City: San German

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano




Photo #: 11 Date: Dec-08-2023,

Facing west, disable person ramp and brick pavement to plaza Santo Domingo.

GOVERNMENT OF PUERTO RICO



Photo #12

Facing east, drainage ditch bordering plaza along Dr. Santiago Veve Street.

Date: Dec-08-2023,

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

**Case ID:** PR-CRP-000876 City: San German

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



GOVERNMENT OF PUERTO RICO

Photo #: 13 Date: Dec-08-2023,

Facing east, Ruiz Belvis Street paved in stone and brick.



Photo # 14

Facing south, tally and planter.

Date: Dec-08-2023,

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

**Case ID:** PR-CRP-000876 City: San German

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



Photo #: 15 Date: Dec-08-2023, Facing southwest, bust, trees, planters and benches along Dr. Santiago Veve Street.



Photo # 16

Facing east, brick pavement covering plaza Santo Domingo.

Date:

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DRPROGRAM INVESTMENT PORTFOLIO FOR GROWTH (IPG) Section 106 NHPA Effect Determination Subrecipient: Municipality of San German	GOVERNMENT OF PUERTO RICO DEPARTMENT OF HOUSING
Case ID: PR-CRP-000876	City: San German
Project Name: Plaza Santo Domingo and Plaza Francisco Mariano	





Photo #:1

Date: Dec-08-2023,

Facing north, streetlamp post.



Photo #2

Date: Dec-08-2023,

Facing south, street lamp post and bench.

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

**Case ID:** PR-CRP-000876

City: San German

GOVERNMENT OF PUERTO RICO

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



Photo #:3 Date: Dec-08-2023,

Facing south, streetlamp post and corner planter.



Photo #4

Facing east, streetlamp post and corner planter.

Date: Dec-08-2023,

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

Case ID: PR-CRP-000876

City: San German

GOVERNMENT OF PUERTO RICO

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



Photo #: 5 Date: Dec-08-2023,

Facing south, tree and planter with seating bench.



Photo # 6

Facing north, corner planter.

Date: Dec-08-2023,

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

**Case ID:** PR-CRP-000876

City: San German

GOVERNMENT OF PUERTO RICO

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



Photo #: 7 Date: Dec-08-2023,

Facing east, pedestrian access to plaza San German and corner planters.



Photo#8

Date: Dec-08-2023,

Facing west, staircase pedestrian access to plaza San German.

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

Case ID: PR-CRP-000876

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



City: San German



Photo #: 9 Date: Dec-08-2023,

Facing north, business booth.



Photo #10

Facing west, staircase and handrail along Padres Agustinos Street.

Date: Dec-08-2023,

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

Case ID: PR-CRP-000876

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



City: San German



Photo #: 11 Date: Dec-08-2023,

Facing west, stair and drainage ditch along Ruiz Belvis Street.



Photo #12

Date: Dec-08-2023,

Facing east, plaza paved in concrete slab, tile and stone, and planters.

PORTFOLIO FOR GROWTH (IPG)

Section 106 NHPA Effect Determination

Subrecipient: Municipality of San German

**Case ID:** PR-CRP-000876 City: San German

Project Name: Plaza Santo Domingo and Plaza Francisco Mariano



The same of Facing west, Padres Agustinos Street paved in stone and brick, and drainage.

Photo #: 13 Date: Dec-08-2023,

# PR-CRP-000876 Plaza Santo Domingo and Plaza Francisco Mariano Project San Germán, Puerto Rico

90% Design Drawings

# PROGRAMA | CDBG-DR - MUNICIPIO DE SAN GERMÁN

# PLAZA SANTO DOMINGO Y PLAZA FRANCISCO MARIANO QUIÑONES

MUNICIPIO DE SAN GERMÁN | HON. VIRGILIO OLIVERA OLIVERA, ALCALDE

PROYECTO NO. 000876 - 9 DE OCTUBRE DE 2023

DOCUMENTOS DE CONSTRUCCIÓN 90% | JORGE RIGAU ARQUITECTOS PSC












FOTO HISTÓRICA DE LA PLAZA FRANCISCO MARIANO QUIÑONES





VISTA DE LA PLAZA SANTO DOMINGO HACIA LA IGLESIA PORTA COELI









Villiam Sarriera - ACE Environmental Consultants. Inc

edro Cortes - PC&A Engineers, PSC

GRIMENSURA:				
grim, Jorge L. Pinero Sierra - V&P Survey Group, PSC				
giiii, soi	INDICE DE HOJAS			
	1			
<b>\-</b> 00	HOJA DE TITULO			
SURV-1	EXISTING CONDITIONS SURVEY			
SURV-2	EXISTING CONDITIONS SURVEY			
CS-101	GEOMETRIC LAYOUT PLANS A AND B			
CS-601	GEOMETRIC TABLES			
CG-101	GRADING PLANS A AND B			
CG-201	STREET PROFILES			
<b>∖-</b> 01	PAVIMENTO PROPUESTO			
<b>\-</b> 02	CONDICIONES / INTERVENCIONES - PLAZA SANTO DOMINGO			
<b>\</b> •03	PLANO DE SITIO - PLAZA SANTO DOMINGO			
<b>\-</b> 04	SECCIONES			
<b>\-</b> 05	DETALLES - PLAZA SANTO DOMINGO ESQ. OESTE			
<b>1</b> •06	DETALLES - PLAZA SANTO DOMINGO ESQ. ESTE			
<b>\-</b> 07	DETALLES - PLAZA SANTO DOMINGO			
<b>1</b> -08	CONDICIONES / INTERVENCIONES - PLAZA FRANCISCO MARIANO			
<b>\-09</b>	PLANO DE SITIO - PLAZA FRANCISCO MARIANO			
<b>\-10</b>	SECCIONES			
A-11	GLORIETA - PLANTA / SECCIONES / 3D			
N-12	GLORIETA - PLAFÓN / TECHO / 3D			
<b>\-13</b>	GLORIETA - ELEVACIONES			
<b>∖-</b> 14	GLORIETA - DETALLES			
<b>∖-</b> 15	BANCO/JARDINERA PROPUESTO - PLAZA FRANCISCO MARIANO			
<b>1</b> -16	MOBILIARIO URBANO PROPUESTO			
30-01	FOUNDATION PLAN & SECTIONS			
30-02	STRUCTURAL ROOF PLAN & SECTIONS			
S-1.1	ELECTRICAL SITE PLAN			
S-1.2	ELECTRICAL SITE PLAN			
S-2.1	S-2.1 LEGEND, NOTES ANS SCHEDULE			
-0.00	ELECTRICAL CALE LINE DIACRAM AND DETAIL C			

# MEMORIAL EXPLICATIVO:

El Municipio de San Germán propone la rehabilitación de los dos espacios públicos más destacados de la ciudad; la Plaza Santo Domingo y la Plaza Francisco Mariano Quiñones, Ambas plazas integran el "espinazo" urbano del pueblo, vinculadas por la calle Ruiz Belvis que comparten, Ambos espacios discurren en dirección este-ceste y alrededor de ellos se adosan varias de las estructuras emblemáticas de "La Ciudad de las Lomas". la Iglesia de San Germán de Auxerre, Porta Coel, la Acadia original de la población y varias residencias notables, entre éstas, la antigua Casa de Waldemar Morales en

Si bien el espacio frente a la idesia parroquial fue siempre plaza y sede de eventos públicos, su contraparte frente al promontorio en que se ubica Porta Coeli, era originalmente un espacio arbolado; de ahí que hasta el dia de hoy algunos se refieran al lugar como "Parque Santo Domingo". En la segunda

Yamil Galib y Carro, La Plaza Mariano Quiñones abarca 1,185 metros cuadrados; la Plaza de Santo Domingo comprende 1,209 metros cuadrados,

presentado problemas de desprendimiento y accidentes. En las plazas como tal, se proponen reparaciones varias: contenes, muros bajos, pavimentación en ladrillo y argamasa. Los trabajos también induyen la restitución de losa canaria. Forman parte del alcance de los t

Se incorporan, además: un reloj de pedestal en la Plaza Santo Domingo (sobre una base escultórica) visible desde ambos espacios públicos; también una glorieta que evoca la que en el entresiglos del S.XX existió en la Plaza Mariano Quiñones. La glorieta estará equipa como de noche. En este juego de planos se incluve información técnica sobre el mobiliario urbano seleccionado.


# PROGRAMA I CDBG-DR - MUNICIPIO DE SAN GERMÁN


PLAZA SANTO DOMINGO Y PLAZA FRANCISCO MARIANO QUIÑONES


SAN GERMÁN, PUERTO RICO, 00683

90% DOCUMENTOS DE CONSTRUCCIÓN

,	iabaj	os, mejoras electricas, mevo	E3-1-2	CAL SITE PLAN			
			ES-2.1	LEGEND.	, NOTES ANS SCHEDULE		
			ES-2.2	ELECTRIC	AL ONE LINE DIAG	RAM AND DETA	LS
a	da pa	ra acoger eventos tanto de di	а 💳				
_							
4							
	ISSUE	CHART			TITLE		
	NO.	DESCRIPTION	DATE	APPROVED			
	no.	DECOMP HON	Dille	74 1 110 123	HOJA DE TÍTUI	LO	
						PRINTED ON	
					SCALE	PHINIEDON	SHEET NO.
					DD 11441 D11		A-00
ORGE RIGAU ARQUITECTOS PSC					DRAWN BY FV		A-00
		CHEEL HYDDE THÁNK, 1023 AVE. LAS MÁNDAS, SA	AL public Percentage	PHASE		DATE	
10-periodores i pass recaudy reconstruction			DOCUMENTOS DE C	ONSTRUCCIÓN 90			
_							







# ADVANCED PRINT: ESTIMATED 60%



# NOT FOR CONSTRUCTION

		Г
		ľ

ALIGNMENTS LINE TABLE						
L	BEARING	FROM	TO	REMARKS		
(M)	(DEG-MIN-SEC)					
16,9267	\$80-59-46E	0+00.00 Y=227653.6218 X=135392.2801	0+16.93 Y=227650.9728 X=135408.9983	RUIZ BELVIS ST. (WEST)		
14.7214	S79-16-13E	0+00.00 Y=227679.2781 X=135396.4285	0+14.72 Y=227676.5374 X=135410.8926	PADRES AGUSTINOS ST. (WEST)		
10,9301	N06-20-19E	0+00.00 Y=227676 5374 X=135410.8926	0+10.93 Y=227687.4006 X=135412.0993	DE LA CRUZ ST. (NORTH)		
8,4610	N06-17-18E	0+00.00 Y=227642.5627 X=135408.0715	0+08.46 Y=227650.9728 X=135408.9983	DE LA CRUZ ST. (SOUTH)		
22.9048	N05-55-28E	0+00.00 Y=227652.2654 X=135410.4385	0+22.90 Y=227675.0479 X=135412.8026	DE LA CRUZ ST.		
77,2524	S83-15-40E	0+00,00 Y=227675,0479 X=135412,8026	0+77.25 Y=227665.9827 X=135489.5213	PADRES AGUSTINOS ST.		
77.8792	\$83-25-28E	0+00.00 Y=227652.2654 X=135410.4385	0+77.88 Y=227643.3473 X=135487.8054	RUIZ BELVIS ST.		
5,9959	S82-05-58E	0+77.88 Y=227643.3473 X=135487.8054	0+83.88 Y=227642.5231 X=135493.7444	RUİZ BELVİS ST.		
26,9153	S80-37-37E	0+83.88 Y=227642.5231 X=135493.7444	1+10,79 Y=227638,1397 X=135520,3004	RUIZ BELVIS ST.		
11.3574	S78-25-55E	1+10.79 Y=227638.1397 X=135520.3004	1+22.15 Y=227635.8622 X=135531.4271	RUIZ BELVIS ST.		
44.7874	S83-38-49E	1+22,15 Y=227635,8622 X=135531,4271	1+66,94 Y=227630,9062 X=135575,9394	RUIZ BELVIS ST.		
8,4276	\$85-00-33E	1+66.94 Y=227630.9062 X=135575.9394	1+75.36 Y=227630.1730 X=135584.3350	RUIZ BELVIS ST.		
62,9377	S86-10-07E	1+75.36 Y=227630.1730 X=135584.3350	2+38.30 Y=227625.9675 X=135847.1321	RUIZ BELVIS ST.		
22.6933	N08-18-01E	0+00.00 Y=227643.5271 X=135486.2453	0+22.69 Y=227665.9827 X=135489.5213	UNNAMED ST. 1		
13,1425	S84-49-39E	0+00.00 Y=227621.4997 X=135508.4013	0+13.14 Y=227620.3148 X=135521.4903	FELIX ARCE LUGO ST. (WEST)		

ARCE LUGO ST.

YAMIL GALIB ST. (SOUTH)

YAMIL GALIB ST.

YAMIL GALIB ST.

0+08.86 Y=227611.6645 X=135647.1599

0+00.00 =227611.7656 =135645.9101

0+14.25 =227625.9675 =135647.1321

0+19.89 Y=227630.7506 X=135650.1134

L25 14,7473

L29 8,8561

130 14 2543

L31 5,6363


N05-57-50E


NOA55.04F

N31-56-08E

		LINE T	ABLE	
,	L (M)	BEARING (DEG-MIN-SEC)	FROM	то
1	4,4934	N37-46-32W	Y=227654,9301 X=135443,7425	Y=227658,4818 X=135440,9900
	3,5044	N06-33-04E	Y=227658,4818 X=135440,9900	Y=227661.9633 X=135441.3898
3	4,4933	N50-52-42E	Y=227661,9633 X=135441.3898	Y=227664,7984 X=135444,8758
	9.9331	S83-26-57E	Y=227664,7984 X=135444,8758	Y=227663,6652 X=135454,7440
,	4,3947	\$38-26-40E	Y=227663,6652 X=135454,7440	Y=227660,1299 X=135457,3547
	3,5044	S06-33-04W	Y=227660.1299 X=135457.3547	Y=227656,6484 X=135456,9549
	4,3948	S49-32-44W	Y=227656,6484 X=135456,9549	Y=227653,7969 X=135453,6108
	9.9331	N83-26-57W	Y=227653.7969 X=135453.6108	Y=227654.9301 X=135443.7425
)	105,7402	S85-54-24E	Y=227626,4789 X=135532,4292	Y=227618.9310 X=135637.8997

PROGRAMA | CDBG-DR - MUNICIPIO DE SAN GERMÁN PROFESSIONAL CERTIFICATION LAW IMPORTANT INFORMATION FOR THE CONTRACTOR GEOMETRY TABLES PLAZA SANTO DOMINGO Y PLAZA FRANCISCO MARIANO QUIÑONES PRINTED ON SHEET NO. SAN GERMÁN, PUERTO RICO, 00683 CS601 DRAWN BY P.J.CORTES JORGE RIGAU ARQUITECTOS PSC DATE PHASE DISEÑO PRELIMINAR





### SECTION 321313.13 **EXPOSED AGGREGATE CONCRETE PAVING**

- A. Cementitious Materials: Portland cement alone or in combination with one or more of blended hydraulic cement, expansive hydraulic cement, fly ash, and other pozzolans, ground granulated blast-furnace slag.
- B. Design Mixtures: For each concrete pavement mixture. Include alternate mix designs when characteristics of materials, project conditions, weather, test results, or other circumstances warrant adjustments.
- C. Samples: 10-lb. sample of exposed aggregate. Information from aggregate supplier indicating source, type, color, and gradation of aggregate shall accompany sample.
- D. Installer Qualifications: Experienced installer who has completed pavement work similar in material, design, and extent to that indicated for Project and whose work has resulted in construction with a record of successful in-service performance.
- F Manufacturer Qualifications:
- Manufacturer of ready-mixed concrete products who complies with ASTM C 94/C 94M requirements for production facilities and equipment.
- 2. Manufacturer certified in according to the National Ready Mix Concrete Association's Plant Certification Program.
- F. Testing Agency Qualifications: An independent testing agency, acceptable to authorities having jurisdiction, qualified according to ASTM C 1077 and ASTM E 329 to conduct the testing indicated as documented according to ADTM E 548.
- G. Mockups: Cast mockups of full-size sections of concrete pavement to demonstrate typical joints, surface finish, texture, color, and standard of workmanship.
- Build a 4' x 4' mockup on site, If location not indicated, as directed by Owner's representative.
- b. Notify Owner's representative seven days in advance of dates and times when mockups will be constructed.
- c. Obtain approval from Owner's representative before starting mockup construction.
- d. Maintain approved mockups during construction in an undisturbed condition as a standard for judging the completed
- Demolish and remove approved mockups from the site when directed by Owner's representative.
- H. Pre-installation Conference: Conduct conference at Project site to comply with requirements in Division 01 Section, "Project Meetings".
- Form Materials: Plywood, metal-framed plywood, or other approved panel-type materials to provide full-depth, continuous, straight, smooth, exposed surfaces.
- 1. Use flexible or curved forms for curves of a radius 100 feet or less.



MUESTRAS DE LOS COLORES 413 CLAY Y 492 MAUVE A UTILIZARSE EN LA PAVIMENTO DE RODAJE

PRUEBA FÍSICA DE LOS COLORES EN EL HORMIGÓN

DATE


PHASE DISEÑO PRELIMINAR

### PROFESSIONAL CERTIFICATION LAW IMPORTANT INFORMATION FOR THE CONTRACTOR PROGRAMA | CDBG-DR - MUNICIPIO DE SAN GERMÁN LICROS SHAND PRIEZ LICENSE 1950. CERTEY THAT IAM THE PROFESSIONAL WIND DESIGNED THESE TALHO MO THE CORPUS CHANT ART SINCE HEAT THAT IALSO CERTETY THAT I LICENSET AND THAT SICH PLANS MOST SELECTION CONCENT WITH THE SHEW IAM CONCENT OF THE ART THE SOLUTION AND MOST SELECTION CONCENT OF THE SHEW IAM OF MOST CONCENT OF THE ART THE SOLUTION SOLUTION FAMILY CORPUS AND THAT IS A SHEW THAT THE SOLUTION OF THE SHEW IN THE SOLUTION SOLUTION FAMILY CORPUS AND THAT IS A SHEW THAT THE SOLUTION OF THE SHEW IN THE SOLUTION SOLUTION OF THE SHEW IN THE LOWERSONS, LEVILS, AND EMERING SITE CONDITIONS SHALL BE VERIFIED BY THE GENERAL METALETOR PRICE TO INFLATING ANY WORK, LEVING HIGHING ANY EMERGENMENT ERRORS OR PAVIMENTO PROPUESTO PLAZA SANTO DOMINGO Y PLAZA FRANCISCO MARIANO QUIÑONES SCALE PRINTED ON SHEET NO. SAN GERMÁN, PUERTO RICO, 00683 THE CONTRACTOR SHALL NOT USE ANY DRAWING GIVEN IN ADVANCE PRIOR TO THE BESINNING OF THE WORK, ALL DRAWINGS USED BY THE CONTRACTOR MUST BEAR THE "FOR CONSTRUCTION ONLY STAMP, GROWN DRIVEN BY THE ARCHEST A-01 DRAWN B CONSTRUCTION DOCUMENTS 90%


492 Mauve




- 1. TODAS LAS PAREDES BAJAS EN LADRILLO SERÁN RESTAURADAS
- 2. TODOS LOS POSTES DE ILUMINACIÓN SERÁN NUEVOS
- 3. TODOS LOS OCHO (8) BANCOS/JARDINERAS SERÁN REHABILITADOS




ESCALA: 1/64" = 1'-0"



PROFESSIONAL CERTIFICATION LAW	IMPORTANT INFORMATION FOR THE CONTRACTOR	PROGRAMA   CDBG-DR - MUNICIPIO DE SAN GERMÁN	ISSUE CHART				TITLE		·
Lucres elevaneres, License reso, certier mant an the recreasional who designed these ruses with the consequentiar predictionless is also certier than fluccestrate that such purpos and sectifications comery with the interpreparation promisers or the critical productions and are purposed promisers of the secululities and codes of adenties resultation souther such or rusal or connectations with a large cities.		PLAZA SANTO DOMINGO Y PLAZA FRANCISCO MARIANO QUIÑONES		DESCRIPTION	DATE	APPROVED	PLANO DE SI	IT <b>I</b> O - PLAZA S	ANTO DOM <b>I</b> NGO
I ACHROMIZEDGE THAT HAY FILSE DECLARATION OF FILSET CATENOOF THE FACTS WHICH HAVE BEEN FROUDED BY THOUGH THAT HAVE SEED BY PROJUCEDUR THAT HAVE ALSO BEEN BEEN OF THE SECOND OF THE SECO	ADDIS CORRECTIONS THE CONTRICTOR HILL BE FILLY REPOWERED FOR SUCH CHORSEPHICES, ESPORS ADDIS ON SECTION THEY ARE NOT INTERPRETOR WHITE.  THE CONTRICTOR SHALL NOT USE ANY CRAWNING SHEET IN THE YEAR TO THE ESCHAFANGE THE CONTRICTOR HILL SHEET IN THE CONTRICTOR SHALL NOT USE ANY CRAWNING SHEET IN THE CONTRICTOR HILL SHEET IN THE CONTRICTOR OF THE CONTRICTOR OF INTERPRETOR HILL SHEET INTERPRETOR HILL SHEET IN THE CONTRICTOR OF INTERPRETOR HILL SHEET INTERPRETOR HILL SHEET IN THE CONTRICTOR OF INTERPRETOR HILL SHEET INTERPRETOR HILL SHEET IN THE CONTRICTOR OF INTERPRETOR HILL SHEET INTERPRETOR HILL SHEET IN THE CONTRICTOR OF INTERPRETOR HILL SHEET INTERPRETOR HILL SHEET INTERPRETOR HILL SHEET INTERPRETOR HILL SHEET INTERPRETOR HILL SHEET INTERPRETOR HILL SHEET INTERPRETOR HILL SHEET INTERPRETOR HILL SHEET I	SAN GERMÁN, PUERTO RICO, 00683					SCALE VARIAS	PRINTED ON	SHEET NO.
ACTIONS THE CHIEF MODIFIES CONFERRY AUTHORITIES INJUDICES, BUT NOT THE TO THE TEMPLITY OF THE PARTITIVAÇÃO INFRORESCIONAL CERTIFICAÇÃO PROCESCIONES IN THE CASE.	STAM BOND AS SEALDER HE MICHTEN.  THESE DRIVINGS WITH THE CONTENT WE PROPERTY OF JURISE MEAN AROUTECTOS PRO- THESE DRIVINGS WITH THE PROPERTY OF THE PROPERTY OF JURISE MEAN THE WERE EMPLITY DEVELOPED. FOR PARTIE, OF PLU, EMPRODUCTION OF MY DEVELOP DO COMBIT ANDORED TO CONTENT WITHOUT PROPULSIA JURISED STEPPING STATUS FORESTOOL.	90% DOCUMENTOS DE CONSTRUCCIÓN	1 6	ORGE RIGAU ARQUITE	MA public Perceptor		DRAWN BY FV PHASE		A-03
	President vinital vinita sud-ura resentante		۱ ۱	The project of the resulting	ORSTRIGUESON	J		CONSTRUCCIÓN 90°	Lunes 9 de octubre, 2023





PROGRAMA | CDBG-DR - MUNICIPIO DE SAN GERMÁN PROFESSIONAL CERTIFICATION LAW IMPORTANT INFORMATION FOR THE CONTRACTOR ALL OMERIONS LEVELS AND DESTINO SITE CONCITIONS SHALL BE VERFEED BY THE GREENAL COMMISSION REPORT OF INTERPOLATE WORK. LINCOLLEGISM OF EXPONENCE SERVICE SERVI Longs from Priez. Libras 1990, certify that I wante recreasional who perbato hese shall not be considerably as estimated and the consideration in south use and seem that the desiration in stock you have shall seem that the consideration in the stock record of the consideration of the stock record of the consideration of the consideration in the stock of the consideration of the consid DETALLES - PLAZA SANTO DOMINGO ESQ. ESTE PLAZA SANTO DOMINGO Y PLAZA FRANCISCO MARIANO QUIÑONES SAN GERMÁN, PUERTO RICO, 00683 SCALE PRINTED ON SHEET NO. A-06 THESE CHAMMES AND THERE CONTEST ARE PROPERTY OF JUPICE HIS WARRANTS FOR THE CONTEST AND PROPERTY OF JUPICE HIS WARRANTS FOR THE PROJECT FOR WHAT THEY MERE FOR JUTA OPPILLOT FOR WHAT THE MERCHANTS FOR JUTA OF THE PROPERTY AND PROPERTY OF THE PROPERTY OF TH DRAWN B RGE RIGAU ARQUITECTOS PS 90% DOCUMENTOS DE CONSTRUCCIÓN PHASE
DOCUMENTOS DE CONSTRUCCIÓN 50%
Lunes 9 de octubre, 2023





IMAGEN 4: Reparación previa de ladrillo a sustituírse por el nuevo "Central Ribbon" (ver hoja A-06)



IMAGEN 5: Remover postes y cablería existentes; previa coordinación con el Municipio.



IMAGEN 6: Mantener tola de acero en uso.



IMAGEN 7: Remover cemento para restituir áreas de siembra. Tola de acera permanece.



IMAGEN 8: Coordinar con el Municipio la nueva pintura a aplicarse en los contenes.



IMAGEN 9: Limpiar base de mármol y monumento según instrucciones del arquitecto.



IMAGEN 10: Reponer pieza faltante de mármol.



IMAGEN 11: Evitar cortes que afecten los materiales existentes.



IMAGEN 12: Remover rótulos y reubicar según instruya el Municipio.

PLAZA DE SANTO DOMINGO / DETALLES ESPECÍFICOS A **ATENDERSE** 

## PROFESSIONAL CERTIFICATION LAW

## IMPORTANT INFORMATION FOR THE CONTRACTOR


# PROGRAMA | CDBG-DR - MUNICIPIO DE SAN GERMÁN


PLAZA SANTO DOMINGO Y PLAZA FRANCISCO MARIANO QUIÑONES


SAN GERMÁN, PUERTO RICO, 00683


90% DOCUMENTOS DE CONSTRUCCIÓN


	ISSUE	CHART			TITLE		
S	NO.	DESCRIPTION	DATE	APPROVED	INTERVENCIO	NES	
					SCALE 1:###	PRINTED ON	SHEET NO.
		ORGE RIGAU ARQUIT	TECTOS PSC		DRAWN BY		A-07
		TEL CHALMO-OCCU I BRING MC THE	SORCHIGALION		PHASE DOCUMENTOS DE CO	ONSTRUCCIÓN 90%	DATE Lunes 9 de octubre, 2023
























### DIMENSIONS

Dimensions: 10.50" W x 19.50" H x 9.00" D Weight: 7.00 lbs



## DETAILS

Material: ALUMINUM

Glass/Shade Description: Clear Seedy Glass -Glass - Seeded

### LAMPING

Light Source: Incandescent

Bulb Included: Yes Bulb Type: Medium Base

Bulb Quantity: 1 Watts per Bulb: 60


## **ELECTRICAL**

Dimmable: Yes Voltage: 120v

Wire Length: 0.5

### INSTALLATION

Location Rating: Wet Install Position: Up





627 Amersale Drive Naperville, IL 60563 Phone: (800) 323-5664 Fax: (630) 897-0573 sales@belson.com

Model # PVCL6

**Dimension Sheet** 


## 6' PARKVIEW CLASSIQUE PARK BENCH WITH STEEL SLATS

### MATERIAL SPECIFICATIONS

- 3/16" x 1-1/2" Flat Bar (Seat Slats) - 5/8" X 3/8" Steel (Slat Supports)

- 1.66" O.D. x 11 Ga. Steel Tube (Seat Frame)





www.belson.com

RELOJ PLAZA FRANCISCO MARIANO QUIÑONES


D

С

FAROLA DE POSTE

BANCO EN ACERO

### TITLE PROFESSIONAL CERTIFICATION LAW IMPORTANT INFORMATION FOR THE CONTRACTOR PROGRAMA I CDBG-DR - MUNICIPIO DE SAN GERMÁN PROYECTO NO. 000876 LONGE SHAFF PRIZE, L'ERNEE 1950, CERTEN THAT I MATTHE PROFESSIONAL WHO DESPARED THESE PLANE MO THE COMPLEXION AND SHEET HAS THOSE ALSO CERTEN THAT I CONDITION THAT SHOTH FLAN MO SHEET HAS THOSE COMEY WITH THE WHOLE THAT SHAFF OF THE AST THE PROBLEMENT OF MOST SHEET HAS THOSE COMEY THAT THE SHEET AND AND COORD OF MOST HAS REDUCTION FOR WHOSE AUTOR PLANE COMPANY THAT WITH A SHEET THAT THE SHEET AND THE SHEET HAS REDUCTION FOR WHOSE AUTOR PLANE COMPANY THAT WHITE AND THAT SHEET THAT THE SHEET HAS THE SHEET THAT THE SHEET THE SHEET THAT THE SHEET THE SHEET THE SHEET THAT THE SHEET THE SHEET THAT THE SHEET THE SHEET THE SHEET THAT THE SHEET THE SHE MOBILIARIO URBANO PROPUESTO PLAZA SANTO DOMINGO Y PLAZA FRANCISCO MARIANO QUIÑONES JORGERIGAU ARQUITECTOS PSO SCALE. PRINTED ON SHEET NO. THE CONTRACTOR SHALL NOT USE ANY DRAWNIG DIVEN IN ADVANCE PHOR TO THE BESINNING OF THE WORK, ALL DRAWNIGS USED BY THE CONTRACTOR MUST BEAR THE "FOR CONSTRUCTION ONLY STAMP, BLAND MO SEALED BY THE ARCHTECT." URB. HYDE PARK, 855 AVE. LAS MARÍAS, SAN JUAN PRO0927 SAN GERMÁN, PUERTO RICO, 00683 TEL: (787) 982-0002 | EMAIL: RIGAU@JORGERIGAU.COM A-16 HON. VIRGILIO OLIVERA OLIVERA, ALCALDE PHASE DISEÑO PRELIMINAR DATE Jueves -3 de agosto de 2023




# ELECTRICAL SITE PLAN - PLAZA FRANCISCO MARIANO QUIÑONES



PROFESSIONAL CERTIFICATION LAW

PROGRAMA | CDBG-DR - MUNICIPIO DE SAN GERMÁN PLAZA SANTO DOMINGO Y PLAZA FRANCISCO MARIANO QUIÑONES SAN GERMÁN, PUERTO RICO, 00683

ISSUE	CHART			TITLE
NO.	DESCRIPTION	DATE	APPROVED	ELECT
				SCALE AS SHOW
	ORGE RIGALI ARQUIT	ECTOS PSC		DRAWN
	TO DETHE OCCUPY DAME RESIDENCE	SAN JOHN PRODUCTION	2	PHASE



EXISTING CEILING MOUNTED FIXTURES TO BE REVAMPED BY CONTRACTOR AS FOLLOWS, I. REMOVE AND PAINT WELLACK RUST OIL PAINT. C. CLEAN LENGES, 3. REPLACE BULBS WOOM LED EQUIVALENT. 4. RE-INSTALL AND RE-CONNECT.

ELECTRICAL PLAN-NEW GLORIETA

**ELECTRICAL PLAN-EXISTING KIOSK** 





PROGRAMA | CDBG-DR - MUNICIPIO DE SAN GERMÁN PLAZA SANTO DOMINGO Y PLAZA FRANCISCO MARIANO QUIÑONES

SAN GERMÁN, PUERTO RICO, 00683

0.	DESCRIPTION	DATE	APPROVED
_			-

TITLE		
ELECTRICAL	SITE PLAN	
SCALE AS SHOWN	PRINTED ON	SHEET NO.
DRAWN BY: EF		ES-1.1B
PHASE DISEÑO PRELIMII	NAR	DATE: SEPT.22.2023





- CONDUIT RUN EXPOSED ON SLAB OR ABOVE HUNG CEILING. CONDUIT RUN EMBEDDED IN FLOOR OR WALL.

- HALL OUTLET FOR LIGHTING FIXTURE AT 7'-O' A.F.F.
- DUPLEX GROUNDING CONVENIENCE RECEPTACLE, 20 AMPS., 125 VOLTS, SPECIFICATION GRADE, AT IS\* A.F., UNLESS OTHERWISE INDICATED. (GPR-GROUND FAULT FEED THE) TYPE)
- SAME AS ABOVE BUT AT 42" A.F.F.
- SAME AS ABOVE BUT AT 6'-0" AFF.
- WP SAME AS ABOVE BUT WITH PVC WATER-PROOF COVER . IB\* A.F.F.
- RANGE RECEPTACLE, GROUNDING TYPE, 2 POLES, 3 WIRES, 50 AMPS. 250 VOLTS AT 1-6° AFF, NEMAL-50R, (FOR IN-LINE WH. HEIGHT SHALL BE COORDINATED W PLUMBING CONTRACTOR)
- WH RECEPTACLE, 250 VOLTS, 30 AMPS., 36\* A.F.F.
- SINSLE POLE SAITCH, 20 AMPS., 125 VOLTS, 41-01 A.F.F.

- SAFETY OR DISCONNECT SMITCH 36" AFF, REFER TO ELECTRICAL PLAN.

- EXISTING TO REMAIN
- ERP EXISTING TO BE REPLACED

- X EXISTING AERIAL FEEDER TO BE REMOVED

- I- ALL ELECTRICAL CONDUITS SHALL BE PVC SCH.40 -I" MINIMUM LARGER OR OTHER TYPE OF CONDUIT AS INDIGATED ON DRAWINGS.
- 2- CONDUCTORS SHALL BE COPPER WITH 600 VOLTS THEN INSULATION. MINIMUM SIZE SHALL BE #10 AJNJG.
- 3- USE WHITE COLOR FOR ALL WIRING DEVICES, PLATES SHALL BE WHITE THERMOPLASTIC.
- 4- THE TELEPHONE SYSTEM SHALL BE WIRED BY OTHERS. A #14 GALV... WIRE SHALL BE LEFT IN EACH OUTLET.
- THE COMPLETE ELECTRICAL INSTALLATION SHALL BE IN COMPLIANCE WITH THE NATIONAL ELECTRICAL CODE, LATEST EDITION, AND THE REGULATIONS OF P.R.E.P.A.
- ALL WIRING DEVICES, EQUIPMENT AND CONDUIT SHALL BE UNDERWRITERS LAB, P.R.EP.A, AND HUD, APPROVED AND SHALL BE SUBMITTED TO THE OWNER OR HIS REPRESENTATIVE FOR APPROVAL.
- 8- AFTER COMPLETION OF THE WORK THE CONTRACTOR SHALL FURNISH TO THE OWNER A CERTIFICATE OF FINAL INSPECTION AND APPROVAL.
- IO- INSTALL A #12th JIMPER BETNEEN CONVENIENCE RECEPTACLE GROUND TERMINAL AND OUTLET BOX GROUND TERMINAL.
- II- GROUND WIRE IN PVG CONDUIT NOT SHOWN, MUST BE PROVIDED.
- I2- VERIFY ALL ELECTRICAL REQUIREMENTS AND EXACT LOCATIONS OF EQUIPMENT WITH DRAWNINGS AND SPECIFICATIONS, CHECK AND VERIFY ALL DIMENSIONS IN THE FIELD.

- MAINTAIN ADEQUATE ACCESS TO ALL JINCTION, TERMINATION AND PULL BOXES, MAINTAIN ADEQUATE ACCESS TO ALL EQUIPMENT FOR OPERATIONS, MAINTENANCE AND REPAIRS.
- 5- ALL MOUNTING HEIGHTS INDICATED ARE TO CENTERLINES OF DEVICES EXCEPT FOR LIGHT FIXTURES AND AS OTHERNISE NOTED OR PER SPECIFICATIONS, MOUNTING HEIGHTS FOR LIGHT FIXTURES ARE TO BOTTOM OF UNITS.
- TRAJES,

  11-SUPPORT MALL MOINTED ELECTRICAL EQUIPMENT (I.E. PANELBOANDS, STARTERS
  TRAINFORMERS, ETC.) BY WINSTRUT CHANNELS SECURED TO FLOOR AND

  CELLING, MURES MALL IS OF MYSORRY TIPE MICH IS OF SUTHORIS
  CONSTRUCTION TO SUPPORT MEIGHT OF EQUIPMENT, OR EXCEPT AS
  OTHERWISE NOTED OR SPECIFICATION.
- OTHERWISE NOTED OR SPECIFIED, INSTALL ALL COMDUTATIONS HAS CELLING AND IN MALLS IN FINISHED AREAS, SPILCE BOXES IN NON-ACCESSIBLE LOCATIONS ARE NOT FERRITHER, IN INFINISHED AREAS E.G. IN ECHANICAL EXPIPMENT ROOMS, ETC.) CUTLET BOXES HAY BE SURPACE MOUNTED AND COMDUTATION BOYOURS.
- IP- DESIGNATIONS TO ELECTRICAL DEVICES SUCH AS LIGHTING FIXTRES, RECEPTACLES, ETC., INDICATE CONTROL, PANEL, AND/OR BRANCH CIRCUIT SERVING THAT DEVICE AND ARE TO BE USED AS A GUIDE FOR PROPER CONTROL, CONNECTION OF MULTI-HIRE CIRCUITS AT PANELS.
- 20- DETERMINE THE ARRANGEMENT AND ROUTING OF BRANCH CIRCUITS IN STRICT ACCORDANCE WITH THE FOLLOWING.
  - A, BALANCE PHASE LOADS ON PANELBOARD BUSES AS EVENLY AS POSSIBLE
  - B. RIM ALL HIRING IN RIGID GALVANIZED STEEL CONDUT IF EMPOSED.
    ELECTRICAL METALLO TUBNIS OF CONCEALED IN HALLS OR ABOVE CELLINGS,
    PVC COATED RIGID STEEL FOR CUITDORS EMPOSED INSTALLATIONS OR AS
    REGUIRED PER DRAININGS, SPECIFICATIONS AND APPLICABLE CODES, ALL
    COMDUIT TO BE CONCEALED IN PRISMED ARREST
  - C, PROVIDE A SEPARATE NEUTRAL FOR ALL LIGHTING AND RECEPTACLE BRANCH CIRCUITS, TREAT NEUTRAL CONDUCTOR AS A CURRENT CARRYING CONDUCTORS IN ACCORDANCE WITH THE NEC.
- D, CONBINING OF 120 VOLT BRANCH CIRCUITS WITHIN A SINSLE CONDUIT IS PERMITTED AS FOLLOWS:

NUMBER.	
OF CURRENT	
CARRYING	
CONDUCTORS	

PERMISSIBLE WIRE SIZE (MAX, 20A CIRCUITS)

- E. 9/ZE HOMERUN BRANCH CIRCUIT CONDUCTORS FROM PANELBOARD TO THE FIRST CUTLET IN ACCORDANCE WITH THE FOLLOWING MAXIMUM CIRCUIT LENGTH LINTS, JURING CENTER OF LOAD SERVED AS THE BASIS FOR FOR COMPUTING LENGTHS.

- 21- INSTALL AND WIRE RECEPTAGLES AND SINGLE PHASE EQUIPMENT IN ACCORDANCE WITH THE FOLLOWING:
  - A, GENERAL LOCATIONS IN ACCORNANCE WITH DRAWINGS, WITH EXACT LOCATION SUBJECT TO DIRECTION OF THE OWNER'S REPRESENTATIVE.
  - B. GROUND ALL RECEPTAGLES VIA SEPARATE GREEN GROUND CONDUCTOR RUN WITH POWER WIRES AND TERMINATING AT PANEL BOARD GROUND BUS.
- 22- INSTALL AND WIRE LIGHTING SYSTEMS IN ACCORDANCE WITH THE FOLLOWING.
  - CONFORM TO THE LIGHTING PIXTURE LAYOUT AND ARRANGEMENT AS SCONLOG ARCHITECTURAL REPLECTED CELLING DEVANIES FOR SECURIOR ARCHITECTURAL REPLECTURAL DEVANIES FOR SECURIOR SECURITARIA SECURITARIA SECURITARIA SECURITARIA SECU
  - B. CONNECT LIGHTING FIXTURES AND DEVICES TO THE PANELBOARDS AND GIRCUITS AS INDICATED, VIA THE ROOM AND/OR AREA SHITCH WHERE
  - C, MOINT EXIT LIGHTS SIX NOVES ABOVE DOORS HIERE APPLICABLE. FOR LOCATIONS OTHER THAN ABOVE DOORS MOINT EXIT LIGHTS EIGHT EIGHET HAMMAN ABOVE FINSHED FLOOR OR THEIL'SE HORIES BELON CEILING, EXCEPT AS OTHERWISE NOTED, ALL NEIGHTS ARE TO SOTTOMS OF FIXINGES,
- 23- HIERE OVERSIZED CONDUCTORS ARE INDICATED ON THE DRAHINGS, MICC CAINDT BE SAFELY TERMINATED DIE TO LUG SUZE OR WIRE BEDDING SPACE LIMITATIONS, PROVIDE LOCAL JUNCTION DOX INTHI BEC COMPLYING FEEDER TAP OF SMALLER WIRE SUZE SUITABLE FOR PROPER TERMINATION AT THE
- 4- PROVIDE EXPANSION FITTINGS IN ALL ELECTRICAL RACEMAY RUNS MERE THEY CROSS BUILDING EXPANSION JOINTS, OR AS NEEDED FOR STRAIGHT RUNS GREATER THAN 150".
- 26- FROVIDE CONTINUOS MIRINS FOR CONTROL AND INSTRUMENTATION SYSTEMS FROM POINT OF ORIGIN TO TERMINALS OF DEVICES AT ENDS OF RUNS (I.E. SPLICES ARE NOT PERMITTED).
- 27- ALTHOUGH NOT SHOWN ON THE PRACHING, SERVEY EXISTING ELECTRICAL DEVOES AND RECEIVED, WACH HAY INTERESTED WITH THE FORK, OF THE PRACHING THE PRACHING THE SHOWN AND THE PRACHING INVESTIGATE OF THE CHARGE SPREIGHBETHATH FOR MEYER DISCONLECT AND ENTER RESPONDED COMPLETY OR USE CALL AND SERVED SHOWN AND AND PRACHING THE CHARGES REPORTED THE CHAR
- 26- MAINTAIN CIRCUIT CONTINUITY FOR ALL EXISTING EQUIPMENT THAT IS TO REMAIN IN SERVICE.
- 24- BROOM CLEAN ALL WORK AREAS UPON COMPLETATION OF WORK EACH DAY.

- 32- ALL EQUIPMENT SHALL BE WIRED BY THE CONTRACTOR IN ACCORDANCE WITH THE EQUIPMENT MANUFACTURERS INSTRUCTIONS, OR SPECIFICATIONS.
- 33- UNLESS OTHERWISE NOTED ALL LIGHTING SMITCHES, DEVICES AND RECEPTACLES ARE FLUSH MOUNTED IN FINISHED AREAS, DEVICES OF DIFFERENT VOLTAGES.
- 36- THE CONTRACTOR SHALL INSTALL ALL RECESSED BOXES FOR LIGHT SHITCHES, RECEPTACLES, ETC, IN A LEVEL/PLIMB ORIENTATION.
- 51- THE CONTRACTOR TO SUBMIT SHOP DRAWINGS FOR APROVAL FOR THE FOLLOWING ITEMS.
  - -ALL ITEMS SHOWN ON ONE-LINE DIAGRAMS,
    -ALL LIGHTING FIXTURES SHOWN ON FIXTURE SCHEDULE,
    -ALL WIRE AND CABLE.
- 36- PROVIDE MILTI-MIRE BRAICH CIRCUITS UTILIZING COMMON NEUTRALS (EXCEPT AS OTHERWISE NOTED), FOR LIGHTINS, RECEPTACLES AND SINGLE PHASE EQUIPMENT, CIRCUIT INMERES ADJACHIT TO FIXINESS, DEVICES AND CUILLETS ARE INDICATED AS A GUIDE FOR PROPER CONNECTION OF MILTI-MIRE CARCIUTS AT PANELS.
- 34- SAFETY SWITCH RATING, FUSE AND POLES WILL BE INDICATED AS FOLLOWS:
  - A. FOR EQUIPMENT CONNECTED TO THE MOTOR CONTROL CENTERS ON THE ONE LINE DIAGRAMMESTIDE THE SYMBOL.

  - C. REFER TO DETAILS ON DWSS, AND TO SPECIFICATIONS SECTIONS 16/TO FOR NEMA TYPE ENCLOSURE AND MOUNTING.
  - D. ALL SAFETY SMITCHES EXPOSED TO THE WEATHER SHALL BE STAINLESS STEEL EXCEPT AS NOTED.
- 40- ALL PANELBOARDS SHALL HAVE STAINLESS STEEL FRONT COVERS WHINSED DOORS.

PROFESSIONAL CERTIFICATION LAW


IMPORTANT INFORMATION FOR THE CONTRACTOR

THESE DRAININGS AND THEIR CONTENT ARE PROPERTY OF JORGE RIGHAL ANGULTECTOS PSC.
SHALL BE USED SOLLLY IN REPERIOLE FOR THE PROJECT FOR WHICH THEY WERE EMPLOTLY
FOR JOHELLY BERNESULTION OF ANY DRAINING DOCUMENT AND/OR ITS CONTENT
WITHOUT PROMOUS AUTHORIZATION IS STRICTLY FORMEDED.

PROGRAMA | CDBG-DR - MUNICIPIO DE SAN GERMÁN PLAZA SANTO DOMINGO Y PLAZA FRANCISCO MARIANO QUIÑONES SAN GERMÁN, PUERTO RICO, 00683

NO.	DESCRIPTION	DATE	APPROVED
	<b>525</b> 0.111 110.1		
_			_

	TITLE		
ÆD	LEGNED, NO	TES AND S	CHEDULE
	SCALE AS SHOWN	PRINTED ON	SHEET NO.
	DRAWN BY: EF		ES-2.1
	PHASE DISEÑO PRELIMINAR		DATE: SEPT.22.2023




	PAN	EL 9	5CHE	DULE
DESCRIPTION	CIRC	POLES	TRIP	USE
"LP-IB"	1/2	2	30	DISCONNECT
	3,4	1	20	RECEPTACLES
PANELBOARD IPH,, 3N,	5	1	20	RECEPTACLES
120/240V.				
IO KAIC IOO Amp, Mlo				
SURFACE MTD.				
NEMA 4X				
STAINLESS STEEL				
WPADLOCK PROVISION				
(12 KM)				
1	6-12	-	20	SPACES


	PAN	EL S	5CHE	EDULE
DESCRIPTION	CIRC	POLES	TRIP	VSE
"LP-2"	1/2	2	30	DISCONNECT (I)
LP-2B"	3,4	1	20	RECEPTACLES
LF-2D	5	1	20	CLOCK (I)
PANELBOARD				
IPH., 3W. 120/240V.				
IO KAIG IOO Amp, MIo				
SURFACE MTD.				
NEMA 4X STAINLESS				
STEEL W/PADLOCK				
PROVISION				
(12 KW)	6-12	-	20	SPACES


### (I) APPLIES ONLY IN "LP-2B".


## ELECTRICAL ONE LINE DIAGRAM

- EXISTING METERBASE AT ALCALDIA 200 AMPS, I20/240V, IPH, 3W, W2-2P-200AMP, MAIN BREAKERS TO REMAIN.
   EXISTING PARELBOARD TO BE CLEAVER AND CONTRACTOR SHALL INSTALL FRONT COVER PLATES.
- EXISTING LIGHTING CONTRACTORS TO REMAIN.
- 4 NEW PANELBOARD, REFER TO SCHEDULE.
- EXISTING PEDESTAL TO REMAIN BUT BE COVERED TO WITHSTAND NEW GLORIETA CEMENT POUR.
- (1) EXISTING FEEDER TO REMAIN.
- ② NEW 3 NO.6 THIN, I NO.6 SND- TO BE WIRED IN EXISTING CONDUIT.
- (3) NEW 3 NO.6 THHN, I NO.8 GND- I" PVC 5CH.4O.














IMPORTANT INFORMATION FOR THE CONTRACTOR THESE PRAISINGS AND THEIR CONTENT ARE PROPERTY OF JOINE RIGHAL ARQUITECTOR PSC SHALL BE USED SOLLLY IN REPERIODE FOR THE PROJECT FOR WHICH THEY SERVE EXPLICITLY DOPELLOPED FOR PARTIAL OR FILL EMPOLUCION OF ANY DRAINING DOCUMENT AND/OR ITS CONTENT WITHOUT PROMISES AUTHORIZATION IN STRICTLY PORMEDON.

PROGRAMA | CDBG-DR - MUNICIPIO DE SAN GERMÁN PLAZA SANTO DOMINGO Y PLAZA FRANCISCO MARIANO QUIÑONES SAN GERMÁN, PUERTO RICO, 00683

NO.	DESCRIPTION	DATE	APPROVED
-			-
_			
			_
	JORGE RIGALI ARQU	OTTO YOU OF	

	DRAWN BY: EF  PHASE DISEÑO PRELIMINAR		DATE: SEPT.22.2023	
			ES-2.2	
	SCALE AS SHOWN	PRINTED ON	SHEET NO.	
D	ELECTRICAL	ONE LINE [	DIAGRAM AND DETAILS	
	TITLE			






## PR-CRP-000876 PLAZA SANTO DOMINGO and PLAZA MARIANO QUIÑONES

## **Exhibit 14 Wetlands Map**

Coordinates 18.0819, -67.0420 / 18.0822, -67.0431







Wild & Scenic Rivers Plaza Santo Domingo and Plaza Mariano Quiñones PR-CRP-000876 Municipality of San Germán







PO Box 1205, Boquerón, PR 00622 (787) 567-1302/567-1301/688-4945 info@acenvironmentalpr.com www.acenvironmentalpr.com

# **TECHNICAL MEMORANDUM TO FILE**

SITE VISIT PROJECT PLAZA SANTO DOMINGO Y PLAZAS FRANCISCO MARIANO QUIÑONES (PR-CRP-000876), MUNICIPALITY OF SAN GERMÁN

DATE: February 1<sup>st</sup>, 2023

This is to confirm that, as a result of a field reconnaissance that took place at the proposed project site on February 1<sup>st</sup>, 2023, with the intent to evaluate environmental aspects pursuant to 24CFR58 regulation, it was not identified relevant regulatory environmental risks. No recognized Environmental Condition (RECs) were identified within the project site. The inspection did not reveal any evidence of contamination related to hazardous substances or petroleum products, such as leaking storage tanks, improperly disposed chemicals, or malfunctioning equipment that could release contaminants into the environment.

All other environmental aspects related to the proposed action have been summarized in the Environmental Review Record (ERR) statutory form.

By:

William Sarriera

**Environmental Consultant** 

## **Environmental Site Visit Check List**

**Property Identification and Location:**Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

Proper 1.	ty Description: Does the municipality	y own this property	<b>/</b> ?
	XYes	No	
2.	Is the property locate	ed in urban surrou	ndings?
	_X Yes	No	Unknown
3.	Is the property locate	ed in rural surround	dings?
	Yes	<u>X</u> No	Unknown
4.	Is the property locate	ed in an industrial o	or manufacturing area?
	Yes	<u>X</u> No	Unknown
5.	Is the property locate	ed in a commercial	area?
	_X Yes	No	Unknown
6.	Is the property locate	ed in a residential a	area?
	_X Yes	No	Unknown
7.	Is the property locate	ed in an undevelop	ed area?
	Yes	X No	Unknown
8.	Is the property an inc	dustrial or manufac	cturing site?
	Yes	X No	Unknown
9.	Is the property a con	nmercial site?	
	Yes	<u>X</u> No	Unknown
10.	. Is the property a mul	tifamily residential	site?
	Yes	X No	Unknown

	11. Is the property	undeveloped land?		
	Yes	<u>X</u> No	Unknown	
	12. Are there any	surface water bodies w	vithin 500 feet (152 r	m) of the property?
	Yes	<b>X</b> No	Unknown R	Río Guanajibo (about 1,448 feet)
	•	n a wetland area as ma areas? See Figure	apped by the Depart	ment of the Interior or state and
		X No ds about 0.22 miles No		Vest of site.
	14. Are there any of processes?		olot plans of the facil	ities and property, or flow charts
	<u>X</u> Yes	No	Unknown	
Site	Appearance: 15. Are there any	indications of contamin	nation or environmer	ntal damage on the property?
	Yes	_ <b>X</b> _ No	Unknown	
	16. Are there any	newly surfaced areas,	areas of disturbed s	oil or mounds of soil?
	Yes	_ <b>X</b> No	Unknown	
	17. Do any ditche	es or easements have a	any signs of sludge,	discoloration, or oil sheen?
	Yes	<u>X</u> No	Unknown	
	•	evidence or knowledge zardous substances or		ds or sumps containing liquids ?
	Yes	No	Unknown	
	_	evidence or knowledge drains or sumps?	of any stains or co	rrosion on any floors, walls, or
	Yes	<u>x</u> No	Unknown	N/A
	20. Has any demo	olition occurred on the p	property?	
	Yes	No	X Unknown	

21	. Is there any construc	tion or demolition of	debris on or buried on the	e property?
	Yes	No	X Unknown	
22	2. Is there any evidence about odors, discharg	_	f any complaints by the the facility?	neighbors or authorities
	Yes	No	X Unknown	
23	B. Does the general app housekeeping"?	pearance of the fac	cility and grounds appear	to be in a state of "good
	_ <b>X</b> _Yes	No	Unknown	N/A
24		ng, endangered s	essessments, audits, regreecies studies or impacenty?	•
	Yes	No	X Unknown	
25	5. Has an environment	al professional rev	iewed the report as part	of this assessment?
	Yes	No	X Unknown	
	onmental Compliance 6. Has the facility been i State, and local laws	n compliance with	all environmental permits ordinances?	s and applicable Federal,
	Yes	No	Unknown	X N/A
27	-		lawsuits or administration	
	Yes	No	Unknown	<u><b>X</b></u> N/A
			uspected onsite or offsite atment, storage, or dispos	
	Yes	<u>X</u> No	Unknown	N/A
29		-	any evidence or knowle	-
	Yes	<u>X</u> No	Unknown	N/A

	•	n-site environmental government agencies	contamination issues to a secondary contamination issues to the secondary contamination issues to the secondary	peing investigated by	/ Federal,
	Yes	_ <b>X</b> No	Unknown	N/A	
	-		cations of any lawsuits o natural resources at t		-
	Yes	No	Unknown	_ <b>X</b> _ N/A	
	32. Has the mul remediation co		any reserves for e	nvironmental comp	liance or
	Yes	No	Unknown	_ <b>X</b> _N/A	
	33. Are there any municipality?	off-site active or ina	ctive land disposal sit	es owned or operat	ed by the
	Yes	No	X Unknown	N/A	
Gro	oundwater: 34. Is the local wa	iter supply provided b	y a central water syste	n?	
	X Yes AAA PRASA (AAA)		Unknown	N/A	
	35. Are there any	known drinking water	wells within a one-mile	radius of the subject	property?
	Yes	No	X Unknown	N/A	
	36. Is the depth to	groundwater known?			
	Yes	No	X Unknown	N/A	
	37. Is there any gr	roundwater well(s) tha	at the facility can or doe	s monitor?	
	Yes	<b>X</b> No	Unknown	N/A	
		nants been identified the subject property?	in any well on the prop	perty or any well witl	nin a one-
	Yes	_ <b>_x</b> No	Unknown	N/A	

at the facility of	on the property?			
Yes	_ <b>X</b> _No	Unknown	N/A	
		e that the manufacturing ditions in connection wi		
Yes	_ <b>X</b> No	Unknown	N/A	
-	-	ge of any repair or ser delivery activities cond	_	
Yes	_ <b>X</b> No	Unknown	N/A	
_	ing, printing or photo	ge of any dry cleaning ographic developing ac		
Yes	X No	Unknown	N/A	
	<del></del>	<del></del>	<del></del>	
43. Is there any evi		e of any waste storage,		activ
43. Is there any evi conducted at th	dence or knowledge ne facility or on the p	e of any waste storage,	recycling or treatment a	activ
43. Is there any evi conducted at th Yes 44. Is there any ev	dence or knowledge ne facility or on the p X_ No	e of any waste storage, property?  Unknown e of any waste, wastew	recycling or treatment a	
43. Is there any evi conducted at th Yes 44. Is there any ev	dence or knowledge ne facility or on the p X_No idence or knowledge ne facility or on the p	e of any waste storage, property?  Unknown e of any waste, wastew	recycling or treatment a	
43. Is there any eviconducted at the Yes  44. Is there any eviconducted at the Yes  45. Is there any eviconducted at the Yes	dence or knowledge ne facility or on the p X No idence or knowledge ne facility or on the p X No	e of any waste storage, property?  Unknown e of any waste, wastew property?  Unknown ge of any prepackaged	recycling or treatment a N/A ater, or land disposal a N/A	activ
43. Is there any eviconducted at the Yes  44. Is there any eviconducted at the Yes  45. Is there any eviconducted at the Yes	dence or knowledge ne facility or on the positive or knowledge ne facility or on the positive or knowledge at the facility or on the facility or o	e of any waste storage, property?  Unknown e of any waste, wastew property?  Unknown ge of any prepackaged the property?	recycling or treatment a N/A ater, or land disposal a N/A	activ
43. Is there any eviconducted at the Yes  44. Is there any eviconducted at the Yes  45. Is there any eviconducted at the Yes  46. Is there any eviconducted at the Yes	idence or knowledge ne facility or on the positive or knowledge ne facility or on the positive or knowledge at the facility or on the facility or	e of any waste storage, property?  Unknown e of any waste, wastew property?  Unknown ge of any prepackaged he property?  Unknown e of any lawn, disinfect	recycling or treatment a  N/A ater, or land disposal a  N/A hazardous substance  N/A	acti <sup>,</sup> s si
43. Is there any eviconducted at the Yes  44. Is there any eviconducted at the Yes  45. Is there any eviconducted at the Yes  46. Is there any eviconducted at the Yes	idence or knowledge ne facility or on the positive or knowledge ne facility or on the positive or knowledge at the facility or on the facility or	e of any waste storage, property?  Unknown e of any waste, wastew property?  Unknown ge of any prepackaged he property?  Unknown e of any lawn, disinfect	recycling or treatment a  N/A ater, or land disposal a  N/A hazardous substance  N/A	activ
43. Is there any eviconducted at the Yes  44. Is there any eviconducted at the Yes  45. Is there any evicondistribution  — Yes  46. Is there any eviconducted at the Yes  47. 7. Is there any	idence or knowledge ne facility or on the positive or knowledge ne facility or on the positive or knowledge at the facility or on the facility or	e of any waste storage, property?  Unknown e of any waste, wastew property?  Unknown ge of any prepackaged he property?  Unknown he of any lawn, disinfect he property?	recycling or treatment a  N/A  ater, or land disposal a  N/A  hazardous substance  N/A  tant, or pest control che  N/A  cleaning, building pain	activ s st

# Applicant ID: PR-CRP-000876

Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

48	. 48. Is there any evidence activities conducted a				yin	g, oil or gas extraction
	Yes	X		Unknown		_ N/A
49	. Is there any evidence hazardous materials o		• •	•		vities involving toxic or the property?
	Yes	X		Unknown		_ N/A
50	. Is the site located in a	ın a	rea with known reg	gional elevated rado	on l	levels?
	Yes	X		Unknown		_ N/A
	Based Paint: . Is there any evidence	or k	nowledge of any le	ead-based paint had	d be	een used at the facility?
	Yes		. NoX	Unknown		_ N/A
	ormaldehyde: . Does the facility have	an	y urea formaldehyd	de insulation?		
	Yes	X		Unknown		_ N/A
	ng Water Lead Pipes: . Is there any evidence	or l	knowledge of any o	drinking water lead	pip	pes?
	Yes			Unknown	X	_ N/A
						high voltage or similar ts or within 300 feet of
	Yes			Unknown	X	_ N/A
<b>Fill Dir</b> 55				fill dirt or fill materia	als	been used on, applied
	Yes		No <u>X</u>	Unknown		_ N/A
Asbes			_	-		ng materials, vinyl floor is or on the property?
	Yes	X		_ Unknown		_ N/A

•		ce or knowledge	that there is fluoresory or on the property?	cent light ballast that could			
	Yes	No	X Unknown	N/A			
58	8. Is there any eviden installed before 1980	•		re any electrical equipment			
	Yes	No	X Unknown	N/A			
_	ground Storage Tank  9. Is there any eviden storage tank at the f	ce, knowledge or		f any existing underground			
	Yes	X No	Unknown	N/A			
	Ground Storage Tan  O. Is there any evidence tanks at the facility of	ce, knowledge or		any above ground storage			
	Yes	_ <b>X</b> _ No	Unknown	N/A			
6	1. Are there any active	above ground sto	orage tanks at the faci	lity or on the property?			
	Yes	<u>X</u> No	Unknown	N/A			
62	2. Are there any out of on the property?	service or abando	oned above ground st	orage tanks at the facility or			
	Yes	<u>X</u> No	Unknown	N/A			
63	3. Has there been any	above ground sto	rage tanks removed for	rom the property?			
	Yes	<b>X</b> _No	Unknown	N/A			
Chemic	Chemical, Hazardous Substances and Petroleum Products:						
64	4. Are there any mater produced or stored a	•	· · · · · · · · · · · · · · · · · · ·	materials or products used,			
	Yes	No	Unknown	<u>X</u> N/A			

# Applicant ID: PR-CRP-000876

Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

Emplo Repo	oyee Right to K rting, Toxic Chem	now, Community nical Release Rep	Right to Know, T	Communication Program, foxic Chemical Inventory y Notification of Releases rting?
Ye	s	_ No	Unknown	X N/A
	•	•	nere are any chemica he facility or on the p	als, hazardous substances property?
Ye	<u>X</u>	_ No	Unknown	N/A
67. Are th	-			substances suspected of
Ye	<u>X</u>	No	Unknown	N/A
	_	or knowledge that to or on the propert		by-products, or throw-offs
Ye	<u>X</u>	No	Unknown	N/A
	re any evidence o	•		ludge or solids generated, ity or on the property?
Ye	<u>X</u>	_ No	Unknown	N/A
	-	_	there are or were any pandoned at the facil	y sludge's or solids ity or on the property?
Ye	s	_ No	Unknown	X N/A
landfi	re any evidence o lls, open dumps,	buried materials		ny waste piles, junkyards, tion debris or abandoned property?
Ye	<u>x</u>	_ No	Unknown	N/A
			at there are or were tes on the property?	any deep wells, injection
Ye	s	_ NoX	Unknown _	N/A

		e that there are or were	any pits, ponds, lakes,	, basins,
Yes	<u>X</u> No	Unknown	N/A	
	idence or knowledg ed, or any waste oil	Oil: e that there are or were generated, stored, treat	-	
Yes	<u>X</u> No	Unknown	N/A	
75. Has any oil or	waste oil been used	d for dust control on the	property?	
Yes	<u>X</u> No	Unknown	N/A	
	vidence or knowled rated or stored at th	ge that there are or wer ne property?	e any industrial or aut	omotive
Yes	<u>X</u> No	Unknown	N/A	
_		lge that there are or we		•
Yes	_X No	Unknown	N/A	
		ge that there are or werest at the facility or on the		s, odors,
Yes	<u>X</u> No	Unknown	N/A	
Sanitary Wastewater: 79. Does the facili	ty discharge sanitar	y wastewater to a muni	cipal sewer system?	
X Yes PRASA (AAA)	No	Unknown	N/A	
80. Does the facili	ty discharge wastev	vater to an onsite septic	system or leaching fie	eld?
Yes	<u>X</u> No	Unknown	N/A	

# Applicant ID: PR-CRP-000876

Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

	sumps that could	d discharge spills	e floor drains, roof dra , leaks, or releases fr ge tanks, machinery o	om process areas, o	hemical
	Yes	No	Unknown	_ <b>X</b> _N/A	
Stor	<b>m Water Runoff:</b> 82. Is storm water ru	noff discharged to	a municipal sewer sys	tem?	
	_ <b>X</b> _Yes	No	Unknown	N/A	
	83. Is storm water ru	noff discharged to	surface water?		
	X Yes	No	Unknown	N/A	
	discharge spills,	leaks, or releases	roof drains, catch bas from process areas, cl r electrical equipment t	nemical storage areas	
	Yes	No	Unknown	<u>X</u> N/A	
	85. Do any floor dracontamination?	ains, roof drains,	catch basins, pits, o	r sumps have any	signs of
	Yes	<u>X</u> No	Unknown	N/A	
	86. Does any surfacontamination?	ace water or sto	rm water discharge	points have any s	signs of
	Yes	<u>X</u> No	Unknown	N/A	
		_	ge that there are or we onds used to store or t		agoons,
	Yes	<u>X</u> No	Unknown	N/A	
Indu	strial Wastewater: 88. Does the facility of	discharge any trea	ted or non-treated indu	ustrial wastewater?	
	Yes	<u>X</u> No	Unknown	N/A	
Neig	_		edge of any industria	l or manufacturing a	activities
	Yes	<u>X</u> No	Unknown	N/A	

-		ge that there are or wer the adjacent properties?	•	anks that
Yes	No	X Unknown	N/A	
	vidence or knowled I at any of the adjac	dge that there are or we cent properties?	re any hazardous su	ıbstances
Yes	_ <b>X</b> _No	Unknown	N/A	
Signature / William/Sar	leva riera		Date: 02-01	1-2023



## **TECHNICAL MEMORANDUM TO FILE**

SITE VISIT PROJECT PLAZA SANTO DOMINGO Y PLAZAS FRANCISCO MARIANO QUIÑONES (PR-CRP-000876), MUNICIPALITY OF SAN GERMÁN

DATE: May 5<sup>th</sup>, 2023

This is to confirm that, as a result of a field reconnaissance that took place at the proposed project site on May 5<sup>th</sup>, 2023, with the intent to evaluate environmental aspects pursuant to 24CFR58 regulation, it was not identified relevant regulatory environmental risks. No recognized Environmental Condition (RECs) were identified within the project site. The inspection did not reveal any evidence of contamination related to hazardous substances or petroleum products, such as leaking storage tanks, improperly disposed chemicals, or malfunctioning equipment that could release contaminants into the environment.

All other environmental aspects related to the proposed action have been summarized in the Environmental Review Record (ERR) statutory form.

By:

William Sarriera

**Environmental Consultant** 

### **Environmental Site Visit Check List**

## **Property Identification and Location:**

Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

Proper 1.	ty Description: Does the municipality	y own this propert	y?
	XYes	No	
2.	Is the property locate	ed in urban surrou	ndings?
	_X Yes	No	Unknown
3.	Is the property locate	ed in rural surroun	dings?
	Yes	X_No	Unknown
4.	Is the property locate	ed in an industrial	or manufacturing area?
	Yes	X_No	Unknown
5.	Is the property locate	ed in a commercia	l area?
	_X Yes	No	Unknown
6.	Is the property locate	ed in a residential	area?
	_X Yes	No	Unknown
7.	Is the property locate	ed in an undevelop	oed area?
	Yes	<u>X</u> No	Unknown
8.	Is the property an inc	dustrial or manufa	cturing site?
	Yes	<u>X</u> No	Unknown
9.	Is the property a com	nmercial site?	
	Yes	_X_ No	Unknown
10	. Is the property a mul	tifamily residential	site?
	Yes	<u>X</u> No	Unknown

	11. Is the property	undeveloped land?			
	Yes	<u>X</u> No	Unknown		
	12. Are there any	surface water bodies wi	thin 500 feet (152 m	) of the property?	
	Yes	<b>X</b> No	Unknown R	ío Guanajibo (about 1,448	feet)
	•	n a wetland area as map areas? See Figure	oped by the Departn	nent of the Interior or state	e and
	Yes Closest wetlan	_X_ No ds about 0.22 miles Nor	Unknown th and 0.42 miles W	est of site.	
	14. Are there any of processes?		lot plans of the facilit	ies and property, or flow c	harts
	_ <b>X</b> _ Yes	No	Unknown		
Site	Appearance: 15. Are there any	indications of contamina	ation or environment	al damage on the propert	:y?
	Yes	_ <b>X</b> _ No	Unknown		
	16. Are there any	newly surfaced areas, a	reas of disturbed so	oil or mounds of soil?	
	Yes	<u>X</u> No	Unknown		
	17. Do any ditche	es or easements have a	ny signs of sludge, o	liscoloration, or oil sheen?	?
	Yes	<u>X</u> No	Unknown		
		evidence or knowledge zardous substances or p	* *	ls or sumps containing lie	quids
	Yes	No	Unknown		
		evidence or knowledge drains or sumps?	of any stains or cor	rosion on any floors, wal	ls, or
	Yes	<b>X</b> No	Unknown	N/A	
	20. Has any demo	olition occurred on the p	roperty?		
	Yes	No	_X Unknown		

21	. Is there any construct	ion or demolition	debris on or buried on	the property?
	Yes	No	X Unknown	
22	. Is there any evidence about odors, discharg	_		he neighbors or authorities
	Yes	No	X Unknown	
23	. Does the general app housekeeping"?	earance of the fa	cility and grounds app	ear to be in a state of "good
	_ <b>X</b> _Yes	No	Unknown	N/A
24		g, endangered s	pecies studies or im	regulatory inspections, soil, pact statements previously
	Yes	No	X Unknown	
25	. Has an environmenta	al professional rev	riewed the report as pa	art of this assessment?
	Yes	No	X Unknown	
	nmental Compliance: . Has the facility been in State, and local laws,	n compliance with	-	mits and applicable Federal,
	Yes	No	Unknown	<b>X</b> _N/A
27	-		f lawsuits or administ vironmental laws and r	ration proceedings alleging egulations?
	Yes	No	Unknown	_ <b>X</b> _N/A
	, .		suspected onsite or offe atment, storage, or dis	site contamination concerns
	Yes	X No	Unknown	N/A
29			any evidence or kno eing conducted at the	owledge that there is any property?
	Yes	X No	Unknown	N/A

Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

3	•	-site environmental coovernment agencies?		peing investigated by I	Federal,
	Yes	_ <b>X</b> No	Unknown	N/A	
3	•		-	or administration proc he facility or on the pro	•
	Yes	No	Unknown	_ <b>X</b> _ N/A	
3	2. Has the muni remediation cos		any reserves for e	nvironmental complia	ance or
	Yes	No	Unknown	_ <b>X</b> _ N/A	
3	3. Are there any municipality?	off-site active or inac	tive land disposal sit	es owned or operated	by the
	Yes	No	X Unknown	N/A	
	ndwater: 4. Is the local wate	er supply provided by	a central water system	m?	
	X Yes AAA PRASA (AAA)	No	Unknown	N/A	
3	5. Are there any k	nown drinking water w	vells within a one-mile	radius of the subject p	roperty?
	Yes	No	X Unknown	N/A	
3	6. Is the depth to	groundwater known?			
	Yes	No	X Unknown	N/A	
3	7. Is there any gro	oundwater well(s) that	the facility can or doe	es monitor?	
	Yes	<b>X</b> No	Unknown	N/A	
3		ants been identified in the subject property?	n any well on the prop	perty or any well withir	n a one-
	Yes	_ <b>_x</b> No	Unknown	N/A	

Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

	Yes	X	No		Unknown	N/A	
40.						g activities are likely to i ith the subject property?	
	Yes	X	No		Unknown	N/A	
41.	•			-	-	vice activities, gas stati ducted at the facility or	
	Yes	X	No		Unknown	N/A	
42.	•	ng, printin		•		, parts cleaning, equipr tivities conducted at the	
	Yes	X	No		Unknown	N/A	
43.	Is there any evi				aste storage,	recycling or treatment a	ctiv
	Yes	_X	No		Unknown	N/A	
		dence or	knowledg	ge of any v		N/A rater, or land disposal a	ctiv
	Is there any evi	dence or le facility o	knowledg	ge of any v		ater, or land disposal a	ctiv
44.	Is there any eviction conducted at the Yes	dence or le facility of the fa	knowledgor on the Noknowled	ge of any version of the property?  ge of any	vaste, wastev Unknown prepackaged	ater, or land disposal a	
44.	Is there any eviconducted at the Yes  Is there any even	idence or le facility of the f	knowledger on the No knowled	ge of any verty?  — ge of any the prope	vaste, wastev Unknown prepackaged	vater, or land disposal an N/A hazardous substances	
44. 45.	Is there any eviconducted at the Yes  Is there any evicon distribution at Yes  Yes	idence or le facility of le facility	knowledger on the  No  knowledelity or on  No  knowledel	ge of any very property?  ge of any the prope  ge of any	vaste, wastew Unknown prepackaged ty? Unknown lawn, disinfed	vater, or land disposal an N/A hazardous substances	st

5 Page

Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

48.	48. Is there any evid activities conducted a	_		rrying, oil or gas extraction
	Yes	_X_ No	Unknown	N/A
49.	•	•	any special or unique ducted at the facility o	activities involving toxic or or the property?
	Yes	<u>X</u> No	Unknown	N/A
50.	Is the site located in a	an area with knowr	n regional elevated rad	don levels?
	Yes	X No	Unknown	N/A
	ased Paint: Is there any evidence	or knowledge of a	ny lead-based paint ha	ad been used at the facility?
	Yes	No	X Unknown	N/A
	ormaldehyde:  Does the facility have	any urea formalde	ehyde insulation?	
	Yes	<u>X</u> No	Unknown	N/A
	ng Water Lead Pipes: Is there any evidence		any drinking water lead	d pipes?
	Yes	No	Unknown	<u>X</u> N/A
	•			eled high voltage or similar ments or within 300 feet of
	Yes	No	Unknown	<u>X</u> N/A
<b>Fill Dir</b> t 55.		_		rials been used on, applied
	Yes	No	X Unknown	N/A
	56. Is there any evide			facing materials, vinyl floor dings or on the property?
	Yes	X_ No	Unknown	N/A

Poly	-			escent light ballast that could ?	
	Yes	No	X Unknown	N/A	
		evidence or knowledg re 1980 at the facility o		vere any electrical equipment	
	Yes	No	X Unknown	N/A	
Und	Underground Storage Tank: Existing Tank: 59. Is there any evidence, knowledge or physical indication of any existing underground storage tank at the facility or on the property?				
	Yes	_ <b>X</b> _ No	Unknown	N/A	
Abo	60. Is there any	ge Tanks (AST's): evidence, knowledge of acility or on the propert		of any above ground storage	
	Yes	_ <b>X</b> _ No	Unknown	N/A	
	61. Are there any	active above ground	storage tanks at the fa	cility or on the property?	
	Yes	_ <b>X</b> _No	Unknown	N/A	
	62. Are there any on the proper		ndoned above ground	storage tanks at the facility or	
	Yes	<u>X</u> No	Unknown	N/A	
	63. Has there be	en any above ground s	storage tanks removed	I from the property?	
	Yes	_ <b>X</b> No	Unknown	N/A	
Che	mical, Hazardous	Substances and Pet	roleum Products:		
	-	material safety data stored at the facility or		w materials or products used,	
	Yes	No	Unknown	<u>X</u> N/A	

Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

Employee Righ Reporting, Toxic	t to Know, Com Chemical Releas	munity Right to Know	ard Communication Program, r, Toxic Chemical Inventory ency Notification of Releases eporting?
Yes	No	Unknown	_ <b>X</b> _ N/A
•	•	e that there are any cher red at the facility or on t	nicals, hazardous substances he property?
Yes	_ <b>X</b> _ No	Unknown	N/A
-	ontainers or drum	s that contain unidentifetroleum products?	ied substances suspected of
Yes	<u>X</u> No	Unknown	N/A
· · · · · · · · · · · · · · · · · · ·	lence or knowledg facility or on the p	-	ste, by-products, or throw-offs
Yes	<u>X</u> No	Unknown	N/A
-	•		ny sludge or solids generated, acility or on the property?
Yes	<u>X</u> No	Unknown	N/A
-	_	le that there are or were d, or abandoned at the f	any sludge's or solids acility or on the property?
Yes	No	Unknown	_ <b>X</b> _ N/A
landfills, open d	dence or knowledo lumps, buried ma		e any waste piles, junkyards, ruction debris or abandoned the property?
Yes	_ <b>X</b> _No	Unknown	N/A
-		dge that there are or way	ere any deep wells, injection by?
Yes	No	X Unknown	N/A

•		e that there are or were a	any pits, ponds, lak	es, basins,
Yes	<u>X</u> No	Unknown	N/A	
-	vidence or knowledge red, or any waste oil	Oil: e that there are or were a generated, stored, treat	•	
Yes	<u>X</u> No	Unknown	N/A	
75. Has any oil or	waste oil been used	for dust control on the	property?	
Yes	<u>X</u> No	Unknown	N/A	
-	vidence or knowledorated or stored at the	ge that there are or were e property?	e any industrial or a	automotive
Yes	<u>X</u> No	Unknown	N/A	
		ge that there are or we ed or disposed of at the	•	
Yes	_ <b>X</b> No	Unknown	N/A	
Air Emissions: 78. Is there any evidence or knowledge that there are or were air emission sources, odors, fumes, visible gas, particles or dust at the facility or on the property?				
Yes	_ <b>X</b> _No	Unknown	N/A	
Sanitary Wastewater: 79. Does the facil	ity discharge sanitar	y wastewater to a munic	cipal sewer system?	?
X Yes PRASA (AAA)	No	Unknown	N/A	
80. Does the facil	ity discharge wastev	vater to an onsite septic	system or leaching	field?
Yes	<u>X</u> No	Unknown	N/A	

	sumps that c	ould discharge spills, above ground stor	s, leaks, or releases f	ains, and catch basins, pits or rom process areas, chemical or electrical equipment to the
	Yes	No	Unknown	<u>X</u> N/A
Stor	m Water Runoff:			
	82. IS Storm water	runon discharged to	o a municipal sewer sys	stem?
	_ <b>X</b> _ Yes	No	Unknown	N/A
	83. Is storm water	runoff discharged to	surface water?	
	X Yes	No	Unknown	N/A
	discharge spil	ls, leaks, or releases		sins, pits or sumps that could hemical storage areas, above to the surface water?
	Yes	No	Unknown	<u>X</u> N/A
	85. Do any floor contamination		, catch basins, pits, o	or sumps have any signs of
	Yes	X No	Unknown	N/A
	86. Does any su contamination		orm water discharge	points have any signs of
	Yes	<u>X</u> No	Unknown	N/A
			ge that there are or w ponds used to store or	ere any ponds, pits, lagoons, treat storm water?
	Yes	X No	Unknown	N/A
Indu	strial Wastewater 88. Does the facil		ated or non-treated ind	ustrial wastewater?
	Yes	X No	Unknown	N/A
Neig	89. Is there any	es: Current and Pas evidence or knowl any of the adjacent p	edge of any industria	al or manufacturing activities
	Yes	<u>X</u> No	Unknown	N/A

	-	•	ge that there are or wer the adjacent properties?	e any containers or tank	ks that
	Yes	No	X Unknown	N/A	
	91. Is there any evide used or stored at	· · · · · · · · · · · · · · · · · · ·	•	re any hazardous subst	ances
	Yes	_X_ No	Unknown	N/A	
Signa	ature Manyler William/Sarriera	va a		Date: 5 May 20	023



## **TECHNICAL MEMORANDUM TO FILE**

SITE VISIT PROJECT PLAZA SANTO DOMINGO Y PLAZAS FRANCISCO MARIANO QUIÑONES (PR-CRP-000876), MUNICIPALITY OF SAN GERMÁN

DATE: May 31<sup>st</sup>, 2024

This is to confirm that, as a result of a field reconnaissance that took place at the proposed project site on May 31<sup>st</sup>, 2024, with the intent to evaluate environmental aspects pursuant to 24CFR58 regulation, it was not identified relevant regulatory environmental risks. No recognized Environmental Condition (RECs) were identified within the project site. The inspection did not reveal any evidence of contamination related to hazardous substances or petroleum products, such as leaking storage tanks, improperly disposed chemicals, or malfunctioning equipment that could release contaminants into the environment.

All other environmental aspects related to the proposed action have been summarized in the Environmental Review Record (ERR) statutory form.

By:

William Sarriera

**Environmental Consultant** 

### **Environmental Site Visit Check List**

**Property Identification and Location:**Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

	Property Description: 1. Does the municipality own this property?				
	XYes	No			
2.	Is the property locate	ed in urban surrour	ndings?		
	_X Yes	No	Unknown		
3.	Is the property locate	ed in rural surround	dings?		
	Yes	X_No	Unknown		
4.	Is the property locate	ed in an industrial o	or manufacturing area?		
	Yes	X_No	Unknown		
5.	Is the property locate	ed in a commercial	area?		
	_X Yes	No	Unknown		
6.	Is the property locate	ed in a residential a	area?		
	_X Yes	No	Unknown		
7.	Is the property locate	ed in an undevelop	ed area?		
	Yes	<u><b>X</b></u> No	Unknown		
8.	Is the property an inc	dustrial or manufac	cturing site?		
	Yes	<u><b>X</b></u> No	Unknown		
9.	Is the property a com	nmercial site?			
	Yes	_ <b>X</b> _No	Unknown		
10	. Is the property a mul	tifamily residential	site?		
	Yes	X No	Unknown		

	11. Is the property undeveloped land?						
	Yes	<u>X</u> No	Unknown				
	12. Are there any surface water bodies within 500 feet (152 m) of the property?						
	Yes	_ <b>X</b> No	Unknown Río Guanajibo (about 1,448 feet)				
	13. Is the facility in a local planning are		napped by the Department of the Interior or state and				
	Yes Closest wetlands a		Unknown North and 0.42 miles West of site.				
	14. Are there any ava of processes?	ailable site layouts	, plot plans of the facilities and property, or flow charts				
	_ <b>X</b> _ Yes	No	Unknown				
Site	• <b>Appearance:</b> 15. Are there any indi	ications of contam	nination or environmental damage on the property?				
	Yes	_ <b>X</b> _ No	Unknown				
	16. Are there any nev	vly surfaced areas	s, areas of disturbed soil or mounds of soil?				
	Yes	_ <b>X</b> No	Unknown				
	17. Do any ditches o	r easements have	e any signs of sludge, discoloration, or oil sheen?				
	Yes	_ <b>X</b> No	Unknown				
	<del>_</del>	-	ge of any pool of liquids or sumps containing liquids or petroleum products?				
	Yes	No	Unknown				
	19. Is there any evid- ceilings, floor drai		ge of any stains or corrosion on any floors, walls, or				
	Yes	_ <b>x</b> No	Unknown N/A				
	20. Has any demolitic	on occurred on the	e property?				
	Yes	No	X Unknown				

21. Is there any construction or demolition debris on or buried on the property?				
Yes		No <u>X</u>	Unknown	
	ny evidence or rs, discharges,		e neighbors or authorities	
Yes		No <u>X</u>	Unknown	
23. Does the one housekee		ance of the facility	and grounds appe	ar to be in a state of "good
_ <b>x</b> _Yes		. No	Unknown	N/A
air, or wa	iter sampling, o			egulatory inspections, soil, act statements previously
Yes		No X	Unknown	
25. Has an ei	nvironmental pr	ofessional reviewe	d the report as pa	rt of this assessment?
Yes		. No <u>X</u>	Unknown	
	cility been in co	mpliance with all er ulations, and ordin		nits and applicable Federal,
Yes		. No	Unknown	<b>X</b> _N/A
		notification of laws		ation proceedings alleging egulations?
Yes		. No	Unknown	_ <b>X</b> _N/A
	any past or curr	ent known or suspe erty or any treatmen		ite contamination concerns oosal facility?
Yes	<u> </u>	. No	Unknown	N/A
-	•	st, is there any o tion testing being o		wledge that there is any roperty?
Yes	<u>x</u>	. No	Unknown	N/A

30	30. Is there any on-site environmental contamination issues being investigated by Federal state, or local government agencies?				
	Yes	_ <b>X</b> _No	Unknown	N/A	
31			cations of any lawsuits on atural resources at the	•	_
	Yes	No	Unknown	<u>X</u> N/A	
32	P. Has the municipate remediation costs?		d any reserves for er	vironmental compliand	e or
	Yes	No	Unknown	_ <b>X</b> _ N/A	
33	B. Are there any off- municipality?	site active or ina	active land disposal site	s owned or operated b	y the
	Yes	No	X Unknown	N/A	
	ndwater: I. Is the local water s	upply provided b	y a central water system	?	
	X Yes AAA PRASA (AAA)	No	Unknown	N/A	
35	5. Are there any know	vn drinking water	wells within a one-mile r	adius of the subject prop	erty?
	Yes	No	X Unknown	N/A	
36	6. Is the depth to grou	undwater known	?		
	Yes	No	X Unknown	N/A	
37	7. Is there any ground	dwater well(s) tha	at the facility can or does	s monitor?	
	Yes	<b>X</b> No	Unknown	N/A	
38	B. Have contaminants mile radius of the s		in any well on the prop	erty or any well within a	one-
	Yes	<b>x</b> No	Unknown	N/A	

Yes	_ <b>X</b> _No	Unknown	N/A
-	<del>_</del>	that the manufacturing itions in connection witl	
Yes	<u>X</u> No	Unknown	N/A
		e of any repair or servi delivery activities condu	
Yes	_ <b>X</b> No	Unknown	N/A
-	ing, printing or photo	e of any dry cleaning, graphic developing acti	
Yes	_ <b>X</b> _No	Unknown	N/A
<del>_</del>	idence or knowledge ne facility or on the pr	of any waste storage, re operty?	ecycling or treatment a
Yes	<u> </u>	Unknown	N/A
14. Is there any ev		of any waste, wastewa	
14. Is there any ev conducted at th	idence or knowledge ne facility or on the pr	of any waste, wastewa	ter, or land disposal a
14. Is there any ev conducted at th  —— Yes 15. Is there any ev	idence or knowledge ne facility or on the pr X_ No	of any waste, wastewa operty? Unknown e of any prepackaged I	ter, or land disposal a N/A
14. Is there any ev conducted at th  —— Yes 15. Is there any ev	idence or knowledgene facility or on the property Novidence or knowledge	of any waste, wastewa operty? Unknown e of any prepackaged I	ter, or land disposal a N/A
14. Is there any ev conducted at the Yes 15. Is there any ever for distribution  Yes 16. Is there any ever	idence or knowledgene facility or on the property Nowledge or knowledge at the facility or on the Nowledge Nowledge or the facility or on the Nowledge Nowle	of any waste, wasteward operty?  —— Unknown  e of any prepackaged Interpreted to the property?  —— Unknown  e of any lawn, disinfectar	ter, or land disposal a N/A nazardous substances N/A
14. Is there any ev conducted at the Yes 15. Is there any ever for distribution  Yes 16. Is there any ever	idence or knowledgene facility or on the providence or knowledgenet the facility or on the matching of the facility or on the matching or knowledgenet or know	of any waste, wasteward operty?  —— Unknown  e of any prepackaged Interpreted to the property?  —— Unknown  e of any lawn, disinfectar	ter, or land disposal a N/A nazardous substances N/A

Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

48	48. 48. Is there any evidence or knowledge of any mining, quarrying, oil or gas extraction activities conducted at the facility or on the property?						
	Yes	_ <b>X</b> _No	Unknown	N/A			
49		_	any special or unique ducted at the facility o	e activities involving toxic or or on the property?			
	Yes	No	Unknown	N/A			
50	. Is the site located in	an area with know	n regional elevated ra	don levels?			
	Yes	_ <b>X</b> _No	Unknown	N/A			
	Based Paint: . Is there any evidence	e or knowledge of a	ny lead-based paint h	ad been used at the facility?			
	Yes	No	X Unknown	N/A			
	formaldehyde:  . Does the facility have	e any urea formald	ehyde insulation?				
	Yes	_ <b>X</b> _No	Unknown	N/A			
	ng Water Lead Pipes . Is there any evidence		any drinking water lea	d pipes?			
	Yes	No	Unknown	<u>X</u> N/A			
	-	the facility, on the		peled high voltage or similar ements or within 300 feet of			
b.		NO	OTIKITOWIT	<u>A</u> IVA			
	Fill Dirt: 55. Is there any evidence or knowledge of any fill dirt or fill materials been used on, applied to, or disposed of on the subject property?						
	Yes	No	X Unknown	N/A			
Asbes	56. Is there any evide			rfacing materials, vinyl floor ldings or on the property?			
	Yes	_ <b>X</b> _No	Unknown	N/A			

57. l		ce or knowledge	that there is fluoresc y or on the property?	cent light ballast that could
	_ Yes	No	X Unknown	N/A
	s there any eviden nstalled before 1980			e any electrical equipment
	_ Yes	No	X Unknown	N/A
59. I	ound Storage Tank s there any eviden storage tank at the f	ce, knowledge or		f any existing underground
	_ Yes	<u>X</u> No	Unknown	N/A
60. I	round Storage Tan s there any evidend anks at the facility o	ce, knowledge or		any above ground storage
	_ Yes	_ <b>X</b> _ No	Unknown	N/A
61. /	Are there any active	above ground sto	orage tanks at the faci	lity or on the property?
	_ Yes	<u>X</u> No	Unknown	N/A
	Are there any out of on the property?	service or abando	oned above ground st	orage tanks at the facility or
	_ Yes	<u>X</u> No	Unknown	N/A
63. I	Has there been any	above ground sto	rage tanks removed fi	rom the property?
	_ Yes	_ <b>X</b> No	Unknown	N/A
Chemica	, Hazardous Subs	tances and Petro	leum Products:	
	Are there any mater produced or stored a			materials or products used,
	_ Yes	No	Unknown	<u>X</u> N/A

Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

Employee Right Reporting, Toxic	65. Has the facility or does the facility participate in a Hazard Communication Program, Employee Right to Know, Community Right to Know, Toxic Chemical Inventory Reporting, Toxic Chemical Release Reporting, or Emergency Notification of Releases of Listed Extremely Hazardous Substances programs or reporting?						
Yes	No	Unknown	_ <b>X</b> _ N/A				
	_	e that there are any cher ored at the facility or on th	nicals, hazardous substances ne property?				
Yes	<u>X</u> No	Unknown	N/A				
	ontainers or drun	ns that contain unidentif etroleum products?	ied substances suspected of				
Yes	<u>X</u> No	Unknown	N/A				
<b>Solid Waste:</b> 68. Is there any evide generated at the	•		ste, by-products, or throw-offs				
Yes	<u>X</u> No	Unknown	N/A				
	_		ny sludge or solids generated, acility or on the property?				
Yes	<u>X</u> No	Unknown	N/A				
•		ge that there are or were d, or abandoned at the f	any sludge's or solids acility or on the property?				
Yes	No	Unknown	_ <b>X</b> _ N/A				
landfills, open d	and Disposal Activities: 71. Is there any evidence or knowledge that there are or were any waste piles, junkyards, landfills, open dumps, buried materials or wastes, construction debris or abandoned materials, drums, tanks, or equipment at the facility or on the property?						
Yes	<u>X</u> No	Unknown	N/A				
<u> </u>		dge that there are or we	ere any deep wells, injection y?				
Yes	No	X Unknown	N/A				

Pits, Ponds, and Surface Impoundments: 73. Is there any evidence or knowledge that there are or were any pits, ponds, lakes, basins, lagoons, or surface impoundments on the property?						
Yes	<u>X</u> No	Unknown	N/A			
	idence or knowledge ed, or any waste oil	Oil: e that there are or were generated, stored, treat				
Yes	<u>X</u> No	Unknown	N/A			
75. Has any oil or	waste oil been used	d for dust control on the	property?			
Yes	<u>X</u> No	Unknown	N/A			
<del>_</del>	vidence or knowledo rated or stored at th	ge that there are or wer ne property?	e any industrial or auto	motive		
Yes	<u>X</u> No	Unknown	N/A			
<u> </u>		lge that there are or we ed or disposed of at the				
Yes	_ <b>X</b> No	Unknown	N/A			
•	~	ge that there are or were st at the facility or on the		odors,		
Yes	<u>X</u> No	Unknown	N/A			
Sanitary Wastewater: 79. Does the facili	ty discharge sanitar	y wastewater to a muni	cipal sewer system?			
<u>X</u> Yes PRASA (AAA)	No	Unknown	N/A			
80. Does the facili	ty discharge wastev	vater to an onsite septic	system or leaching fiel	ld?		
Yes	<u>X</u> No	Unknown	N/A			

Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

sumps that could	discharge spills, lea	aks, or releases fro	om process areas, chemical
Yes	No	Unknown	<u>X</u> N/A
m Water Runoff: 82. Is storm water runo	ff discharged to a m	unicipal sewer syst	em?
X Yes	No	Unknown	N/A
83. Is storm water runo	ff discharged to surf	ace water?	
X Yes	No	Unknown	N/A
discharge spills, lea	aks, or releases fron	n process areas, ch	emical storage areas, above
Yes	No	Unknown	<u>X</u> N/A
85. Do any floor drain contamination?	ns, roof drains, cat	ch basins, pits, or	sumps have any signs of
Yes	<u>X</u> No	Unknown	N/A
86. Does any surface contamination?	e water or storm	water discharge	points have any signs of
Yes	<u>X</u> No	Unknown	N/A
	_		
Yes	<u>X</u> No	Unknown	N/A
strial Wastewater: 88. Does the facility dis	charge any treated	or non-treated indu	strial wastewater?
Yes	<u>X</u> No	Unknown	N/A
89. Is there any evide	ence or knowledge	of any industrial	or manufacturing activities
Yes	<u>X</u> No	Unknown	N/A
	sumps that could of storage areas, aboronage areas, aboro	sumps that could discharge spills, leastorage areas, above ground storage sanitary sewer? YesNo  m Water Runoff: 82. Is storm water runoff discharged to a mage of the sum of	YesNoUnknown  **Mater Runoff:  82. Is storm water runoff discharged to a municipal sewer syst  **X** YesNoUnknown  83. Is storm water runoff discharged to surface water?  **X** YesNoUnknown  84. If yes, are there any floor drains, roof drains, catch basi discharge spills, leaks, or releases from process areas, ch ground storage tanks, machinery or electrical equipment toYesNoUnknown  85. Do any floor drains, roof drains, catch basins, pits, or contamination?  **YesXNoUnknown  86. Does any surface water or storm water discharge contamination?  *YesXNoUnknown  87. Is there any evidence or knowledge that there are or we surface impoundments or settling ponds used to store or toYesXNoUnknown  85. Does the facility discharge any treated or non-treated indu  *YesXNoUnknown  87. Is there any evidence or knowledge or non-treated indu  *

Plaza Santo Domingo and Plaza Mariano Quiñones San Germán, Puerto Rico

	90. Is there any evidence or knowledge that there are or were any containers or tanks tha contain chemicals used at any of the adjacent properties?							
Yes	No	X Unknown	N/A					
	91. Is there any evidence or knowledge that there are or were any hazardous substances used or stored at any of the adjacent properties?							
Yes	<u>X</u> No	Unknown	N/A					
Signature William	Sarriera		Date: 31 Ma	y 2024				