# Environmental Assessment Determinations and Compliance Findings for HUD-assisted Projects 24 CFR Part 58

# Project Information

Project ID: PR-RGRW-00518

Project Name: Ángeles Rodríguez Sepúlveda

Responsible Entity: Puerto Rico Department of Housing

Grant Recipient (if different than Responsible Entity): Same as above

State/Local Identifier: Puerto Rico / Ponce, PR

Preparer: Patricia Carmenatty

**Certifying Officer Name and Title:** Permit and Environmental Compliance Officers: Sally Acevedo Cosme, Pedro de León Rodriguez, Ivelisse Lorenzo, Janette Cambrelen, Santa Ramirez, Limary Vélez Marrero, Mónica M. Machuca Ríos, Javier Mercado-Barrera, Abdul Feliciano Plaza and Priscilla Toro Rivera. María T. Torres Bregón - Environmental Manager, Angel G. Lopez Guzman - Deputy Director, Aldo A. Rivera-Vazquez – Director for Program Management, and Juan Carlos Perez Bofill - Director for Disaster Recovery CDBG Program.

Consultant: Behar Ybarra & Associates LLC

**Direct Comments to:** Puerto Rico Department of Housing: (<u>environmentcdbg@vivienda.pr.gov</u>)

### **Project Location:**

Carr. 505 Barrio Monte Llano, Sector Seto 2, Ponce, PR 00717

Storage warehouse location: latitude 18.114682 longitude -66.6171013

Parcel cadastral #: 317-000-001-31-002

Description of the Proposed Project [24 CFR 58.32; 40 CFR 1508.25]:

The proposed activities for PR-RGRW-00518 consist of installation of a 12' x 12' storage warehouse. The installation of the storage warehouse will require ground disturbance. The storage warehouse will be installed on a concrete slab measuring 12' x 12' and have a depth of 8 inches. The concrete slab will be provided by the applicant. Additionally, the proposed project includes the purchase of a coffee grinder, coffee roasting machine

and farm equipment. The farm equipment includes: a Truper digger, a Truper shovel, a Pretul shovel, Truper hoe, Truper pickaxe, Truper round shovel with long handle, Pretul round shovel with short handle, Truper round shovel with short handle, stick with extension (6'-12') and a water pump. The purpose of storage is to store the new equipment for the farm. No water connection will be necessary for the new warehouse. The power needed to operate the coffee toaster and coffee grinder will be provided by an inverter, no transfer switch will be necessary. A LUMA/PREPA connection will not be necessary for the proposed project. Both machinery will go inside of the warehouse but will not be fixed to the ground. The project area is located at PR-505 Barrio Monte Llano, Sector El Seto 2, within the Municipality of Ponce. Based on a review of historical aerial imagery, the general area has been used for agricultural purposes for the past 20 years.

The Area of Potential Effect (APE) has been defined as the area potentially impacted by ground disturbing activities related to the installation of the concrete slab for the storage warehouse. Based on this definition and the nature and scope of the Undertaking, the Program has determined that the direct APE for this project is the location of the concrete slab for the storage warehouse plus a 15-meter buffer and the visual APE is the viewshed of the proposed project.

A site Map is included in Figure 1, illustrating the location of the storage warehouse on the property. Photos of the location are included in Section 106 documentation, Appendix 1. Refer to Appendix 3 for Site Inspection Report.

**Statement of Purpose and Need for the Proposal** [40 CFR 1508.9(b)]: The Re-Grow Puerto Rico Urban-Rural Agriculture Program (RGRW) will increase agricultural capacity while promoting and increasing food security island wide. This Program will enhance and expand agricultural production related to economic revitalization and sustainable development activities. This agricultural project associated with the of installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment are in keeping with the overall objectives of the Economic Development Program.

### **Existing Conditions and Trends** [24 CFR 58.40(a)]:

The area where the storage warehouse will be installed is semi-flat, covered with grass. Currently the area where the storage warehouse will be installed has not been worked on due to the wait for funds. The parcel is currently used for coffee planting. Therefore, there is little to no change in land use associated with these placements.

# Funding Information

Grant Number	HUD Program	Funding Amount
B-18-DP-72-0001	Community Planning and	\$11,938,162,230.00
B-17-DM-72-0001	Development (CPD) /	

B-19-DP-78-0002	Community Development		
B-18-DE-72-0001	Block Grant - Disaster		
	Recovery (CDBG-DR)		

Estimated Total HUD Funded Amount: \$18,813.86

Estimated Total Project Cost (HUD and non-HUD funds) [24 CFR 58.32(d)]: \$20,413.86

### Compliance with 24 CFR 58.5 and 58.6 Laws and Authorities

Record below the compliance or conformance determinations for each statute, executive order, or regulation. Provide credible, traceable, and supportive source documentation for each authority. Where applicable, complete the necessary reviews or consultations and obtain or note applicable permits of approvals. Clearly note citations, dates/names/titles of contacts, and page references. Attach additional documentation as appropriate.

<b>Compliance Factors</b> : Statutes, Executive Orders, and Regulations listed at 24 CFR §58.5 and §58.6	Are formal compliance steps or mitigation required	Compliance determinations
STATUTES, EXECUTIVE ORDERS,	AND REGULATION	ONS LISTED AT 24 CFR 58.6
<b>Airport Hazards</b> 24 CFR Part 51 Subpart D	Yes No	This project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment and will have no impact on any Airports. The site is located 39,922 feet from the nearest major civil airport (Mercedita Airport in Ponce) and 239,365 feet from the nearest military airport (Luis Muñoz Marín International Airport in San Juan). This topic is in compliance with the HUD's Airport Hazard regulations without further evaluation. See the attached Airport map Runway Protection Zone, Figure 2.

Coastal Barrier Resources Coastal Barrier Resources Act, as amended by the Coastal Barrier Improvement Act of 1990 [16 USC 3501]	Yes No	This project is not located in a CBRS Unit. The project is located 50,530 feet northwest of the nearest Coastal Barrier Resource System, PR-56. Therefore, this project has no potential to impact a CBRS Unit and is in compliance with the Coastal Barrier Resources Act. See the attached CBRS map, Figure 3.
Flood Insurance Flood Disaster Protection Act of 1973 and National Flood Insurance Reform Act of 1994 [42 USC 4001-4128 and 42 USC 5154a]	Yes No	The project is located in Zone X, Panel 72000C1655J, 11/18/2009 on the FEMA FIRM. The project does not require flood insurance or is excepted from flood insurance. See attached Flood Map, Figure 4. The project is in compliance with the Flood Insurance without further evaluation.
STATUTES, EXECUTIVE ORDERS, AND REGULATIONS LISTED AT 24 CFR 58.5		
Clean Air Clean Air Act, as amended, particularly section 176(c) & (d); 40 CFR Parts 6, 51, 93	Yes No	This project consists of the of installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment for an agricultural site located in the Municipio of Ponce. The project is not located in a nonattainment municipality of Puerto Rico (Arecibo, Bayamón, Cataño, Guaynabo, Salinas, San Juan, Toa Baja). The installation and operation of this project will have no impact and is in compliance with the Clean Air Act without further evaluation. See attached published list of Puerto Rico Nonattainment/Maintenance Status for each country by year for all criteria pollutants in Appendix 2.

Coastal Zone Management		
Coastal Zone Management Act, sections 307(c) & (d)	Yes No	The project is located 45,071 feet from the nearest Coastal Zone Management Area and does not affect a Coastal Zone as defined in the state Coastal management Plan. The project is in compliance with the Coastal Zone Management Act. See the attached CZMA map, Figure 5.
Contamination and Toxic Substances 24 CFR Part 58.5(i)(2)	Yes No	This project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment for an agricultural project. On-site or nearby toxic, hazardous, or radioactive substances that could affect the health and safety of project occupants or conflict with the intended use of the property were not found. There are no sites of environmental concern identified within 3,000 feet near the proposed storage location. During the project site visit, no toxic, hazardous or radioactive substances were found on or near the site that could affect the health and safety of project occupants or conflict with the intended use of the property. HUD's environmental regulations at 24 CFR 58.5(i)(2)(i) and (ii)4 state that, [i]t is HUD's policy that all properties that are being proposed for use in HUD programs be free of hazardous materials, contamination, toxic chemicals and
		gases, and radioactive substances, where a hazard could affect the health and safety of occupants or conflict with the intended utilization of the property. For the proposed project, which involves the installation of a storage warehouse, radon analysis will not be required. This is because the facility qualifies for an exemption, as it is a non-residential

		structure that will not be occupied for more than 4 hours per day. The project is in compliance with Contamination and Toxic Substances requirements. See attached Toxics Map, Figure 6. See Appendix 3 for Site Inspection Report.
Endangered Species Endangered Species Act of 1973, particularly section 7; 50 CFR Part 402	Yes No	After reviewing data from the United States Fish and Wildlife Service (USFWS) Information and Planning Consultation (IPaC) and the Puerto Rico Department of Natural and Environmental Resources (DNER) database, the Puerto Rican boa (Chilabothrus inornatus), Puerto Rican Broad-winged Hawk (Buteo platypterus brunnescens), Puerto Rican Parrot (Amazona vittata), Puerto Rican Sharp- shinned Hawk (Accipiter striatus venator) and the Puerto Rican harlequin butterfly (Atlantea tulita) could be found in the project area. The scope of work includes continued agricultural use of the property with no intention of cutting down trees where the storage warehouse will be installed. The type of work to be performed does not require heavy machinery, the area where the storage warehouse will be installed is only grass. The nature of the project, scope of work, information available, a careful analysis of the IpaC, the Puerto Rico Boa conservation measures, the Caribbean Dkey in the US Fish and Wildlife Service's online IPaC application, and the observations during the field visit on February 16, 2024, were used to evaluate the potential impacts to federally listed species from this project. Based on that information and the answer inputted into the Dkey, USFWS concurred that the proposed action will have "No Effect" determination on the Puerto Rican

Broad-winged Hawk (Buteo platypterus brunnescens) and Puerto Rican Sharp- shinned Hawk (Accipiter striatus venator). An Informal Consultation was submitted to USFWS on 4/4/2024 and Concurrence Letter was received on 5/16/2024 Based on the nature of the project, scope of work, information available and existing habitat, the Service recommends a reconsideration of the No Effect determination for the Puerto Rican boa to a May Affect, but is Not Likely to Adversely Affect (NLAA) determination. PRDOH'S accepts the reconsideration in an Effect Determination Acceptance Letter dated 7/22/2024.
Also, based on the nature of the project, scope of work, information available and existing habitat, PRDOH determined and USFWS concur that the proposed project has NE on the Puerto Rican parrot due to the lack of suitable habitat.
The PRDOH determined and USFWS concur that the proposed project may affect but is not likely to adversely affect (NLAA) Puerto Rican harlequin butterfly since the project area has been used for agricultural purposes for the past 20 years. The closest Critical Habitat is 43,080 feet from the project location.
If a Puerto Rican Boa is found in the project activity site, work shall cease until the Boa moves off on its own. If the Boa does not move off, the Construction Manager shall contact the Puerto Rico Department of Natural and Environmental Resources and ask for them to relocate the Boa. As established by the USFWS Puerto Rican Boa Conservation Measures Guideline.

		https://ipac.ecosphere.fws.gov/guidelin e/design/population/156/office/41430.p df If a Puerto Rican harlequin butterfly is found at the project site, the contractor must follow the conservation measures proposed by USFWS as indicated in the consultation letter and inform all personnel. This project is in compliance with the Endangered Species Act. See attached USWFS Concurrence letter and supporting documents in Appendix 4. See attached Endangered Species map,
		Figure 7.
Explosive and Flammable Hazards 24 CFR Part 51 Subpart C	Yes No	This project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment and does not include development, construction or rehabilitation that will increase residential density. This project is in compliance with Explosive and Flammable hazards without further evaluation.
Farmlands Protection Farmland Protection Policy Act of 1981, particularly sections 1504(b) and 1541; 7 CFR Part 658	Yes No	This project does not include any activities that could potentially convert agricultural land to non-agricultural use. The project activities will occur in an area designated as not prime farmland. The scope of work includes the installation of a storage warehouse on a concrete slab, and this is a construction limited to on- farm structures needed for farm operations. The project is in compliance with the Farmland Protection Policy Act. See the attached Farmlands map, Figure 8.
Floodplain Management Executive Order 11988 as amended by Executive	Yes No	The Department of Housing and Urban Development (HUD) introduced new floodplain regulations under 89 FR 30850, effective June 24, 2024, establishing the

Order 13690, particularly section 2(a); 24 CFR Part 55		Federal Flood Risk Management Standard (FFRMS). PFIRMs in Puerto Rico were only developed for certain sections of the municipalities of Carolina, Canovanas, Loiza, San Juan and Trujillo Alto. The proposed project is located in the municipality of Ponce; therefore, PFIRM information was not available for the area and therefore was not considered in the review.
		This project installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment and was evaluated using the 0.2 Percent-Annual- Chance Floodplain Approach (0.2 PFA) to determine the extent of the FFRMS. The current project involves non-critical actions that are located outside the 0.2- percent-annual-chance floodplain (500- year flood elevation). This approach ensures compliance with the FFRMS, meaning no mitigation is required, and the project adheres to the regulations set forth in 24 CFR Part 55. The project is not located in the 500-year floodplain or ABFE special flood hazard area; therefore, no further action is required. The project is in compliance with Executive Order 11988, as amended by Executive Order 13690. See attached ABFE Map (Figure 9).
Historic Preservation National Historic Preservation Act of 1966, particularly sections 106 and 110; 36 CFR Part 800	Yes No	The site was visited on February 19, 2024, by SOI-qualified archaeologist. Based on the nature and scope of the undertaking, the APE has been defined as the area potentially affected by ground-disturbing activities related to installation of storage warehouse. Documentation with photographs and maps was subsequently submitted to SHPO

		(attached Appendix 1). In a response from PR SHPO dated March 14, 2024, SHPO concurred with a finding of <b>No</b> <b>Historic Properties Affected</b> within the project's Area of Potential Effects (see attached Appendix 1). The property is not considered historic or contributing to an historic district (See attached Historic map, Figure 10). Therefore, this activity is in compliance with National Historic Preservation Act.
Noise Abatement and Control Noise Control Act of 1972, as amended by the Quiet Communities Act of 1978; 24 CFR Part 51 Subpart B	Yes No	This project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment for an agricultural site. The project does not include new construction for residential use or rehabilitation of an existing residential property. The site is rural in nature and there will be no impact to or from the surrounding area from a noise perspective. This topic is in compliance with Noise abatement and Control without further evaluation.
Sole Source Aquifers Safe Drinking Water Act of 1974, as amended, particularly section 1424(e); 40 CFR Part 149	Yes No	There are no EPA Sole Source Aquifers in Puerto Rico. The project is in compliance with Sole Source aquifers without further evaluation. See attached Sole Source Aquifers maps, Figure 11.
Wetlands Protection Executive Order 11990, particularly sections 2 and 5	Yes No	There are no wetlands in or near the proposed project area, therefore, no wetland will be affected by the project undertaking. The project is in compliance with Executive Order 11990. See the attached Wetlands map, Figure 12.
Wild and Scenic Rivers Wild and Scenic Rivers Act of 1968, particularly section 7(b) and (c)	Yes No	This project is not within proximity of the NWSRS river. The project is located 291,610 feet from the nearest Wild and Scenic River. The project is in compliance

		with the Wild and Scenic Rivers Act. See Map, Figure 13.
ENVIRONMENTAL JUSTICE		
Environmental Justice Executive Order 12898	Yes No	Based on the scope of work for this project, there will be no additional impact on low-income or minority residents. This proposed activity will not have a negative impact on Environmental Justice. Therefore, the proposed activity complies with this section.

**Environmental Assessment Factors** [24 CFR 58.40; Ref. 40 CFR 1508.8 & 1508.27] Recorded below is the qualitative and quantitative significance of the effects of the proposal on the character, features and resources of the project area. Each factor has been evaluated and documented as appropriate and in proportion to its relevance to the proposed action. Verifiable source documentation has been provided and described in support of each determination, as appropriate. Credible, traceable and supportive source documentations have been provided. Where applicable, the necessary reviews or consultations have been completed and applicable permits of approvals have been obtained or noted. Citations, dates/names/titles of contacts, and page references are clear. Additional documentation is attached, as appropriate. **All conditions, attenuation or mitigation measures have been clearly identified.** 

**Impact Codes**: Use an impact code from the following list to make the determination of impact for each factor.

- (1) Minor beneficial impact
- (2) No impact anticipated
- (3) Minor Adverse Impact May require mitigation

(4) Significant or potentially significant impact requiring avoidance or modification which may require an Environmental Impact Statement.

Environmental	Impact	
Assessment Factor	Code	Impact Evaluation
LAND DEVELOPM	ENT	
Conformance with Plans / Compatible Land Use and	2	This project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment

Zoning / Scale and Urban Design		and is continued agricultural use of property which is compatible with a zoning code of A-I (Intermediate Agricultural) and existing land use of SREP-AH (Rustic Land Specially Protected - Agricultural and Water). There is no urban design associated with this rural, agricultural site.
Soil Suitability/ Slope/ Erosion/ Drainage/ Storm Water Runoff		This project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment. The soil is currently being used for agriculture purposes. There is no change in land use since the land will continue to be used to agriculture purposes. The soil in this area has been classified as Consumo clay, 40 to 60 percent slopes (CuF). This is a very steep, well-drained soil on side slopes of maturely dissected humid uplands.
	2	The landslide data indicates moderate to very high landslide susceptibility; however, no erosion is expected to occur from this project, since the terrain of the place where the warehouse will be installed is relatively flat. The project will not affect the drainage in the area. Soil suitability will be assessed prior to construction. Contractors will be required to use BMPs during construction if erosion impacts occur. The construction manager should investigate if a DNER authorization is required for any land alteration associated with the proposed project activities. There will be no additional runoff associated with the project. See Landslide Susceptibility Map, Figure 14.
Hazards and Nuisances including Site Safety and Noise	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment. There are no specific environmental hazards that have been identified for this site. The site is not in a high Noise Level area. While construction is underway, there will be a temporary rise in noise levels. Contractors will be required to comply with the applicable local noise ordinances. Noise impacts will be mitigated by restricting construction activities to daylight hours. Additionally, the project does not include housing or such to where inhabitants would be affected.

Energy Consumption	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment on an existing agricultural farm. The power needed to operate the coffee toaster and coffee grinder will be provided by an inverter, no transfer switch will be necessary. A LUMA/PREPA connection will not be necessary for the proposed project. The proposed project will have no impact on the energy consumption.
Environmental Assessment Factor	Impact Code	Impact Evaluation
SOCIOECONOMI	С	·
Employment and Income Patterns	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment and will result in short-term benefit to employment when contractors are hired for the construction and installation of these items. After construction, there may be a net positive benefit for the farm, a small business receiving this funding for economic development recovery purposes, which will aid in the continued operations of the intended use of the farm which products will be used by Puerto Rico population. The project is not anticipated to have a significant impact on Employment and Income Patterns, however, the project may help restore employment opportunities and income patterns.
Demographic Character Changes, Displacement	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment and will not alter the demographic characteristics of Ponce, PR. The applicant is already located at this location and the project will provide opportunities for the continuous agricultural growth of the business.
Environmental Justice	2	<ul> <li>In the project area within a one-mile radius:</li> <li>The people of color are 100% compared to PR average of 96%.</li> <li>88 % of the people are low income compared to PR average of 70%.</li> </ul>

• 15% of the people are unemployed compared to PR average of 15%.
The proposed activities of the installation of the storage warehouse will have a positive impact on creating jobs for local people. Therefore, the proposed activity complies with this section. See EJScreen Report in Appendix 3.

Environmental Assessment Factor	Impact Code	Impact Evaluation
COMMUNITY FAC	CILITIES AI	ND SERVICES
Educational and Cultural Facilities	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment for an agricultural site and will have no impact on educational and cultural facilities.
Commercial Facilities	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment and may aid in restoring the demand for local commercial services by selling their agricultural products directly to local markets, restaurants, or consumers increases demand for local commercial services, such as transportation, packaging, and marketing; however, not to the point of putting undue pressure on commercial facilities.
Health Care and Social Services	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment for an agricultural site and will have no impact on Health Care and Social Services.
Solid Waste Disposal / Recycling	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment and will have no impact on Solid Waste Disposal / Recycling services. The products and by-products are agricultural, and any waste would be biodegradable.

		The remaining construction solid waste materials would be collected for transport to the local landfill.
Wastewater / Sanitary Sewers	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment and this activity will not produce any wastewater. Based on the scope of work is not expected to result in any changes in wastewater or sanitary sewer generation. The proposed project will have no impact on Wastewater / Sanitary Sewers.
Water Supply	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment. For the operation of the warehouse and the coffee machines, a water connection will not be necessary. The proposed project will have no impact on the water supply.
Public Safety - Police, Fire and Emergency Medical	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment for an agricultural site and will have no impact on Public Safety.
Parks, Open Space and Recreation	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment and will have no impact on Parks, Open Space and Recreation. The property being used is agricultural and it will continue as agricultural use.
Transportation and Accessibility	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment for an agricultural site and will have no impact on transportation and accessibility.

Environmental Assessment Factor	Impact Code	Impact Evaluation
NATURAL FEATURES		

Unique Natural Features, Water Resources	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment and will be situated on previous agriculture property and will have no impact on unique natural features or water resources. There are no water resources within the parcel. This means that the project's activities are isolated from any existing water bodies, further reducing the likelihood of impact. In addition, the project does not involve extracting water from any existing water sources such as rivers, lakes, or groundwater. Therefore, the project will have no impact on water resources.
Vegetation, Wildlife	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment and will occur on land previously used for agricultural purposes and will continue in that capacity. There may be wildlife attracted to the storage but no negative impact on wildlife. The project involves minimal vegetation removal, primarily limited to grass, and does not entail the cutting off trees on the project site. This aspect further contributes to the preservation of the existing ecosystem and minimizes disturbance to the natural surroundings.
Climate Change	2	The project consists of the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment. The Re-Grow Program proposed project aims to increase resiliency in the agricultural industry to prepare for future climate related disasters. The project will not contribute to climate change and will provide a minor net benefit by allowing for increased food production. In terms of the project's susceptibility to climate change, the agricultural components may encounter challenges due to the potential impact of drought conditions. This is a small agricultural project with no measurable impact on climate change factors.

Additional Studies Performed: Not applicable.

Field Inspection (Date and completed by): February 19, 2024, Jaqueline Lopez, SOI-Qualified Archaeologist.

#### List of Sources, Agencies and Persons Consulted [40 CFR 1508.9(b)]:

FAA, National Plan for Integrated Airport Systems: <u>www.faa.gov/airports/planning\_capacity/npias/reports/NPIAS-Report-2017-2021-</u> Appendix-B-Part6.pdf

John H. Chafee Coastal Barrier Resources System, Puerto Rico map. www.fws.gov/CBRA/Maps/Locator/PR.pdf

National Park Service, National Registry of Natural Landmarks. www.nature.nps.gov/nnl/docs/NNLRegistry.pdf

US Fish and Wildlife Service, Wild and Scenic Rivers – correspondence to Agency on October 16, 2018

National Wild and Scenic Rivers System: <u>www.rivers.gov/puerto-rico.php</u>

Puerto Rico Community Development Block Grant Disaster Recovery Action Plan, July 2018. <u>www.cdbg-dr.pr.gov/en/action-plan/</u>

Programmatic Agreement among the Federal Emergency Management Agency, the Puerto Rico State Historic Preservation Office and the Central Office for Recovery, Reconstruction and Resilience – amended to include the Puerto Rico Department of Housing.

Sierra Research for Office of Mobile Sources. US Environmental Protection Agency. Report No. SR93-03-02, Evaluation of Methodologies to Estimate Nonroad Mobile Source Usage, March 19, 1993: <u>http://nepis.epa.gov/Exe/ZyPURL.cgi?Dockey=9100UR51.txt</u>

US Environmental Protection Agency, National Ambient Air Quality Standards, Nonattainment Areas for Criteria Pollutants (Green Book): www3.epa.gov/airquality/greenbook/anayo\_pr.html

US EPA, Environmental Topics, Air Topics: <u>www.epa.gov/environmental-topics/air-topics</u>

US Fish and Wildlife Service, Environmental Conservation Online System: <u>https://ecos.fws.gov/ecp0/reports/species-listed-by-state-report?state=PR&status=listed</u>

Federal Emergency Management Agency, Flood Mapping Service: <u>https://msc.fema.gov/portal/home (compilation of numerous maps)</u>

Puerto Rico Planning Board, Communication regarding Floodplain Management, November 29, 2018.

US Fish and Wildlife Service, National Wetlands Inventory: www.fws.gov/wetlands/data/mapper.html (compilation of numerous maps) US Army Corps of Engineers, Jacksonville District, Antilles Section, Communication regarding Wetlands Management, November 13, 2018.

Puerto Rico Coastal Zone Management Program Plan, September 2009.

Puerto Rico Planning Board, Communication regarding Coastal Zone Management, November 16, 2018 (No response).

US EPA, Sole Source Aquifers. Esri HERE, Garmin, NOAA, USGS, EPA.

US Fish and Wildlife Service, Caribbean Ecological Services Field Office. E-mail communication regarding October 23, 2018 letter on Threatened and Endangered Species and Critical Habitats.

NOAA Fisheries / National Marine Fisheries Service, NEPA Coordinator Southeast Regional Office. Communication on October 16, 2018 regarding designated critical habitat. (No response).

US Geological Survey, Data Release of May Showing Concentration of Landslides Caused by Hurricane Maria, <u>https://doi:10.5066/F7JD4VRF</u>

### List of Permits Obtained: None.

**Public Outreach** [24 CFR 58.43]: The recovery process has seen significant proactive involvement from the local community. Puerto Rico Department of Agriculture has worked closely with the agricultural community. This project will include a FONSI/NOI-RROF in compliance with NEPA regulations for HUD.

**Cumulative Impact Analysis** [24 CFR 58.32]: In accordance with 24 CFR 58.32 (Aggregation), there are no cumulative impacts associated with the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment for an agricultural site. The activities involved, such as storage warehouse installation, equipment setup, and infrastructure additions, are discrete and confined to the immediate project area. They do not extend beyond the boundaries of the site, minimizing the potential for cumulative effects on surrounding environments. The project's location on an existing agricultural site suggests that the area may have already undergone land use changes and modifications.

### Alternatives [24 CFR 58.40(e); 40 CFR 1508.9]

The Regrow Program purpose is to enhance and expand agricultural production related to economic revitalization and sustainable development activities while promoting and increasing food security island wide. The "Alternative" action would mean that the applicant would consider other locations for the new storage warehouse. However, other locations may result in tree clearing prior to construction and/or need to fill in some steep area and an added cost to the applicant. Any option that requires going off-site would not contribute to the improvement and growth of agricultural production or enable economic development for this applicant.

#### No Action Alternative [24 CFR 58.40(e)]:

The 'No-Action' alternative would mean that the applicant would not receive federal funding to provide the installation of a 12' x 12' storage warehouse and the purchase of a coffee grinder, coffee roasting machine and farm equipment for an agricultural site which would inhibit the economic growth opportunity that the applicant would not otherwise have under the PRDOH Re-Grow Puerto Rico program. As a result, these owners may not be able to experience the growth needed to recover and expand their agriculture activities. A provision of the grant allows for economic development for this applicant.

**Summary of Findings and Conclusions:** The proposed activity has been found to not have any adverse effects on the environmental nor is there the requirement for further consultation with any agency. There are no environmental review topics addressed that result in the need for formal compliance steps or the requirement for mitigation.

# Mitigation Measures and Conditions [40 CFR 1505.2(c)]

Summarize below all mitigation measures adopted by the Responsible Entity to reduce, avoid, or eliminate adverse environmental impacts and to avoid non-compliance or non-conformance with the above-listed authorities and factors. These measures/conditions must be incorporated into project contracts, development agreements, and other relevant documents. The staff responsible for implementing and monitoring mitigation measures should be clearly identified in the mitigation plan.

Law, Authority, or Factor	Mitigation Measure
Soil Suitability/ Slope/ Erosion/ Drainage/ Storm Water Runoff	Soil suitability will be assessed prior to construction. Contractors will be required to use BMPs during construction if erosion impacts occur. The construction manager should investigate if a DNER authorization is

	required for any land alteration associated with the proposed project activities.
<b>Endangered Species</b> Endangered Species Act of 1973, particularly section 7; 50 CFR Part 402	The USFWS has developed the following conservation measures for the Boa:
particularly section 7; 50 CFR Part 402	<ol> <li>Inform all project personnel about the potential presence of the PR boa in areas where the proposed work will be conducted. A pre-construction meeting should be conducted to inform all project personnel about the need to avoid harming the species as well as penalties for harassing or harming PR boas. An educational poster or sign with photo or illustration of the species should be displayed at the project site.</li> <li>Prior to any construction activity, including removal of vegetation and earth movements, the boundaries of the project and areas to be excluded and protected should be clearly marked in the project plan and in the field in order to avoid further habitat degradation into forested and conservation areas.</li> <li>Once areas are clearly marked, and prior to the use of heavy machinery and any construction activity (including removal of vegetation and earth movement), a biologist or project personnel with experience on this species should survey the areas to be cleared to verify the presence of any PR boa within the work area.</li> <li>If a PR boa is found within any of the working or construction areas, activities should stop at that area and information recorded (see #5). Do not capture the boa. If boas need to be moved out of harm's way, designated personnel shall immediately contact the Puerto Rico Department of Natural and Environmental Resources (PRDNER) Rangers for safe capture and relocation of the animal (PRDNER phone #s: (787) 724-5700, (787) 230-5550, (787) 771-1124). If immediately relocation is not an option, project-related</li> </ol>

activition at that area must stan until the
activities at that area must stop until the boa moves out of harm's way on its own.
,
Activities at other work sites, where no boas
have been found after surveying the area,
may continue.
5. For all boa sightings (dead or alive),
record the time and date of the sighting
and the specific location where it was
found. PR boa data should also include a
photo of the animal (dead or alive), site
GPS coordinates, the time and date, and
comments on how the animal was
detected and its behavior. Last Revised:
January 2024
6. If a PR boa is captured by PRDNER
personnel, record the name of that person
and information on where the PR boa will
be taken. This information should be reported to the Service.
7. Measures should be taken to avoid and
minimize PR boa casualties by heavy
machinery or motor vehicles being used on
site. Any heavy machinery left on site (staging) or near potential PR boa habitat
(within 50 meters of potential boa habitat), needs to be thoroughly inspected each
morning before work starts to ensure that no boas have sheltered within engine
compartments or other areas of the
equipment. If PR boas are found within
vehicles or equipment, do not capture the
animal, and let it move on its own or call
PRDNER Rangers for safe capture and
relocation of the animal (see #4). If not
possible, the animal should be left alone
until it leaves the vehicle on its own.
8. PR boas may seek shelter in debris piles.
Measures should be taken to avoid and
minimize boa casualties associated with
sheltering in debris piles as a result of
project activities. Debris piles should be
placed far away from forested areas. Prior
to moving, disposing or shredding, debris
piles should be carefully inspected for the
presence of boas. If debris piles are left on
site, we recommend they be placed in

areas that will not be disturbed in the future. 9. If a dead PR boa is found, immediately cease all work in that area and record the information accordingly (see #5). If the PR boa was accidentally killed as part of the project actions, please include information on what conservation measures had been implemented and what actions will be taken to avoid further killings. A dead boa report should be sent by email (see contacts below) to the Service within 48 hours of the event. 10. Projects must comply with all state laws and regulations. Please contact the PRDNER for further guidance.
The USFWS has developed the following conservation measures for the harlequin butterfly: 1. All project construction personnel must be informed about the potential presence of the PR harlequin butterfly or its occupied host plant, prickly bush ( <i>Oplonia spinosa</i> ), in the project areas and the need to avoid harming the species and its occupied host plant. All personnel will be advised that there are civil and criminal penalties for harming, harassing, or killing species protected under the Endangered Species Act. Educational material (e.g., posters, flyers, or signs with photos or illustrations of all the life stages of the PR harlequin butterfly (i.e., eggs, caterpillar, chrysalis, and adult) as well as its host plant, should be prepared and available to all personnel for reference. 2. Before starting any project activity, including removal of vegetation and earth movement, the boundaries of the work area in the field clearly delineate to avoid unnecessary habitat impacts. Once the project areas are clearly marked, and before any work activity, including site preparation, personnel with knowledge and ability to identify the PR harlequin butterfly (all life stages) and the prickly bush

must survey the areas where the work will be performed for the presence of the species and its host plant.
It is important to note that the PR harlequin butterfly can be observed year-round in all
its life stages; thus, oviposition (egg-laying) may occur at any time during the year.
3. If the prickly bush is present on the project site, try to avoid cutting it off, even
if no eggs, caterpillars, or chrysalis are
present. 4. If there is no prickly bush within the
project area, and the butterfly is observed flying within the project area, do not harass,
harm, pursue, wound, kill, trap, capture, collect, or attempt to engage in any such
conduct, the species.
5. Adult butterflies are often observed flying near the host plant as part of their mating
behavior and laying eggs. Project-related activities must stop if the prickle bush is
found in the project area and the PR
harlequin butterfly is observed flying in that same area where the plan is located. A
temporary 50-meter (164 feet) buffer zone of no activity or human disturbance should
be established and clearly marked around
that prickly bush until the butterfly moves out on its own.
6. Once the PR harlequin butterfly has moved away, within a period of 24 to 36
hours, a search of the prickly bush that has been buffered should be conducted to
determine the presence of eggs,
caterpillars, or chrysalids of the butterfly on the plant. The contractor or the Applicant
should send a report of the observation and its findings to
caribbean_es@fws.gov after the 36-hour search is concluded.
7. If, after the initial search or after the 24 to
36-hour search, any life stage of the PR harlequin butterfly is found in the prickly
<ul> <li>bush, take the following actions:</li> <li>Clearly mark the host plant with</li> </ul>
<ul> <li>Cleany mark me nost plant with flagging tape</li> </ul>

Hazards and Nuisances including Site	<ul> <li>Establish a 10-meter (32-foot) buffer zone around the bush to protect it.</li> <li>Eggs are typically found on the prickly bush's newly grown, tender branches. Once an egg hatches, the caterpillar moves and feeds throughout the plant. Therefore, avoid cutting off the prickly bush within the project site even if no eggs, caterpillars, or chrysalids are present.</li> <li>Work within the 10-meter buffered area may resume when no signs of any live life stage of the butterfly are detected, which usually takes approximately 60 to 120 days.</li> <li>For all PR harlequin butterfly sightings (all life stages), the time and date of the butterfly was found must be recorded. Data should also include a photo of the butterfly (if possible) and the habitat where it was observed, site GPS coordinates, and comments on how the butterfly was detected and its behavior. All PR harlequin butterfly sighting reports should be sent to the U.S. Fish and Wildlife Service, Caribbean Ecological Service Field Office at caribbean_es@fws.gov.</li> <li>For questions regarding the PR harlequin butterfly, the Point of Contact is:         <ul> <li>José Cruz-Burgos, Threatened and Endangered Species Program Coordinator:                 <ul> <li>Mobile: 305-304-1386</li> <li>Office phone: 786-244-0081</li> <li>Office Direct Line: 939-320-3120</li></ul></li></ul></li></ul>
Safety and Noise	be a temporary rise in noise levels. Contractors will be required to comply with the applicable local noise ordinances. Noise impacts will be mitigated by restricting construction activities to daylight hours.

#### Determination:

Finding of No Significant Impact [24 CFR 58.40(g)(1); 40 CFR 1508.27]	l
---	---

The project will not result in a significant impact on the quality of the human environment.

**Finding of Significant Impact** [24 CFR 58.40(g)(2); 40 CFR 1508.27]

The project may significantly affect the quality of the human environment.

Preparer Signature: \_\_\_\_\_\_Date: \_\_10/10/2024\_\_\_\_

Name/Title/Organization: <u>Patricia Carmenatty / Environmental Specialist/ Behar Ybarra</u> <u>& Associates LLC</u>

Certifying Officer Signature:

ANC. Date: 10/16/204

Name/Title: Abdul X. Feliciano Plaza, Permits and Environmental Specialist

This original, signed document and related supporting material must be retained on file by the Responsible Entity in an Environmental Review Record (ERR) for the activity/project (ref: 24 CFR Part 58.38) and in accordance with recordkeeping requirements for the HUD program(s).



Environmental Assessment Determinations and Compliance Findings for HUD-assisted Projects24 CFR Part 58


**Figures** 



554, Altamira, San Juan, P.R. 00920 Tel.(787)783-0290

# Figure 1:Location Aerial Map Puerto Rico Department of Housing ReGrow

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.6171013




# Legend:

Storage Warehouse

Parcel-00518





Earthstar Geographics, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors and Google Earth

1:5,000

#### Source


Centro de Recaudación de Ingresos Municipales (CRIM) https://catastro.crimpr.net/cdprpc/

BEHAR-YBARRA & ASSOCIATES LLC CONSULTING ENGINEERS, ARCHITECTS AND PLANNERS

554. Altamira, San Juan, P.R. 00920 Tel.(787)783-0290 Suite J-3 Calle P

# Figure 2: Airports Puerto Rico Department of Housing ReGrow

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.6171013




#### Legend:



**Civil Runaway** 

#### Accident Potential Zone






Service Layer Credits: Sources: Esri, HERE, DeLorme, USGS, Intermap, increment P Corp., NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand), MapmyIndia, © OpenStreetMap contributors, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors

#### Source

Federal Aviation Administration (FAA) https://adds-faa.opendata.arcgis.com/



### Application ID: PR-RGRW-00518 Application ID: PR-RGRW-00518 Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Puerto Rico Department of Housing ReGrow



#### Legend:




PR-RGRW-00518

# **Coastal Barrier Resources System (CBRS)**

Otherwise Protected Area

System Unit



Service Layer Credits: Sources: Esri, HERE, DeLorme, USGS, Intermap, increment P Corp., NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand), MapmyIndia, @ OpenStreetMap contributors, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors

#### Source

U.S. Fish and Wildlife Service (FWS) https://www.fws.gov/program/coastal-barrier-resources-act



1:150,000






o 554. Altamira, San Juan, P.R. 00920 Tel.(787)783-0290 Suite J-3. Calle Pe

# Figure 4: Flood Insurance Rate Map Puerto Rico Department of Housing ReGrow

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013



#### Legend:



PR-RGRW-00518

Area of Minimal Flood Hazard Zone X

**FIRM Panel** 



Service Layer Credits: Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors



1:10,000

Federal Emergency Management Agency (FEMA) https://msc.fema.gov/portal/home


Source

BEHAR-YBARRA & ASSOCIATES LLC CONSULTING ENGINEERS, ARCHITECTS AND PLANNERS

Altamira, San Juan, P.R. 00920 Tel.(787)783-0290 Suite J.S. Calle F

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013


# Figure 5: Coastal Zone Management Puerto Rico Department of Housing ReGrow



#### Legend:

PR-RGRW-00518

Coastal Zone Management Act Boundary



Service Layer Credits: Sources: Esri, HERE, DeLorme, USGS, Intermap, increment P Corp., NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand), MapmyIndia, © OpenStreetMap contributors, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors

#### Source

NOAA Office for Coastal Management (NOAA/OCM) https://www.fisheries.noaa.gov/inport/item/53132






554. Altamira, San Juan, P.R. 00920 Tel.(787)783-0290

# Figure 6: Toxic and Hazardous Facilities Puerto Rico Department of Housing ReGrow

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013




#### Legend:

- PR-RGRW-00518
- ICIS
- NCDB
- NP DES
- FACILITY INTERESTS
- NPDES MAJOR

3,000 Ft. Buffer

- RCRA
- RCRA ACTIVE
- RCRA INACTIVE
- RCRA LQG




Service Layer Credits: Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors

### Source

EPA Facility Registry Service (FRS) https://www.epa.gov/frs



1:12,000



#### Legend:

PR-RGRW-00518

Critical Habitat

BEHAR-YBARRA & ASSOCIATES LLC



Service Layer Credits: Sources: Esri, HERE, DeLorme, USGS, Intermap, increment P Corp., NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand), MapmyIndia, © OpenStreetMap contributors, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors

#### Source

NOAA Office of Response and Restoration https://response.restoration.noaa.gov/



Application ID: PR-RGRW-00518

BEHAR-YBARRA & ASSOCIATES LLC CONSULTING ENGINEERS, ARCHITECTS AND PLANNERS

o 554. Altamira, San Juan, P.R. 00920 Tel.(787)783-0290 1 Suite J-3. Calle Perse

# Figure 8: Farmland Protection Puerto Rico Department of Housing ReGrow

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013



### Legend:



PR-RGRW-00518

#### **Farm Class**

Farmland of statewide importance

Not prime farmland



Service Layer Credits: Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors




1:5,000 National Resources Conservations Service (NRCS) Gridded Soil Survey Geographic Database (gSSURGO) https://data.nal.usda.gov/dataset/soil-survey-geographic-database-ssurgo




554. Altamira, San Juan, P.R. 00920 Tel.(787)783-0290 Suite J-3 Calle Pr

# Figure 9: Advisory Base Flood Elevation Puerto Rico Department of Housing ReGrow


Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013



#### Legend:







Geographics, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors

#### Source

Federal Emergency Management Agency (FEMA), Junta de Planificacion de Puerto Rico (JP), Mapas de Niveles de Inundacion Base Recomendados, https://maps.jp.pr.gov/



1:5,000



Altamira, San Juan, P.R. 00920 Tel.(787)783-0290

# Figure 10: Historic Preservation Map Puerto Rico Department of Housing ReGrow

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013



#### Legend:

PR-RGRW-00518


Archaeological Resource Zones

Traditional Urban Center

**Historic Communities** 



- Cultural Resourses Registry ICP
- Cultural\_Resourses Historic Places JP
- Cultural\_Resourses Scenic Places
- Cultural\_Resourses - Cultural Value Places
  - Cultural\_Resourses Railway Vestiges



Service Layer Credits: Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors

#### Source

1:5,000 National Park Service (NPS) - National Register of Historic Places(NRHP) https://www.nps.gov/subjects/nationalregister/index.htm State Historic Preservation Office (SHPO) https://oech.pr.gov/Pages/default.aspx



Cond. Iberia 1 Suite J-3, Calle Perseo 554, Altamira, San Juan, P.R. 00920 Tel.(787)783-0290

## Figure 11: EPA Sole Source Aquifers Puerto Rico Department of Housing ReGrow

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013




## Legend:



PR-RGRW-00518

EPA Sole Source Aquifers



Source

Service Layer Credits: Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors




U.S. Environmental Protection Agency https://epa.maps.arcgis.com/apps/webappviewer/index.html ?id=9ebb047ba3ec41ada1877155fe31356b

BYA BEHAR-YBARRA & ASSOCIATES LLC CONSULTING ENGINEERS, ARCHITECTS AND PLANNERS

Cond. Iberia 1 Suite J-3, Calle Perseo 554, Altamira, San Juan, P.R. 00920 Tel.(787)783-0290

## Figure 12: Wetlands Map Puerto Rico Department of Housing ReGrow

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013




## Legend:



## National Wetlands Inventory

Riverine



1:5,000

Service Layer Credits: Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors

#### Source


U.S. Fish and Wildlife Service - National Weatlands Inventory https://www.fws.gov/program/national-wetlands-inventory

BEHAR-YBARRA & ASSOCIATES LLC CONSULTING ENGINEERS, ARCHITECTS AND PLANNERS

554. Altamira, San Juan, P.R. 00920 Tel.(787)783-029 Suite J-3. Calle Po

# Figure 13: Wild and Scenic Rivers Puerto Rico Department of Housing ReGrow


Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013



## Legend:

PR-RGRW-00518

Wild and Scenic Rivers



Service Layer Credits: Sources: Esri, HERE, DeLorme, USGS, Intermap, increment P Corp., NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand), MapmyIndia, © OpenStreetMap contributors, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors

#### Source

FWS National Wild and Scenic Rivers System https://www.rivers.gov/mapping-gis.php







Altamira, San Juan, P.R. 00920 Tel.(787)783-0290 Suite J-3 Calle


# Figure 14: Landslide Susceptibility Puerto Rico Department of Housing ReGrow

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013



## Legend:





Service Layer Credits: Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors

Source

1:5,000

U.S. Geological Survey (USGS) https://pubs.er.usgs.gov/publication/ofr20201022



Environmental Assessment Determinations and Compliance Findings for HUD-assisted Projects24 CFR Part 58

## Appendix 1



GOVERNMENT OF PUERTO RICO STATE HISTORIC PRESERVATION OFFICE Executive Director | Carlos A. Rubio Cancela | carubio@prshpo.pr.gov

Thursday, March 14, 2024

## Lauren B Poche

269 Avenida Ponce de Leon, San Juan, PR, 00917

SHPO-CF-03-13-24-01 PR-RGRW-00518 (Ponce), Ángeles Rodríguez

March 13, 2024

Lauren Bair PocheHORNE 10000 Perkins Rowe, Suite 610, Bldg GBaton Rouge, LA 70810

SHPO CF-03-13-24-01 SECTION 106 NHPA EFFECT DETERMINATION SUBMITTAL: PR-RGRW-00518 ÁNGELES RODRÍGUEZ SEPÚLVEDA – CARR. 505, BARRIO MONTE LLANO, SECTOR SETO 2, PONCE, PUERTO RICO

Dear Ms. Poche,

Our Office has received and reviewed the above referenced project in accordance with 54 U.S.C. 306108 (commonly known as Section 106 of the National Historic Preservation Act) and 36 CFR Part 800: Protection of Historic Properties. Our records support your finding of no historic properties affected for this undertaking.Please note that should you discover other historic properties at any point during project implementation, you should notify the SHPO immediately. If you have any questions regarding our comments, please do not hesitate to contact our Office.

Sincerely,

Carlos A. Rubio-CancelaState Historic Preservation Officer

CARC/GMO/MB



OFICINA ESTATAL DE CONSERVACIÓN HISTÓRICA OFICINA DEL GOBERNADOR

STATE HISTORIC PRESERVATION OFFICE OFFICE OF THE GOVERNOR

Cuartel de Ballajá (Tercer Piso), Calle Norzagaray, Esq. Beneficencia, Viejo San Juan, PR 00901 | PO Box 9023935, San Juan, PR 00902-3935



Sincerly,

mby apartir

Carlos A. Rubio Cancela State Historic Preservation Officer CARC/GMO/ MB



March 13, 2024

Carlos A. Rubio Cancela State Historic Preservation Officer Puerto Rico State Historic Preservation Office Cuartel de Ballajá (Tercer Piso) San Juan, PR 00902-3935

Puerto Rico Disaster Recovery, CDBG-DR Re-Grow PR Urban-Rural Agricultural (Re-Grow PR) Program

Section 106 NHPA Effect Determination Submittal: PR-RGRW-00518 – Ángeles Rodríguez Sepúlveda -Carr. 505, Barrio Monte Llano, Sector Seto 2, Ponce, Puerto Rico – No Historic Properties Affected

Dear Architect Rubio Cancela,

In accordance with Section 106 of the National Historic Preservation Act and its implementing regulations, 36 CFR Part 800, HORNE is providing information for your review and requesting your concurrence regarding the above-referenced projects on behalf of the Puerto Rico Department of Housing (PRDOH) and the Home Repair, Reconstruction, or Relocation (R3) Program. On February 9, 2018, an allocation of Community Development Block Grant - Disaster Recovery (CDBG-DR) funds were approved by the United States Department of Housing and Urban Development (HUD) under the Federal Register Volume 83, No. 28, 83 FR 5844, to assist the Commonwealth of Puerto Rico in meeting unmet needs in the wake of Hurricanes Irma and Maria. On August 14, 2018, an additional \$8.22 billion recovery allocation was allocated to Puerto Rico under the Federal Register Volume 83, No. 157, 83 FR 40314. With these funding allocations, the Puerto Rico Department of Housing (Housing) aims to lead a comprehensive and transparent recovery for the benefit of Puerto Rico residents.

On behalf of PRDOH and the subrecipient, the Puerto Rico Department of Agriculture, we are submitting documentation for activities proposed by Ángeles Rodríguez Sepúlveda at Carr. 505 Barrio Monte Llano, Sector Seto 2 in the municipality of Ponce. The undertaking for this project includes the installation of a 12' x 12' storage warehouse. The installation of the storage warehouse will require ground disturbance. The storage warehouse will be installed on a new concrete slab measuring 12' x 12' which will be provided by the applicant. The purpose of storage is to store the new equipment for the farm. No water connection will be necessary for the new warehouse. There will be no water or electricity connections, the power needed will be provided by an inverter.

Based on the submitted documentation, the Program requests a concurrence that a determination of No Historic Properties Affected is appropriate for this proposed project.



Please contact me by email at <u>lauren.poche@horne.com</u> or phone at 225-405-7676 with any questions or concerns.

Kindest regards,

Jauan B. Pocke

Lauren Bair Poche, M.A. Architectural Historian, EHP Senior Manager LBP/JLE

Attachments



Applicant: Ángeles Rodríguez Sepúlveda

Case ID: PR-RGRW-00518

City: Ponce

Project Location: Carr. 505 Barrio Monte Llano, Sector Seto 2, Ponce, PR 00717				
Project Coordinates: 18.114682 - 66.6171013				
<b>TPID</b> (Número de Catastro): 317-000-001-31-002				
Type of Undertaking:				
Substantial Repair/Improvements				
⊠ New Construction				
Construction Date (AH est.): n/a	Property Size (acres): 8.10			

SOI-Qualified Archaeologist: Jaqueline López Meléndez	
Date Reviewed: February 19, 2024	

In compliance with Section 106 of the National Historic Preservation Act (NHPA), the Program is responsible for identifying historic properties listed in the NRHP and any properties not listed that would be considered eligible for listing that are located within the geographic area of potential effects (APE) of the proposed project and assessing the potential effects of its undertakings on these historic properties.

## Project Description (Undertaking)

The proposed activities for PR-RGRW-00518 consist of installation of a 12' x 12' storage warehouse. The installation of the storage warehouse will require ground disturbance. The storage warehouse will be installed on a concrete slab measuring 12' x 12' which will be provided by the applicant. The purpose of storage is to store the new equipment for the farm. No water connection will be necessary for the new warehouse. There will be no water or electricity connections, the power needed will be provided by an inverter. The project area is located at PR-505 Barrio Monte Llano, Sector El Seto 2, within the Municipality of Ponce. Based on a review of historical aerial imagery, the general area has been used for agricultural purposes for the past 20 years.

## Area of Potential Effects

As defined in 36 CFR §800.16(d), the area of potential effects (APE) is the geographic area or areas within which an undertaking may directly or indirectly cause changes in the character or use of historic properties if any such properties exist. Based on this definition and the nature and scope of the Undertaking, the Program has determined that the direct APE for this project is the location of the storage warehouse plus a 15-meter buffer and the visual APE is the viewshed of the proposed project.

## Identification of Historic Properties - Archaeology

Existing information on previously identified historic properties has been reviewed to determine if any such properties are located within the APE of this undertaking. The review of this existing information by a Program contracted Historic Preservation Specialist meeting

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DR PROGRAM	
ReGrow Puerto Rico Program	GOVERNMENT OF PUERTO RICO
Section 106 NHPA Effect Determination	
Applicant: Ángeles Rodríguez Sepúlveda	
Case ID: PR-RGRW-00518	City: Ponce

the Secretary of the Interior's Professional Qualification Standards (36 CFR Part 61), shows that there are no reported archaeological sites within a half-mile (0.50 miles) radius of the project location. The nearest cultural resource is the Pre-Columbian site Petroglifo de Maragüez (SHPO: PO0100067), located 0.72 miles northeast. The proposed project is located in the mountainous area of Ponce at an elevation of 1,870 feet above sea level. Per the USGS/NRCS Web Soil Survey, the project area is within mapped soil series: Consumo. The project area APE is in CuF. The closest freshwater sources are an unnamed creek located 0.33 miles northwest and another unnamed creek, located 0.32 miles southwest of the project area. The south coast is approximately 9.11 miles (14.66 km) from the project area.

There are no cultural resource studies within a half-mile radius of the property.

The soil in this area has been classified as Consumo clay, 40 to 60 percent slopes (CuF). This is a very steep, well-drained soil on side slopes of maturely dissected humid uplands. Permeability and the available water capacity are moderate. Runoff is very rapid, and erosion is a hazard. Natural fertility is medium.

Visual inspection of the APE and its surroundings found no evidence of cultural materials.

## Determination

No historic properties were identified within the APE.

Based on the results of our historic property identification efforts, the Program has determined that project actions will not affect historic properties that compose the Ar Potential Effect. The project area is not within or adjacent to the boundaries of a National Register of Historic Places (NRHP)-eligible or listed historic district or Traditional Urban Center. There are no reported archaeological materials or significant cultural properties within a half-mile radius of the proposed project location. There are no known archaeological sites or NRHP listed/eligible historic properties are within or adjacent to the property or the parcel in which the Area of Potential Effect of case PR-RGRW-00518 is located. The closest freshwater body is approximately 0.32 miles southwest of the project area. The construction of public roads and residential structures/agricultural infrastructure has minimally disturbed the surrounding terrain. Therefore, no historic properties will be affected by the proposed project activities.

 PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DR PROGRAM

 REGROW PUERTO RICO PROGRAM

 Section 106 NHPA Effect Determination

 Applicant: Ángeles Rodríguez Sepúlveda

 Case ID: PR-RGRW-00518

 City: Ponce

## Recommendation (Please keep on same page as SHPO Staff Section)

The Puerto Rico Department of Housing requests that the Puerto Rico SHPO concur that the following determination is appropriate for the undertaking (Choose One):

 $\boxtimes$  No Historic Properties Affected

□ No Adverse Effect

Condition (if applicable):

□ Adverse Effect

Proposed Resolution (if appliable)

## This Section is to be Completed by SHPO Staff Only

The Puerto Rico State Historic Preservation Office has reviewed the above information and:

□ **Concurs** with the information provided.

Does not concur with the information provided.

Comments:

Carlos Rubio-Cancela	Date:
State Historic Preservation Officer	Dule.

PUERTO RICO 2017 DISASTER RECOVERY, CDBG-DR PROGRAM REGROW PUERTO RICO PROGRAM Section 106 NHPA Effect Determination	GOVERNMENT OF PUERTO RICO
Applicant: Ángeles Rodríguez Sepúlveda	
Case ID: PR-RGRW-00518	City: Ponce

Case ID: PR-RGRW-00518

Project Coordinates: 18.114425 -66.617139

# Table of archaeological sites, historic properties and historic districts located within the projectarea or within a 0.50-miles radius

Name	SHPO id #	IPRC id #	Distance/Direction	Description	NRHP (listed, eligible, non-eligible, no data)
None	-	-	-	-	-


# Table of cultural resources surveys conducted within the project area or within a 0.50-miles radius.

Author	Phase/Title	Year	SHPO / IPRC code	Results	Distance/ Direction	
None	-	-	-	-	-	



Applicant: Ángeles Rodríguez Sepúlveda


Case ID: PR-RGRW-00518





Applicant: Ángeles Rodríguez Sepúlveda


Case ID: PR-RGRW-00518





Applicant: Ángeles Rodríguez Sepúlveda


Case ID: PR-RGRW-00518





Applicant: Ángeles Rodríguez Sepúlveda


Case ID: PR-RGRW-00518





Applicant: Ángeles Rodríguez Sepúlveda


Case ID: PR-RGRW-00518





Applicant: Ángeles Rodríguez Sepúlveda


Case ID: PR-RGRW-00518





Applicant: Ángeles Rodríguez Sepúlveda

Case ID: PR-RGRW-00518





City: Ponce

Applicant: Ángeles Rodríguez Sepúlveda

Case ID: PR-RGRW-00518

Photo #:1	Description (include direction): Area where the storage warehouse will be installed, looking southeast.
Date: February 16, 2024	
Photo #:2	Description (include direction): Area where the storage warehouse will be installed, looking northwest.
Date: February 16, 2024	





October 20, 2022

## Arch. Carlos A. Rubio Cancela

Executive Director State Historic Preservation Officer Cuartel de Ballajá Bldg. San Juan, Puerto Rico

## **Re:** Authorization to Submit Documents

Dear Arch. Rubio Cancela:

The U.S. Department of Housing (HUD) approved the allocations of Community Development Block Grant (CDBG-DR) funds on February 9, 2018. It also approved the allocation of Community Development Block Grant Mitigation (CDBG-MIT) funds on January 27, 2020. The purpose of these allocations is to address unsatisfied needs as a result of Hurricanes Irma and Maria in September 2017; and to carry out strategic and high-impact activities to mitigate disaster risks and reduce future losses.

To comply with the environmental requirements established by HUD, the Department of Housing of Puerto Rico (PRDOH) contracted Horne Federal LLC to provide environmental registry review services, among others, that will support the objectives of the agenda for both CDBG-DR and CDBG -MIT Programs.

In line to expedite the processes, Horne Federal LLC, is authorized to submit to the State Historic Preservation Officer, documentation of projects related to both the CDBG-DR and CDBG-MIT on behalf of PRDOH.

Cordially,

Juan C Pérez Bofill, P.E. M.Eng Director of Disaster Recovery CDBG DR-MIT

CDBG-DR FUNDS I HOUSING



Environmental Assessment Determinations and Compliance Findings for HUD-assisted Projects24 CFR Part 58

# Appendix 2

You are here: EPA Home > Green Book > >National Area and County-Level Multi-Pollutant Information >Puerto Rico Nonattainment/Maintenance Status for Each County by Year for All Criteria Pollutants

## Puerto Rico Nonattainment/Maintenance Status for Each County by Year for All Criteria Pollutants

Data is current as of March 31, 2023

Listed by County, NAAQS, Area. The 8-hour Ozone (1997) standard was revoked on April 6, 2015 and the 1-hour Ozone (1979) standard was revoked on June 15, 2005.

\* The 1997 Primary Annual PM-2.5 NAAQS (level of 15 μg/m<sup>3</sup>) is revoked in attainment and maintenance areas for that NAAQS. For additional information see the PM-2.5 NAAQS SIP Requirements Final Rule, effective October 24, 2016. (81 FR 58009)

Change	the	State:
Change	uie	State.

PUERIO RICO • GO	PUERTO RICO 🗸	GO
------------------	---------------	----

Important	Notes		Download	d National Datas	et: dbf   xls	Data	dictionary	(PDF)
	NAAQS	Area Name	Nonattainment in Year	Redesignation to Maintenance	Classification	Whole or/ Part County	Population (2010)	State/ County FIPS Codes
PUERTO	RICO							
Arecibo Municipic	Lead (2008)	Arecibo, PR	11121314151617181920212223			Part	32,185	72/013
Bayamon Municipic	Sulfur Dioxide (2010)	San Juan, PR	181920212223	//		Part	22,921	72/021
Catano Municipic	Sulfur	San Juan, PR	181920212223	//		Whole	28,140	72/033
Guaynabo Municipio		Mun. of Guaynabo, PR	929394959697989900010203040506070809	02/11/2010	Moderate	Part	90,470	72/061
Guaynabo Municipio	Sulfur Dioxide (2010)	San Juan, PR	181920212223			Part	23,802	72/061
Salinas Municipio	Sulfur	Guayama-		/ /		Part	23,401	72/123
San Juan Municipic	Sulfur	San Juan, PR	181920212223	/ /		Part	147,963	72/127
Toa Baja Municipic	Sulfur Dioxide (2010)	San Juan, PR		//		Part	52,441	72/137

Important Notes



Environmental Assessment Determinations and Compliance Findings for HUD-assisted Projects24 CFR Part 58

## Appendix 3



BEHAR-YBARRA & ASSOCIATES LLC CONSULTING ENGINEERS, ARCHITECTS AND PLANNERS

		I I		
Applicant ID:	PR-RGRW-00518	Service State	at a	
Name:	Angeles Rodriguez Sepulveda	1322	(139)	S
Parcel ID:	317-000-001-31-002		a state	Campoti Se
Latitude:	18.114682	and the second	Contract &	An All States
Longitude:	-66.6171013	22.10		
Elevation:	568.6019876747463	200	5	
Development			Monte Llano	
Street Address:	Carr. 505 Barrio Monte Llano, Sector Seto 2	2 Ala	A	
Municipio:	Ponce	1. 30		and the second s
Zip Code:	PR 00717	Sec.		The second second
Site Inspector:	Patricia Carmenatty	your h	Ball of the	
Date of Visit:	February 16, 2024	Erri LIEDE	Paurana di huy Enzi	Esri, Maxar Powered by Esri
Time of Visit:	10:10	ESH, HERE,	Powered by Esri	Esri, Maxar Powered by Esri
	FIELD	OBSERVATI	ONS	
	Question	Answer		Notes
A. Is the structure in use	9?	No		
B. Is the structure a gre	enhouse?	No		
C. Is Electricity connecte		No		
D. Is water connected?	· · · · · ·	No		
	or housekeeping on site? (mounds of rubble,	No		
garbage, strom debri pesticides, cleaning f	s, solid waste, petroleum products, paint, iluids, vehicle batteries, abandoned vehicles, pits, rdous substances, etc.)	NO		
2. Are there any 55-gall	on drums visible on site? If yes, are they leaking?	No		
<ol><li>Are there any (or sign property?</li></ol>	ns of any) underground storage tanks on the	No		
4. Are there signs of AS approximate size and	T on the parcel or adjacent parcel? If yes, list d contents, if known.	No		
5. Is there any stained s	soil or pavement on the parcel?	No		
6. Is a water drainage s	ystem in use?	No		
7. Is a warehouse in us	e for storage of Fertilizer or Pesticides?	No		
8. Are there any ground parcel?	lwater monitoring wells on the site or adjacent	No		
9. Is there evidence of a	a faulty septic system?	No		
10. Is there distressed ve	egetation on the parcel?	No		
11. Is there any visible in	dication of mold?	No		
12. Is there any visible en peeling paint, or haza	vidence of asbestos, chipping, and flaking or ardous materials present in or on the structure?	No		
13. Are any additional sit	e hazards observed?	No		
	ent standing water, such as a pond or stream, o not include ponding from recent rain / weather	No		
15. Does the subject pro	perty have water frontage?	No		
16. Is there any indicatio	n of the presence of wetlands?	No		
17. Are there any obviou site?	s signs of animals or birds nesting on or near the	No		
	e of any signifcant historcal event or persons tructure, or of it being located in a historic district/	No		
19. Is a historic marker p	resent?	No		
P		-		

**APPLICANT/LOCATION INFORMATION** 




















































# **Detailed Facility Report**

## Facility Summary

TALLER MECANICA AUTOMOLIVIA

### PR-123 KM 8.0, PONCE, PR 00731

FRS (Facility Registry Service) ID: 110028227425 EPA Region: 02 Latitude: 18.116667 Longitude: -66.611944 Locational Data Source: ICIS Industries: --Indian Country: N

## **Enforcement and Compliance Summary**

No data records returned

## **Regulatory Information**

Clean Air Act (CAA): No Information Clean Water Act (CWA): No Information Resource Conservation and Recovery Act (RCRA): No Information

Safe Drinking Water Act (SDWA): No Information

## **Other Regulatory Reports**

Air Emissions Inventory (EIS): No Information Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

**Compliance and Emissions Data Reporting Interface (CEDRI):** No Information

Go To Enforcement/Compliance Details Known Data Problems <a href="https://epa.gov/resources/echo-data/known-data-problems">https://epa.gov/resources/echo-data/known-data-problems</a>

## **Facility/System Characteristics**

## **Facility/System Characteristics**

Syste	n Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110028227425					Ν	18.116667	-66.611944
ICIS		600006760					Ν	18.116667	-66.611944

## **Facility Address**


System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110028227425	TALLER MECANICA AUTOMOLIVIA	PR-123 KM 8.0, PONCE, PR 00731	Ponce Municipio
ICIS		600006760	TALLER MECANICA AUTOMOLIVIA	CARR. #123 KM. 8.0, PONCE, PR 00731	Ponce Municipio

## Facility SIC (Standard Industrial Classification) Codes

System Identifier SIC Code SIC Description

No data records returned

## Facility NAICS (North American Industry Classification System) Codes



No data records returned

## **Enforcement and Compliance**

Com	plian	ce M	onitorir	ng History	st 5 Years		
Statute	Source ID	System	Activity Type	Compliance Monitoring Typ	e Lead Agency	Date	Finding (if applicable)

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <a href="https://www.epa.gov/compliance/compliance-monitoring-programs">https://www.epa.gov/compliance/compliance-monitoring-programs</a> activities or because they are not counted as inspections within EPA's Annual Results <a href="https://www.epa.gov/enforcement/">https://www.epa.gov/compliance/compliance/compliance/compliance/compliance/compliance/compliance/compliance/compliance///www.epa.gov/enforcement/</a> enforcement-data-and-results>.

## **Compliance Summary Data**



## Three-Year Compliance History by Quarter

Informa	l Enforc	ement Act	ions	Last 5 Years	]	
Statute	System	Source ID	т	ype of Action	Lead Agency	Date

No data records returned

*Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.* 

## Formal Enforcement Actions Last 5 Years

Statute	System	Law/ Section	Source ID	Type of Action	Case No.	Lead Agency	Case Name	Filed	Settlements/ Actions	Settlement/ Action Date	Federal Penalty Assessed	State/ Local Penalty Assessed	Penalty Amount Collected	SEP Value	Comp Action Cost	
---------	--------	-----------------	--------------	----------------------	-------------	----------------	--------------	-------	-------------------------	----------------------------	--------------------------------	--	--------------------------------	--------------	------------------------	--

No data records returned

## **Environmental Conditions**

## Watersheds

No data records returned

## Assessed Waters From Latest State Submission (ATTAINS)

State	Report Cycle	Assessment Unit ID	Assessment Unit Name	Water Condition	Cause Groups Impaired	Drinking Water Use	Ecological Use	Fish Consumption Use	Recreation Use	Other Use
No data records returned										
Air Quality Nonattainment Areas										
Polluta	Pollutant     Within Nonattainment Status     Nonattainment Status Applicable     Within Maintenance Status     Maintenance Status Applicable       Area?     Standard(s)     Area?     Standard(s)							licable		
No data records returned										

## Pollutants

Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID	/ear Air Surface Water Emissions Discharges	Off-Site Transfers to POTWs (Publicly Owned Treatment Works)	Underground Injections	Disposal to Land	Total On-Site Releases	Total Off-Site Transfers	
--------------------	--	--	---------------------------	---------------------	---------------------------	-----------------------------	--

No data records returned

## Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

**Chemical Name** 

No data records returned

## **Community** Environmental Justice

This section shows indexes from EJScreen, EPA's screening tool for environmental justice (EJ) concerns. EPA uses these indexes to identify geographic areas that may warrant further consideration or analysis for potential EJ concerns. Use of these indexes does not designate an area as an "EJ community" or "EJ facility." EJScreen provides screening level indicators, not a determination of the existence or absence of EJ concerns. For more information, see the EJScreen home page.

### **Potential Environmental Justice Concerns**

### **US** Territory

Located in an area having 1 or more Census Block Supplemental State or US Percentiles >= 90%

Located in an area having 1 or more 1-Mile Average Supplemental State or US Percentiles >= 90%

### **EJScreen Indexes Shown**

### **Related Reports**

Index Type

Supplemental (default)

### **EJScreen Community Report**

#### Download Data

Census Block Group ID: 721130726003	US (I	Percentile)		State	(Percentile)	
Supplemental Indexes	Facility Census Block Group	1-mile Avg	1-mile Max	Facility Census Block Group	1-mile Avg	1-mile Max
Count of Indexes At or Above 90th Percentile	5	4	6	2	1	5
Particulate Matter 2.5		N/A			N/A	
Ozone		N/A			N/A	
Diesel Particulate Matter	0	3	6	16	30	45
Air Toxics Cancer Risk	56	55	56	92	88	92
Air Toxics Respiratory Hazard Index	23	32	40	0	28	92
Toxic Releases to Air	99	99	<b>D</b> 99	95	<b>9</b> 92	95
Traffic Proximity	72	86	<b>9</b> 97	20	37	67
Lead Paint	94	84	<b>9</b> 94	70	45	70
Risk Management Plan (RMP) Facility Proximity	94	99	<b>D</b> 99	57	78	<b>9</b> 94
Hazardous Waste Proximity	82	85	<b>9</b> 91	28	34	49
Superfund Proximity	99	99	<b>D</b> 99	52	67	82
Underground Storage Tanks (UST)	0	0		0	0	

Census Block Group ID: 7211307	US (I	Percentile)		State (Percentile)				
Supplemental Indexes	Supplemental Indexes		Facility Census Block Group 1-mile Avg		Facility Census Block Group	1-mile Avg	1-mile Max	
Wastewater Discharge		99	99	99	64	86	96	
Map Display Based or Display Map Layer		US () S	State per of Ind	dexes				

+	23
—	

1 mi Earthstar Geographics | Esri, TomTom, Garmin, Foursquare, SafeGraph,... Powered by Esri <a href="http://www.esri.com/">http://www.esri.com/</a>>

## Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2010 U.S. Census and 2017 - 2021 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and

≣

longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and the census blocks (for U.S. Census demographics) and census block groups (for ACS demographics) in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <a href="https://epa.gov/help/reports/dfr-data-dictionary#demographics">https://epa.gov/help/reports/ dfr-data-dictionary#demographic>.</a>

General Statistics (U.S. Census)					
Total Persons	526				
Population Density	166/sq.mi.				
Housing Units in Area	181				
General Statistics (ACS (American Community	Survey))				
Total Persons	431				
Percent People of Color	100%				
Households in Area	153				
Households on Public Assistance	22				
Persons With Low Income	381				
Percent With Low Income	88%				
Geography					
Radius of Selected Area	1 mi.				
Center Latitude	18.116667				
Center Longitude	-66.611944				
Land Area	99%				
Water Area	1%				
Income Breakdown (ACS (American Communit	y Survey)) -				
Households (%)					
Less than \$15,000	93 (61.18%)				
\$15,000 - \$25,000	22 (14.47%)				
\$25,000 - \$50,000	22 (14.47%)				
\$50,000 - \$75,000	11 (7.24%)				
Greater than \$75,000	4 (2.63%)				

Age Breakdown	(U.S. Census	) - Persons (%)
---------------	--------------	-----------------

Children 5 years and younger	34 (6%)
Minors 17 years and younger	118 (22%)
Adults 18 years and older	408 (78%)
Seniors 65 years and older	60 (11%)


Race Breakdown (U.S. Census) - Persons (%)							
White	439 (83%)						
African-American	41 (8%)						
Hispanic-Origin	526 (100%)						
Asian/Pacific Islander	0 (0%)						
American Indian	0 (0%)						
Other/Multiracial	46 (9%)						

Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%)

Less than 9th Grade	94 (29.19%)
9th through 12th Grade	46 (14.29%)
High School Diploma	87 (27.02%)
Some College/2-year	18 (5.59%)
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	53 (16.46%)

## SEPA EJScreen Community Report

This report provides environmental and socioeconomic information for user-defined areas, and combines that data into environmental justice and supplemental indexes.




Notes: Numbers may not sum to totals due to rounding. Hispanic population can be of any race. Source: U.S. Census Bureau, American Community Survey (ACS) 2017-2021. Life expectancy data comes from the Centers for Disease Control.


### **Environmental Justice & Supplemental Indexes**

**EJ INDEXES** 

The environmental justice and supplemental indexes are a combination of environmental and socioeconomic information. There are thirteen EJ indexes and supplemental indexes in EJScreen reflecting the 13 environmental indicators. The indexes for a selected area are compared to those for all other locations in the state or nation. For more information and calculation details on the EJ and supplemental indexes, please visit the EJScreen website.



SUPPLEMENTAL INDEXES The supplemental indexes offer a different perspective on community-level vulnerability. They combine data on percent low-income, percent linguistically isolated, percent less than high school education, percent unemployed, and low life expectancy with a single environmental indicator.  $\equiv$ 



SUPPLEMENTAL INDEXES FOR THE SELECTED LOCATION

These percentiles provide perspective on how the selected block group or buffer area compares to the entire state or nation. Report for 1 mile Ring Centered at 18.114682,-66.617103

### **EJScreen Environmental and Socioeconomic Indicators Data**

SELECTED VARIABLES	VALUE	STATE Average	PERCENTILE IN STATE	USA AVERAGE	PERCENTILE IN USA
POLLUTION AND SOURCES					
Particulate Matter (µg/m <sup>3</sup> )	N/A	N/A	N/A	8.08	N/A
Ozone (ppb)	N/A	N/A	N/A	61.6	N/A
Diesel Particulate Matter (µg/m <sup>3</sup> )	0.0195	0.0667	23	0.261	0
Air Toxics Cancer Risk* (lifetime risk per million)	20	20	15	25	5
Air Toxics Respiratory HI*	0.16	0.19	0	0.31	1
Toxic Releases to Air	1,700	4,300	75	4,600	69
Traffic Proximity (daily traffic count/distance to road)	31	180	32	210	31
Lead Paint (% Pre-1960 Housing)	0.04	0.16	29	0.3	24
Superfund Proximity (site count/km distance)	0.087	0.15	54	0.13	62
RMP Facility Proximity (facility count/km distance)	0.34	0.47	66	0.43	70
Hazardous Waste Proximity (facility count/km distance)	0.13	0.76	24	1.9	25
Underground Storage Tanks (count/km <sup>2</sup> )	0	1.7	0	3.9	0
Wastewater Discharge (toxicity-weighted concentration/m distance)	0.3	2.3	78	22	87
SOCIOECONOMIC INDICATORS					
Demographic Index	94%	83%	79	35%	99
Supplemental Demographic Index	58%	43%	89	14%	99
People of Color	100%	96%	31	39%	98
Low Income	88%	70%	78	31%	98
Unemployment Rate	15%	15%	59	6%	91
Limited English Speaking Households	88%	67%	90	5%	99
Less Than High School Education	43%	21%	94	12%	97
Under Age 5	4%	4%	67	6%	46
Over Age 64	22%	22%	50	17%	72
Low Life Expectancy	N/A	N/A%	N/A	20%	N/A

\*Disel participate matter air toxics cancer risk, and air toxics respiratory hazard index are from the EPA's Air Toxics Data Undate, which is the Agency's ongoing, comprehensive evaluation of air toxics in the United States. This effort aims to prioritize air toxics, emission sources, and locations of interest of fourther study. It is important to remember that the air toxics data greened here provide broad estimates of sources are provided and the country, not definitive risks to specific individuals or locations. Cancer risks and hazard indices from the Air Toxics Data Update are reported to one significant figure and any additional significant figures here are due to rounding. More information on the ir Toxics Data Update can be found at <u>https://www.eaa.gov/hapa/air\_toxics-data-update</u>.

#### Sites reporting to EPA within defined area:

Superfund	0
Hazardous Waste, Treatment, Storage, and Disposal Facilities	0
Water Dischargers	0
Air Pollution	0
Brownfields	0
Toxic Release Inventory	0

### Other community features within defined area:

Hospitals	s		 							
Places of	f Worshir	1								

#### Other environmental data:

Air Non-attainment	No
Impaired Waters	Yes

Selected location contains American Indian Reservation Lands*	No
Selected location contains a "Justice40 (CEJST)" disadvantaged community	Yes
Selected location contains an EPA IRA disadvantaged community	Yes

Report for 1 mile Ring Centered at 18.114682,-66.617103

### EJScreen Environmental and Socioeconomic Indicators Data

HEALTH INDICATORS									
INDICATOR	VALUE	STATE AVERAGE	STATE PERCENTILE	US AVERAGE	US PERCENTILE				
Low Life Expectancy	N/A	N/A	N/A	20%	N/A				
Heart Disease	N/A	N/A	N/A	6.1	N/A				
Asthma	N/A	N/A	N/A	10	N/A				
Cancer	N/A	N/A	N/A	6.1	N/A				
Persons with Disabilities	26.2%	21.6%	73	13.4%	96				

CLIMATE INDICATORS										
INDICATOR	VALUE	STATE AVERAGE	STATE PERCENTILE	US AVERAGE	US PERCENTILE					
Flood Risk	N/A	N/A	N/A	12%	N/A					
Wildfire Risk	N/A	N/A	N/A	14%	N/A					

CRITICAL SERVICE GAPS										
INDICATOR	VALUE	STATE AVERAGE	STATE PERCENTILE	US AVERAGE	US PERCENTILE					
Broadband Internet	41%	32%	70	14%	95					
Lack of Health Insurance	3%	7%	16	9%	24					
Housing Burden	No	N/A	N/A	N/A	N/A					
Transportation Access	No	N/A	N/A	N/A	N/A					
Food Desert	No	N/A	N/A	N/A	N/A					

Report for 1 mile Ring Centered at 18.114682,-66.617103

www.epa.gov/ejscreen



Environmental Assessment Determinations and Compliance Findings for HUD-assisted Projects24 CFR Part 58

## Appendix 4

To whom it may concern:

This email is to acknowledge receipt of PRDOH letter confirming the Service the changes in effect determination for the PR boa from NE to NLAA and the implementation of the PR harlequin butterfly and PR boa conservation measures provided by the Service on May 16, 2024 for the PRDOH consultation of April 04, 2024. Keep this email for your records.

Thanks

\*\* If you need assistance, please contact me at emails or mobile below. If you are sending a request for technical assistance or Section 7 consultation, please contact us at Caribbean\_es@fws.gov\*\*

Need a project evaluation? Please visit our Consultation Guidelines website.

Cordially,

### Damarís Román Ruíz

Biological Science Technician US Fish and Wildlife Service Caribbean Ecological Service Field Office P.O Box 491/Road 301 km 5.1 Boqueron PR 00622

*Office Park I Suite 303 State Road #2, Km 156.5 Mayagüez, PR 00680* 

Office Desk Phone (939) 320-3135 Mobile (786) 244-0081 damaris\_roman@fws.gov caribbean\_es@fws.gov Office Homepage: <u>https://www.fws.gov/southeast/caribbean/</u> Facebook: <u>https://www.facebook.com/USFWSCaribbean?ref=hl</u> Flicker: <u>https://www.flickr.com/photos/usfwssoutheast/sets/72157626859158391/</u>

From: environmentcdbg <environmentcdbg@vivienda.pr.gov>
Sent: Tuesday, July 23, 2024 10:09 AM
To: Caribbean ES, FW4 <Caribbean\_ES@fws.gov>
Cc: Roman, Damaris <damaris\_roman@fws.gov>
Subject: [EXTERNAL] RE: CDBG-DR PR-RGRW-00518 Ángeles Rodríguez Sepúlveda

## This email has been received from outside of DOI - Use caution before clicking on links, opening attachments, or responding.

To whom it may concern:

In order to complete the environmental review process, attached please find a letter of acceptance by PRDOH regarding the case PR-RGRW-00518 for the CDBG-DR Re-Grow PR Urban-Rural Agriculture Program. This document contains the confirmation of the implementation of the conservation measures regarding this case.

Should you need additional information, do not hesitate to contact our office.

Cordially,

### Permits and Environmental Compliance Division

Disaster Recovery Office <u>environmentcdbg@vivienda.pr.gov</u> | 787.274.2527 Visit us: <u>recuperacion.pr.gov</u> Contact us: <u>infocdbg@vivienda.pr.gov</u>



NOTA DE CONFIDENCIALIDAD: Esta transmisión electrónica contiene información perteneciente al Departamento de Vivienda de Puerto Rico, la cual es confidencial y / o privilegiada legalmente. Si usted no es el destinatario previsto, informe inmediatamente al remitente por correo electrónico de respuesta o por teléfono que este mensaje se le ha transmitido inadvertidamente y elimine este correo electrónico de su sistema. Si ha recibido esta transmisión por error, por la presente se le notifica que cualquier divulgación, copia, distribución o cualquier acción basada en el contenido de la información está estrictamente prohibida. El uso, difusión, distribución o reproducción no autorizados de este mensaje por personas que no sean el destinatario previsto está estrictamente prohibido y puede ser ilegal.

**CONFIDENTIALITY NOTE:** This electronic transmission contains information belonging to the Puerto Rico Housing Department, which is confidential and/or legally privileged. If you are not the intended recipient, please immediately advise the sender by reply e-mail or telephone that this message has been inadvertently transmitted to you and delete this e-mail from your system. If you have received this transmission in error, you are hereby notified that any disclosure, copying, distribution or the taking of any action in reliance on the contents of the information is strictly prohibited. Unauthorized use, dissemination, distribution or reproduction of this message by other than the intended recipient is strictly prohibited and may be unlawful. 7

From: Roman, Damaris <damaris\_roman@fws.gov>
Sent: Friday, May 17, 2024 9:16 AM
To: Juan C. Perez-Bofill <jcperez@vivienda.pr.gov>
Cc: environmentcdbg <environmentcdbg@vivienda.pr.gov>; Angel G. Lopez-Guzman <a.lopez@vivienda.pr.gov>; allison.cullet@horne.com
Subject: CDBG-DR PR-RGRW-00518 Ángeles Rodríguez Sepúlveda

Mr. Pérez

See attached file regarding the referenced project. Should you have any questions, contact us at <u>caribbean\_es@fws.gov</u>

#### Thanks

\*\* If you need assistance, please contact me at emails or mobile below. If you are sending a request for technical assistance or Section 7 consultation, please contact us at <u>Caribbean\_es@fws.gov\*\*</u>

#### Need a project evaluation? Please visit our Consultation Guidelines website.

Cordially,

### Damarís Román Ruíz

Biological Science Technician US Fish and Wildlife Service Caribbean Ecological Service Field Office P.O Box 491/Road 301 km 5.1 Boqueron PR 00622

*Office Park I Suite 303 State Road #2, Km 156.5 Mayagüez, PR 00680* 

Office Desk Phone (939) 320-3135 Mobile (786) 244-0081 <u>damaris\_roman@fws.gov</u> <u>caribbean\_es@fws.gov</u> This email has been scanned by the Symantec Email Security.cloud service. For more information please visit <u>http://www.symanteccloud.com</u>

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com



HOUSING

July 22, 2024

Caribbean Ecological Services Field Office U.S. Fish and Wildlife Service P.O. Box 491 Boquerón, Puerto Rico 00622 Email: <u>caribbean@es@fws.gov</u>

### Re: Puerto Rico Department of Housing / Re-Grow Program Ángeles Rodríguez Sepúlveda | PR-RGRW-00518 Effect Determination Acceptance

To whom it may concern:

The Puerto Rico Department of Housing (PRDOH) acknowledges receipt of the U.S. Fish and Wildlife Service correspondence dated on May 4 2024 for the project PR-RGRW-00518. According to Section 7(a)(2) of the Endangered Species Act (Act) (87 Stat. 884, as amended; 16 United States Code 1531 et seq.), PRDOH confirms the acceptance to the reconsideration of the No Effect (NE) determination for the Puerto Rican Boa to a May Affect, but is Not Likely to Adversely Affect (NLAA) determination, as well as the implementation of the pertinent conservation measures for the Puerto Rican Boa and the Puerto Rican Harlequin Butterfly.

As it is stated, with this communication, the PRDOH completes its responsibility under Section 7 of the Endangered Species Act with the Services' requirements for concurrence.

Should you need additional information, do not hesitate to contact our office.

Sincerely,

Permits and Environmental Compliance Division Disaster recovery Office <u>environmentcdbg@vivienda.pr.gov</u> | (787)274-2527 ext. 4320

### **CDBG-DR** FUNDS



### United States Department of the Interior

FISH AND WILDLIFE SERVICE Caribbean Ecological Services Field Office Bayamón | Mayagüez | Maricao | Río Grande | St Croix P.O. Box 491 Boquerón, Puerto Rico 00622



In Reply Refer to: FWS/R4/CESFO/72113-Gen

Submitted Via Electronic Mail: jcperez@vivienda.pr.gov

Juan Carlos Pérez-Bofill, PE, MEng. Director – Disaster Recovery CDBG-DR Program Puerto Rico Department of Housing P.O. Box 21365 San Juan, P.R 00928-1365

> Re: CDBG-DR PR-RGRW-00518 Ángeles Rodríguez Sepúlveda, Ponce, Puerto Rico

Dear Mr. Pérez-Bofill

Thank you for your letter dated April 04, 2024, requesting informal consultation on the above referenced project. As per your request, our comments are provided under the Endangered Species Act (Act) (87 Stat. 884, as amended; 16 United States Code 1531 et seq.), and the Fish and Wildlife Coordination Act (48 Stat. 401, as amended; 16 U.S.C. 661 et seq.).

The Puerto Rico Department of Housing (PRDOH) is proposing the installation of storage warehouse (12 feet x 12 feet) that will require ground disturbance. The proposed project will be located at State Road PR-505, Bo. Montellano, Sector Seto 2 (18°06'52.9"N 66°37'01.6"W) in the municipality of Ponce.

Using the U.S. Fish and Wildlife Service's (Service) Information for Planning and Consultation (IPaC) system, the PRDOH has determined that the proposed project site is located within the range of Puerto Rican boa (*Epicrates inornatus* now known as *Chilabothrus inornatus*), Puerto Rican broad-winged hawk (*Buteo platypterus brunnescens*), Puerto Rican parrot (*Amazona vittata*), Puerto Rican sharp-shinned hawk (*Accipiter striatus venator*) and Puerto Rican harlequin butterfly (*Atlantea tulita*).

PRDOH used the Caribbean Determination Key (DKey) in the IPaC application to evaluate the potential impacts of the proposed project on federally listed species (Project code: 2024-0064204). Based on the answers provided, a consistency letter was obtained for the Puerto Rican boa, Puerto Rican broad-winged hawk and Puerto Rican sharp-shinned hawk, which determined that the proposed actions for this project would have "No Effect" (NE) for these species. The Service acknowledges receipt of the NE DKey consistency letter for the Puerto Rican broad-winged hawk and Puerto Rican sharp-shinned hawk.

#### Mr. Pérez-Bofill

As for the Puerto Rican boa, since ground disturbance will occur, the Service believes that the proposed project may affect but is not likely to adversely affect (NLAA) this species. Therefore, the NE consistency letter obtained using the DKey for the Puerto Rican boa is nullified. Thus, the Service recommends PRDOH to reconsider its NE determination for this species to a NLAA and implement the following Puerto Rican boa conservation measures:

- 1. Inform all project personnel about the potential presence of the PR boa in areas where the proposed work will be conducted. A pre-construction meeting should be conducted to inform all project personnel about the need to avoid harming the species as well as penalties for harassing or harming PR boas. An educational poster or sign with photo or illustration of the species should be displayed at the project site.
- 2. Prior to any construction activity, including removal of vegetation and earth movements, the boundaries of the project and areas to be excluded and protected should be clearly marked in the project plan and in the field in order to avoid further habitat degradation into forested and conservation areas.
- 3. Once areas are clearly marked, and prior to the use of heavy machinery and any construction activity (including removal of vegetation and earth movement), a biologist or project personnel with experience on this species should survey the areas to be cleared to verify the presence of any PR boa within the work area.
- 4. If a PR boa is found within any of the working or construction areas, activities should stop at that area and information recorded (see #5). Do not capture the boa. If boas need to be moved out of harm's way, designated personnel shall immediately contact the Puerto Rico Department of Natural and Environmental Resources (PRDNER) Rangers for safe capture and relocation of the animal: (787) 999-2200 ext. 2911. If immediate relocation is not an option, project-related activities at that area must stop until the boa moves out of harm's way on its own. Activities at other work sites, where no boas have been found after surveying the area, may continue.
- 5. For all boa sightings (dead or alive), record the time and date of the sighting and the specific location where it was found. PR boa data should also include a photo of the animal (dead or alive), site GPS coordinates, the time and date, and comments on how the animal was detected and its behavior.
- 6. If a PR boa is captured by PRDNER personnel, record the name of that person and information on where the PR boa will be taken. This information should be reported to the Service.
- 7. Measures should be taken to avoid and minimize PR boa casualties by heavy machinery or motor vehicles being used on site. Any heavy machinery left on site (staging) or near potential PR boa habitat (within 50 meters of potential boa habitat), needs to be thoroughly inspected each morning before work starts to ensure that no boas have sheltered within engine compartments or other areas of the equipment. If PR boas are found within vehicles or equipment, do not capture the animal, and let it move on its own or call PRDNER

Rangers for safe capture and relocation of the animal (see #4). If not possible, the animals should be left alone until it leaves the vehicle on its own.

- 8. PR boas may seek shelter in debris piles. Measures should be taken to avoid and minimize boa casualties associated with sheltering in debris piles as a result of project activities. Debris piles should be placed far away from forested areas. Prior to moving, disposing or shredding, debris piles should be carefully inspected for the presence of boas. If debris piles will be left on site, we recommend they be placed in areas that will not be disturbed in the future.
- 9. If a dead PR boa is found, immediately cease all work in that area and record the information accordingly (see #5). If the PR boa was accidentally killed as part of the project actions, please include information on what conservation measures had been implemented and what actions will be taken to avoid further killings. A dead boa report should be sent by email (see contacts below) to the Service within 48 hours of the event.
- 10. Projects must comply with all state laws and regulations. Please contact the PRDNER for further guidance.

If you have any questions regarding the above conservation measures, please contact the Service:

- José Cruz-Burgos, Endangered Species Program Coordinator
  - o Email: jose cruz-burgos@fws.gov
  - o Office phone (305) 304-1386
- •Jan Zegarra, Fish and Wildlife Biologist
  - Email: jan\_zegarra@fws.gov
  - o Office phone (786) 933-1451

Based on the nature of the project, scope of work, information available and existing habitat, the PRDOH has determined that the proposed project has NE on the Puerto Rican parrot due to the lack of suitable habitat. The Service acknowledges receipt of PRDOH's NE determination for the Puerto Rican parrot. Currently, we do not have information to refute that determination. Because the PRDOH made a NE determination, the PRDOH is not required to conduct formal or informal section 7 consultation with the Service, and the Service is not required to concur with PRDOH's NE determination.

As for the Puerto Rican harlequin butterfly, PRDOH has determined that the proposed project may affect, but is not likely to adversely affect the Puerto Rican harlequin butterfly since the project area has been used for agricultural purposes for the past 20 years.

We have reviewed the information provided and our files, and concur with PRDOH's determination that the proposed actions may affect but are not likely to adversely affect the Puerto Rican harlequin butterfly if PRDOH agrees to implement the following conservation measures for this species:

### Mr. Pérez-Bofill

- 1. The contractor must inform all personnel about the potential presence of the Puerto Rican harlequin butterfly or its occupied host plant "prickly bush" (*Oplonia spinosa*) in the project areas. A pre-work meeting should inform all project personnel about the need to avoid harming this butterfly and its occupied host plant. Educational material (e.g., posters, flyers or signs with photos or illustrations of all the life stages of the Puerto Rican harlequin butterfly (i.e., eggs, caterpillar, chrysalids and adult, and its host plant) should be prepared and available to all personnel for reference.
- 2. Before starting any project activity, including removal of vegetation and earth movement, the contractor must clearly delineate the boundaries of the working area in the field to avoid unnecessary habitat impacts. Once the project areas are clearly marked, and before any work activity, including site preparation, personnel with knowledge and ability to identify the Puerto Rican harlequin butterfly (all life stages) and the "prickly bush" must survey the areas where the work will be performed for the presence of the species and its host plant. It is important to note that the Puerto Rican harlequin butterfly can be observed year-round in all its life stages; thus, oviposition (egg-laying) may occur at any time during the year.
- 3. If the "prickly bush" is present on the project site, try to avoid cutting it off, even if no eggs, caterpillars, or chrysalids are present.
- 4. If there is no prickly bush within the project area, and the butterfly is observed flying within the project area, do not harass, harm, pursue, wound, kill, trap, capture, collect, or attempt to engage in any such conduct, the species.
- 5. Adult butterflies are often observed flying near the host plant as part of their mating behavior and laying eggs. Project-related activities must stop if the prickly bush is found in the project area and the Puerto Rican harlequin butterfly is observed flying in that same area. A temporary 50-meter (164 feet) buffer zone of no activity or human disturbance should be established and clearly marked around that prickly bush until the butterfly moves out on its own.
- 6. Once the Puerto Rican harlequin butterfly has moved away, within a period of 24 to 36 hours, a search of the prickly bush that has been buffered should be conducted to determine the presence of any eggs, caterpillars, or chrysalids of the butterfly on the plant. The contractor or the Applicant should send a report of the observation and its findings to caribbean es@fws.gov after the 36-hour search is concluded.
- 7. If, after the initial search or after the 24 to 36-hour search, any life stage of the Puerto Rican harlequin butterfly is found in the prickly bush, take the following actions:
  - Clearly mark the host plant with flagging tape.
  - Establish a 10-meter (32-foot) buffer zone around the bush to protect it.
  - Eggs are typically found on the prickly bush's newly grown, tender branches. Once an egg hatches, the caterpillar moves and feeds throughout the bush. Therefore, avoid cutting off the prickly bush within the project site even if no eggs, caterpillars, or chrysalids are present.

#### Mr. Pérez-Bofill

- Work within the 10-meter buffered area may resume when no signs of any live life stage of the butterfly are detected, which usually takes approximately 60 to 120 days.
- 8. For all Puerto Rican harlequin butterfly sightings (all life stages), the time and date of the sighting and the specific location where the butterfly was found must be recorded. Data should also include a photo of the butterfly (if possible) and the habitat where it was observed, site GPS coordinates, and comments on how the butterfly was detected and its behavior. All Puerto Rican harlequin butterfly sighting reports should be sent to the USFWS Caribbean Ecological Service Field Office at caribbean\_es@fws.gov.
- 9. For questions regarding the Puerto Rican harlequin butterfly, the Point of Contacts are:

José Cruz-Burgos, Endangered Species Coordinator:

- Mobile: 305-304-1386
- Office phone: 786-244-0081
- o Office Direct Line: 939-320-3120
- Email: jose\_cruz-burgos@fws.gov

This consultation will be completed once we receive PRHOD's confirmation of the NLAA determination for the Puerto Rican boa as well as the implementation of the above mentioned conservation measures for the Puerto Rican harlequin butterfly and Puerto Rican boa.

Thank you for the opportunity to comment on this project. If you have any questions or require additional information, please contact us via email at <u>caribbean\_es@fws.gov</u> or by phone at (786) 244-0081.

Sincerely,

ROBERT TAWES

RÓBERT TAWES Date: 2024.05.16 21:45:20 -04'00'

Robert Tawes Acting Field Supervisor

drr

cc: Allison Cullet, <u>allison.cullet@horne.com</u>

BYAA BEHAR YBARRA & ASSOCIATES LLC ENGINEERING, ARCHITECTURE, ENVIRONMENTAL, PLANNING

March 20, 2024

Robert Tawes Division Supervisor, Environmental Review U.S. Fish and Wildlife Service Southeast Regional Office 1875 Century Boulevard Atlanta, GA 30345 email: robert\_tawes@fws.gov

## RE: Informal Consultation for Case PR-RGRW-00518 located at Carr. 505 Barrio Monte Llano, Sector Seto 2, Ponce, PR 00717.

Dear Mr. Tawes:

The Puerto Rico Department of Housing is requiring informal consultation under Section 7 (a)(2) of the Endangered Species Act (Act) (87 Stat. 884, as amended; 16 United States Code 1531 et seq.), and in accordance with the Fish and Wildlife Coordination Act (47 Stat. 401, as amended; 16 U.S.C. 661 et seq.) for the proposed project PR-RGRW-00518, located at coordinates for the new storage warehouse: latitude 18.114682, longitude -66.6171013 on Carr. 505 Barrio Monte Llano, Sector Seto 2, Ponce, PR 00717, see Figure 1: Location Map and Figure 2: Topographic Map. The project is part of the Re-Grow Puerto Rico Urban-Rural Agriculture Program (RGRW) that aims to increase agricultural capacity while promoting and increasing food security inland wide. This Program will enhance and expand agricultural production related to economic revitalization and sustainable development activities.

The proposed activities for PR-RGRW-00518 consist of installation of a 12' x 12' storage warehouse. The installation of the storage warehouse will require ground disturbance. The storage warehouse will be installed on a concrete slab measuring 12' x 12' which will be provided by the applicant. The purpose of storage is to store the new equipment for the farm. No water connection will be necessary for the new warehouse. There will be no water or electricity connections, the power needed will be provided by an inverter. Based on a review of historical aerial imagery, the general area has been used for agricultural purposes for the past 20 years. The Area of Potential Effect (APE) has been defined as the area potentially impacted by ground disturbing activities related to the installation of the storage warehouse, see Figure 3: Area of Potential Effect.

#### **Existing Conditions and Trends**:

The proposed project parcel 317-000-001-31-002 is designated as Not Prime Farmland, See Figure 4: Farmland Protection Map. The project area is located in the mountainous area of Ponce. The area where the storage warehouse will be placed has a flat topography, refer to Photo 1 and Photo 2. The soil in this area has been classified as Consumo clay, 40 to 60 percent slopes (CuF). This is a very steep, well-drained soil on side slopes of maturely dissected humid uplands. The land has been used for agricultural uses for more than 20 years and the proposed project will not change the land use associated with these placements. The closer Final Critical Habitat is located 43,080 feet from the project location, see Figure 5: Critical Habitats Map. There are no wetlands on or near the project activity area, see Figure 6: Wetlands Map.

BYA BEHAR YBARRA & ASSOCIATES LLC ENGINEERING, ARCHITECTURE, ENVIRONMENTAL PLANNING

Using the Information for Planning and Consultation (IPaC) system (See Exhibit B), we have determined that the proposed project lies within the range of the following federally listed species and critical habitats:

Name of species	Threatened/Endangered/Candidate	
Reptiles		
Puerto Rican boa (Chilabothrus inornatus)	Endangered	
Birds		
Puerto Rican Broad-winged Hawk (Buteo	Endangered	
platypterus brunnescens)		
Puerto Rican Parrot (Amazona vittata)	Endangered	
Puerto Rican Sharp-shinned Hawk (Accipiter	Endangered	
striatus venator)		
Insects		
Puerto Rican Harlequin Butterfly (Atlantea	Threatened	
tulita)		
Critical Habitat		
There are no critical habitats within the project area.		

The nature of the project, scope of work, information available, a careful analysis of the IpaC, the Puerto Rico Boa conservation measures, the Caribbean Dkey dated March 18, 2024, in the US Fish and Wildlife Service's online IPaC application, and the observations during the field visit, were used to evaluate the potential impacts to federally listed species from this project. Based on that information and the answer inputted into the Dkey, it was determined that the proposed action will have "No Effect" determination on the Puerto Rican Boa, Puerto Rican Broad-winged Hawk and Puerto Rican Sharp-shinned Hawk, see Exhibit B. In addition, the type of work to be performed does not require heavy machinery and as can be seen in the photos, the area where the storage warehouse will be installed is only grass. Based on the provided information and the observations in the filed visit it was determined that it will also be a "No Effect" for the Puerto Rican Parrot.

Name of the species	Effect Determination	Conservation Measures that will be implemented
Puerto Rican boa ( <i>Chilabothrus inornatus</i> )	No Effect (NE)	No conservation measures
Puerto Rican Broad-winged Hawk (Buteo platypterus brunnescens)	No Effect (NE)	No conservation measures
Puerto Rican Parrot (Amazona vittata)	No Effect (NE)	No conservation measures
Puerto Rican Sharp-shinned Hawk (Accipiter striatus venator)	No Effect (NE)	No conservation measures
Puerto Rican Harlequin Butterfly	May Affect, but is Not	No conservation measures
(Atlantea tulita)	Likely to Adversely	
	Affect (NLAA)	
Critical Habitats		



There are no critical habitats within the project area.

In order to complete the informal consultation process, we are requesting your concurrence for the NE determination for the Puerto Rican Parrot and a NLAA determination for the Puerto Rican Harlequin Butterfly. Attached to this letter, we are including the documents used to reach our effect determinations for the listed species. Should you require any additional information, please contact Allison Cullett at <u>allison.cullett@horne.com</u>.



### **References:**

### Puerto Rican boa (Chilabothrus inornatus)

Species Profile: https://ecos.fws.gov/ecp/species/6628 USFWS Puerto Rican boa Conservation Measures

**Puerto Rican Broad-winged Hawk** (*Buteo platypterus brunnescens*) Species Profile: https://ecos.fws.gov/ecp/species/5512

**Puerto Rican Parrot** (*Amazona vittata*) Species profile: https://ecos.fws.gov/ecp/species/3067

### Puerto Rican Sharp-shinned Hawk (Accipiter striatus venator)

Species profile: https://ecos.fws.gov/ecp/species/604

#### Puerto Rican Harlequin Butterfly (Atlantea tulita)

Species profile: https://ecos.fws.gov/ecp/species/9005



**Exhibit A: Figures** 






# Location: Aerial Map Puerto Rico Department of Housing ReGrow


Application ID: PR-RGRW-00518

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013



#### Legend:





Source Centro de Recaudación de Ingresos Municipales (CRIM) https://catastro.crimpr.net/cdprpc/

Figure 1: PR-RGRW-00518 Location Map






### Location: USGS Topographic Map

Puerto Rico Department of Housing ReGrow

Application ID: PR-RGRW-00518

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013









## Area of Potential Effect


Puerto Rico Department of Housing ReGrow

#### Application ID: PR-RGRW-00518

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013



### Legend: Area of Potential Effect (15 mts) Storage Warehouse Parcel-00518 CRIM\_Parcels\_2018



Source Centro de Recaudación de Ingresos Municipales (CRM) https://catastro.crimpr.net/cdprpc/

Figure 3: PR-RGRW-00518 Area of Potential Effect Map





DOTEL REPAIL DURD and, GRED PETRO DEA, AMERICAN, BAN AMERICAN, P.P. 002020 TELEVERYPED-02200

## Farmland Protection

Puerto Rico Department of Housing ReGrow

Application ID: PR-RGRW-00518

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013





0.1 0.2 km Service Layer Oredh: Source: Exi, Maxar, Earthstor Geographics, and the GS User Community Exi, Garmin, GEBCO, NOAA NGDC, and other contributors Source

Source 1:5,000 Nafland Resources Conservations Service (NRCS) Oridald Sal Survey Geographic Database (pSSURGO) https://data.nal.usda.gov/datasel/soil-survey-geographic-database-surgo

Figure 4: PR-RGRW-00518 Farmland Protection Map






#### Application ID: PR-RGRW-00518


Angeles Rodríguez Sepulveda

Puerto Rico Department of Housing ReGrow

Threatened & Endangered Species Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.11462, Long:-66.617013







NOAA Office of Response and Restoration https://response.restoration.noaa.gov/



1:100.000

Figure 5: PR-RGRW-00518 Critical Habitats Map





# Wetlands Map Puerto Rico Department of Housing ReGrow

Application ID: PR-RGRW-00518

Angeles Rodríguez Sepulveda Carr 505 Barrio Monte Ilano, Sector Seto 2, Ponce, PR 00717 Catastro: 317-000-001-31-002 Lat: 18.114682, Long:-66.617013



Legend:



0.2 mi 0.1 0.3 km 0.15

1:5,000

er Credits: Source: Esi, Maxar, Earthsta Geographics, and the GS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contribu

Source

U.S. Fish and Wildlife Service - National Weatlands Inventory https://www.lws.gov/program/national-weitlands-inventory

Figure 6: PR-RGRW-00518 Wetlands Map



**Exhibit B: Information for Planning and Consultation (IPaC)** 



## United States Department of the Interior

FISH AND WILDLIFE SERVICE Caribbean Ecological Services Field Office Post Office Box 491 Boqueron, PR 00622-0491 Phone: (939) 320-3135 Fax: (787) 851-7440 Email Address: <u>CARIBBEAN ES@FWS.GOV</u>



In Reply Refer To: Project Code: 2024-0064204 Project Name: PR-RGRW-00518 03/18/2024 16:54:39 UTC

# Subject: List of threatened and endangered species that may occur in your proposed project location or may be affected by your proposed project

To Whom It May Concern:

The enclosed species list identifies threatened, endangered, proposed, and candidate species, as well as proposed and final designated critical habitat, that may occur within the boundary of your proposed project and/or may be affected by your proposed project. The species list fulfills the requirements of the U.S. Fish and Wildlife Service (Service) under section 7(c) of the Endangered Species Act (Act) of 1973, as amended (16 U.S.C. 1531 *et seq.*).

New information based on updated surveys, changes in the abundance and distribution of species, changed habitat conditions, or other factors could change this list. Please feel free to contact us if you need more current information or assistance regarding the potential impacts to federally proposed, listed, and candidate species and federally designated and proposed critical habitat. Please note that under 50 CFR 402.12(e) of the regulations implementing section 7 of the Act, the accuracy of this species list should be verified after 90 days. This verification can be completed formally or informally as desired. The Service recommends that verification be completed by visiting the IPaC website at regular intervals during project planning and implementation for updates to species lists and information. An updated list may be requested through IPaC by completing the same process used to receive the enclosed list.

The purpose of the Act is to provide a means whereby threatened and endangered species and the ecosystems upon which they depend may be conserved. Under sections 7(a)(1) and 7(a)(2) of the Act and its implementing regulations (50 CFR 402 *et seq.*), Federal agencies are required to utilize their authorities to carry out programs for the conservation of threatened and endangered species and to determine whether projects may affect threatened and endangered species and/or designated critical habitat.

A Biological Assessment is required for construction projects (or other undertakings having similar physical impacts) that are major Federal actions significantly affecting the quality of the human environment as defined in the National Environmental Policy Act (42 U.S.C. 4332(2)

(c)). For projects other than major construction activities, the Service suggests that a biological evaluation similar to a Biological Assessment be prepared to determine whether the project may affect listed or proposed species and/or designated or proposed critical habitat. Recommended contents of a Biological Assessment are described at 50 CFR 402.12.

If a Federal agency determines, based on the Biological Assessment or biological evaluation, that listed species and/or designated critical habitat may be affected by the proposed project, the agency is required to consult with the Service pursuant to 50 CFR 402. In addition, the Service recommends that candidate species, proposed species and proposed critical habitat be addressed within the consultation. More information on the regulations and procedures for section 7 consultation, including the role of permit or license applicants, can be found in the "Endangered Species Consultation Handbook" at: <a href="https://www.fws.gov/sites/default/files/documents/endangered-species-consultation-handbook.pdf">https://www.fws.gov/sites/default/files/documents/endangered-species-consultation-handbook.pdf</a>

**Migratory Birds**: In addition to responsibilities to protect threatened and endangered species under the Endangered Species Act (ESA), there are additional responsibilities under the Migratory Bird Treaty Act (MBTA) and the Bald and Golden Eagle Protection Act (BGEPA) to protect native birds from project-related impacts. Any activity, intentional or unintentional, resulting in take of migratory birds, including eagles, is prohibited unless otherwise permitted by the U.S. Fish and Wildlife Service (50 C.F.R. Sec. 10.12 and 16 U.S.C. Sec. 668(a)). For more information regarding these Acts, see <u>Migratory Bird Permit | What We Do | U.S. Fish & Wildlife</u> <u>Service (fws.gov)</u>.

The MBTA has no provision for allowing take of migratory birds that may be unintentionally killed or injured by otherwise lawful activities. It is the responsibility of the project proponent to comply with these Acts by identifying potential impacts to migratory birds and eagles within applicable NEPA documents (when there is a federal nexus) or a Bird/Eagle Conservation Plan (when there is no federal nexus). Proponents should implement conservation measures to avoid or minimize the production of project-related stressors or minimize the exposure of birds and their resources to the project-related stressors. For more information on avian stressors and recommended conservation measures, see <a href="https://www.fws.gov/library/collections/threats-birds">https://www.fws.gov/library/collections/threats-birds</a>.

In addition to MBTA and BGEPA, Executive Order 13186: *Responsibilities of Federal Agencies to Protect Migratory Birds*, obligates all Federal agencies that engage in or authorize activities that might affect migratory birds, to minimize those effects and encourage conservation measures that will improve bird populations. Executive Order 13186 provides for the protection of both migratory birds and migratory bird habitat. For information regarding the implementation of Executive Order 13186, please visit <u>https://www.fws.gov/partner/council-conservation-migratory-birds</u>.

We appreciate your concern for threatened and endangered species. The Service encourages Federal agencies to include conservation of threatened and endangered species into their project planning to further the purposes of the Act. Please include the Consultation Code in the header of this letter with any request for consultation or correspondence about your project that you submit to our office. Attachment(s):

Official Species List

## **OFFICIAL SPECIES LIST**

This list is provided pursuant to Section 7 of the Endangered Species Act, and fulfills the requirement for Federal agencies to "request of the Secretary of the Interior information whether any species which is listed or proposed to be listed may be present in the area of a proposed action".

This species list is provided by:

### **Caribbean Ecological Services Field Office**

Post Office Box 491 Boqueron, PR 00622-0491 (939) 320-3135

## **PROJECT SUMMARY**

Project Code:	2024-0064204
Project Name:	PR-RGRW-00518
Project Type:	New Constr - Above Ground
Project Description:	The proposed activities for PR-RGRW-00518 consist of installation of a
	12' x 12' storage warehouse. The installation of the storage warehouse
	will require ground disturbance. The storage warehouse will be installed
	on a concrete slab measuring $12' \ge 12'$ which will be provided by the
	applicant. Additionally, the proposed project includes the purchase of a
	coffee grinder, coffee roasting machine and farm equipment. The purpose
	of storage is to store the new equipment for the farm. No water
	connection will be necessary for the new warehouse. The power needed to
	operate the coffee toaster and coffee grinder will be provided by an
	inverter. The project area is located at PR-505 Barrio Monte Llano, Sector
	El Seto 2, within the Municipality of Ponce. Based on a review of
	historical aerial imagery, the general area has been used for agricultural
	purposes for the past 20 years.

### Project Location:

The approximate location of the project can be viewed in Google Maps: <u>https://www.google.com/maps/@18.11430225,-66.61629021540689,14z</u>



Counties: Ponce County, Puerto Rico

## **ENDANGERED SPECIES ACT SPECIES**

There is a total of 5 threatened, endangered, or candidate species on this species list.

Species on this list should be considered in an effects analysis for your project and could include species that exist in another geographic area. For example, certain fish may appear on the species list because a project could affect downstream species.

IPaC does not display listed species or critical habitats under the sole jurisdiction of NOAA Fisheries<sup>1</sup>, as USFWS does not have the authority to speak on behalf of NOAA and the Department of Commerce.

See the "Critical habitats" section below for those critical habitats that lie wholly or partially within your project area under this office's jurisdiction. Please contact the designated FWS office if you have questions.

1. <u>NOAA Fisheries</u>, also known as the National Marine Fisheries Service (NMFS), is an office of the National Oceanic and Atmospheric Administration within the Department of Commerce.

### BIRDS

NAME	STATUS
Puerto Rican Broad-winged Hawk <i>Buteo platypterus brunnescens</i> No critical habitat has been designated for this species. Species profile: <u>https://ecos.fws.gov/ecp/species/5512</u>	Endangered
Puerto Rican Parrot <i>Amazona vittata</i> No critical habitat has been designated for this species. Species profile: <u>https://ecos.fws.gov/ecp/species/3067</u>	Endangered
Puerto Rican Sharp-shinned Hawk Accipiter striatus venator No critical habitat has been designated for this species. Species profile: <u>https://ecos.fws.gov/ecp/species/604</u>	Endangered

### REPTILES

NAME	STATUS
Puerto Rican Boa Chilabothrus inornatus	Endangered
No critical habitat has been designated for this species.	
Species profile: <u>https://ecos.fws.gov/ecp/species/6628</u>	
General project design guidelines:	
https://ipac.ecosphere.fws.gov/project/VWJFMYXOJBEANJ2YT27ECRSFJ4/documents/	
generated/7159.pdf	

### **INSECTS**

NAME	STATUS
Puerto Rican Harlequin Butterfly Atlantea tulita	Threatened
There is <b>final</b> critical habitat for this species. Your location does not overlap the critical habitat.	
Species profile: <u>https://ecos.fws.gov/ecp/species/9005</u>	
General project design guidelines:	
https://ipac.ecosphere.fws.gov/project/VWJFMYXOJBEANJ2YT27ECRSFJ4/documents/	
generated/7168.pdf	

### **CRITICAL HABITATS**

THERE ARE NO CRITICAL HABITATS WITHIN YOUR PROJECT AREA UNDER THIS OFFICE'S JURISDICTION.

YOU ARE STILL REQUIRED TO DETERMINE IF YOUR PROJECT(S) MAY HAVE EFFECTS ON ALL ABOVE LISTED SPECIES.



## United States Department of the Interior

FISH AND WILDLIFE SERVICE Caribbean Ecological Services Field Office Post Office Box 491 Boqueron, PR 00622-0491 Phone: (939) 320-3135 Fax: (787) 851-7440 Email Address: <u>CARIBBEAN ES@FWS.GOV</u>



In Reply Refer To: Project code: 2024-0064204 Project Name: PR-RGRW-00518 03/18/2024 16:57:25 UTC

Subject: Consistency letter for the project named 'PR-RGRW-00518' for specified threatened and endangered species, that may occur in your proposed project location, pursuant to the IPaC determination key titled Caribbean Determination Key (DKey).

Dear Applicant:

Thank you for using the assisted evaluation keys in IPaC. This letter is provided pursuant to the Service's authority under the Endangered Species Act of 1973, as amended (ESA) (87 Stat. 884; 16 U.S.C. 1531et seq.). On March 18, 2024, Egon Gonzalez used the Caribbean DKey; dated January 19, 2024, in the U.S. Fish and Wildlife Service's online <u>IPaC application</u> to evaluate potential impacts to federally listed species, from a project named 'PR-RGRW-00518'. The project is located in Ponce County, Puerto Rico (shown below).

The approximate location of the project can be viewed in Google Maps: <u>https://www.google.com/maps/@18.11430225,-66.61629021540689,14z</u>



The following description was provided for the project 'PR-RGRW-00518':

The proposed activities for PR-RGRW-00518 consist of installation of a 12' x 12' storage warehouse. The installation of the storage warehouse will require ground disturbance. The storage warehouse will be installed on a concrete slab measuring 12' x 12' which will be provided by the applicant. Additionally, the proposed project includes the purchase of a coffee grinder, coffee roasting machine and farm equipment. The purpose of storage is to store the new equipment for the farm. No water connection will be necessary for the new warehouse. The power needed to operate the coffee toaster and coffee grinder will be provided by an inverter. The project area is located at PR-505 Barrio Monte Llano, Sector El Seto 2, within the Municipality of Ponce. Based on a review of historical aerial imagery, the general area has been used for agricultural purposes for the past 20 years.

Based on your answers and the assistance of the Service's Caribbean DKey, you determined the proposed Action will have "No Effect" on the following species:

Species	Listing Status	Determination
Puerto Rican Boa (Chilabothrus inornatus)	Endangered	No effect
Puerto Rican Broad-winged Hawk (Buteo platypterus	Endangered	No effect
brunnescens)		
Puerto Rican Sharp-shinned Hawk (Accipiter striatus	Endangered	No effect
venator)		

Thank you for informing the Service of your "No Effect" determination(s) for this project. No further consultation/coordination for this project is required for these species. However, be aware that reinitiation of consultation may be necessary if later modifications are made to the project so that it no longer meets the criteria or outcome described above, or if new information reveals effects of the action that could affect listed species or critical habitat in a manner or to an extent not previously considered, or if a new species is listed.

This letter serves as documentation of your consideration of the federally listed species as required under section 7 of the ESA. However, effects to the other federally listed species or critical habitat as listed below from the "IPaC print-out for the project" (see below) should be considered as part of your ESA review for the project.

The Service will notify you within 30 calendar days if we determine that this proposed Action does not meet the criteria for a "No Effect" (NE) determination for Federally listed species in the Caribbean. If we do not notify you within that timeframe, you may proceed with the Action under the terms of the NE concurrence provided here. This verification period allows the Caribbean Ecological Services Field Office to apply local knowledge to evaluate the Action, as we may identify a small subset of actions having unanticipated impacts. In such instances, the Caribbean Ecological Services Field Office may request additional information to verify the effects determination reached through the DKey.

**Note:** Projects located within the range of the Puerto Rican boa or the Virgin Islands tree boa might encounter these species during project activities. **This letter does not provide take to handle or move these species**. If relocation of the species is needed, please contact either the

Puerto Rico Department of Natural Resources (DNER) at 787-724-5700, 787-230-5550, or 787-771-1124 for projects in Puerto Rico, or the Virgin Islands Department of Planning and Natural Resources, Division of Fish and Wildlife (DFW) at 340-775-6762 for projects in the Virgin Islands. Otherwise, contact the Caribbean Ecological Services Field Office (caribbean\_es@fws.gov) to determine whether the consultation needs to be reinitiated.

In addition to the species listed above, the following species and/or critical habitats may also occur in your project area and **are not** covered by this conclusion. Effects to the other federally listed species or critical habitat as listed below should be considered as part of your ESA review for the project.

- Puerto Rican Harlequin Butterfly Atlantea tulita Threatened
- Puerto Rican Parrot Amazona vittata Endangered

If the proposed project is located within species range where a DKey has not been developed for those species, please follow the established guidance for initiating section 7 consultation Caribbean Ecological Services Field Office.

We appreciate your interest in protecting endangered species and their habitats. It is the Service's mission to work with others to conserve, protect, and enhance fish, wildlife, and plants and their habitats for the continuing benefit of our people. If you have any questions or require additional information, please contact our office at Caribbean\_es@fws.gov.

### **Action Description**

You provided to IPaC the following name and description for the subject Action.

### 1. Name

PR-RGRW-00518

### 2. Description

The following description was provided for the project 'PR-RGRW-00518':

The proposed activities for PR-RGRW-00518 consist of installation of a 12' x 12' storage warehouse. The installation of the storage warehouse will require ground disturbance. The storage warehouse will be installed on a concrete slab measuring 12' x 12' which will be provided by the applicant. Additionally, the proposed project includes the purchase of a coffee grinder, coffee roasting machine and farm equipment. The purpose of storage is to store the new equipment for the farm. No water connection will be necessary for the new warehouse. The power needed to operate the coffee toaster and coffee grinder will be provided by an inverter. The project area is located at PR-505 Barrio Monte Llano, Sector El Seto 2, within the Municipality of Ponce. Based on a review of historical aerial imagery, the general area has been used for agricultural purposes for the past 20 years.

The approximate location of the project can be viewed in Google Maps: <u>https://www.google.com/maps/@18.11430225,-66.61629021540689,14z</u>



## **QUALIFICATION INTERVIEW**

1. Is the proposed project an EPA Multi-Sector General Permit (MSGP) renewal for an existing project? (MSGP Fact Sheet)

No

2. Is the proposed project within an urban developed area? (i.e., cities, downtowns, shopping malls etc.)

**Note:** Urban and developed areas has one or more of the following characteristics: Presence of existing buildings, residential areas, and commercial establishments. Well-established infrastructure including roads, utilities, and urban facilities. High population density. Established neighborhoods and urban amenities ("urbanizaciones"). Developed landscape with paved surfaces, parking lots, and industrial areas. Signs of human activity and urbanization, such as shopping centers and recreational facilities. Location within the boundaries of a city or town ("casco urbano"). High concentration of built-up structures and limited open spaces. Aerial imagery might be requested to the applicant. .

No

3. Does the proposed project consist of rehabilitation or demolition of existing single-family homes and buildings?

No

4. Does the proposed project consist of improvements to existing facilities?

**Note:** Examples of facilities are occupied single family homes, and buildings; existing recreational facilities, including the installation of roofs to existing basketball courts, etc.

No

5. Does the proposed project consist of repavement or repair of existing roads and installing transit signage or guardrails?

No

6. Does the proposed project consist of the construction of gutters and/or sidewalks along existing roads, and developments?

No

7. Does the proposed project consist of replacement or repair of existing bridges which include cutting vegetation or earth movement?

No

8. Does the proposed project consist of activities within existing Right of Ways (ROWs) along roads which include cutting vegetation or earth movement?

No

9. Is the proposed project located within a rural area covered by grassland (pasture lands "pastos")?

Yes

10. [Hidden Semantic] Does the proposed project intersect the Puerto Rican boa area of influence?

Automatically answered *Yes* 

11. Does the proposed project intersect the Puerto Rican sharp-shinned hawk area of influence?

Automatically answered Yes

12. Does the proposed project intersect the Puerto Rican Broad-winged hawk area of influence?

Automatically answered *Yes* 



**Exhibit C: Field Visit Photos** 



Photo #:1	Description (include direction): Area where the storage warehouse will be installed, looking southeast.	
Date: February 16, 2024	warenouse will be installed, looking soonledst.	
Photo #:2	Description (include direction): Area where the storage warehouse will be installed, looking northwest.	
Date: February 16, 2024	Autoriouse will be installed, tooking nontwest.	



### Transmittal Letter

July 22, 2024

### To: José Luis Rivera Rivera

Deputy Director for Economic Recovery Grant Management Re-Grow PR Urban Rural Agriculture Program

### Re: Endangered Species Concurrence - Conservation Measures Implementation Ángeles Rodríguez Sepúlveda | PR-RGRW-00518

Dear Mr. Rivera:

This memorandum is to notify the Re-Grow PR Urban-Rural Agriculture Program (Re-Grow Program) that on April 4, 2024, for the case **PR-RGRW-00518**, the CDBG-DR/MIT Permits and Environmental Compliance Division submitted an informal consultation under Section 7 (a)(2) of the Endangered Species Act (Act) (87 Stat. 884, as amended; 16 United States Code 1531 et seq.), and in accordance with the Fish and Wildlife Coordination Act (47 Stat. 401, as amended; 16 U.S.C. 661 et seq.) for the proposed project of the construction of a storage warehouse over a new concrete slab, for Ángeles Rodríguez Sepúlveda, an agricultural business, located at carretera PR-505, barrio Monte Llano, sector Seto 2, Ponce, PR 00717; coordinates18.114682, -66.6171013.

Using the Information for Planning and Consultation (IPaC) system, the proponent has determined that the proposed project lies within the range of the following federally listed species:

Name of Species	Status
Puerto Rican Boa (Chilabothrus inornatus)	Endangered
Puerto Rican Broad-winged Hawk (Buteo platypterus brunnescens)	Endangered
Puerto Rican Parrot (Amazona vittata)	Endangered
Puerto Rican Sharp-shinned Hawk (Accipiter striatus venator)	Endangered
Puerto Rican Harlequin Butterfly (Atlantea tulita)	Threatened

There were no Critical Habitats noted within the project area.

The United States Fish and Wildlife Service (USFWS) Caribbean Ecological Services Field Office reviewed the information provided and their files, and on May 16, 2024 concurred with the determination that the proposed project actions will have **No Effect (NE)** on the Puerto Rican Parrot, Puerto Rican Broad-winged Hawk and Puerto Rican Sharp-shinned Hawk. Also, the PRDOH together with the USFWS have determined that the proposed project **May Affect, but is Not Likely to Adversely Affect (NLAA)** the Puerto Rican Boa and Puerto Rican Harlequin Butterfly.

The USFWS NLAA concurrence is conditioned to the following: (1) if a Boa is encountered, the Conservation Measures will be in accordance with the USFWS Puerto Rican Boa Conservation Measures 2024, (2) if a Puerto Rican Parrot is encountered on the site, the USFWS Caribbean Office will be notified immediately, (3) if a Puerto Rican Broad-winged Hawk is encountered on the site, the USFWS Caribbean Office will be notified immediately, (3) if a Puerto Rican Broad-winged Hawk is encountered on the site, the USFWS Caribbean Office will be notified immediately, (4) if a Puerto Rican Sharp-shinned Hawk is encountered on the site, the USFWS Caribbean Office will be notified immediately, and (5) if a Puerto Rican Harlequin Butterfly is encountered in the site, the Conservation Measures will be in accordance with the USFWS Puerto Rican Harlequin Butterfly Conservation Measures.

Obligations under section 7 of the Act must be reconsidered if: (1) new information reveals impacts of this identified action that may affect listed species or critical habitat in a manner that was not previously considered; (2) this action is subsequently modified in a manner not previously considered in this assessment; or, (3) a new species is listed, or critical habitat determined that may be affected by the identified action.

In conclusion, the USFWS concurred with the CDBG-DR/MIT Permits and Environmental Compliance Division NLAA determination. However, the applicant must be informed about the conditions of the determination of concurrence and implement them as described.

In order to facilitate the species identification, please, find attached the Caribbean Endangered and Threatened Animals Fact Sheets for: Puerto Rican Boa, Puerto Rican Parrot, Puerto Rican Broad-winged Hawk, Puerto Rican Sharp-shinned Hawk and Puerto Rican Harlequin Butterfly.

USFWS Caribbean Ecological Services Field Office key contact information:

 José Cruz-Burgos, Endangered Species Coordinator Office phone (786) 244-0081 or mobile (305) 304-1386 Email: jose\_cruz-burgos@fws.gov

Sincerely,

Permits and Environmental Compliance Division Disaster Recovery Office <u>environmentcdbg@vivienda.pr.gov</u> (787)274-2527 | ext. 4320

### **CDBG-DR** FUNDS




### U.S. FISH AND WILDLIFE SERVICE CARIBBEAN ECOLOGICAL SERVICES FIELD OFFICE

#### Conservation Measures for the Puerto Rican boa (Chilabothrus inornatus)

Section 7 (a)(1) of the Endangered Species Act (ESA) charges Federal agencies to aid in the conservation of listed species, and section 7 (a)(2) requires the agencies, through consultation with the U.S. Fish and Wildlife Service (Service), to ensure their activities are not likely to jeopardize the continued existence of listed species or adversely modify designated critical habitats. Section 7 applies to the management of Federal lands as well as Federal actions that may affect federally listed species, such as Federal approval of private activities through the issuance of Federal funding, permits, licenses, or other actions. Any person that injures, captures, or kills a Puerto Rico boa is subject to penalties under the ESA. If Federal funds or permits are needed, the funding or permitting agency should initiate Section 7 consultation with the Service. To initiate a consultation under the Section 7 of the ESA, you must submit a project package with the established minimum requirements. These conservation measures should be incorporated into the project plans to minimize possible impacts to the species.

The endangered Puerto Rican (PR) boa (*Chilabothrus inornatus*, formerly *Epicrates inornatus*) is the largest endemic snake species that inhabits Puerto Rico. The PR boa is non-venomous and does not pose any life threatening danger to humans, but some individuals may try to bite if disturbed or during capture or handling. Its body color ranges from tan to dark brown with irregular diffuse marking on the dorsum, but some individuals lack marking and are uniformly dark. Juveniles may have a reddish color with more pronounced markings. In general, as they mature, their body color tends to darken.



Last Revised: January 2024

The PR boa was federally listed in 1970. Currently, the species has an island-wide distribution and occurs in a wide variety of habitat types, ranging from wet montane to subtropical dry forest and can be found from mature forest to areas with different degrees of human disturbance such as roadsides or houses, especially if near their habitat in rural areas. The PR boa is considered mostly nocturnal, remaining less active, concealed or basking under the sun during the day.

The Service has developed the following conservation measures with the purpose of assisting others to avoid or minimize adverse effects to the PR boa and its habitat. These recommendations may be incorporated into new project plans and under certain circumstances into existing projects. Depending on the project, additional conservation measures can be implemented besides the ones presented in this document.

Conservation Measures:

- 1. Inform all project personnel about the potential presence of the PR boa in areas where the proposed work will be conducted. A pre-construction meeting should be conducted to inform all project personnel about the need to avoid harming the species as well as penalties for harassing or harming PR boas. An educational poster or sign with photo or illustration of the species should be displayed at the project site.
- 2. Prior to any construction activity, including removal of vegetation and earth movements, the boundaries of the project and areas to be excluded and protected should be clearly marked in the project plan and in the field in order to avoid further habitat degradation into forested and conservation areas.
- 3. Once areas are clearly marked, and prior to the use of heavy machinery and any construction activity (including removal of vegetation and earth movement), a biologist or project personnel with experience on this species should survey the areas to be cleared to verify the presence of any PR boa within the work area.
- 4. If a PR boa is found within any of the working or construction areas, activities should stop at that area and information recorded (see #5). Do not capture the boa. If boas need to be moved out of harm's way, designated personnel shall immediately contact the Puerto Rico Department of Natural and Environmental Resources (PRDNER) Rangers for safe capture and relocation of the animal (PRDNER phone #s: (787) 724-5700, (787) 230-5550, (787) 771-1124). If immediate relocation is not an option, project-related activities at that area must stop until the boa moves out of harm's way on its own. Activities at other work sites, where no boas have been found after surveying the area, may continue.
- 5. For all boa sightings (dead or alive), record the time and date of the sighting and the specific location where it was found. PR boa data should also include a photo of the animal (dead or alive), site GPS coordinates, the time and date, and comments on how the animal was detected and its behavior.

Last Revised: January 2024

- 6. If a PR boa is captured by PRDNER personnel, record the name of that person and information on where the PR boa will be taken. This information should be reported to the Service.
- 7. Measures should be taken to avoid and minimize PR boa casualties by heavy machinery or motor vehicles being used on site. Any heavy machinery left on site (staging) or near potential PR boa habitat (within 50 meters of potential boa habitat), needs to be thoroughly inspected each morning before work starts to ensure that no boas have sheltered within engine compartments or other areas of the equipment. If PR boas are found within vehicles or equipment, do not capture the animal, and let it move on its own or call PRDNER Rangers for safe capture and relocation of the animal (see #4). If not possible, the animal should be left alone until it leaves the vehicle on its own.
- 8. PR boas may seek shelter in debris piles. Measures should be taken to avoid and minimize boa casualties associated with sheltering in debris piles as a result of project activities. Debris piles should be placed far away from forested areas. Prior to moving, disposing or shredding, debris piles should be carefully inspected for the presence of boas. If debris piles will be left on site, we recommend they be placed in areas that will not be disturbed in the future.
- 9. If a dead PR boa is found, immediately cease all work in that area and record the information accordingly (see #5). If the PR boa was accidentally killed as part of the project actions, please include information on what conservation measures had been implemented and what actions will be taken to avoid further killings. A dead boa report should be sent by email (see contacts below) to the Service within 48 hours of the event.
- Projects must comply with all state laws and regulations. Please contact the PRDNER for further guidance.
- If you have any questions regarding the above conservation measures, please contact the Service:
  - José Cruz-Burgos, Endangered Species Program Coordinator
    - Email: jose\_cruz-burgos@fws.gov
    - Office phone (305) 304-1386
  - Jan Zegarra, Fish and Wildlife Biologist
    - Email: jan\_zegarra@fws.gov
      - o Office phone (786) 933-1451

### Cotorra puertorriqueña Amazona vittata vittata

#### Familia: Psittacidae Orden: Psittaciformes

#### Descripción

La cotorra puertorriqueña o Iguaca, como la llamaban los indios taínos, es un ave verde brillante con una mancha roja en la frente, un anillo blanco alrededor del ojo y plumas primarias azules. Su pico es color marfil y el borde de su cola es redondo. Los juveniles son bastante parecidos a los adultos. Tanto hembras como machos son parecidos y miden cerca de doce pulgadas (aprox. 30 centímetros). A veces, la franja roja en la frente es más ancha en los machos que en las hembras. Mientras vuela emite un fuerte y ruidoso "kar...kar." Este sonido se escucha a gran distancia. Emite otros sonidos para comunicarse con otras cotorras y para defender su territorio.

#### Información biológica

#### Reproducción

La cotorra puertorriqueña alcanza su edad reproductiva entre los 3 a 5 años. Las cotorras usualmente forman

Distribución 📕

parejas que perduran por mucho tiempo, normalmente de por vida. Las parejas permanecen juntas casi todo el año, excepto cuando la hembra está incubando y el macho asume la responsabilidad de proveer alimento. La cotorra usa como nido las cavidades que se encuentran en árboles de gran tamaño como el palo colorado (*Cyrilla racemiflora*), entre otros. De ser necesario, también podría anidar en las cavidades de roca caliza. El anidamiento comienza en los meses de febrero y marzo, hasta junio. Tradicionalmente, la anidación coincide con el período más seco del año y durante el período de fructificación (producir frutos) de plantas cuyas semillas, frutas y hojas le sirven de alimento.

#### Dieta

La cotorra come plantas tales como: palma de sierra, palma real, maricao, maria, guaba, cupey, guaraguao y yagrumo, entre otros árboles.

#### Distribución

La cotorra puertorriqueña, ave endémica a Puerto Rico fue abundante en Puerto Rico, incluyendo las islas de Culebra, Vieques y Mona. Esta cotorra es la última especie de psitácidos existentes y originaria en territorio de los Estados Unidos. Los psitácidos son la familia de aves, en su mayoría tropicales, con plumas de colores vivos y pico corto, alto y muy encorvado (ej. guacamayo y cotorra). La población silvestre de cotorras puertorriqueñas se limita actualmente a la Sierra de Luquillo, mayormente en el Bosque Nacional El Yunque, al este de Puerto Rico y en el Bosque Estatal de Río Abajo, en el norte central de Puerto Rico, entre Arecibo y Utuado. Al menos tres de las cotorras liberadas en Río Abajo se han dispersado y en 2012 fueron vistas entre Morovis, Vega Baja y Manatí.



### Guaraguao de bosque Buteo platypterus brunnescens



#### Descripción

El guaraguao de bosque de Puerto Rico o guaraguaito es de color marrón oscuro con barras blancas y rojizas en la parte ventral. Es una subespecie endémica de Puerto Rico de tamaño mediano, que mide aproximadamente 39 centímetros (15.5 pulgadas). Es más pequeño que el Buteo platypterus platypterus pero más grande que la subespecie que ocurre en las Antillas Menores. El guaraguao de bosque es la subespecie de halcón de ala ancha más oscuro. En los adultos, la cola es de un color negro claro con bandas blancas horizontales en la base, medio y extremo de la cola, y esto, junto con el pecho rojizo, caracteriza a la especie. Los machos y las hembras son muy similares en apariencia, pero las hembras son un poco más grandes. Las aves juveniles tienen barras oscuras en el pecho y no tienen las bandas distintivas en la cola. La población del guaraguao de bosque de Puerto Rico oscila cerca de los 125 individuos.

Distribución 📕

### Información biológica

#### Reproducción

Esta especie anida en bosques secundarios maduros y plantaciones antiguas. En el Bosque Estatal de Río Abajo (RACF, por sus siglas en inglés), los sitios de anidación están caracterizados por la presencia de árboles tales como el palo María (Calophyllum antillanum), la teca (Tectona grandis), la caoba hondureña (Swietenia macrophylla) y la majagua (Hibiscus elatus). Los guaraguaos de bosque colocan sus nidos en la parte superior de árboles grandes que sobrepasan la cubierta forestal. Información recientemente recopilada sobre la abundancia y características demográficas del guaraguao de bosque en RACF indica un alto nivel de fidelidad entre parejas; una tasa de sobrevivencia en nidos de 0.67 a través de la temporada de reproducción; y una productividad de 1.1 crías por nido. Entre los años 2001 a 2003, se marcaron con radio transmisores y se colocaron bandas en las patas a varias crías de guaraguaos en el RACF. En 2013, al visitar el área donde se marcaron, se documentó que seguían vivas (Llerandi-Román and Ríos-Cruz pers. comm.). Por ejemplo, una hembra joven que fue marcada entre el 2001 al 2003 en el RACF fue documentada anidando exitosamente entre los años 2007 al 2009. (Ríos-Cruz pers. comm.)

#### Hábitat

Esta especie habita en bosques enanos, bosques de palmas de sierra, de caimitillo-granadillo y de tabonuco. Estos bosques se encuentran en las reservas forestales del Bosque Estatal de Carite, Bosque Estatal Toro Negro, Bosque Los Tres Picachos y el Bosque Nacional El Yunque. También habita en



plantaciones madereros maduros, en cafetales bajo sombra y en bosques secundarios maduros del área de carso al norte-central de Puerto Rico dentro y cerca del Bosque Estatal de Río Abajo y el área de Río Encantado entre los pueblos de Florida y Ciales. La topografía húmeda de los bosques del carso le provee al guaraguao de bosque otra alternativa como área para anidar. En estudios recientes, se han documentado miembros de una especie similar de guaraguao (guaraguao de cola roja; *Buteo jamaicensis jamaicensis*) anidando en las laderas del carso adyacentes al RACF.

#### Distribución

El guaraguao de bosque es un ave de rapiña poco común y extremadamente localizado, que se encuentra en los bosques montañosos de tierra alta de Puerto Rico. Las poblaciones existentes se hallan primariamente dentro de cinco bosques: el RACF, el Bosque Estatal Carite, el Bosque Estatal Toro Negro, el Bosque Los Tres Picachos y el Bosque Nacional El Yunque. Llerandi-Román (2006) halló trece territorios de guaraguao de bosque justo fuera de los límites de RACF, en seis sitios diferentes con hábitat apropiado para los guaraguaos de bosque. Los territorios se encuentran a lo largo del valle del Río Tanamá, al noroeste del RACF

#### <u>Amenazas</u>

La abundancia y la distribución del guaraguao de bosque es limitada. Cualquier amenaza que atente contra su población y su hábitat puede resultar en detrimento para esta especie. De forma natural, los huracanes constituyen una amenaza ya que destruyen su hábitat debido a las intensas lluvias y a los fuertes vientos. No obstante, existe una gran variedad de actividades humanas que también amenazan las poblaciones de esta especie. La construcción de instalaciones recreativas, de estructuras para energía y comunicaciones y de carreteras contribuye a la destrucción y fragmentación de su hábitat. De igual manera, la caza ilegal, las malas prácticas de manejo y la carencia de planes de manejo para los bosques públicos también afectan las poblaciones del guaraguao de bosque. Los bajos números poblacionales de esta especie pueden, por sí mismos, estar afectando la población ya que se pierde la variación genética de esta.

### Medidas de conservación

El guaraguao de bosque está incluido en la lista de especies amenazadas desde el 1994. La Ley Federal de Especies en Peligro de Extinción de 1973, según enmendada, prohíbe matar, dañar, molestar, atrapar, comprar o vender una especie, así como partes o productos derivados de ellas. El tener la especie en la lista federal fomenta y ayuda a crear acciones de conservación por las agencias federales, estatales, privadas, y por grupos e individuos particulares. La Ley de Especies En Peligro fomenta la compra de terrenos y la cooperación con el Estado, y requiere que se ejecuten acciones de recuperación en relación a todas las especies listadas. Entre las medidas esenciales para proteger el hábitat y fomentar el crecimiento de las poblaciones existentes están: la protección de los sitios de anidamiento y alimento en las áreas públicas y privadas, el mejoramiento de los hábitats, la reforestación en áreas abiertas, la actualización de la información acerca de la distribución y la identificación o creación de corredores biológicos entre poblaciones cercanas (tales como RACF, Los Tres Picachos y Toro Negro) con tal de facilitar el movimiento de los guaraguaos de bosque entre los bosques.

### **Referencias**

Delannoy, C.A. 1992. Status surveys of the Puerto Rican sharpshinned hawk (*Accipiter striatus venator*) and Puerto Rican broad-winged hawk (*Buteo platypterus brunnescens*). Final report submitted to the U.S. Fish and Wildlife Service as specified in work contract no. 14-16-0004-91-031.

Hengstenberg D.W., and F.J. Vilella. 2004. Nesting Ecology and Behavior of Broad-winged Hawks in Moist Karst Forests of Puerto Rico. Journal of Raptor Research. 39(4): 404-416.

Hernández, E. 1980. Estudio de aves, reptiles y anfibios en la reserva forestal de Carite. Informe presentado como requisito del curso Ciencias Naturales 306, Programa de Mantenimiento Ambiental. Facultad de Ciencias Naturales, Universidad de Puerto Rico, Recinto de Rio Piedras, Rio Piedras, Puerto Rico.

Llerandi –Roman, I.C. 2006. Red-tailed Hawk Home range, habitat use, and activity patterns in north-central Puerto Rico. Thesis. Mississippi State University. Mississippi State, MS.

Llerandi-Román, I.C., Rios-Cruz, J.M. and F.J. Vilella. 2009. Cliff-nesting by the Red-tailed Hawk in Moist Karst Forests of Northen Puerto Rico.



Miranda-Castro, L.,A.R. Puente, and S. Vega-Castillo. 2000. First list of the vertebrates os Los Tres Picachos State Forest, Puerto Rico, with data on relative abundance and altitudinal distribution. Caribbean Journal of Science 36(1-2):117-126.

Raffaele, H.A. 1989. A guide of the Birds of Puerto Rico and the Virgin Islands. Princeton University Press, New Jersey.

Snyder, N.F., J.W. Wiley and C.B. Kepler. 1987. The parrots of Luquillo: Natural history and conservation of the Puerto Rican parrot. Western Foundation of Vertebrate Zoology, Los Angeles, California.

U.S. Fish and Wildlife Service. 2010. Puerto Rican broad-winged hawk or guaraguao de bosque (*Buteo platypterus brunnescens*)
5-Year Review. Caribbean Ecological Services Field Office, Boquerón, Puerto Rico.

U.S. Fish and Wildlife Service. 1994. Endangered and Threatened Wildlife and Plants; Determination of Endangered Status for the Puerto Rican broad-winged hawk and the Puerto Rican sharp-shinned hawk. Federal Register 59:46710-46715.

Wiley, J.W. and G.P. Bauer. 1985. Caribbean National Forest, Puerto Rico. American Birds 39:12-18.

Vilella F.J. & D.W. Hengstenberg. 2006. Broad-Winged Hawk (*Buteo platypterus brunnecsens*) movement and habitat use in a moist limestone forest of Puerto Rico. Ornitología Neotropical. 17: 563–579

### Información adicional

Oficina de Servicios Ecológicos del Caribe Dirección: PO Box 491, Boquerón, PR 00622 Teléfono: 787-851-7297 / Fax: 787-851-7440 Internet: www.fws.gov/caribbean







#### Puerto Rican Harlequin Conservation Measures

- The contractor must inform all personnel about the potential presence of the Puerto Rican harlequin butterfly or its occupied host plant "prickly bush" (Oplonia spinosa) in the project areas. A pre-work meeting should inform all project personnel about the need to avoid harming this butterfly and its occupied host plant. Educational material (e.g., posters, flyers or signs with photos or illustrations of all the life stages of the Puerto Rican harlequin butterfly (i.e., eggs, caterpillar, chrysalids and adult, and its host plant) should be prepared and available to all personnel for reference.
- 2. Before starting any project activity, including removal of vegetation and earth movement, the contractor must clearly delineate the boundaries of the working area in the field to avoid unnecessary habitat impacts. Once the project areas are clearly marked, and before any work activity, including site preparation, personnel with knowledge and ability to identify the Puerto Rican harlequin butterfly (all life stages) and the "prickly bush" must survey the areas where the work will be performed for the presence of the species and its host plant. It is important to note that the Puerto Rican harlequin butterfly can be observed year-round in all its life stages; thus, oviposition (egg-laying) may occur at any time during the year.
- 3. If the "prickly bush" is present on the project site, try to avoid cutting it off, even if no eggs, caterpillars, or chrysalids are present.
- 4. If there is no prickly bush within the project area, and the butterfly is observed flying within the project area, do not harass, harm, pursue, wound, kill, trap, capture, collect, or attempt to engage in any such conduct, the species.
- 5. Adult butterflies are often observed flying near the host plant as part of their mating behavior and laying eggs. Project-related activities must stop if the prickle bush is found in the project area and the Puerto Rican harlequin butterfly is observed flying in that same area. A temporary 50-meter (164 feet) buffer zone of no activity or human disturbance should be established and clearly marked around that prickly bush until the butterfly moves out on its own.
- 6. Once the Puerto Rican harlequin butterfly has moved away, within a period of 24 to 36 hours, a search of the prickly bush that has been buffered should be conducted to determine the presence of any eggs, caterpillars, or chrysalids of the butterfly on the plant. The contractor or the Applicant should send a report of the observation and its findings to caribbean\_es@fws.gov after the 36-hour search is concluded.
- 7. If, after the initial search or after the 24 to 36-hour search, any life stage of the Puerto Rican harlequin butterfly is found in the prickly bush, take the following actions:
  - Clearly mark the host plant with flagging tape.
  - $_{\odot}$   $\,$  Establish a 10-meter (32-foot) buffer zone around the bush to protect it.

- Eggs are typically found on the prickly bush's newly grown, tender branches. Once an egg hatches, the caterpillar moves and feeds throughout the bush. Therefore, avoid cutting off the prickly bush within the project site even if no eggs, caterpillars, or chrysalids are present.
- Work within the 10-meter buffered area may resume when no signs of any live life stage of the butterfly are detected, which usually takes approximately 60 to 120 days.
- 8. For all Puerto Rican harlequin butterfly sightings (all life stages), the time and date of the sighting and the specific location where the butterfly was found must be recorded. Data should also include a photo of the butterfly (if possible) and the habitat where it was observed, site GPS coordinates, and comments on how the butterfly was detected and its behavior. All Puerto Rican harlequin butterfly sighting reports should be sent to the USFWS Caribbean Ecological Service Field Office at caribbean\_es@fws.gov.
- 9. For questions regarding the Puerto Rican harlequin butterfly, the Point of Contacts are: José Cruz-Burgos, Endangered Species Coordinator:
  - o Mobile: 305-304-1386
  - o Office phone: 786-244-0081
  - Office Direct Line: 939-320-3120
  - Email: jose\_cruz-burgos@fws.go∨

# Falcón de sierra striatus venator



Distribución 📕

#### Hábitat

El falcón de sierra es una subespecie endémica en Puerto Rico que se encuentra en áreas boscosas asociadas a las zonas de vida conocidas como bosque húmedo subtropical montano bajo y bosque húmedo subtropical (ej. bosque enano, palma de sierra, caimitillo-granadillo y tabonuco).

#### Dieta

Se alimenta primordialmente de aves pequeñas tales como: el comeñame (*Loxigilla portoricensis*), la reinita común (*Coereba flaveola*) y la llorosa (*Nesospingus speculiferus*).

#### Distribución

Las únicas cinco poblaciones existentes de falcón de sierra se encuentran en los bosques montañosos del Bosque Nacional El Yunque y los Bosques Estatales de: Maricao, Toro Negro, Guilarte y Carite. En el año 1992, se estimó una población general de 150 individuos para estos bosques. En censos hechos entre 2012 y 2013 se nota una disminución significativa de individuos en varios de los bosques.

### <u>Amenazas</u>

La destrucción y la modificación del hábitat en Puerto Rico es uno de los factores más importantes que ha afectado el número y la distribución del falcón de sierra. La distribución tan limitada de esta especie puede haber sido resultado de la fragmentación de áreas forestadas que ha ocurrido durante este siglo. Esta ave ha experimentado una merma poblacional de un 60% en el Bosque de Carite y de un 93% en el Bosque Nacional El Yunque. La causa de esta merma es desconocida para los investigadores.



### Familia: Accipitridae Orden: Falconiformes

### <u>Descripción</u>

El falcón de sierra de Puerto Rico es un ave de rapiña que tiene un tamaño de aproximadamente 11 a 13 pulgadas (28 a 33 centímetros). Los adultos tienen la región dorsal del cuerpo de color gris pizarra y la región ventral con barras densas de color rubio-rojizo. Los juveniles son de color marrón claro por encima y densamente listados por debajo. Al vuelo, esta ave muestra las alas cortas, de forma redondeada y la cola estrecha. El falcón de sierra vuela alternando el batir de las alas con el planeo.

### Información biológica

#### Reproducción

Esta ave construye sus nidos de varitas en lo alto de los árboles y pone en ellos tres huevos blancos con manchas pequeñas. La temporada de anidamiento del falcón de sierra comienza en marzo y continúa hasta julio. Entre las amenazas que se han identificado para esta especie se encuentran: prácticas de manejo y cultivo de madera en los bosques, construcción de veredas y carreteras en los bosques, construcción de facilidades recreativas, aumento en el uso de los bosques para fines recreativos y la posibilidad de cacería furtiva. Se ha identificado el parasitismo por la mosca parasítica del género Philornis como un factor de mortandad para pichones del falcón de sierra en Maricao. El falcón de sierra también es susceptible a disturbios naturales tales como las tormentas tropicales fuertes y los huracanes ya que le modifican su hábitat. Sin embargo, el problema principal del falcón de sierra es su baja densidad y lo limitado de su distribución. Esto hace a esta subespecie extremadamente vulnerable a la pérdida de un individuo.

### Medidas de conservación

El falcón de sierra fue incluido en la lista federal de especies en peligro de extinción en 1994 y el plan de recuperación se escribió en 1997. La medida principal que se debe tomar para la conservación del falcón de sierra es la protección de los individuos restantes y de su habitáculo. Debido a que se encuentra en áreas públicas, es imprescindible la implementación de planes de manejo adecuados para asegurar la supervivencia de esta subespecie en los bosques.

La Ley Federal de Especies en Peligro de Extinción de 1973, según enmendada, prohíbe matar, dañar, molestar, atrapar, comprar o vender una especie, así como partes o productos derivados de ellas.

#### <u>Referencias</u>

Cruz, A. and C.A. Delannoy. 1986. Status, breeding biology and conservation needs of the Puerto Rican sharp-shinned hawk, *Accipiter striatus venator*. Final report submitted to the U.S. Fish and Wildlife Service as specified in work contract No. 14-16-0004-82-031. Delannoy, C.A. and A. Cruz. 1991. *Philornis* parasitism and nestling survival of the Puerto Rican Sharp-shinned Hawk. In J.E. Loye and M. Zuk (eds.), Bird-parasite interactions, ecology, evolution and behavior, pp. 93-103. Oxford University Press, New York, 406pp.

Delannoy, C.A. 1997. Status of the broad-winged hawk and sharp-shinned hawk in Puerto Rico. Caribb. J. Sciences 33: 21-33.

Delannoy, C.A. 1992. Status surveys of the Puerto Rican sharpshinned hawk (*Accipiter striatus venator*) and Puerto Rican broad-winged hawk (*Buteo platypterus brunnescens*). Final report submitted to the U.S. Fish and Wildlife Service as specified in work contract No. 14-16-0004-91-031.

Departamento de Recursos Naturales y Ambientales. 2006. Plan de Manejo Forestal y de Vida Silvestre para el Bosque Estatal de Río Abajo, Arecibo y Utuado, Puerto Rico. (Forest Management and Wildlife Plan for the Rio Abajo Commonwealth Forest, Arecibo and Utuado, Puerto Rico), Departamento de Recursos Naturales y Ambientales. 433 pp.

Ewel, J.L. & J.L. Whitmore. 1973. The ecological life zones of Puerto Rico and the U.S. Virgin Islands. USDA Forest Service. Res. Pap. ITF-18.

Raffaele, H.A. 1989. A guide of the birds of Puerto Rico and the Virgin Islands. Princeton University press, New Jersey

Tossas, A. G. 2006. Effects of Hurricane Georges on the resident avifauna of Maricao State Forest, southwestern Puerto Rico. Caribb. J. Sci. 42:81-87

U.S. Fish and Wildlife Service. 1994. Endangered and threatened wildlife and plants; determination of endangered status for the Puerto Rican broad-winged hawk and the Puerto Rican sharp-shinned hawk. Federal Register Vol. 59 (174): 46710-46715.

U.S. Fish and Wildlife Service. 1997. Puerto Rican broad-winged hawk and Puerto Rican sharp-shinned hawk (*Buteo platypterus brunnescens* and *Accipiter striatus venator*) Recovery Plan. U.S. Fish and Wildlife Service, Atlanta, Georgia. 23pp.

### Información adicional

Oficina de Servicios Ecológicos del Caribe Dirección: PO Box 491, Boquerón, PR 00622 Teléfono: 787-851-7297 / Fax: 787-851-7440 Internet: www.fws.gov/caribbean



